

REPAIR ESTIMATE*

VEHICLE NO : SHC 7036R

DATE 10/9/2018 11:20

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>ea</i>			\$ 1,110.10	
	Radiator Grille H Emblem <i>+ 2</i>			\$ 39.50	
	Front Bumper Cover <i>Advised</i>			\$ 1,052.20	
	Front Bumper Sponge <i>3 su</i>			\$ 99.20	
	Front Bumper Reinforcement <i>3 su</i>			\$ 402.10	
	Front Bumper Bracket Top (LH/RH) <i>3 su</i>		\$ 22.40	\$ 44.80	
	Front Bumper Bracket (LH/RH) <i>3 su</i>		\$ 24.60	\$ 49.20	
	SUB TOTAL			\$ 2,797.10	
	LESS 20%			\$ 559.42	
	DISCOUNTED TOTAL			\$ 2,237.68	
	Front Number Plate <i>X su</i>			\$ 25.00	Nett
	Front No Plate Trim Cover <i>X su</i>			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge			<i>200</i>	
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 250.00	
				<i>200</i>	
	TOTAL LABOUR			\$ 600.00	
	ESTIMATE TOTAL			\$ 2,892.68	
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

Larry Ng

