

Jonpin
LKK

KANG

AUTO ENGINEERING PTE LTD

Sin Ming Auto City



160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015
Email: kangauto@singnet.com.sg

M/S ONG CHIN SHENG
BLK319 JURONG EAST
STREET.31, #12-52
SINGAPORE 600319

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP18/09/1121
VEHICLE NO : SJE1852G
MAKE/MODEL : MADAZ 6
DATE OF ACCIDENT : 04.08.18

1 PC	REAR BUMPER	X Repair	607.55	X
1 SET	REAR BUMPER CLIPS	/ all	13.50	/
1 PC	REAR BUMPER LH RETAINER	X NN	16.05	X
1 PC	REAR R/H FENDER	X Repair	661.20	X
1 PC	REAR R/H FENDER INNER SHIELD	X NN	64.80	X
1 PC	PETROL COVER	X NN	89.00	X
1 PC	REAR LH DOOR	/ Bue	1210.50	/
1 PC	REAR LH DOOR REGULATOR	X	569.00	X
1 PC	REAR LH DOOR COVER	X	205.00	X
1 SET	REAR LH DOOR HINGES	X	85.00	X
1 SET	REAR DOOR STONE GUARD	/ Scr	50.00	/
			S\$ 3571.60	1274
			LESS 20%	714.32
			S\$ 2857.28	1019.2
TO CHECK WIRING			S\$ 50.00	X NN
TO TRANSFER NEW DOOR			120.00	60
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL			80.00	40
TO PUTTY & SPRAY PAINT ON DAMAGE PARTS			1200.00	800
LABOUR CHARGE			800.00	400
			S\$ 5107.28	1300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey before/after (4 points) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Suppliers must be resurveyed and is subject to final approval from Insurance Company

YOURS FAITHFULLY

Acknowledged by Repairer
Signature: _____
Date: _____

KANG AUTO ENGINEERING PTE LTD

SGD FIVE THOUSAND ONE HUNDRED SEVEN AND CENTS TWENTY-EIGHTY ONLY.

Chang.
Unpaid repair
After repair photos.
Gue Qiang - 82880282
04/10/18.

2319.2
20%: 1850

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium