



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

10/09/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chim

Asher

CR425008789

Accident date: 07/09/2018

Estimated repair cost for vehicle no: GX3788G TOYOTA LITEACE 2.2 M '04

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Distorted		\$1,072.25 ✓
2	2	Rear Boot Lid Hinge Not new	\$91.80	\$183.60 X
3	2	Rear Boot Lid Shock Absorber Not new	\$291.60	\$583.20 X.
4	1	Rear Boot Lid Emblem Sticker ?		\$43.70 ✓
5	1	Rear Boot Lid LiteAce Sticker new		\$43.50 ✓
6	1	Rear Boot Lid 70km/h Sticker		\$30.00 15(SN).
7	1	Rear Boot Lid Windscreen Seal new		\$105.00 60(SN)
8	1	Rear Boot Lid Windscreen Moulding new		\$171.40 ✓
9	1	Rear Boot Lid Inner Lock Damaged		\$374.80 285.80
10	1	Rear Boot Lid Inner Rubber Lt		\$381.90 285.20
11	1	Rear Boot Lid Inner Trim Board torn		\$781.10 195
12	10	Rear Boot Lid Inner Trim Board Clip new	\$6.50	\$65.00 30
13	1	Rear Boot Lid Number Plate New		\$50.00 X
14	1	Rear Boot Lid Centre Moulding ?		\$277.10 +
15	1	Rear Boot Lid Wiper Arm		\$181.70 +
16	1	Rear Boot Lid Wiper Cover Not new		\$45.50 X
17	1	Rear Boot Lid Wiper Motor		\$589.30 +
18	1	Rear Boot Lid Auto Lock Motor Assy		\$378.40 X
19	2	Rear Tail Lamp Not new	\$329.10	\$658.20 +.
20	2	Rear Fender Repair	\$1,218.10	\$2,436.20 +.
21	1	Rear Bumper Deformed		\$381.10 ✓
22	8	Rear Bumper Clip new	\$6.50	\$52.00 30
23	2	Rear Bumper Side Retainer new	\$131.35	\$262.70 ✓
24	2	Rear Bumper Side Reflector Not new	\$81.10	\$162.20 X.
25	1	Rear Bumper Reverse Sensor Damaged		\$350.00 200(SN)
26	1	Rear End Panel Dented.		\$581.45 ✓
27	1	Rear End Panel Top Garnish 3 Not new		\$277.10 +
28	6	Rear End Panel Top Garnish Clip 3 new	\$6.50	\$39.00 X.
29	1	Rear Exhaust Not new		\$781.10 +

3386.20

2539.65

S.N: 275

Subtotal :- \$11,338.50

Labour charges

To remove & refit cushion	\$120.00 60.
To remove & refit reverse sensor	\$50.00 ✓
To remove & refit rear exhaust	\$280.00 x
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 30
Towing fee	\$100.00 x
Tuff kote	2180 \$150.00 50.
Panel beating	\$1,800.00 1000.
Spray painting	\$1,600.00 800.

Subtotal :- \$4,370.00

Total:- \$15,708.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claim is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 49946.5

H/s: AK.

06 Days.

AK