

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500

Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 7 SEPTEMBER 2018

Third Party Insurer: AIG

Vehicle No: SKJ7807K

Third Party Veh No: SJY9013D

Model: AUDI Q3 2.0

Date of Accident: 5 SEPTEMBER 2018

Chassis: WAUZZZ8UXDR074551 - 2013

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BUMPER		\$1,205.00
2	REAR BUMPER SIDE RETAINER RH/LH	\$37.00	\$74.00
1	REAR BUMPER LOWER DIFFUSER		\$412.50
1	REAR BUMPER REINFORCEMENT		\$544.50
2	REAR BUMPER REVERSE SENSOR	\$210.50	\$421.00
2	REAR BUMPER REVERSE SENSOR RUBBER SEAL	\$9.00	\$18.00
1	REAR BUMPER WIRE HARDNESS		\$490.00
SUB TOTAL			\$3,165.00
Less 5%			-\$158.25
PARTS TOTAL			\$3,006.75

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

2500
\$1,000.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$600.00 2200

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

\$250.00 ?

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$120.00 600

TO CHECK WIRING WITH TEST

\$100.00 200

LABOUR TOTAL \$2,070.00

PEI TING

TOTAL \$5,076.75

*Not Authorized
1.A.1
Reserve Repairs*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

knownedged by Repairer
Signature:
Date: