

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

TP INSURER: India International Insurance Pte Ltd (HQ)

MARK PAUL HENSEL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

*not Advised
Lak Marcus
Take photo before
painting
7 day
11/9/18*

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	18/III/TP-183 (09)
Policy No:		Date of Loss:	06/09/2018
Vehicle Reg. No.:	SLT612L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	WONG CHUI TEING	Driver (Insured):	WONG CHUI TEING

Make/Model: HONDA VEZEL, 1.5 (A)
 Vehicle Colour: BLACK
 Engine No: LEB5947323
 Odometer: 0 KM

Paint Type:
 List Item Discount: 20.00 %
 Total Loss? NO
 Est. Duration of Repair 7 (day)

Vehicle Reg. Date: 16/10/2017

LKK Auto Consultants hence notify
 the Repairer of the following:
 Chassis No: RU31247306

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Description of Accident/Loss ON 06/09/2018 AT 6.30PM, I WAS DRIVING MY CAR (SLT612L) TURNING LEFT FROM KALLANG AIRPORT WAY. I STOPPED TO ALLOW ON-COMING VEHICLE GOING STRAIGHT. SUDDENLY, I FELT A HUGE IMPACT ON MY REAR. WHEN I WAS ALIGHTING, A TAXI (VEH B SHA5845X) THAT COLLIDED ONTO MY REAR THEN DROVE FORWARD AND AGAIN COLLIDED ONTO MY RIGHT DOOR. LUCKILY I AVOIDED IT OR VEHICLE B WOULD HAVE COLLIDED ONTO ME PHYSICALLY. AFTER VEHICLE B REVERSE, I WAS THEN ABLE TO ALIGHT AND I REALISED THERE WAS A THIRD CAR (VEHICLE C SLF1588R) INVOLVED. VEHICLE C'S DRIVER TOLD ME THAT VEHICLE B COLLIDED ONTO ME AND REVERSED TO COLLIDE ONTO HIM AND DROVE FORWARD TO COLLIDE ONTO MY RIGHT DOOR AGAIN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	7,364.48
Miscellaneous Items	320.00
Labour	4,325.00

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLT612L/10/09/2018 11:54

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR GATE <i>300/500</i>	20.00	0.00	*955.00 FL <i>—</i>
2	4		*REAR WINDSCREEN MOULDING <i>ner</i>	20.00	0.00	*180.00 FL <i>—</i>
3	1		*REAR GATE VEZEL EMBLEM <i>ner</i>	20.00	0.00	*49.00 FL <i>—</i>
4	1		*REAR GATE HYBRID EMBLEM <i>ner</i>	20.00	0.00	*48.00 FL <i>—</i>
5	1		*REAR BUMPER (CENTER) <i>7.5</i>	20.00	0.00	*645.00 FL <i>—</i>
6	2		*REAR BUMPER RETAINER <i>0/5 Ref</i>	20.00	0.00	*56.00 FL <i>1pc</i>
7	10		*REAR BUMPER CLIP <i>ner</i>	20.00	0.00	*55.00 FL <i>—</i>
8	1	<i>buys</i>	*REAR RH CORNER LAMP <i>ner</i>	20.00	0.00	*149.00 FL <i>—</i>
9	1		*REAR RH TAIL LAMP	20.00	0.00	*448.00 FL <i>?</i>
10	1		*REAR RH FENDER <i>3.0/500/300</i>	20.00	0.00	*603.00 FL <i>—</i>
11	1		*REAR RH FENDER PROTECTOR <i>To.1</i>	20.00	0.00	*202.00 FL <i>—</i>
12	1		*REAR RH FENDER AIR DUCT <i>4.0/1</i>	20.00	0.00	*35.00 FL <i>2</i>
13	1		*REAR RH FENDER INNER COWLING <i>To.1</i>	20.00	0.00	*95.00 FL <i>—</i>
14	10		*INNER COWLING CLIP <i>ner</i>	20.00	0.00	*55.00 FL <i>—</i>
15	1		*REAR END PANEL	20.00	0.00	*445.00 FL <i>?</i>
16	1		*REAR BUMPER REFLECTOR RH <i>ner</i>	20.00	0.00	*151.00 FL <i>—</i>
17	1		*REAR END PANEL TOP GARNISH <i>1.1</i>	20.00	0.00	*69.00 FL <i>X</i>
18	4		*REAR END PANEL TOP GARNISH CLIP <i>1.1</i>	20.00	0.00	*31.60 FL <i>X</i>
19	1		*REAR EXHAUST BOX <i>R</i>	20.00	0.00	*558.00 FL <i>X</i>
20	1		*REAR EXHAUST BOX CHROME FINISHER <i>1.1</i>	20.00	0.00	*145.00 FL <i>—</i>
21	2		*REAR EXHAUST BOX RUBBER HOLDER <i>1.1</i>	20.00	0.00	*70.00 FL <i>X</i>
22	1		*FRT RH DOOR <i>0/500</i>	20.00	0.00	*845.00 FL <i>—</i>
23	3		*FRT RH DOOR INNER RUBBER <i>ner</i>	20.00	0.00	*114.00 FL <i>—</i>
24	1		*FRT RH DOOR TOP STICKER <i>ner</i>	20.00	0.00	*35.00 FL <i>—</i>
25	1		*FRT RH DOOR LOCK <i>1.1</i>	20.00	0.00	*225.00 FL <i>X</i>
26	1		*FRT RH DOOR HINGE (TOP)	20.00	0.00	*45.00 FL <i>?</i>
27	1		*FRT RH DOOR HINGE (LOWER)	20.00	0.00	*45.00 FL <i>?</i>
28	1		*REAR RH SHOCK ABSORBER <i>1.1</i>	20.00	0.00	*210.00 FL <i>X</i>
29	1		*REAR RH WHEEL HUB	20.00	0.00	*314.00 FL <i>?</i>
30	1		*REAR AXLE <i>1.1</i>	20.00	0.00	*1,513.00 FL <i>?</i>
31	1		*REAR RH SPORTS RIM <i>1.1</i>	20.00	0.00	*815.00 FL <i>450</i>

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 9,205.60

- List Item Discount on L Items (\$\$) 1,841.12

Total Parts (\$\$) 7,364.48

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	1	REAR WINDSCREEN GUM	new	60.00 40
2	1	REVERSE SENSOR	cm	250.00 200
3	1	OD/TP Case (Insurer)	new	10.00
Sub Total (S\$)				320.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00 ✓
3	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00 60
4	CAVITY PROTECTION ON ALL AFFECTED AREA	New	150.00 100
5	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New	350.00 ?
6	4 WHEEL ALIGNMENT	New	65.00 ✓
7	REMOVE & REFIX EXHAUST BOX	New	120.00 60
8	REMOVE & REFIX CUSHION AND SEATS	New	150.00 80
9	TRANSFER DOOR COMPONENTS FROM OLD TO NEW	New	120.00 60
10	LABOUR CHARGE	New	1,600.00 1200
11	SPRAY PAINTING	New	1,500.00 1200
Gross Labour Cost (S\$)			4,325.00

SME Motor Pte Ltd/SLT612L/10/09/2018 11:54. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >