

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05846

Vehicle Insured : SLH8058Y
Accident Date : 08-Sep-2018

Date : 11-Sep-2018

Our Ref : 218151 (AIG) / CHAN

PAGE : 1

KALAIVANI D/O GOVINDASAMY
MRS KAVINCHELVAN KALAIVANI
BLK 5 BOON KENG ROAD
#06-92
Singapore 330005

Not Authorised
11 Sep @ ?
Resurvey After Paint

ESTIMATED COST OF REPAIR FOR M/BENZ E300A SLP4358R

1 pc	Front n/s fender	<i>B</i>	1,184.00	✓
1 pc	Front n/s fender inner shield	<i>cm</i>	272.00	✓
1 pc	Front n/s fender lower moulding	<i>cm</i>	28.00	✓
1 pc	Front n/s fender inner panel	<i>R</i>	3,178.00	X
1 pc	N/s headlamp	<i>cm</i>	3,651.00	✓
1 pc	N/s headlamp control unit		1,865.00	?
1 pc	N/s headlamp HID bulb		568.00	?
1 pc	N/s headlamp top panel	<i>R</i>	166.00	X
1 pc	N/s headlamp lower panel		282.00	?
1 pc	N/s headlamp lower bracket		56.00	?
1 pc	N/s headlamp nozzle		245.00	?
1 pc	N/s headlamp nozzle cover	<i>m/s</i>	112.00	✓
1 pc	N/s nozzle cover spring		15.00	?
1 pc	Front bumper fascia	<i>cm</i>	1,668.00	✓
1 pc	Front n/s bumper side retainer	<i>D</i>	18.00	✓
1 pc	Frt n/s bumper inner parts		79.00	?
1 pc	Front n/s bumper sponge		117.00	?
1 pc	Front bumper reinforcement	<i>R</i>	583.00	X
1 pc	N/s reinforcement side bracket		312.00	?
1 pc	Front n/s bumper day light(LED)	<i>su</i>	589.00	X
1 pc	Front n/s day light cover	<i>Red</i>	81.00	✓
2 pcs	Frt n/s bumper parking sensor @ S\$297.00	<i>Red</i>	594.00	✓
2 pcs	N/s parking sensor o ring @ S\$ 12.00	<i>mc</i>	24.00	✓
1 pc	Front n/s sport rim 17"	<i>Red</i>	1,216.00	✓
1 pc	Front n/s shock absorber		947.00	?
1 pc	Front n/s stabiliza bar link		116.00	?
1 pc	Front n/s knuckle arm		1,368.00	?

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Don't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH8058Y

Page : 2

1 pc	Front n/s knuckle bearing hub	794.00	7
1 pc	Front n/s lower arm	545.00	7
1 pc	Front n/s lower arm ball joint	165.00	7
1 pc	Front n/s thrust arm	561.00	7
1 pc	Front n/s thrust arm bush	182.00	7

21,581.00

Less 10% : 2,158.10

1 pc N/s headlamp chrome moulding

19,422.90
80.00 sn ✓

To rewire damaged parts online to
programme & reset headlamp beam

350.00 7

To dismantle and lower front
undercarriage

250.00 7

To check and adjust wheel alignment

65.00 601

To putty and spray replaced parts

1,000.00 7001

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 500k

To transfer tyre rim and balance

50.00 201

Total : S\$22,117.90

=====

Singapore Dollars Twenty Two Thousand One Hundred
and Seventeen and Cents Ninety Only