

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
Murray B & pain
1-B-1
7 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **10.09.2018**

Accident Date : 07.09.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Alphard" Reg. No. SLZ2201U Claiming Against Your Insured Reg. No. SLD3673A			
1pc	Headlamp Assy RH		3,090.00 X
1pc	Front Bumper	3.80	1,856.00 ✓
13pcs	Front Bumper Clips		49.40 —
1pc	Front Fender RH		1,086.00 —
1pc	Front Fender Shield		281.00 —
10pcs	Front Fender Shield Clips	3.80	38.00 —
1pc	Front Fender Lower Protector		216.00 ?
4pcs	Front Fender Lower Protector Clips	4.80	19.20 ?
1pc	Front Fender Lower Protector Core		245.00 ?
1pc	Front Wheel Rim		1,835.60 ✓
1pc	Front Shock Absorber		426.00 ?
1pc	Front Knuckle Arm		522.00 ?
1pc	Front Knuckle Arm Bearing		514.00 ?
1pc	Front Knuckle Arm Bearing Hub		495.00 ?
1pc	Front Lower Arm		513.00 ?
1pc	Front Lower Arm Ball Joint		205.00 ?
1pc	Front Door RH		1,723.00 ?
1pc	Front Door Sticker (Top)		95.30 —
1pc	Front Door Sticker (Side)		119.00 —
1pc	Front Door Lower Protector		1,086.00 —
10pcs	Front Door Lower Protector Clips	4.80	48.00 —
1pc	Front Door Lower Hinge		91.00 X
1pc	Front Door Rubber Seal (1)		112.00 ?
1pc	Front Door Rubber Seal (2)		136.00 ?
1pc	Front Door Weatherstrip		362.00 X
1pc	Front Door Trim Board		1,510.00 X
1pc	Front Door Lower Inner Trim		265.00 ?
1pc	Rear Door RH		1,650.00 —
1pc	Rear Door Lower Protector		1,160.00 —
10pcs	Rear Door Lower Protector Clips	4.80	48.00 —
1pc	Rear Door Sticker		207.00 ?
1pc	Rear Door Vertical Sensor Rubber Seal		1,107.00 —
1pc	Rear Door Protector Core		315.00 ?
1pc	Rear Door Lower Rubber Seal		147.00 ?
1pc	Rear Door Side Rubber Seal		98.00 ?
1pc	Rear Door Reflector (Red) Inner		56.00 —
1pc	Rear Door Warning Sticker		51.00 —
1pc	Rear Fender Lower Protector		240.00 —
5pcs	Rear Fender Lower Protector Clips	4.80	24.00 —
	C/F		22,041.50

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 10.09.2018

Accident Date : 07.09.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Alphard" Reg. No. SLZ2201U Claiming Against Your Insured Reg. No. SLD3673A		
		B/F	22,041.50
1pc	Rear Bumper		CM 1,636.00
10pcs	Rear Bumper Clips	3.80	~ 38.00
1pc	Rear Bumper Top Retainer RH		Dir 101.00
1pc	Rear Bumper Corner Holder RH		CM 123.00
1pc	Rear Wheel Rim RH		R 1,835.60 X
1pc	Rear Wheel Bearing		~ 912.00
1pc	Rear Upper Arm		SL 329.00
1pc	Rear Knuckle Arm		SL 842.00
1pc	Rear Trailing Arm		SL 285.90
1pc	Rear Lower Arm		SL 611.00
1pc	Rear Lower Arm (2)		SL 439.00
			29,194.00
	Less 25%		7,298.50
			21,895.50
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc / Reprogram Headlamp LED		~ 250.00 X
	To Dismantle / Transfer 2 x Door Fittings / Ancillary Accessories		300.00 1601
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		250.00 7
	To Dismantle / Replace Rear Wheel Bearing		~ 100.00 X
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		~ 250.00 X
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		200.00 901
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Provide Transportation (Towing)		(Bill) 120.00 ?
		C/F	23,445.50

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 10.09.2018

Accident Date : 07.09.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Alphard" Reg. No. SLZ2201U Claiming Against Your Insured Reg. No. SLD3673A		
		B/F	23,445.50
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Door "B" Pillar, O/S Rocker Panel, Rear Fender and Parts Replacement		950.00
	To Respray Affected Areas		1,500.00
		Total :	25,895.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: