



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAYA

Xiao Tong

Accident date: 10/09/2018

Estimated repair cost for vehicle no: SMC2427U HYUNDAI ELANTRA 1.6 A '18

CHASSIS: KMHD841CMJU686838

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid Dented.		\$1,358.00	✓
2	2	Rear Boot Lid Hinge Not new	\$84.30	\$168.60	X
3	1	Rear Boot Lid Emblem Logo 2 new		\$28.80	✓
4	1	Rear Boot Lid Elantra Logo		\$38.50	✓
5	2	Rear Boot Lid Side Reflector Not new	\$168.80	\$337.60	X
6	1	Rear Boot Lid Inner Lock Dented		\$116.20	✓
7	1	Rear Boot Lid Inner Rubber new		\$80.60	X
8	1	Rear Boot Lid Inner Trim Board ?		\$144.60	X
9	8	Rear Boot Lid Inner Trim Board Clip Not new	\$6.50	\$52.00	X
10	1	Rear Boot Lid Number Plate new		\$50.00	X
11	1	Rear Boot Lid Camera		\$550.00	X
12	2	Rear Tail Lamp Cracked.	\$876.00	\$1,752.00	✓
13	4	Rear Tail Lamp Clip new	\$8.00	\$32.00	10
14	2	Rear Tail Lamp Lower Bracket Not new	\$28.00	\$56.00	X
15	1	Rear Bumper Deformed		\$489.00	✓
16	10	Rear Bumper Clip new	\$6.50	\$65.00	30
17	2	Rear Bumper Side Retainer new	\$40.00	\$80.00	✓
18	2	Rear Bumper Side Reflector LH at	\$38.00	\$76.00	38
19	1	Rear Bumper Lower Deformed.		\$242.80	✓
20	1	Rear Bumper Reinforcement Bent.		\$328.00	✓
21	2	Rear Bumper Reinforcement Bracket Not new	\$34.00	\$68.00	X
22	5	Rear Bumper Top & Lower Bracket Bent	\$36.00	\$180.00	36
23	1	Rear Bumper Reverse Sensor Damaged		\$380.00	200(SN)
24	1	Rear End Panel Dented		\$379.00	✓
25	1	Rear End Panel Top Garnish Deformed.		\$105.00	✓
26	2	Rear Fender Inner Trim Board Not new	\$287.00	\$574.00	X
27	1	Rear Spare Tyre Panel Repair		\$416.00	X
28	1	Rear Spare Tyre Panel Top Cover torn		\$225.00	✓
29	1	Rear Spare Tyre Panel & End Panel Sealant Not new		\$450.00	X

\$256.30
4205.04

S.N 200

Subtotal :- \$8,822.70

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit camera	\$180.00 50
To check wiring	\$100.00 30
Towing fee	\$100.00 X
Tuff kote	\$150.00 40
Panel beating	\$1,600.00 100
Spray painting	\$1,600.00 100

Subtotal :- \$4,110.00

Total:- \$12,932.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 663504

1/5: 5.3K.

06 Days

5.3K 06 days