



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 10th September 2018
Motor claims Department
Axa Insurance Singapore Pte Ltd
8 Shenton Way #27-01
Axa Tower
Singapore 068811
Dear Sirs,

Re: Cost of repair to Kawasaki KRR2000 - FU 6033

1 pc of Side box	S\$ 2600.00 ✓
" Tank cover	400.00 ✓
" Rear footrest bracket LH	600.00 X NN
" Lower cowling LH	115.00 X NN
" Mirror	45.00 X NN
" Clutch lever	100.00 X NN
" Seat lock	45.00 ✓
" Handle bar LH	75.00 X NN
" Front signal LH	20.00 X NN
	702.00 353
	70.20 10%
	631.80 317.70

Less 10%

Nett

spray painting
Alignment fork
Labour

200.00	100.00	} 170
65.00	X	
15.00	70	
S\$ 1046.80		
		317.70
		170.00
		487.70
		20%
		390.16
		420.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Rasul
4p 90010068

2 days

4/5

11/09/18 @ 1130

Reg after repair

Tel : 6840 4888

Email : motor_survey @ axa.com.sg