Surveyor: auxili	ASSIGNMENT	The same of the sa	
From (Person): Peter Wan	of ASM(	AXA)	Date/Time: 11/09/201
Estimated Cost:	Bill	to:	
OD TP+WS+TP RES / OD RI			
To Inspect Vehicle No:	EV 8866R	Insur	
at Workshop m/s	Trans Euro ker	T	el: 6395 7877
of	5 ubi Close		
Policy No:		laim No:S81	1 0042P
Sum Insured:			
		Excess:	NIL
Make of Veh:	. —	Excess:	1 11.0
(Client's Record)	l 13 consistent.		D.O.A 10/09/18 4/9/18@after 2pm
(Client's Record)  Authorize of damag  CA) REV REP. / REV 24 I	IKS	2	D.O.A. 10109118 419118@ after 2pm H.O.D. Endorsement:
(Client's Record)	IKS	2	D.O.A. 10/09/18 419/18@after 2pm
(Client's Record Authorize of dames (CA) REV REP. / REV 24 I	Person Contacted:	vion	D.O.A. 10109118 419118@ after 2pm H.O.D. Endorsement:
CA) REV   REP.   REV 24 I Date/Time: 1230pm@ 1119116  Date/Time Action/Instruction	Person Contacted:  Estimate  R - ×	Yion AFC : qan	D.O.A. 10109118 419118@after 2pm H.O.D. Endorsement: Vehicle-IN/OUT
CA) REV   REP.   REV 24 I Date/Time: 1230pm@ 11/9/10 Date/Time Action/Instruction  EV 88 66  Wald I @ 10,38 an 1	Person Contacted:  Ly Estimate  R - X  Wised to Lynn	VION  INSP: 27A +	D.O.A. 10109/18 419/18@after 2pm H.O.D. Endorsement: Vehicle IN/OIT  onjorg punym.  Smart claim,
CA) REV   REP.   REV 24 I Date/Time: 1230pm@ 11/9/10 Date/Time Action/Instruction  EV 88 66  Wald I @ 10,38 an 1	Person Contacted:  Ly Estimate  R - X  Wised to Lynn	VION  INSP: 27A +	D.O.A. 10109118 419118@after 2pm H.O.D. Endorsement: Vehicle-IN/OUT

Shrania Taylin REF: ASM (	(AXA)	
001400	ASSIGNMENT	
From Date 24141	18 Veh No. EV8866R	Yr Regn. 2016, Ju
	Type: (A. Cycle / Bus / Van / I	
Estimated Cost:	Truck / Trailer or	
OD) TP / WS / TP RES / OD RES / EVA / INV / MV		. c.c /196
To Inspect Vehicle No: EV 86 66	Make: Marzdr 3 Colour 5 the	A/C: Insured / Std / NI / NA
at Workshop m/s . Trans Euro Kars	a aux	T/Radio: Insured / Std / NI / NA
27A Tanjung Penjuru	op.rodding 7/2/	
nsured	Eng/No:	42489034073
Policy No.	C	
Claims No.	Gen. Cond: Good / Fair / Poor / Bur	
Sum Insured: Excess: NLL	Steering: Inorder / Jammed / Leake	d/Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leake	d/Burnt or
Make of Veh: Vion @ 63957877	Modi: Nil / \$/R/m / STD A/Rim	or / will
1	Tyre Size: F:	worl boxis.
(Policy Condition)	R:	l .
Remark: The veh had commenced its	BS / DUN / EXNOVA / GY / FS / LIZ	A / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO YOKO OF	
01116		Rear
Sale of Market Votes.	Front C mm	R/Bal. C mm
DAC Accident Rport: Consistent? : Yes or No	The state of the s	L/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm	D.O.I. 24/9/18
Est. Repairs: days Res.: Yes or No		1110
Lum Sum: % 3 Val.: Yes or No		
il damage consistent CA) / REV / REP. 1-24 HRS	Des. of Damages : Frt / Rear / O/	S I N/S I U/C I Rooftop or
Vehicle	B. IM / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Bo	ody Structure affected due to collision
Date / Time Action / Instruction		
BEAGUED	0.0.11011.0040	
RECEIVED	2 6 NOV 2018	
_		
p		
Onte/Line, File Pass to? : Preli. Report	Days Of Repair:	
1) W   MWW . : Final Report	Resurvey No. of Trip:	Survey Fee. 290
Date/Time, File Return to?	A 14 F [ ]	Transportation
5	Add Fee: Site Insp (\$	)S+RS,SI
· Court Class.	Interview (\$	) Photos
Report Format: Smart Claim  Lump Sum / I.B.I: (\$ 7349.17	Tech Invs (\$	) Others
Lump Sum / I.B.I: (\$ 7349.17	Weekend (\$	(-)
		TOTAL 297



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Auto	mobile
AXA INSUR	ANCE PT	ELTD	Ref : CS/ASM18016	6565/T1qd3
8 SHENTON AXA TOWE		4-01 ORE 068811	Date: 11-09-2018 Code: ASM	
1.7		Policy Particula	ars :- OWN DAMAGE	
Insure	ed Veh.		Veh. Inspected	EV 8866R
Policy	/ No.		Coverage (\$)	0.00
Claim	No.	S8M00UZP	Excess (\$)	0.00
Assig	n From	SMARTCLAIM (PETER WANG)	Assign Date	11/09/2018
2.		Vehicle Partic	culars & Condition	
Make	& Model		c.c	0
Engin	e No.	HIDDEN Year of Reg.		
Chass	ssis No. Colour			
Odom	eter	•	Steering	
Brakes	S		Modification	
Gener	al			
3.		Condition	ons of Tyres	
		Size	Make	Balance
	ont Tyre			mm
	ont Tyre			mm
	ear Tyre			mm
	ar Tyre			mm
		Descriptio	n of Damages	
· Carle more	- Klon D	Cananal		
	nt Date	10/00/2010	Information	04/00/0040
100000000000000000000000000000000000000	held at	27A TANJUNG PENJURU	Inspection Date	24/09/2018
	pairer	TRANS EUROKARS PTE LTD		
a.			marks	
A)THE N	MARKET VA	ALUE IS S\$(FST AVERA	GE)	
B)IN AC	CORDANO	E TO YOUR INSTRUCTIONS, WE	HAVE AUTHORISED RE	PAIRS.

LKK AUTO CONSULTANTS PTE LTD (OD) -

Menu



# Service Request Details

Claim

S8M00UZP

Reference

None Ø

Loss Date

September 10, 2018

Request Date

September 11, 2018

Due Date

September 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

#### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

EV8866R

Make

MAZDA

Model 3 1.5 SALOON

,,,

Service Address

Primary Contact/Insured

CHOW KWAN LEONG APT BLK 454, CHOA CHU KANG AVE 4, #11-109, 680454, Singapore

CHOWKL@USA.NET

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: Trans Eurokars @ Ubi Excess: Nil To authorize if damage is consistent

Messages Invoices History Documents Assessment Metrics Notes

New Message

### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 8 November 2018 3:53 PM

To: Cc:

catherinechua@eurokars.com.sg; Taufikh (LKKAuto) vion.lim@eurokars.com.sg; SUR; CS A Team; Admin A

Subject:

RE: EV8866R - FINALISATION OF COR

Dear Catherine.

WITHOUT PREJUDICE

Confirm final fig \$7,349.17 before excess NIL & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>

Sent: Tuesday, 30 October 2018 11:01 AM
To: Taufikh (LKKAuto) < Taufikh@lkkauto.com>

Cc: vion.lim@eurokars.com.sg; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-

a@lkkauto.com>

Subject: EV8866R - FINALISATION OF COR

Dear Taufikh

Our COR computation and B4 paint photos are attached for your agreement.

COR: \$7349.17 (Excess: NIL) before GST

5 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121

FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <mazdacanon@mazda.com.sg>

Sent: 30 October 2018 9:11 AM

To: Catherine Chua < catherinechua@eurokars.com.sg>

Subject: Attached Image

LKK AUTO CONSULTANTS PTE LTD (OD) \*

Menu



## IA OF VEHICLE EV 8866R UPLOAD

Type

Question

Message

Dear Lynn, please be informed that the IA of vehicle EV 8866R uploaded. We have authorise repair. - Shiau Chan

Reply

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

### **Immediate Advice**

To: AXA Insurance Pte Ltd

### Date: 26/09/18

### **Survey Details:**

Date of loss	10-Sep-18
Date of appointment	11-Sep-18
Date of survey	24-Sep-18
Location of survey	TRANS EUROKARS

### Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	EV 8866R	
Make and Model	MAZDA 3 4DR SEDAN 1.5L	
Date of registration	27/6/2016	
Excess	=	
Market Value	\$	66,000.00
Parf Rebate	\$ 46,656.00	
Nett Loss	\$ 19,344.00	

### Repair details:

Initial Estimate	\$ 12,580.15

### Proposed/Revised repair cost:

3,490.00
7,449.17

Number of days for repair	5

51 UBLAVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

### Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOR	MICAL. WE
HAVE AUTHORISE REPAIR.	

## Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

## > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Owner ID Type:	Singapore NRIC
Owner ID:	5104A
Vehicle Details	3104A
Vehicle No.:	EV8866R
/ehicle to be Exported:	No
ntended Deregistration Date:	26 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	P520363416
Chassis No.:	JM6BM42A8G0340731
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,622.00
Original Registration Date:	27 Jun 2016
First Registration Date:	27 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$13,622.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2026
PARF Rebate Amount:	\$10,216.00
ntended COE Rebate Details	
COE Expiry Date:	26 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$36,440.00
Total Rebate Amount:	\$46,656.00

The information contained herein is correct as at 26 Sep 2018

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	10/09/2018 15:22
Date Of Accident	10/09/2018 11:30
Exact Location Of Accident	HARDING ROAD OPEN CARPARK OPP ST JAMES KINDERGARTE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	EV8866R
Insured/Policyholder	
Name Of Registered Owner	CHOW KWAN LEONG
NRIC No	S0015104A
Email Address	CHOWKL@USA.NET
Mobile Phone No	(LOCAL) +65-98399688
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MAZDA
Model	3-1.5 L 4-DOOR SEDAN SP.6AT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA213083 / 1
Cover Note Number	
Driver	
Name of Driver	CHOW KWAN LEONG
NRIC No	S0015104A
Date Of Birth	20/05/1951
Occupation	INDOOR
Date Of Driving Pass	07/04/1970
Driving Experience	48 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98399688
E 11 1	

OFFICE-NOPHONE

CHOWKL@USA.NET

Address BLK 454 CHOA CHU KANG AVE 4 #11-109

680454 Postcode

Was driver an employee of the Insured's Company NO

**OWNER** If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY

CLEAR Weather Conditions Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Passenger 1

NO

NO

NO

2

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NAME:

: GRAND DAUGHTER

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s).
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No .:

SKETCH PLAN			
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT		00114
		LICENSE PLATE NO:	EV 8866K
ACCIDENT DATE: 10	SED 2018	CONTACT NUMBER:	9839 9688
ACCIDENT TIME: //.	30 AM	EMAIL: CHONKL	Q USA.NET
LOCATION: TARALNA	ROMO- OPEN	AIR COR PARK E CHURCH KINDERS	
- 0	PROSITA ST TALL	· CHURCH KINDON	***************************************
	i - i e di Oilm	E CHARA MADERY	(144
the left the pole the lef	3ide, and S , and then 1 side of m	t from the part is a pole (10) then Knocked caused the clar	on do
NOTE: PLEASE NOTE THAT YOUR INS		E FOR YOU TO SUBMIT AN OWN DAMAGE	CLAIMS UNDER YOUR OWN POLIC
PLEASE STATE: CLAIM	OWN POLICY ( ) CLAIM THIS	RD PARTY ( )REPORTING ONLY	
ECLARATION We declare the to regoing particle		V	
olicyholder's Signature ate & Time: 10/9/18	Driver's Signature (If driver is not the policyho Date & Time:		tre Personnel's Signature
and committee in the contraction of the contraction			













**AXA Insurance Pte Ltd** 

1800 880 4888 (Within Singapore) (65) 6880 4888 (International)

(65) 6880 4740

⊠ customer.care@axa.com.sg

www.axa.com.sg

### Certificate of Insurance

account number

03861

-Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960-Road Transport Act. 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

#### **Policy details**

Policyholder name

CHOW KWAN LEONG

Certificate number

GA213083 / 1

Cover Plan name Comprehensive

Chassis number Engine number

JM6BM42A8G0340731 P520363416

NCD applicable Vehicle registration number Period of Insurance

50% **FVRRRRR** 

from 27/06/2018 to 26/06/2019 (both dates inclusive)

Finance loan company

#### Persons or classes of persons entitled to drive\*

(a) The Policyholder

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

#### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

- 1. S\$500 for unnamed Authorised Driver
- 2. S\$500 for declared Young and Inexperienced Driver
- 3. \$\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to \$\$2,500 if You have chosen AXA Premium Workshops.

#### Additional clauses & endorsements to your policy

Nit

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

#### AXA Insurance Pte Ltd

Authorised signature

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period falling which there would be no liability under the policy, renewal certificate,

AXA Insurance Pte Ltd (199903512M) 8 Shenton Way, #24-01, AXA Tower, Singapore 068811 Customer Centre, #B1-01

1 of 3



### TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605



ESTIMATE COST OF REPAIRS

AXA INSURANCE PTE LTD

NAME:

Mr Chow Kwan Leong

WIP:

8 SHENTON WAY

ADDRESS: 454 CHOA CHU KANG AVE 4

EXCESS:

#24-01 AXA TOWER

#11-109

11-Sep-18

22422

SINGAPORE 068811

Singapore 680454

DATE:

ATTN.:

MOTOR CLAIMS

TEL:

98399688

EV.	v	
11	^	٠
$\overline{}$	_	-

VEH NO:	EV8866R	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO :	JM6BM42A8G0340731	MILEAGE :		TYPE OF CLAIM:	OWN DAMAGED CLAIM
MODEL .	MAZDA3	DATE REG :	27-Jun-16	POLICY NO ·	

#### NATURE OF WORKS

		Parts Description	on			
NO		QTY		REVISED	1	PRICES
1	FRONT BUMPER	1	MBHR3-50-031BBB	de/	\$	1,031.70
2	BRACKET LHS	1	MBHN1-50-162	ne	\$	15.10
3	RETAINER LHS	1	MBHN1-50-0U1E	w	\$	18.70
4	CHROME LHS, FOGLAMP	1	MBJE1-50-C22	and	\$	106.10
5	COVER LHS, FOGLAMP	1	MBJE1-50-C21A	WA-	\$	46.40
6	LAMP LHS, SIDE TURN	1	MB45A-51-360A	Xin	\$	157.30
7	FOGLAMP LHS	1	MTK21-51-690A	X MM	\$	351.40
8	BRACKET LHS, FOGLAMP	1	MBHR1-51-694A	NA ×	\$	17.30
9	FASTENER, FRONT BUMPER	2	MB45A-56-146A	we -	\$	5.60
10	CLIP, FRONT BUMPER	12	MC274-50-133	ue-	\$	42.00
11	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	nei/	\$	5.40
12	HEADLAMP LHS	1	MBHT6-51-041A	and-	\$	2,245.00
13	HID CONTROL UNIT LHS	1	MBHN3-51-0H3	8 nn	\$	895.50
14	GASKET, CONTROL UNIT	1	MC236-51-0B2	3x un	\$	13.60
15	BOOSTER UNIT LHS	1	MKD53-51-0H5	200	\$	304.90
16	RIVET, HEADLAMP	1	MB092-51-833	wei-	\$	3.30
17	CLIP, HEADLAMP	2	MFB01-50-133C	ne/	\$	7.60
18	FRONT PANEL UPPER	1	MB45A-53-150A	X Nu	\$	124.00
19	FRONT SUPPORT PANEL	1	MGHR5-53-110B	× Au	\$	469.70
20	FASTENER, PLATE SEAL	4	MKD45-50-EA1	× an	\$	10.00
21	FRONT FENDER LHS	1	MB45A-52-211B	67	\$	333.90
22	STAY LHS, FENDER	1	MB45A-52-240	61	\$	39.90
23	MUDGUARD LHS	1	MB45A-56-140H	de	\$	97.00
24	FASTENER, MUDGUARD	15	MB45A-56-146A	he /	\$	42.00
25	RIVET, FRONT BUMPER	<u>6</u>	MS51S-51-833	ner-	\$	22.80
26	RIVET, FRONT BUMPER	<u>4</u>	MTK21-50-355	Nei-	\$	34.80
27	FASTENER, FRONT BUMPER	<u>8</u>	MGD7A-50-EA1	nel/	\$	24.00
28	RADIATOR COOLANT	<u>5</u>		X nn-	\$	68.50
			TOTAL PARTS		\$	6,533.50

			LESS 10%		\$	653.35
		Л	TOTAL PARTS COST		\$	5,880.15
		Labour Description	n		_	
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	O REPAIR REINF WHEEL HOUSE	1320.	\$	1,980.00
2	MZ-SP-SFRT01	TO RESPRAY FRONT BUMPER, FRONT FENDER LH AND R	1260.	\$	1,890.00	
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND F CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	Xin	\$	660.00	
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE ANI	X WA	\$	660.00	
5	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			\$	560.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	1503/	\$	250.00	
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$	250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORK	KS.	180.	\$	350.00
9	MZ-BR-SUNDRI	SUNDRIES.		20 · /	\$	100.00
			TOTAL LABOUR	\$ -	\$	6,700.00
			TOTAL PARTS	\$ -	\$	5,880.15
			TOTAL	\$ -	\$	12,580.15
			LESS EXCESS	\$ -	\$	
			TOTAL AFTER EXCESS	\$ -		
			GST 7%	\$ -	\$	12
			GRAND TOTAL	\$ -	\$	

#### REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

#### TRANS EUROKARS PTE LTD

Authorised Signature



### TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605 FINALISED COST OF REPAIRS



(TP)

**AXA INSURANCE PTE LTD** 

NAME:

Mr Chow Kwan Leong

WIP:

22422

8 SHENTON WAY

ADDRESS: 454 CHOA CHU KANG AVE 4

EXCESS:

#24-01 AXA TOWER

#11-109

DATE: 11-Sep-18

SINGAPORE 068811

Singapore 680454

ATTN.:

MOTOR CLAIMS

TEL:

FAX:

98399688

Vion 63957877

VEH NO:

EV8866R CHASSIS NO: JM6BM42A8G0340731

MILEAGE:

TYPE OF CLAIM:

CONTACT PERSON:

OWN DAMAGED CLAIM

MODEL:

MAZDA3

DATE REG.:

DATE IN:

27-Jun-16 POLICY NO. :

NATURE OF WORKS

		Parts Description	on			
NO		QTY		REVISED	PRICES	
1	FRONT BUMPER	1	MBHR3-50-031BBB	\$ 1,031.70	\$	1,031.7
2	BRACKET LHS	1	MBHN1-50-162	\$ 15.10	\$	15.10
3	RETAINER LHS	1	MBHN1-50-0U1E	\$ 18.70	\$	18.70
4	CHROME LHS, FOGLAMP	1	MBJE1-50-C22	\$ 106.10	\$	106.10
5	COVER LHS, FOGLAMP	1	MBJE1-50-C21A	\$ 46.40	\$	46.40
6	LAMP LHS, SIDE TURN	1	MB45A-51-360A		\$	157.30
7	FOGLAMP LHS	1	MTK21-51-690A		\$	351.40
8	BRACKET LHS, FOGLAMP	1	MBHR1-51-694A		\$	17.30
9	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$	5.60
10	CLIP, FRONT BUMPER	12	MC274-50-133	\$ 42.00	\$	42.00
11	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$	5.40
12	HEADLAMP LHS	1	MBHT6-51-041A	\$ 2,245.00	\$	2,245.00
13	HID CONTROL UNIT LHS	1	MBHN3-51-0H3		\$	895.50
14	GASKET, CONTROL UNIT	1	MC236-51-0B2		\$	13.60
15	BOOSTER UNIT LHS	1	MKD53-51-0H5		\$	304.90
16	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30	\$	3.30
17	CLIP, HEADLAMP	2	MFB01-50-133C	\$ 7.60	\$	7.60
18	FRONT PANEL UPPER	1	MB45A-53-150A		\$	124.00
19	FRONT SUPPORT PANEL	1	MGHR5-53-110B		\$	469.70
20	FASTENER, PLATE SEAL	4	MKD45-50-EA1		\$	10.00
21	FRONT FENDER LHS	1	MB45A-52-211B	\$ 333.90	\$	333.90
22	STAY LHS, FENDER	1	MB45A-52-240	\$ 39.90	\$	39.90
23	MUDGUARD LHS	1	MB45A-56-140H	\$ 97.00	\$	97.00
24	FASTENER, MUDGUARD	15	MB45A-56-146A	\$ 42.00	\$	42.00
25	RIVET, FRONT BUMPER	6	MS51S-51-833	\$ 22.80	\$	22.80
26	RIVET, FRONT BUMPER	4	MTK21-50-355	\$ 34.80	\$	34.80
27	FASTENER, FRONT BUMPER	8	MGD7A-50-EA1	\$ 24.00	\$	24.00
28	RADIATOR COOLANT	5			\$	68.50
			TOTAL PARTS	\$ 4,121.30	\$	6,533.50
-			LESS 10%	\$ 412.13	\$	653.35

			TOTAL PARTS COST	\$	3,709.17	\$ 5,880.15
		<u>Labour De</u>	scription			
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR REINF WHEEL HOUSE LH AND ALL AREAS AFFECTED BY THE ACCIDENT.		\$	1,320.00	\$ 1,980.00
2	MZ-SP-SFRT01	TO RESPRAY FRONT BUMPER, FRONT FENDER LH AND REINF WHEEL HOUSE LH.			1,260.00	\$ 1,890.0
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.				\$ 660.0
4	MZ-BR-TOP-UP	MZ-BR-TOP-UP TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.				\$ 660.0
5	MZ-BR-WHEALI	ALI TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			560.00	\$ 560.0
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			150.00	\$ 250.0
7	MZ-BR-ELECTR	CTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150.00	\$ 250.0
8	MZ-BR-REPROG	-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$	180.00	\$ 350.0
9	MZ-BR-SUNDRI	SUNDRIES.		\$	20.00	\$ 100.0
			TOTAL LABOUR	\$	3,640.00	\$ 6,700.0
			TOTAL PARTS	\$	3,709.17	\$ 5,880.1
			TOTAL	\$	7,349.17	\$ 12,580.1
			LESS EXCESS	\$		\$
			TOTAL AFTER EXCESS	\$	7,349.17	
			GST 7%	\$	514.44	\$ :
			GRAND TOTAL	Ś	7,863.61	\$

#### REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



#### AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way #24-01 AXA Tower Singapore 068811

Attn: Motor Claims Department

DATE: 15/11/2018

Car Regn No : EV8866R

#### Accident involving EV8866R on 10/09/2018

#### Own Damage Claim

Dear Sirs

The repair has been completed for EV8866R. We submit the following documents for your perusal:

1) Invoice No: 30002230

7,863.61

2) Discharge Voucher signed by client

7,863.61

Please pay Trans Eurokars Pte Ltd the sum of \$7,863.61 as soon as possible and mail your cheque to 12 Sungei Kadut Avenue Singapore 729648.

Yours faithfully,

Stanley Ngu

Manager - Body & Paint Division

DID:63602845 FAX:63602899

e-mail: stanley@eurokars.com.sg

(5) TRANSELROKARS Corporate Head Office

: Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sungel Kadut Ave Singapore 729648 Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

Showroom & Service Centres : 5 Ubi Close Singapore 408605
Sales Tel : 6395 8888 Service Tel : 6395 8899
Sales Fax : 6846 1700 Service Fax : 6744 9402

23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 6476 7073 Service Fax: 6476 7417

zoom-zoom

1D: t05

A0002

INS-AXA

TAX INVOICE

GST Reg No: M90364005A

PAGE NO

30002230

INVOICE NO: DEPT/POS ID:

12

AXA INSURANCE PTE LTD

8 SHENTON WAY

DATE IN DATE PRINTED: 12/11/2018

24/09/2018

#24-01 AXA TOWER

JOB NO: CSO/OP CODE: 22422

SINGAPORE 068811

TEL NO:

Catherine Chua

MODEL: CHASSIS NO:

CUSTOMER:

ADDRESS:

MAZDA3 1.5L SDN HIGH GRADE BLA

REGN NO: REGN DATE: EV8866R

ENGINE NO:

JM6BM42A8G0340731

27/06/2016

P520363416

MILEAGE:

39592

REQUISITION NO: VION DESCRIPTION: Body repair

CODE	DESCRIPTION	AMOUNT
NOTES	INSURANCE CLAIM: OWN DAMAGE	0.00
MZ-BR-FR	DATE OF ACCIDENT: 10/09/2018 TO REPLACE FRONT BUMPER AND LH FRONT FENDER.	1320.00
MZ-SP-SF MZ-BR-WH	REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. TO RESPRAY FRONT BUMPER AND FRONT FENDER. TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	1260.00 560.00
MZ-BR-RE	TO CARRY-OUT BODY CAVITY PRESERVATION. TO CHECK ELECTRICAL SYSTEM TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. SUNDRIES	150.00 150.00 180.00 20.00
BHR3-50-031 BHN1-50-162 BHN1-50-001	BBB FRT BUMPER BM 1.0 1031.70 BRACKET LHF BUMPER B 1.0 15.10 E RETAINER LHF BM/BN 1.0 18.70	928.53 13.59 16.83
BJE1-50-C21 BJE1-50-C21 B45A-56-146 C274-50-133	A COVER(L), HOLE-LAMP B 1.0 46.40 A FASTENER 2.0 2.80	95.49 41.76 5.04 37.80
0574-30-135	101,0E11 12.0 3.30	32.00
	ORIGINAL COPY	

All major repaired parts stated above are covered under a 6 months or 10,000 km warranty, whichever comes lirst. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to neglience or improper handlings.

Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER NO:

Customer Signature

Authorised Signature

TRANS EUROKARS PTE LTD

(5) TRANSEUROKARS

Corporate Head Office

: Trans Eurokars Pta Ltd, Eurokars Centre 12 Sungei Kadut Ave Singapore 729648

Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

| Showroom & Service Centre : 5 Ubi Close Singapore 408605 |
| Sales Tel : 6395 8888 | Service Fax : 6846 1700 | Service F Service Tel : 6395 8899 Service Fax : 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel : 6603 6118 Service Tel : 6603 6128 Sales Fax : 6476 7073 Service Fax : 6476 7417

zoom-zoom

ID: t05

CUSTOMER:

ADDRESS:

MODEL:

CHASSIS NO:

DESCRIPTION:

ENGINE NO:

A0002

INS-AXA

AXA INSURANCE PTE LTD

TAX INVOICE

GST Reg No: M90364005A

PAGE NO:

2

INVOICE NO: DEPT/POS ID: 30002230

I / 12

DATE

24/09/2018 DATE PRINTED: 12/11/2018

JOB NO:

22422

CSO/OP CODE:

Catherine Chua

SINGAPORE 068811 SINGAPORE

TEL NO:

EV8866R

MAZDA3 1.5L SDN HIGH GRADE BLA JM6BM42A8G0340731

Body repair

#24-01 AXA TOWER

8 SHENTON WAY

P520363416

REGN NO: REGN DATE:

27/06/2016

MILEAGE:

39592

REQUISITION NO: VION

CODE	DESCRI	PTION	AMOUNT
GHP9-50-0Z5 BHT6-51-041A B092-51-833 FB01-50-133C B45A-52-211B B45A-52-24C B45A-56-14CH B45A-56-146A S51S-51-833 TK21-50-355 GD7A-50-EA1	GROMMET, SCREW HEADLAMP LH BM RIVET NUT, CLIP LHF FENDER BM/BN STAY LHF FENDER BM/B MUD GUARD LHF BM FASTENER RIVET, SPLASH SHIELD RIVET FASTENER	2.0 2.70 1.0 2245.00 1.0 3.30 2.0 3.80 1.0 333.90 1.0 39.90 1.0 97.00 15.0 2.80 6.0 3.80 4.0 8.70 8.0 3.00	4.86 2020.50 2.97 6.84 300.51 35.91 87.30 37.80 20.52 31.32 21.60
	Parts 3,709.17 Surcharge 0.00 Labour 3,640.00 Menus 0.00	Net G.S.T. 7% Total Paid Amount Due	7349.17 514.44 7863.61 0.00 7863.61

All major repaired parts stated above are covered under a 6 months or 10,000 km warranty, whichever comes first. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to neglience or improper handlings.

Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER NO:

**ORIGINAL COPY** 

Customer Signature

**Authorised Signature** 

TRANS EUROKARS PTE LTD

(5) TRANSEUROKARS

Corporate Head Office

: Trans Eurokars Pte Ltd, Eurokars Centre 12 Sungei Kadut Ave Singapore 729648 Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

Service Tel : 6395 8899 Service Fax : 6744 9402

zoom-zoom



### **DISCHARGE VOUCHER**

I/ We hereby acknowledge having red	ceived from the under-mentioned
repairers my/our vehicle No:	which has been
repaired to my satisfaction and I/we a	dmit that the payment for such
repairs by Trans Eurokars Pte Ltd is in	full and final discharge of my claim
under policy number:	in respect of damage
caused to the said vehicle as a result o	of an accident that occurred on
10 9 18 at HARDING	RO OPEN CARPARK.
Mr.	1 10 18
Witnessed by Repairers	Date
Signature by Insured	No 18

: Trans Eurokars Pto Ltd, Eurokars Contre, 12 Sungol Kadut Ave Singapore 729648 Tol: 6363 3003 Pax: 6369 3003 BRN.199103859N zri<sup>tri</sup>i

Showroom & Service Centre: 23 Leng Koe Road Singapore 159095
Sales Hotline: 6603 6118 Service Hotline: 6603 8128
Sales Fax : 6476 7073 Service Fax : 6476 7417



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	nationale Des Experts En Autor	mobile
AXA INSURANCE PT	E LTD	Ref : CS/ASM18016	3565/T1qd3e2
8 SHENTON WAY #2 AXA TOWERSINGAP	ORE 068811	Date: 06-12-2018	
ATTN : PETER WANG	3	Code: ASM	
1.	Policy Partic	culars :- OWN DAMAGE	NACCE THE PARTY.
Insured Veh.		Veh. Inspected	EV 8866R
Policy No.	GA213083/1	Coverage (\$)	0.00
Claim No.	S8M00UZP	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	11/09/2018
2.	Vehicle Pa	articulars & Condition	
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BM42A8G0340731	Colour	BLUE
Odometer	39587	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Con	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	тоуо	6 mm
4.		iption of Damages	
THE VEHICLE SI	USTAINED DAMAGES AT THE	FRONT N/S PORTION.	
DAMAGES SEE I	DETAILS.		
5.	Gen	eral Information	
Accident Date	10/09/2018	Inspection Date	24/09/2018
Survey held at	27A TANJUNG PENJURU		
Repairer	TRANS EUROKARS PTE LT	TD	
5a.		Remarks	
A)THE MARKET B)IN ACCORDAN	VALUE IS S\$66,000.00(EST. A NCE TO YOUR INSTRUCTIONS	VERAGE) S, WE HAVE AUTHORISED I	REPAIRS.
5b.	Estim	ate Days of Repair	

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EV 8866R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,031.70	1,031.70
1	BRACKET LHS (CONSISTENT)	NECESSARY	15.10	15.10
1	RETAINER LHS (CONSISTENT)	NECESSARY	18.70	18.70
1	CHROME LHS, FOGLAMP (CONSISTENT)	CUT	106.10	106.10
1	COVER LHS, FOG LAMP (CONSISTENT)	CUT	46.40	46.40
1	LAMP LHS, SIDE TURN (CONSISTENT)	NOT NECESSARY	157.30	-
1	FOGLAMP LHS (CONSISTENT)	NOT NECESSARY	351.40	7=
1	BRACKET LHS, FOGLAMP (CONSISTENT)	NOT NECESSARY	17.30	-
2	FASTENER, FRONT BUMPER (CONSISTENT)	NECESSARY	5.60	5.60
12	CLIP, FRONT BUMPER (CONSISTENT)	NECESSARY	42.00	42.00
2	GROMMET, FRONT BUMPER (CONSISTENT)	NECESSARY	5.40	5.40
1	HEADLAMP LHS (CONSISTENT)	CUT	2,245.00	2,245.00
1	HID CONTROL UNIT LHS (CONSISTENT)	NOT NECESSARY	895.50	-
1	GASKET, CONTROL UNIT (CONSISTENT)	NOT NECESSARY	13.60	
1	BOOSTER UNIT LHS (CONSISTENT)	NOT NECESSARY	304.90	9-
1	RIVET, HEADLAMP (CONSISTENT)	NECESSARY	3.30	3.30
2	CLIP, HEADLAMP (CONSISTENT)	NECESSARY	7.60	7.60
1	FRONT PANEL UPPER (CONSISTENT)	NOT NECESSARY	124.00	1.0
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	469.70	
4	FASTENER, PLATE SEAL (CONSISTENT)	NOT NECESSARY	10.00	04
1	FRONT FENDER LHS (CONSISTENT)	BENT	333.90	333.90
1	STAY LHS, FENDER (CONSISTENT)	BENT	39.90	39.90
1	MUDGUARD LHS (CONSISTENT)	DEFORMED	97.00	97.00
15	FASTENER, MUDGUARD (CONSISTENT)	NECESSARY	42.00	42.00
6	RIVET, FRONT BUMPER (CONSISTENT)	NECESSARY	22.80	22.80
4	RIVET, FRONT BUMPER (CONSISTENT)	NECESSARY	34.80	34.80
8	FASTENER, FRONT BUMPER (CONSISTENT)	NECESSARY	24.00	24.00
5	RADIATOR COOLANT (CONSISTENT)	NOT NECESSARY	68.50	-
	LESS 10% DISCOUNT		-653.35	-412.13
			5,880.15	3,709.17

Report Ref No. CS/ASM18016565/T1qd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	20.00
			100.00	20.00
	LABOUR			
	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR REINF WHEEL HOUSE LH AND ALL AREAS AFFECTED BY THE ACCIDENT.		1,980.00	1,320.00
	TO RESPRAY FRONT BUMPER, FRONT FENDER LH AND REINF WHEEL HOUSE LH.		1,890.00	1,260.00
	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NOT NECESSARY	660.00	3
	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	NOT NECESSARY	660.00	S4
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		560.00	560.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			6,600.00	3,620.00
	GRAND TOTAL		12,580.15	7,349.17

REC	COMMENDED COST OF REPAIRS	7,349.17
KEC	COMMENDED COST OF REPAIRS	1,045.17

Report Ref No. CS/ASM18016565/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

**Automotive Assessor** 

, , , , ,

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.