

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

AXA Insurance Singapore Pte Ltd
 8 Shenton Way
 # 27-01
 Singapore 068811
 Tel : 6338 - 7288
 Fax : 6880 - 4838

Quotation
 DATE : 25.09.2018
 VEH NO : SJK767U
 MODEL : BMW 318i
 D O A : 07.09.2018
 YR REF : FBM9073M

Vivian

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJK767U (BMW 318i)

Item	Description	Qty	Amnt
NO	LIST ITEMS		
1	Front Fender - LH <i>dented</i>	1	768.00 ✓
2	Front Door - LH <i>dented</i>	1	1,152.60 ✓
3	Front Door Lock - LH <i>xt new</i>	1	229.10 ✓
4	Front Door Weatherstripe - LH <i>xt new</i>	1	147.40 ✓
5	Front Door Glass Regulator Gear - LH <i>xt new</i>	1	312.60 ✓
6	Front Wing Mirror - LH <i>Damaged</i>	1	743.30 ✓
			\$ 3,353.00
	Less 5%		(167.65)
			\$ 3,185.35
	Total Parts		\$ 3,185.35

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$ 600.00 400
2	To putty & spray up paint works	\$ 600.00 500
3	To wiring	\$ 50.00 30
4	To transfer door fittings	\$ 150.00 80
	Total Labour	\$ 1,400.00

Grand Total **\$ 4,585.35**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: