



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : YK2077LMake & Model : HINO XZU710R-HKFMS3Year of Manufacture : 2016Chassis No. : JHHUCS3H60K018316Ins Company : QBE / EQEngine No. : N04CUS29020

Excess : \_\_\_\_\_

Policy No. : 8-V0016213-MVADate of Accident : 31/08/2018Time of Accident : 15:20

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**Case Owner : ROHANI

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 3,150.00Plus/Less 15% \$ 472.50Total of Cost / List \$ 3,622.50(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,622.50Labour (Appendix B) \$ 1,230.00Total Repair Cost \$ 4,852.50

Contact No

**Frt Counter Operation**

63837466 - Patrick Tia

63837730 - Brenda Ng

63837890 - Rohani

braddell\_cr@sparkcarcare.com

**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell\_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Chao Pui - 82880282Company : ckkSurvey conducted on : 13/9/18 at \_\_\_\_\_Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 5 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

lampen repair.  
After repair photos.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : YK2077L Case Owner : ROHANI

Make & Model : HINO XZU710R-HKFMS3 Year Manufacture : 2016

Chassis No : JHHUCS3H60K018316 Engine No : N04CUS29020

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front centre panel / <i>BUC</i>	1	\$ 390.00				
2	Front grille badge logo / <i>CRA</i>	1	\$ 50.00				
3	Front radiator grille Centre / <i>SEP.</i>	1	\$ 450.00				
4	Front corner garnish LH <i>X NN</i>	1	\$ 260.00				
5	Front Grille Garnish / <i>CRA</i>	1	TBA				
6	LH Headlamp ?	1	\$ 800.00				
7	Front windscreen / <i>CRA</i>	1	\$ 1,200.00				
8	Front windscreen moulding / <i>NEG</i>	1	TBA				
9	Front windscreen weatherstrip / <i>NEG</i>	1	TBA				
10	0						
11	0						
12	0						
13	0						
14	0						
15	0						
16	0						
17	0						
18	0						
19	0						
20	0						
21	0						
22	0						
23	0						
24	0						
25	0						
26	0						
27	0						
28	0						
29	0						
30	0						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*