

INS. CASE OWNER: CC 4/EQ1801 6587, Kwb3 / LKK IDAC

Surveyor: Fendeth DOI: 11/11/18 Date/Time: 11/11/18
Registered in Meritex: _____

Pre-assign / CCU / FTE

Insured Vehicle No.: GBH 216R Claim No.: _____
 Name of Insured: LOW PROJECTS PTE Policy No.: 00000000-01543
 Insured Tel No.: _____ HP: _____ Make / Model: TOYOTA
 Excess Sec II :\$5 D.O.A.: 10/11/18 Place of Accident: JUNCTION OF RAFFLES QUAY & CROSS ST.
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: AHMED FOYEZ OI GIA REPORT: (YES / NO) : TP GIA REPORT: (YES / NO)
 Driver Tel No.: _____ (V/L YES / NO) Insured Liability: 0 % Final? Yes / No

CUK 74093

INSRS: WSP: Tel: Liability: RMKS: Esteeem
 INSRS: WSP: Tel: Liability: RMKS: _____
 INSRS: WSP: Tel: Liability: RMKS: _____
 INSRS: WSP: Tel: Liability: RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>11/11/18</u>	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	<u>11/11/18</u>
	After call Itr to OI	<u>11/11/18</u>
<u>11/11/18</u>	Documentation Check List: Handler	Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	(days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>6/5/19</u>	Confirm with: <u>CARMU</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>50</u>	(Agreed / Assessed) BOLA S/N No.:	<u>NIL</u>
Repair Cost:	<u>4478.75</u>	\$5 <u>2239.38</u>	
Loss of Rental (LOR):	<u>4478.75</u>	(<u>6</u> days) X <u>80.95</u>	
Loss of Use (LOU):	\$5	(5 x days)	
Loss of Income (LOI):	\$5	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search:	<u>7.45</u>	\$5 <u>7.45</u>	
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow / Independent)	
Legal Cost:	\$5		
Total:	<u>4471.90</u>	\$5 <u>2489.68</u>	Global Sum \$5:
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5 <u>2489.68</u>	Name 1: <u>Esteeem Performance Pte Ltd</u>	
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

CLAIM

OK
8/5/18
04

ASS. REC. BY:

REF: 2Q /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 2.8% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLK 74091 Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Prius^A c.c. 1798

Colour: M. Silver AC: Insured / Std / NI / NA

Sp. Reading: 155996 T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: JTOKB3FU003540154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: Davanti 195/65R15

R: YOKO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 10/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/19	File pass to Catherine
30/4/19	Confirm 2.B.2 # 4185.75 with 4 working days

(pid = #14) 0.17
26.1)

Date/Time, File Pass to? : Prell. Report : Final Report

1) Date/Time, File Return to?
 2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:
Transportation:
\$ - RS. \$
Fixtur
Others
TOTAL

Report Format :
Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18016587/Kwb3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-09-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 2216R	Veh. Inspected	SLK 7409J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/09/2018	Inspection Date	11/09/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

<p>A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.</p>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 3, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118016587/Kwb3

Date: 12.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLK7409J

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.09.2018 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>5,605.92</u>
Revised Estimate Amount	: S\$	<u>4,185.75</u>
"Check" Items Amount	: S\$	<u>683.03</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

10

Kw



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.estoemperf.com.sg

Repair Estimates

SLK 7409 J

Parts	(a) Cost / List Price Items	\$	5,581.22
	Plus/Less 25%	\$	1,395.31
	Total of Cost / List	\$	4,185.92
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	4,185.92
Labour		\$	1,420.00
Total		\$	5,605.92

Finalised

4367.67
1091.92
3275.75

Not Authorized
1.B.1
Resurvey 134 party

910
4185.75 ✓ OK

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : UICK

Survey conducted on : 11/9/18 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 04 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : Lc Date: 11/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemporf.com.sg

Spare Parts

Vehicle No. : SLK 7409 J
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU003540154

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender	1	\$868.70		✓
2	LH front fender undershield	1	\$176.50		✓
3	LH front fender undershield clip	10	\$25.00		✓
4	LHF fender wording "HYBRID"	1	\$45.17		✓
5	LH front fender quarter garnish	1	\$122.70		✓
6	LH front hub cap	1	\$195.65		X
7	Headlamp LH	1	\$2,531.60		✓
8	Front bumper	1	\$450.80		✓
9	Front bumper clip	10	\$40.00		✓
10	Front bumper side retainer RH	1	\$107.20		X
11	Front bumper side retainer LH	1	\$107.20		✓
12	Fog lamp LH	1	\$910.70		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4367.67



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLK 7409 J

*Not Authorized
1.B.1
Resurvey 134 part*

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Parts	(a) Cost / List Price Items	\$	<u>5,581.22</u>
	Plus/Less 25%	\$	<u>1,395.31</u>
	Total of Cost / List	\$	<u><u>4,185.92</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items		_____
Total Parts Cost		\$	<u><u>4,185.92</u></u>
Labour		\$	<u><u>1,420.00</u></u>
Total		\$	<u><u>5,605.92</u></u>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Hennrich

Company : LKK

Survey conducted on : 11/9/11 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : lc Date: 11/9/11

Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 11 September, 2018 1:15 PM
To: 'assignments'
Cc: Admin A
Subject: RE: Our ref: GBH2216R- REQUEST FOR PRI SURVEY SLK7409J
Attachments: 20180911110705058.pdf; EQIC-MARS00002710-GBH2216R-GIA.PDF; SAS2469934.PDF

Dear all,

Please arrange to attend to the PRS.

Liability is not cleared yet. Request for video footage from both parties.

Thank you.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t

From: serence ctc [mailto:serence@esteemperf.com.sg]
Sent: Tuesday, September 11, 2018 11:37 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Carmen Lim <carmen@esteemperf.com.sg>
Subject: Re: Our ref: GBH2216R- REQUEST FOR PRI SURVEY SLK7409J

Dear Janet,

We prefer LKK Auto Consultants Pte Ltd to survey the car.

11.09.2018 @ 1:24pm
serence veh in
Kenneth.

Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

E: serence@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



On Tue, Sep 11, 2018 at 11:35 AM, Janet Tan <janet.tan@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Sir/Madam,

For pre repair survey request, please email to egiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283

	Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Tan Wei Yin
Sent: Tuesday, September 11, 2018 11:09 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: serence ctc <serence@esteemperf.com.sg>; Carmen Lim <carmen@esteemperf.com.sg>
Subject: FW: REQUEST FOR PRI SURVEY SLK7409J

FYNA

Regards,


Tan Wei Yin

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110
did 65 54969882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies c

From: serence ctc [<mailto:serence@esteemperf.com.sg>]
Sent: Tuesday, September 11, 2018 11:07 AM
To: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Cc: Carmen Lim <carmen@esteemperf.com.sg>
Subject: REQUEST FOR PRI SURVEY SLK7409J

Dear Sir / Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SLK 7409 J

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385, Sin Ming Drive Singapore 575718

Tel : 6753 2112

Fax : 6451 0394

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.



Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

E: serence@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)

385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com







ESTEEM PERFORMANCE PTE LTD

Blk 6033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

6566 2112
20

Your Ref : GBH 2216 R
Our Ref : SLK 7409 J



Date : 05-11-18

EQ Insurance Company Limited
5 Maxwell Road
#17-00 Tower Block,
MND Complex,
Singapore 069110

RE : ACCIDENT INVOLVING SLK 7409 J & GBH 2216 R
ACCIDENT DATE 10-09-2018
ACCIDENT ALONG FINLAYSON GREEN TOWARDS RAFFLES QUAY

We are the workshop for the owner of motor vehicle no : SLK 7409 J which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured GBH 2216 R we are submitting these claims for your consideration.

1	Cost of repair	S \$	4,478.75
2	Loss of rental <u>6</u> days @ <u>\$ 80.95</u> / day	S \$	485.70
3	Surveyor Fee	S \$	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)	S \$	0.00
5	LTA Fee	S \$	7.45
		S \$	4,971.90

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim
Claims Executive
Email : carmen@esteempert.com.sg

WITHOUT PREJUDICE	
ACKNOWLEDGE RECEIPT ONLY	
OUR REF:	DM18H002411JT
OIC:	JANETTAN 18/11/18
EQ Insurance Co. Ltd	



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQI18016587/Kwb3

02 October 2018

Icon Projects Pte Ltd
10 Kaki Bukit Ave 4
#07-72 Premier @Kaki Bukit
Singapore 415874

Dear Sir/Madam,

ACCIDENT INVOLVING GBH 2216R & SLK 7409J ON 10/09/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 15/10/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg
GST Registration No: 20-0005485-N CO Registration: 200005485N

M/S : EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK, MND COMPLEX,
SINGAPORE 069110

ATTN: Motor Claim Department

Your Ref No: GBH2216R
Claim Type: Third Party
Accident Date: 10/09/2018
TP Veh Reg No: GBH2216R

Claim No: CER1301112
Final No: CIV1301419
Date: 22 Oct 2018
Policy No: A29069766MKF
Veh Reg No: SLK7409J
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU003540154
Engine No:
Reg. Date:

Tax Invoice to Vehicle No :SLK7409J

Description	Quantity	List Price	Amount
Others		<u>SS</u>	<u>SS</u>
1 COST OF REPAIR	1 PCS	4,185.75	
		4,185.75	4,185.75
		Total	SS 4,185.75
		Add GST @ 7%	293.00
		Total Amount Payable	SS 4,478.75

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FOUR HUNDRED SEVENTY EIGHT AND CENTS SEVENTY FIVE ONLY

The above vehicle was surveyed by KENNETH on 11/09/2018

For Esteem Performance Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



Our Ref: GR-ACC-2017-02

1st Nov 2017

Esteem Performance Pte Ltd
Blk 5033 Ang Mo Kio Ind Park 2
#01-259
Singapore 569536

Mailing Address

18 Sin Ming Lane,
#01-08 Midview City,
Singapore 573960
Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$80.95
02	Mazda 3 1.5 (A) Sedan	\$66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee
Grab Rental Pte Ltd

> Back to OneMotoring



Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 10 Sep 2018 / 19:00:56

Receipt Date/Time : 10 Sep 2018 / 19:00:56

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180910-002277

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - GBH2216R As at 10 Sep 2018/09:35:00 Insurance Co: EQ INSURANCE COMPANY LTD			
1	Insurance Enquiry - GBH2216R Enquiry Fee 20180910190016713575	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45

Paid By

20180910190022606 Direct Debit: eNETS Debit
(Internet Banking) 7.45

Total 7.45
 Cash Change 0.00
 Tended Amount 7.45
 Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



To : M/s EQ INSURANCE COMPANY LTD

Date: 17/05/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBH 2216R (Insd Veh)	Your Ref. No. : DMCPHQ18-001543
	SLK 7409J (TP Veh)	Our Ref. No. : CC4/EQI18016587/Kwb3q2
Date of Accident	10/9/2018	

Liability	50%	
Final Repair Cost	: \$ 2,239.38	
Loss of Use	: \$	days
Rental (If any)	: \$ 242.85	6 days
Others:	: \$ 7.45	
	: \$	
	2,489.68	
Final Settlement Sum	: \$ 2,489.68	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	ESTEEM PERFORMANCE PTE LTD	: \$ 2,489.68
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18016587/Kwb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 17-05-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 2216R	Veh. Inspected	SLK 7409J
Policy No.	DMCPHQ18-001543	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET	Assign Date	11/09/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU003540154	Colour	METALLIC SILVER
Odometer	155996	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/09/2018	Inspection Date	11/09/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7409J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH FRONT FENDER	BENT	868.70	868.70
1	LH FRONT FENDER UNDERSHIELD	DISTORTED	176.50	176.50
10	LH FRONT FENDER UNDERSHIELD CLIP	NECESSARY	25.00	25.00
1	LH FENDER WORDING 'HYBRID'	NECESSARY	45.17	45.17
1	LH FRONT FENDER QUARTER GARNISH	DISTORTED	122.70	122.70
1	LH FRONT HUB CAB	SERVICEABLE	195.65	-
1	HEADLAMP LH	CRACKED	2,531.60	2,531.60
1	FRONT BUMPER	CRACKED	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	107.20	-
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	107.20	107.20
1	FOG LAMP LH	SERVICEABLE	910.70	-
	LESS 25% DISCOUNT		-1,395.31	-1,091.92
			4,185.91	3,275.75
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (LH FRONT FENDER ,FRONT BUMPER).		600.00	400.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA ,(LH FRONT FENDER ,FRONT BUMPER).		600.00	400.00
	TO CHECK WIRING & FOCUS HEADLAMP.		50.00	20.00
	TO TUFF COAT.		50.00	30.00
	TO DO WHEEL ALIGNMENT,		120.00	60.00
			1,420.00	910.00
GRAND TOTAL			5,605.91	4,185.75
RECOMMENDED COST OF REPAIRS				4,185.75

Report Ref No. CC4/EQ18016587/Kwb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.