



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemp Perf.com.sg

## Repair Estimates

SLK 7409 J

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>5,581.22</u>
	Plus/Less 25%	\$	<u>1,395.31</u>
	<b>Total of Cost / List</b>	\$	<u><u>4,185.92</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items		_____
<b>Total Parts Cost</b>		\$	<u><u>4,185.92</u></u>
<b>Labour</b>		\$	<u><u>1,420.00</u></u>
<b>Total</b>		\$	<u><u>5,605.92</u></u>

*Not Authorized  
1. B. 1  
Resurvey B4 part*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 11/9/18 at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : lc Date: 11/9/18



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : SLK 7409 J Submit By : Carmen Lim  
 Make & Model : TOYOTA PRIUS Year Manufacture : 2016  
 Chassis No : JTDKB3FU003540154 Engine No. : \_\_\_\_\_  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender	1	\$868.70		✓
2	LH front fender undershield	1	\$176.50		✓
3	LH front fender undershield clip	10	\$25.00		✓
4	LHF fender wording "HYBRID"	1	\$45.17		✓
5	LH front fender quarter garnish	1	\$122.70		✓
6	LH front hub cap	1	\$195.65		X
7	Headlamp LH	1	\$2,531.60		✓
8	Front bumper	1	\$450.80		✓
9	Front bumper clip	10	\$40.00		✓
10	Front bumper side retainer RH	1	\$107.20		X
11	Front bumper side retainer LH	1	\$107.20		✓
12	Fog lamp LH	1	\$910.70		?
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

