

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

11 SEP 2018

E S T I M A T E

Estimate No. : b1 48389	Page No. : 1 of 5
Date Estimated : 11/09/2018	
Prepared By : Gary Poh Chai Hoon	

- ESTIMATE REPAIR FOR - Heng Kee Meng 90 Tampines Road Singapore 535115	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFG1213M	BH13121	29/03/2018	420iA GC	0

DESCRIPTION	VALUE
To replace rear bumper and attachment cause by the accident .	850 1,700.00
Painting rear bumper	934 1,088.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1: 2,995.00	

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER ECE COVER	1	432.90	? 432.90
LEFT PROTECT	1	61.00	? 61.00
RIGHT PROTEC	1	5.25	? 5.25
RR BUMPER LH SIDE GUIDE	1	7.00	X 7.00
RR BUMPER RH SIDE GUIDE	1	48.10	? 48.10
REAR BUMPER CENTRE GUIDE	1	48.10	? 48.10
REAR BUMPER BOTTOM REINFORCEMENT	1	55.40	? 55.40
TRIM STRIP (SPORT LINE)	1	67.10	? 67.10
REAR BUMPER PANEL PRIMED (LINE/PDC)	1	71.65	SUA 71.65
FLAP TOWING EYE PRIMED	1	1,189.90	SUA 1,189.90
REAR RH REAR REFLECTOR	1	42.20	X 42.20
DECOUPLING RING PDC TORQUE CONVERTE	1	35.20	SCA 35.20
PDC SENSOR GLACIER SILVER (A83)	4	5.05	? 20.20
	2	368.80	? 737.60
Total Parts :			2,821.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 48389	Page No. :	2 of 5
Date Estimated	: 11/09/2018		
Prepared By	: Gary Poh Chai Hoon		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFG1213M	BH13121	29/03/2018	420iA GC	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 22/10/18 @ 1405 Excess S\$ _____

Surveyor's Name RKaul Sign _____

Surveyor's Tel 90000068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes P.M.L. Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Dear Surveyor
Note : BMW provide car to owner
22/10/18 10:00

Labour 1	:	2,995.00
Parts	:	2,821.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	407.16
Grand Total	:	6,223.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **