

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGV8282B/1809130

11th September 2018

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

not Arthur
in line
4/5 3
Hdy.
13/9/18
Theophanes Athanasopoulos

Date of Accident : 10th September 2018
Location : Arthur Road
Third Party Claim Vehicle No : SKF 6464 T
Repair Cost For Vehicle No : SGV 8282 B BMW 640I

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia DIS	1	1,513.40	\$ 1,513.40
2	Front bumper clips nu	1set	50.00	\$ 50.00
3	Front bumper bracket RH set	1	41.25	\$ 41.25
4	Front bumper sponge	1	57.45	\$ 57.45
5	Front bumper reinforcement beam	1	745.95	\$ 745.95
6	Front bumper sensor cu	2	236.85	\$ 473.70
7	Front bumper fog lamp RH	1	417.15	\$ 417.15
8	Front bumper fog lamp chrome RH sca	1	41.40	\$ 41.40
9	Front bumper fog lamp cover RH	1	90.85	\$ 90.85
10	Headlamp RH sca/cu	1	2,776.80	\$ 2,776.80
11	Headlamp bracket RH	1	128.45	\$ 128.45
12	Headlamp washer jet RH	1	189.30	\$ 189.30
13	Headlamp washer jet cover RH	1	50.65	\$ 50.65
14	Front fender RH CPA	1	1,074.90	\$ 1,074.90
15	Front fender cowling RH	1	279.70	\$ 279.70
16	Front fender cowling clips	1set	50.00	\$ 50.00
17	Front support panel	1	411.90	\$ 411.90
				\$ 8,392.85

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGV8282B/1809130

11th September 2018

Balance b/f \$ 8,392.85

Labour Charges :-

Cut out, renew, knocking & welding front bumper fascia, front fender RH, remove & install all damage parts, straighten & re-align body

Amounts
\$ 1,380.00 600

Tuff-kote on damage parts

1 - \$ 40.00 x

Spray painting on damage parts

\$ 1,400.00 600

Remove & refix front bumper sensor

\$ 120.00 50

Check all lighting after repairs

\$ 50.00 30

Re-programme front headlamp

\$ 400.00

Computerise wheel alignment

\$ 180.00 100

Labour Charge

\$ 3,570.00

Total Amount

\$11,962.85

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: