ASS. REC. BY:	C(3/7ml18016606/Kgbn2
14	SSIGNMENT
From: Date:	Veh No: 5147 7821 Yr Regn: 06, 16
	Type: M.Car / M.Cycle / Bus / Van / Lorry / (axi) Prime Mover /
OD VTP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	- A:
at Workshop m/s Tears Cob	- THENEUT CONTUCE CC 1975
of	- Insured / Std / NI / NA
Insured: GBH 6536 R	Sp.Reading 338039 T/Radio: Insured / Std / NI / NA Eng/No:
Policy No. MT105673	The state of the s
Claims No. M180 4500	CNO: VIELABLISAUE 283311
Sum Insured: Excess:	- Gen. Cond: Bood Fair / Poor / Burnt
(Client's Record)	Steering: Inorger / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inofder / Jammed / Leaked / Burnt or
	Modi: MI SIRIM / STD A/Rim or
(Policy Condition)	Tyre Size: F: 215/60R16
	R:
Remark: The veh had commenced its repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or
Bal. or Market Value:	Front
IDAC Accident Rport: Consistent? : Yes or No	R/Rail 9
GIA / PR Seen: Consistent?: Yes or No	UBal. 9 mm R/Bal. 0 mm
Est. Repairs: 03 days Res.: Yes or No	D.O.A. 8/8/18 D.O.I. 11/8/10
Lum Sum: 1-B-/% 3 Val.: Yes or No	Survey held at D.O.I. 11/9/18
CA / REV / REP. / 24 HRS	
- Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
12/9 Fix pars to Cornere	
12/6/18/032.16 (Red 5 28709.	61, 83%)
12/9/18 @ 2.56 pm Email GIA report, poc.	ce report to Estimate to Trul.
GBN 6586R - X	
- 1200 V	
RECEIVED	
NEOFIAED !	0 DEL X010
Data/Time, File Pass to?	
Prell. Report Da	ays Of Repair: 3
11/2/19 10/15/4	survey No. of Trip: Survey Fee:
1/2008 (1997) 1 1 1 2 1 2 1 2 1 2 1 1 1 1 1 1 1 1 1	
Add Fee:	Site Inen /S
	Intension (\$
Report Format: MER-TP	Tech lave (\$
Lump Sum / I.B.I: (S 6032-/6)	Weekend (\$
	TOTAL I OLO I

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 12 September 2018 2:56 PM

To:

'Motor Claims'

Cc:

SUR

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE

LTD DOA: 08/09/2018, SHF 782A (TP VEHICLE), GBH 6536R (OI VEHICLE)

Attachments:

SHF782 PR.pdf; SHF782 GIA.pdf; SHF782 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHF 782A M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE	Rebate for Registered	Vehicle
------------------	-----------------------	---------

Vehicle Owner Particulars	Company
Owner ID Type:	
Owner ID:	3878K
Vehicle Details	SHF782A
Vehicle No.:	Yes Yes
Vehicle to be Exported:	10 Sep 2018
Intended Deregistration Date:	8 SVERTAN CONTROL
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003237
Chassis No.:	VF1ABL15AUC283311
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$26,956.00
Total Rebate Amount: Message	\$41,954.00
4 H 10 H 1	he further renewed. The vehicle must be de-registered upon COF expiry or when the

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Sep 2018

OK

MTCS18116647 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE & TIME: 10/09/2018 09:48 SUBMITTED SY: Kek ZheWei

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Date Of Birth

Occupation

Gender

Date Of Driving Pass

Driving Experience

Mobile Number Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	10/09/2018 09:48
Date Of Accident	08/09/2018 18:40
Exact Location Of Accident	SERANGOON ROAD
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHF782A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2:0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No. Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	LAM WENG FATT
NRIC No	S1483146J
	70.0000.0000.0000.000

28/06/1961

OUTDOOR

21/03/1983

MALE

NOEMAIL

35 YEARS AND 5 MONTHS

(LOCAL) +65-90023013

BLK 261A PUNGGOL WAY Address

#06-345

821261 Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

OTHER - HIRER

NO

YES

NO

1

YES

NO

TAMPINES N.P.C

TEL NO: - FAX NO:

General Information of the Accident

COLLISION - MAJOR/MINOR RD Type Of Accident

Weather Conditions CLEAR DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name

Police Station Address

Police Station Contact

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

YES NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

COMMERCIAL VEHICLE

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

G2692733T

RAMASWAMY THANGAM MANIKANDAN

ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

GBH6536R

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LAM WENG FATT

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHF782A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

M

Driver's Signature (If driver is not the policyholder)

Date & Time:

Zhour

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Policyholder's Signature

Date & Time:

Sketch Plan #2 Pg. 1

							П				A: SHE	1844
											A: SHE B: G:8	sH6536
	Sarangoor	Rond.		+								
								4	+++	-	-	
++++						1	M	(3)		1		
			HH	+++			\times	15	TI	4		
									Hinds	1 Root		
							-					
++++												
			++++	1	1	1	14		111			
				1		1	111		+++	++-		
	- 1/2 - 2/0	========										
			0.c. +	D+ 4	- 1							
		1	hefer to	Police A	iqort:							
	CONTRACTOR		Refer to	Police R	ieport:							
			heler to	Police R	iqort:					447		
			Refer to	Police R	uprt:							
			hever to	Police R	uport:							
			Refer to									
			Refer to									
			heler to									
			Refer to									

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





1 of 3

Report No. T/20180909/2032

Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682 Tel No: 1800-5871999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/09/2018 13:12			Vide Report No.:	Station Diary No. 22			
Informa	nt's Partice	ulars	NAME OF THE OWNER OF THE OWNER.				
Name of Informant: LAM WENG FATT			Address: APT BLK 261A PUNGGOL WAY #06-345 SINGAPORE 821261				
ID Type / ID No.: NRIC NO / S1483146J			Contact No.: Home/Office:	Mobile: 90023013			
Nationality: SINGAPORE CITIZEN Sex: Age: Date of Birth: Male 57 28/06/1961 Race: Chinese Occupation:		EN	Email:				
		Date of Birth:	Type of Informant: Driver				
		1	Language: English	Institution / School Name:			
			Driving Licence Information:	Date of Expiry:			

General Infor	mation of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/09/2018 18:40	Type of Location T-Junction	
Location: Junction of R SERANGOO HINDOO RO			1	8	
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	() () () () () () () () () ()	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No	

Details of V	enicie invo	ivea			10 mi	N (D
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
GBH6536R	Van	NISSAN	NV350	Silver	Slightly Damaged	1
SHF782A	TAXI	RENAULT	LATITUDE	Red	Seriously Damaged	200.000

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20180909/2032

Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

CONTINUATION OF REPORT

Driver					G2692733T
Name	RAMASWAMY THANGAM MAN	NIKANDAN	ID No.		G26927331
Related Vehicle	GBH6536R (Van)	9,4	Contact No.		NIL .
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	
Date Treatment	NIL	Date Disc		NIL	
No. of Days gran	ted Medical Leave NIL	Degree of	f Injury	NIL	
Driver				Henry	044004461
Name	LAM WENG FATT		ID No.		S1483146J
Related Vehicle	SHF782A (TAXI)			ct No.	90023013
Hospital/Clinic	CARE MEDICAL CLINIC			of g ce & Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/09/2018	charge 09/09/201			
No. of Days gran	Degree o	of Injury	Serio	ous	

Brief Details.

On 08/09/2018 at about 1840hrs, I was driving my taxi Reg no: SHF782A along Serangoon Road towards Mustafa Centre. I was travelling along the right most lane. As I was driving pass Hindoo Road, suddenly a silver in colour van Reg no: GBH6356R came from Hindoo Road and hit onto the right side of my taxi. The van had hit onto the driver door and I could not open the door to came out from my vehicle. I manage to go out by the front passenger door and at that time I do not feel much pain and only felt some giddiness. I told them I do not need the ambulance.

A police car came after a while and took down our particulars. I took photos of both my taxi and the van. My taxi driver door was badly damaged and dented. The van had slight damages on its front. I then left the accident scene in my taxi.

On 09/09/2018 at about 0900hrs, I wake up and feeling pain around the back, rear of the neck and shoulders. I also feel numb on both hands and legs. I then went to the clinic and was given 5 days medical leave.





3 of 3

Report No. T/20180909/2032

Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

	7		
Signature Of Officer Record G / Sr Staff Sgt MUHAMAD FA SALEH	./	Signature Of Informant:	
Signature Of Interpreter: Not applicable		Date/Time: 09/09/2018 13:12	
Officer In Charge Of Case:	141	Classification Of Case:	
TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	SINGAPORE POLICE FORCE		
Authentication Stamp NP168 SIGNA		TURE	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 782A

AUC283311

Not Nothersel Rearry 184 paint

AAD1809-058

RINE

Vehicle No.:	SHF 782A
Chassis No.:	VF1ABL15A
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	8.9.2018
Third Party Insurer:	TOKIO MA

PART		LIST		
1	FENDER PANEL FRT RH	\$	783.83	
1	WHEELARCH FRT RH	\$	Dir 278.84	
1	FENDER BRACKET LOWER RH	\$	5m 15.79 ×	
1	FENDER INSULATOR RH	\$	∫∽ 130.84 ≺	
1	WHEEL HOUSING COMPLETE SET FRT RH	\$	7 5,978.22 X	
1	DOOR PANEL FRT RH	\$	B 2,844.66	
1	DOOR HINGE UPPER RH	\$	7 261.28	
1	DOOR HINGE LOWER RH	\$	7 300.55	
1	DOOR CHECK FRT RH	\$	∫ 194.77 Å	
1	DOOR LOCK FRT RH	\$	7 908.75	
1	DOOR CATCH FRT RH	\$	Ju 131.23	
1	DOOR HANDLE OUTER FRT RH	\$	√ _← 477.76	
1	DOOR HANDLE COVER FRT RH	\$	∫ 13.22 X	
1	DOOR HANDLE MODULE FRT RH	\$	133.60	
1	DOOR REGULATOR FRT RH	\$	7 505.19	
1	DOOR REGUALTOR MOTOR FRT RH	\$	5× 796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	5h 120.97	
1	LOWER ARM RH	\$	Se 685.76	
1	KUNCKLE ARM RH	\$	<i>S</i> ∽ 846.98	
1	ABSORBER FRT RH	\$	∫ 360.54	
1	STABILIZER BAR FRT	\$	Sm 604.65	
1	DRIVESHAFT RH	\$	1,747.45	
1	WIPER RESERVOIR	\$	رے 348.25	
1	WIPER RESERVOIR NECK	\$	√L 136.11	
1	WIPER RESERVOIR MOTOR	\$	Sh 270.06	
1	DOOR MIRROR ASSY RH	\$	cm 1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	54 466.51 ×	
1	ROCKER PANEL INNER RH	\$	N 1,024.79 \	
1	ROCKER PANEL CENTER RH	\$	N 990.25 ⊀	
1	DOOR HARNESS WIRE	\$	SL 2,670.00 €	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 782A

SHF 782A	k?		
			\$ 25,510.71
	1	0%	\$ 2,551.07
		,	\$ 22,959.64
	Specical Nett		
			5e-100300-5
1SET	FRAME FULL SUPPORT PANEL CLIP		\$ ~~ 70.00 x
2	FRAME FULL SUPPORT PANEL NUT		\$ 1 ≥ 20.00 ×
2	FRAME FULL SUPPORT PANEL STUD		\$ 12 30.00 X
1SET	WHEELARCH CLIP FRT LH		\$ No 30.50
1	FRONT DOOR STICKER 'Trans-cab'		\$ Ma 80.00 605A
1	DOOR CHECK BOLT		\$ an 22.69)
1	DOOR GUIDE SCREW		\$ 10.85
1	DOOR HINGE BOLT		\$ 10.85
1	DOOR HINGE NUT RH		\$ 14.60 > X
1	DOOR CHECK BOLT		\$ 22.69
1	DOOR CHECK NUT		\$ an 3.75
1	DOOR LOCK SCREW L70Y		\$ AL 6.12
1	DOOR CATCH SCREW L70Y		\$ ~~ 10.06)
	тот	AL	\$ 332.13
	TOTAL PA	RTS	\$ 23,291.77
	LAROUR		
	LABOUR		
	Panel beating, knocking and straightening the		
	necessary portion, remove and renewal of parts, adju	ust	450
	and realign the same		\$ 4,500.00
	Putty and spray painting of the affected portion.		\$ 4,200.00 500
	To rust-proofing of the affected areas.		\$ 170.00 601
	To remove and refit interior fittings, trimings, garnis	h,	929
	fittings and other, to enable repair.		\$ NN 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-058

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF 782A

To check steering geometry and computer wheel alignment	\$	12 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~~ 170.00 X
To transfer of tire, fill and on wheel balancing.	335	
To Check Electrical Lighting Concerned.	\$	170.00 20
To transfer of front fender fittings, attachment and	90	4
perform water seepage test.	\$	~~ 380.00 X
To transfer of front door fittings, attachment and		
perform water seepage test.	\$	380.00 601
Towing Fees.	\$	nn 120.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic		
pneumatic jack.	\$	~~ 380.00 X
Labour charge to mount and dismount vehicle on jig		
bench, to facilitate repair.	\$	12 380.00 X
TOTAL	\$	11,450.00
Over All Total	\$	34,741.72
LUMP SUM (REPAIR DAY)		30/27, 34741.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI18016605/KQBN2

19/09/2018

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MT105673

Claimant

SHF782A

Insured Vehicle No:

GBH6536R

Vehicle No: Date of Loss:

08/09/2018

Nature of Claim:

TP

Claim No: M1804500

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHF782A

Make & Model:

RENAULT LATITUDE, 2.0 D dCi (A)

Engine No: Chassis No: M9R8839C003237

Reg. Date: Colour:

30/06/2016 (Man. Year: 2015) Metallic White/Red

Odometer:

VF1ABL15AUC283311 338039 km

Engine Capacity:

Market Value/New Car

1995 cc

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

215/60R16

Rear Tyre Size:

215/60R16

Front Left Side:

Giti 9 mm

Giti 8 mm

Rear Left Side:

Front Right Side:

Giti 9 mm

Rear Right Side:

Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,291.75	4,942.16	18,349.59	78.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,450.00	1,090.00	10,360.00	90.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,741.75	6,032.16	28,709.59	82.64
+ GST 7.00/7.00% (S\$)	2,431.92	422.25	2,009.67	82.64
Nett Amount (S\$)	37,173.67	6,454.41	30,719.26	82.64

INSPECTION

Date of Assignment:

12/09/2018

Date Inspected:

11/09/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Amount

Repairer's

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 19 Sep 2018) Part Source: MRM-SG

RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SHF782A)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

Condition

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Re	com	mende	ed Parts
No.	Qty	Part No.	Particulars

NO.		 Particulars	1911/1911/1911/1919	(Confinences)	17.100000000000000000000000000000000000
1	1	*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
2	1	*WHEELARCH FRT RH	Distorted	278.84 FL	*278.84 FL
3	1	*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*-FL
4	1	*FENDER INSULATOR RH	Serviceable	130.84 FL	*-FL
5	1	*WHEEL HOUSING COMPLETE SET FRT RH	Repair	5,978.22 FL	*-FL
3	1	*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
7	1	*DOOR HINGE UPPER RH	Repair	261.28 FL	*-FL
3	1	*DOOR HINGE LOWER RH	Repair	300.55 FL	*-FL
)	1	*DOOR CHECK FRT RH	Serviceable	194.77 FL	*-FL
10	1	*DOOR LOCK FRT RH	Repair	908.75 FL	*-FL
11	1	*DOOR CATCH FRT RH	Serviceable	131.23 FL	*-FL
12	1	*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*-FL
13	1	*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*-FL
14	1	*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*-FL
15	1	*DOOR REGULATOR FRT RH	Repair	505.19 FL	*-FL
16	1	*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*-FL
17	1	*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*-FL
18	1	*LOWER ARM RH	Serviceable	685.76 FL	*-FL
19	1	*KNUCKLE ARM RH	Serviceable	846.98 FL	*-FL
20	1	*ABSORBER FRT RH	Serviceable	360.54 FL	*-FL
21	1	*STABILIZER BAR FRT	Serviceable	604.65 FL	*-FL
22	1	*DRIVESHAFT RH	Repair	1,747.45 FL	*-FL
23	1	*WIPER RESERVOIR	Serviceable	348.25 FL	*-FL
24	1	*WIPER RESERVOIR NECK	Serviceable	136.11 FL	*-FL
25	1	*WIPER RESERVOIR MOTOR	Serviceable	270.06 FL	*-FL
26	1	*DOOR MIRROR ASSY RH	Cracked	1,483.40 FL	*1,483.40 FL
27	1	*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*-FL
28	1	*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*-FL
29	1	*ROCKER PANEL CENTER RH	Repair	990.25 FL	*-FL
30	1	*DOOR HARNESS WIRE	Serviceable	2,670.00 FL	*-FL
31	1	*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
32	2	*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
33	2	*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
34	1	*SET WHEELARCH CLIP FRT LH	Necessary	30.50 FS	*30.50 FS
35	1	*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
36	1	*DOOR CHECK BOLT	Not Necessary	22.69 FS	
37	1	*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- F8
38	1	*DOOR HINGE BOLT	Not Necessary	10.85 FS	
39	4	*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*-F8
	1	*DOOR CHECK BOLT	Not Necessary	22.69 FS	*-F5
40	4	*DOOR CHECK NUT	Not Necessary	3.75 FS	
41	4	*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	
42		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
_			Sub Total (S\$)	25,842.82	5,481.23
			- List Item Discount on L Items 10.00/10.00% (S\$)	2,551.07	539.07
			Total Parts (S\$)	23,291.75	4,942.16
			Report was unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		4 500 00	450.00
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,500.00	450.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	500.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	-
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
9	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	60.00
10	TOWING FEES	New	120.00	
11	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	ž .
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	
	Gross Labou	r Cost (S\$)	11,450.00	1,090.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.