





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18016610/Nrb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 12-09-2018  
189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 1040E	Veh. Inspected	SHC 4267K
Policy No.	5087272209-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/09/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	08/09/2018	Inspection Date	11/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**TP Claims against NTUC Income: Follow-Through Survey**

Date: 25/10/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1010771-002	SMRT TAXIS PTE LTD	SHC 4267K	SLT 1040E	08/09/2018	3:45	\$ 5,519.70	\$ 1,150.00
2	MT/1016153-002	CITYCAB	SHD 8847E	SLJ 5029R	15/10/2018	19:50	\$ 10,714.80	\$ 5,500.00

Claim received from LKK Auto

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

My Desktop  
Notice of Loss

Policy Query

Policy No.  Date of Accident

Vehicle No.(For Motor)  Certificate Number

Search

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5087272209-01		HUA HONG PTE. LTD.	200900309M	GFT	drive PREMIUM	SLT1040E	SLT1040E	03/01/2018	

Continue

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/09/2018 09:46
Date Of Accident	08/09/2018 03:45
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4267K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	KUAR HUA MENG
NRIC No	S7033351A
Date Of Birth	25/09/1970
Occupation	OUTDOOR
Date Of Driving Pass	22/01/1991
Driving Experience	27 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 11  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - U-TURN  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS TRAVELLING ALONG RIVER VALLEY ROAD AND WAS MAKING A U TURN ON THE RIGHT. WHILST I WAS MAKING A U TURN, SUDDENLY A VEHICLE SLT1040E WHICH WAS TRAVELLING ON MY LEFT, MADE AN ILLEGAL U TURN AND COLLIDED ONTO THE FRONT LEFT PORTION OF MY TAXI.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE TOO BIG  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLT1040E  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver UNKNOWN  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

 8/9/2018

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

 8/9/2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Transfer Fee Enquiry

[> Back to OneMotoring](#)

## Enquire Transfer Fee

## Vehicle Details

Vehicle No.: SHC4267K  
 Vehicle Type: H10 - Public Transport Taxi (Motor Car)  
 Vehicle Attachment 1: Air-Con (Taxi)  
 Vehicle Scheme: Taxi (Company)  
 Vehicle Make: TOYOTA  
 Vehicle Model: PRIUS TAXI (SMRT)  
 Chassis No.: JTDKN36U305705402  
 Propellant: Petrol-Electric  
 Engine No.: 2ZR5906227  
 Motor No.: 3JM5906227  
 Engine Capacity: 1798 cc  
 Power Rating: 60.0 kW  
 Maximum Power Output: 100.0 kW ( 134 bhp)  
 Maximum Laden Weight: 1805 kg  
 Unladen Weight: 1370 kg  
 Year Of Manufacture: 2013  
 Original Registration Date: 22 Nov 2013  
 Lifespan Expiry Date: 21 Nov 2021  
 COE Category: A - Car (1600cc & below)  
 PQP Paid: \$63,297.00  
 COE Expiry Date: 21 Nov 2021  
 Road Tax Expiry Date: 21 May 2019  
 PARF Eligibility Expiry Date: 21 Nov 2021  
 Inspection Due Date: 21 May 2019  
 Intended Transfer Date: 16 Nov 2018  
 CO2 Emission: 92.00 (g/km)  
 CEV/VES Rebate Utilised: \$30,000.00  
 Amount:  
 CO Emission: -  
 HC Emission: -  
 NOx Emission: -  
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

**Amount Payable**

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Total Amount Payable:</b>			<b>25.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

TP

### SMRT Accident Taxi Repair Estimates

**Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre**

Reg. No. : SHC 4267K Ref. No. TAX 9 / 18 / 2027

Make / Model : TOYOTA PRIUS Reg. Date : 20/11/2015

Name of Driver : KUAR HUA MENG

Date/Time of Accident : 08/09/2018 15:43

Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)

Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097863

Special Instruction to ARC, if any :

---




---



---

Signed : \_\_\_\_\_ Date : \_\_\_\_\_



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U305705402 Mileage : \_\_\_\_\_

Date Prepared : 10/09/2018 Repair Completed date/time: \_\_\_\_\_

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>676.00</u>	\$ _____
Total Spray Painting Charges :	\$ <u>558.00</u>	\$ _____
Total Material Charges :	\$ <u>3386.36</u>	\$ _____
Other Charges :	\$ <u>296.00</u>	\$ _____
<b>TOTAL</b> :	\$ <u>4916.36</u> <i>5519.70</i>	\$ <u>0</u> ( )
No. of Repair Days :	[ <u>4</u> ] days	[ <u>2</u> ] days
Signature :	Prepared by: <u>MING</u> <u>10/09/2018 10:46</u>	Adjusted by: _____

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

QN No. \_\_\_\_\_ Invoice No. \_\_\_\_\_ Invoice Date \_\_\_\_\_

Signed : \_\_\_\_\_ Date : \_\_\_\_\_

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	507.00	300 /
<b>Total Labour</b>	<b>\$ 507.00</b>	<b>\$ -</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	<del>378.00</del>	200 /
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	<del>180.00</del>	80 /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$ 558.00</b>	<b>\$ -</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	X 00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	X 20 /
TO REPLACE SUNDRY PARTS	100.00	X 00
TO WASH AND VACUUM	60.00	X 00
<b>Total Other Costs</b>	<b>\$ 296.00</b>	<b>\$ -</b>

Section D - Details of Repair Estimates

Ref. No. TAX 9 / 16 / 2027

Part 4 - Spare Parts / Material Usage

Reservation No : \_

Page ( )

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (I)	Not given (x) Repair (R) Replace (I)
52119-47930	BUMPER FRT	1	482	25%	361.5	/	X R
52116-47040	BUMPER SUPPORT F/LH	1	76.4	25%	57.3	/	? X SVC
90467-07211	BUMPER CLIPS	10	2.1	25%	15.75	/	X m
81521-47050	LENS & BODY, FR TURN LH	1	511.8	10%	460.62	/	/ SCR
81529-47040	BRACKET, FR TURN UPPER LH	1	24.4	25%	18.3	/	?
81529-47050	BRACKET, FR TURN LOWER LH	1	26	25%	19.5	/	?
81529-47060	BRACKET, FR TURN CENTER LH	1	58.2	25%	43.65	/	?
52611-47080	BUMPER ENERGY ABSORBER FRT	1	78.8	25%	59.1	/	? X SVC
52021-47023	BUMPER REINFORCEMENT FRT	1	498.4	25%	373.8	/	?
57014-47030	ARM SUB-ASSY, FR BUMPER LH	1	250.4	25%	187.8	/	?
81170-47500	HEAD LAMP LH	1	945.2	10%	850.68	/	?
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1	311.1	25%	233.33	/	/ CRA
52128-47903	COVER, FR BUMPER HOLE LH	1	18.5	25%	13.88	/	/ DEF
	NUMBER PLATE FRAME	1	12	0%	12	/	X SVC
	NUMBER PLATE	1	15	0%	15	/	X SVC
52114-47140	BRACKET, FR BUMPER	1	110.4	25%	82.8	/	? SVC
81220-12230	FOG LAMP LH	1	280.1	25%	252.09	/	? SVC
53876-47030	FENDER LINER FRT/LH	1	171.7	25%	128.78	/	X SVC
52618-47050	BUMPER FRT ABSORBER LOWER	1	127.7	25%	95.78	/	? SVC
76851-47020	BUMPER LIP FRT	1	139.6	25%	104.7	/	/ CRA
			4158.70				
<b>TOTAL MATERIALS</b>						\$	<b>3,386.36</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from the Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

NA2 LKK  
11/9/18 1040  
LIS  
2 DAYS  
APTEL REPAIR PHOTO  
12/9/18

5519.70



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63683552
Estimate Telephone Number : 68662523
Accident Reporting Number : 65662672

Date Generated : 23/10/2018

User ID : PohSuan

Section A - Accident Details	
Registration Number	SHC4267K
Case Reference Number	TAX/09/18/2027
Registration Date	22/11/13
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	KUAR HUA MENG
Type of Accident	Side Swipe
Accident Date and Time	08/09/18 3:43 AM
Accident Reported Date and Time	08/09/18 9:30 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097863
Special Instruction to ARC,if any	
Prepared Date and Time	13/10/18 10:55 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$558.00	\$280.00
Total Spare Part Cost	\$3,372.18	\$812.53
Total Other Cost	\$296.00	(\$242.53)
<b>TOTAL COST</b>	<b>\$4,733.18</b>	<b>\$1,150.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date		
Signature	<input type="checkbox"/>	<input type="checkbox"/>
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-1810-0470	Invoice Number	
Quotation Date	23.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	\$507.00	\$300.00
<b>Total Labour</b>	<b>\$507.00</b>	<b>\$300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$80.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$558.00</b>	<b>\$280.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$262.53)
<b>Total Other Costs</b>	<b>\$296.00</b>	<b>(\$242.53)</b>

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6505517		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$0.00	Replace	Repair R
			BUMPER SUPPORT F/LH	0.00	\$76.40	25.00	\$0.00	Replace	Not Given X
		52161-16010	BUMPER CLIPS	0.00	\$2.10	25.00	\$0.00	Replace	Not Given X
			LENS & BODY, FR TURN LH	1.00	\$511.80	10.00	\$460.62	Replace	Replace ✓
			BRACKET, FR TURN UPPER LH	0.00	\$24.40	25.00	\$0.00	Replace	Not Given X
			BRACKET, FR TURN LOWER LH	0.00	\$26.00	25.00	\$0.00	Replace	Not Given X
			BRACKET, FR TURN CENTER LH	0.00	\$58.20	25.00	\$0.00	Replace	Not Given X
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	25.00	\$0.00	Replace	Not Given X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	25.00	\$0.00	Replace	Not Given X
			ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	25.00	\$0.00	Replace	Not Given X
6505436		81170-47500	HEAD LAMP LH	0.00	\$945.20	10.00	\$0.00	Replace	Not Given X
			BUMPER GRILLE SUB-ASSY,	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
			COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace ✓
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given X
			BRACKET, FR BUMPER	0.00	\$110.40	25.00	\$0.00	Replace	Not Given X
6505438		81220-12230	FOG LAMP LH	0.00	\$280.10	10.00	\$0.00	Replace	Not Given X
			FENDER LINER FRT/LH	0.00	\$171.70	25.00	\$0.00	Replace	Not Given X
6505540		52618-47050	BUMPER FRT ABSORBER	0.00	\$127.70	25.00	\$0.00	Replace	Not Given X
6505616		76851-47020	BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
<b>Total</b>					<b>\$4,139.80</b>		<b>\$812.53</b>		

812.53  
 + 300.00  
 + 300.00  
 -----  
 1412.53  
 - 202  
 1130.02

4/5 \$1150/-

## Janice Lee (LKKAuto)

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
<YeoPohsuan@smrt.com.sg>  
**Sent:** Wednesday, October 24, 2018 11:58 AM  
**To:** Naz (LKKAuto)  
**Cc:** SUR; CS A Team  
**Subject:** SHC 4267K  
**Attachments:** img-X24115737-0001.pdf

Hi Naz,

Attached herewith the repair estimate of SHC 4267K having Case No: TAX/09/18/2027.

There is no change to the approved amount of \$1,150 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
**Sent:** Wednesday, 24 October 2018 11:58 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
**Subject:** Scan Data from FX-D421D6

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Thursday, October 25, 2018 12:53 PM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Naz (LKKAuto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHC 4267K

Dear Poh Suan,

Confirm L/S \$1,150.00 @ 2 DAYS

Thank you.

Best Regards,  
Jannice Lee (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Wednesday, October 24, 2018 11:58 AM  
**To:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>  
**Subject:** SHC 4267K

Hi Naz,

Attached herewith the repair estimate of SHC 4267K having Case No: TAX/09/18/2027.

There is no change to the approved amount of \$1,150 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
**Sent:** Wednesday, 24 October 2018 11:58 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
**Subject:** Scan Data from FX-D421D6



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18016610/Nrbs2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 16-11-2018
	Code: INC4



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 1040E	Veh. Inspected	SHC 4267K
Policy No.	5087272209-01	Coverage (\$)	0.00
Claim No.	MT/1010771-002	Excess (\$)	0.00
Assign From		Assign Date	11/09/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U305705402	Colour	MAROON
Odometer	367882	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	6 mm
L/H Front Tyre	195/65R15	FALKEN	6 mm
R/H Rear Tyre	195/65R15	FALKEN	5 mm
L/H Rear Tyre	195/65R15	FALKEN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	08/09/2018	Inspection Date	11/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4267K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.33
1	COVER, FR BUMPER HOLE LH (DISC 25%)	DEFORMED	18.50	13.88
1	BUMPER LIP FRT (DISC 25%)	CRACKED	139.60	104.70
1	LENS & BODY, FR TURN LH (DISC 10%)	SCRATCHED	511.80	460.62
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BRACKET, FR TURN UPPER LH	SERVICEABLE	24.40	-
1	BRACKET, FR TURN LOWER LH	SERVICEABLE	26.00	-
1	BRACKET, FR TURN CENTER LH	SERVICEABLE	58.20	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	HEAD LAMP LH	SERVICEABLE	945.20	-
1	NUMBER PLATE FRAME	SERVICEABLE	12.00	-
1	NUMBER PLATE	SERVICEABLE	15.00	-
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	FENDER LINER FRT/LH	SERVICEABLE	171.70	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
10	BUMPER CLIPS @ \$2.10	NOT NECESSARY	21.00	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
			<b>4,158.70</b>	<b>812.53</b>
<b><u>LABOUR</u></b>				
PANEL BEATING AND BODYWORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT.			507.00	300.00
SPRAY PAINT.			558.00	280.00
TOWING CHARGE.			56.00	-
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO REPLACE SUNDRY PARTS.			100.00	-

Report Ref No. NS/INC18016610/Nrbs2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,361.00	600.00
<b>GRAND TOTAL</b>			<b>5,519.70</b>	<b>1,412.53</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,150.00</b>

Report Ref No. NS/INC18016610/Nrbs2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.