

ASS. REC. BY:

REF:

CS/CTL18076615/Avbn2

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTL

Date/Time:

12092018 1035am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 5769 X

Insured:

SJV 3333 K

at Workshop m/s

Hui Huang Hong Bao

Tel:

8102 5571

of

2 Kaki Bukit Ave 2 #02-11

Policy No:

DMPCSN3029851800

Claim No:

SNM18D04285002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08092018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

12092018 11:20am

Person Contacted:

Alison

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLR 5769 X - X

SJV 3333 K - X

16/10/18

Adrian confirmat LS \$4000 (Red 1582.36, 287)

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR5769 X Yr Regn: 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Shuttle C.C. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 67503 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GP711 14284
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/50 R16
 R: 205/50 R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Achilles
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 12/09/18
 Survey held at Hui Huang, Hong Kong
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-----------------------------|---------------------------|
| | <u>TP Hit Sup Chines.</u> |
| RECEIVED 17 OCT 2018 | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) 16/10 - typist
 Report Format: merimen
 Lump Sum / I.B.I: (\$) 4000

Days Of Repair: 6
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

| | |
|-----------------|------------|
| Survey Fee: | |
| Transportation: | |
| \$ + RS \$ | |
| Photos | |
| Others | |
| TOTAL | <u>220</u> |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|-------------|--------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 12 Sep 2018 | | 12 Sep 2018 10:35 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | |
|----------------------------------|---|---------------------------------|---|
| Insured: | LIM PUI LING DOREEN, ID: S7528202H | | |
| Main Claimant: | POPULAR RENT A CAR PTE LTD, | Co. Reg. No.: 199608195Z | |
| Vehicle Reg. No.: | SLR5769X | Date of Loss: | 08/09/2018 16:00 - :59 |
| Claim Type: | TP / SNM18D04385C02 | Policy/Cover Note No.: | DMPCSN3029851800 (Comprehensive) Coverage: 16/04/2018 - 18/05/2019 |
| Vehicle Reg. No. (Insured): | SJV3333K | Policy No. (Claimant): | 9999994983/100829569 |
| | | Excess: | S\$0.00 |
| Repairer: | HUI HUANG HONG BAO MOTORS (HQ) 2 Kaki Bukit Ave 2, #02-11 Kakit Bukit @ Autohub, 417921 Kaki Bukit - Tel: 6844 7414 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174] | | |
| Claimant's Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/09/2018] | | |
| Adj Asg. Remarks: | 1) AGREED SJE 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS. | | |
| ASSOCIATED MAIL RECEIVED | | View All | Compose Case Mail |
| There are no mail for this case. | | | |
| ALL ASSOCIATED TASKS | | View All | Search Tasks |
| | | Create New Task | Complete |
| Due Date | Priority | Type | Task Group |
| | | | Subject |
| | | | Handler |
| | | | Assigned By |
| | | | Completed On |
| | | | Created On |
| | | | Done? |
| No results. | | | |

Veron Chen (LKKAuto)

From: Hui Huang Hong Bao Motors Alison <alisonhhib@gmail.com>
Sent: Thursday, 13 September 2018 4:21 PM
To: Admin-D (LKKAuto)
Subject: SLR 5769 X
Attachments: SLR 5769 X gia 2.pdf

Hi Catherine,

Enclosed is the estimated cost of repairs
and GIA report for Adrian to finalize

Regards
Alison

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|---------------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 8195Z |
| Vehicle Details | |
| Vehicle No.: | SLR5769X |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 13 Sep 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | SHUTTLE HYBRID 1.5 AUTO |
| Primary Colour: | Silver |
| Manufacturing Year: | 2017 |
| Engine No.: | LEB6317412 |
| Chassis No.: | GP71114284 |
| Maximum Power Output: | 101.0 kW (135 bhp) |
| Open Market Value: | \$20,253.00 |
| Original Registration Date: | 18 Aug 2017 |
| First Registration Date: | 18 Aug 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,000.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 17 Aug 2027 |
| PARF Rebate Amount: | \$3,750.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 17 Aug 2027 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$54,406.00 |
| COE Rebate Amount: | \$48,570.00 |
| Total Rebate Amount: | \$52,320.00 |

The information contained herein is correct as at 13 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---|
| Date Of Report | 10/09/2018 12:19 |
| Date Of Accident | 08/09/2018 16:20 |
| Exact Location Of Accident | LORONG SESUAI SLIP ROAD TO BUKIT TIMAH ROAD |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SLR5769X |
| Insured/Policyholder | |
| Name Of Registered Owner | POPULAR RENT A CAR PTE LTD |
| Co Reg No | 199608195Z |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-67428888 |

Vehicle Particulars

| | |
|--|------------------------|
| Manufacturer | HONDA |
| Model | SHUTTLE HYBRID-1.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG ASIA PACIFIC INSURANCE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 9999994983/100829569 |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | TAN KAY MUIR |
| NRIC No | S1347033B |
| Date Of Birth | 17/01/1959 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 12/06/1990 |
| Driving Experience | 28 YEARS AND 2 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-90912578 |
| Fax Number | |
| Contact Number | |
| EEmail Address | NOEMAIL |

Address BLK 1 TANJONG PAGAR PLAZA #14-52 (S) 082001
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : APRIL ONG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] CAIRNHILL NPP
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER WITH ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name
 Phone Number 94243856
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV3333K
 Vehicle Make/Model/Colour BMW 740I
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver NEO KHOON SENG
 NRIC/Passport Number S6942241A
 Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAY KAR MUIR

Approximate Age

Injuries Sustain

A LIFE CLINIC PTE LTD - 5 DAYS MC

Injured person in which vehicle?

SLR5769X

Were seat belts worn?

YES


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921
 Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbbb@gmail.com

LKK Advian
12/9/18

M/s Popular Rent A Car Pte Ltd
 501 Guillemard Road
 Singapore 399840

12th September 2018

TP China.
Veron.

Estimate cost of repairs to Honda Shuttle - SLR 5769 X

| | | | | |
|-------|--|------------------|----------------------|------------|
| 1 pc | Tailgate <i>Distorted</i> | | \$ 1,193.40 | ✓ |
| 1 pc | Tailgate 'H' emblem | | \$ 33.10 | ✓ |
| 1 pc | Tailgate 'Hybrid' emblem | <i>3 new</i> | \$ 65.20 | ✓ |
| 1 pc | Tailgate 'Shuttle' emblem | | \$ 55.00 | ✓ |
| 1 pc | Tailgate weatherstrip | <i>the new</i> | \$ 95.10 | ✓ |
| 1 pc | Tailgate inner lock | <i>Damaged</i> | \$ 175.10 | ✓ |
| 1 pc | LH rear lamp | <i>Called</i> | \$ 520.50 | ✓ |
| 1 pc | Rear end panel | <i>Dented</i> | \$ 601.50 | ✓ |
| 1 pc | Rear bumper | <i>Distorted</i> | \$ 1,150.60 | ✓ |
| 2 pcs | Rear bumper retainers @S\$28.60 | <i>new</i> | \$ 57.20 | ✓ |
| | | | \$ 3,946.70 | |
| | Less 20% | | \$ (789.34) | |
| | | | \$ 3,157.36 | |
| | | <i>3851.60</i> | | |
| | | <i>3081.28</i> | | |
| 1 set | Tailgate inner trim clips | <i>new</i> | \$ 20.00 | SN ✓ |
| 1 set | Rear bumper clips | <i>new</i> | \$ 25.00 | SN ✓ |
| 1 pc | Rear windscreen sealant | <i>new</i> | \$ 40.00 | SN ✓ |
| | To remove and refit rear windscreen glass | <i>85</i> | \$ 150.00 | <i>120</i> |
| | To remove and refit reverse sensors | | \$ 60.00 | <i>40</i> |
| | To remove and refit tailgate interior fittings | | \$ 120.00 | <i>80</i> |
| | Tuff kote | | \$ 60.00 | <i>40</i> |
| | To remove and refit back-up camera | | \$ 50.00 | <i>40</i> |
| | Wiring charges | | \$ 50.00 | <i>30</i> |
| | Labour charges to repair boot floor panel, to cut out rear end panel, to panel beating, welding and straightening, to remove, renew and align replaced | | | |

parts etc

\$ 800.00 ⁷⁰⁰

Spray painting

1750

\$ 800.00 ⁷⁰⁰

\$ 5,332.36

5582.36

Dollars : Five thousand three hundred thirty-two and cents thirty-six only.

Supplementary : 200.

total : 5116.28

L/S : A K.

06 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbbb@gmail.com

M/s Popular Rent A Car Pte Ltd
501 Guillemard Road
Singapore 399840

18th September 2018

Supplementary cost of repairs to Honda Shuttle - SLR 5769 X

| | | | | |
|-------|-----------------|----------------|----|--|
| 1 set | Reverse sensors | <i>Damaged</i> | \$ | 250.00 SN <i>200(SN)</i> |
|-------|-----------------|----------------|----|--|

Dollars: Two hundred and fifty only.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118016615/AVBN2
Date: 19/10/2018

REFERENCE

| | | | |
|-----------------------|---|----------------------|------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSN3029851800 |
| Claimant Vehicle No : | SLR5769X | Insured Vehicle No : | SJV3333K |
| Date of Loss: | 08/09/2018 | Nature of Claim: | TP |
| | | Claim No: | SNM18D04385C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------|-------------|------------|
| Reg No: | SLR5769X | Engine No: | LEB6317412 |
| Make & Model: | HONDA SHUTTLE HYBRID, 1.5 (A) | Chassis No: | GP71114284 |
| Reg. Date: | 18/08/2017 (Man. Year: 2017) | Odometer: | 67503 km |
| Colour: | Silver | | |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/50R16 | Rear Tyre Size: | 205/50R16 |
| Front Left Side: | Achilles 6 mm | Rear Left Side: | Achilles 6 mm |
| Front Right Side: | Achilles 6 mm | Rear Right Side: | Achilles 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 3,492.36 | 3,366.28 | 126.08 | 3.61 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,090.00 | 1,750.00 | 340.00 | 16.27 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,582.36 | 5,116.28 | 466.08 | 8.35 |
| Approved Total (Overridden) (S\$) | | 4,000.00 | | |
| Nett Amount (S\$) | 5,582.36 | 4,000.00 | 1,582.36 | 28.35 |

INSPECTION

| | | |
|---------------------|--------------------------|--|
| Date of Assignment: | 12/09/2018 | |
| Date Inspected: | 12/09/2018 Inspected At: | HUI HUANG HONG BAO MOTORS (HQ) 2 Kaki Bukit Ave 2, #02-11 Kakit Bukit @ Autohub Singapore 417921 |

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | |
|----------------------|--|
| Reference | |
| Part Source: | (Last Synchronised: 19 Oct 2018) |
| Parts: | N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database) |
| Labour: | Repairer's (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLR5769X) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|--------------------------------|---------------|--|-----------------|-----------------|
| 1 | 1 | | *TAILGATE | Distorted | 1,193.40 FL | *1,193.40 FL | |
| 2 | 1 | | *TAILGATE H EMBLEM | Necessary | 33.10 FL | *33.10 FL | |
| 3 | 1 | | *TAILGATE HYBRID EMBLEM | Necessary | 65.20 FL | *65.20 FL | |
| 4 | 1 | | *TAILGATE SHUTTLE EMBLEM | Necessary | 55.00 FL | *55.00 FL | |
| 5 | 1 | | *TAILGATE WEATHERSTRIP | Not Necessary | 95.10 FL | *. FL | |
| 6 | 1 | | *TAILGATE INNER LOCK | Damaged | 175.10 FL | *175.10 FL | |
| 7 | 1 | | *LH REAR LAMP | Cracked | 520.50 FL | *520.50 FL | |
| 8 | 1 | | *REAR END PANEL | Dented | 601.50 FL | *601.50 FL | |
| 9 | 1 | | *REAR BUMPER | Distorted | 1,150.60 FL | *1,150.60 FL | |
| 10 | 2 | | *REAR BUMPER RETAINERS | Necessary | 57.20 FL | *57.20 FL | |
| 11 | 1 | | *SET TAILGATE INNER TRIM CLIPS | Necessary | 20.00 FS | *20.00 FS | |
| 12 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 25.00 FS | *25.00 FS | |
| 13 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 40.00 FS | *40.00 FS | |
| 14 | 1 | | *SET REVERSE SENSORS | Damaged | 250.00 FS | *200.00 FS | |
| | | | | | Sub Total (\$\$) | 4,281.70 | 4,136.60 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (\$\$) | 789.34 | 770.32 |
| | | | | | Total Parts (\$\$) | 3,492.36 | 3,366.28 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REFIT REAR WINDSCREEN GLASS | New | 150.00 | 120.00 |
| 2 | TO REMOVE AND REFIT REVERSE SENSORS | New | 60.00 | 40.00 |
| 3 | TO REMOVE AND REFIT TAILGATE INTERIOR FITTINGS | New | 120.00 | 80.00 |
| 4 | TUFF KOTE | New | 60.00 | 40.00 |
| 5 | TO REMOVE AND REFIT BACK-UP CAMERA | New | 50.00 | 40.00 |
| 6 | WIRING CHARGES | New | 50.00 | 30.00 |
| 7 | LABOUR CHARGES TO REPAIR BOOT FLOOR PANEL, TO CUT OUT REAR END PANEL, TO PANEL BEATING, WELDING AND STRAIGHTENING, TO REMOVE, RENEW AND ALIGN REPLACED PARTS ETC | New | 800.00 | 700.00 |
| 8 | SPRAY PAINTING | New | 800.00 | 700.00 |
| Gross Labour Cost (S\$) | | | 2,090.00 | 1,750.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >