

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484

E-mail : tsac303@singnet.com.sg

M / s : **India International Ins Pte Ltd**
64, Cecil Street, #04-00 IOB Bldg,
Singapore 049711

Estimate bill : TT 43 / 18 / TP / WT

Registration No : SLU7811C

Attn : Motor Claims Department
Tel : 62238122
Fax : 62257743

Make / model : Nissan Qashqai

Not Botherted
Phony B6 pain

Mileage :

Date : 10 / 10 / 2018

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SHA3482Y AND SLU7811C ALONG BEDOK NORTH AVENUE 4 TOWARDS BEDOK NORTH ROAD JUNCTION ON 11 SEPTEMBER 2018 AT ABOUT 0458 HRS.

1pc	Front grille with chrome moulding		\$	850.00	✓
1pc	Front bumper		\$	945.00	✓
1pc	Front bumper grille (Centre, Top)		\$	365.00	✓
	Sub A total :		\$	2,160.00	
	Less 30% discount :		\$	648.00	
	A total :		\$	1,512.00	
Special net items					
1pc	Front grille 'Nissan emblem'		\$	153.00	✓
14pcs	Front fender wheel arch clip	(Each \$7.00)	\$	98.00	✓
1pc	Front license plate		\$	45.00	✓
1pc	Front license plate casing		\$	296.00	✓
	B total		\$		
	Remove and transfer front bumper necessary attachment spare part items.		\$	400.00	✓
	Remove and refit front grille chrome moulding, front bumper, front bumper grille (Centre, Top).		\$		
	Heat / weld / beating / pull / straighten / align front chassis frame by Chassis Alignment Jack.		\$		
	Tuff koff front damaged portion.		\$	150.00	✓
	Putty / primer application, spray painting front bumper.		\$	300.00	✓
	Grand amount :		\$	2,658.00	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: