

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SLS9465R	Accident Date	: 08/09/2018
Make	: AUDI A5	Policy No.	: 1700063587
Assignment Date	: 12/09/2018	Excess	: S\$3,800.00
Date of Inspection	: 12/09/2018	Est. Duration of Repair	: 4 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,295.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	13,254.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,688.00
Total	:S\$	14,942.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	170,000.00
COE / PARF Rebate	:S\$	75,443.00
Salvage Value	:S\$	
Margin for Repair	:S\$	94,557.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 246.00