

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7693Z****AAD1809-080***Not Authorized  
L1 Lys \$14502*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHB 7693Z**

KL1LA69RJB078418

CHEVROLET

EPICA 2.0

10.9.2018

**QBE**

| PART |   |                                     | LIST |                    |                   |
|------|---|-------------------------------------|------|--------------------|-------------------|
| 1    | 1 | Rear Bumper                         | \$   | <i>Bu</i> 1,202.00 | <i>✓</i>          |
| 2    | 1 | Rear Bumper Beam                    | \$   | <i>Bu</i> 239.94   | <i>✓</i>          |
| 3    | 1 | Rear Bumper Centre Absorber         | \$   | <i>su</i> 260.00   | <i>X</i>          |
| 4    | 1 | Rear Bumper Side Retainer RH        | \$   | <i>su</i> 68.76    | <i>}</i>          |
| 5    | 1 | Rear Bumper Side Retainer LH        | \$   | <i>su</i> 68.76    |                   |
| 6    | 1 | Rear Bumper Reflectors RH           | \$   | <i>su</i> 119.74   |                   |
| 7    | 1 | Rear Bumper Reflectors LH           | \$   | <i>su</i> 119.74   |                   |
| 8    | 1 | Rear Bumper Tow Hook Cover          | \$   | <i>su</i> 93.00    |                   |
| 9    | 1 | Rear End Panel Outer                | \$   | <i>su</i> 623.76   |                   |
| 10   | 1 | Rear End Panel Inner Trim           | \$   | <i>su</i> 263.84   |                   |
| 11   | 1 | Rear Luggage Floor Panel            | \$   | <i>su</i> 973.00   |                   |
| 12   | 1 | Rear Luggage Floor Panel Insulator  | \$   | <i>su</i> 63.50    |                   |
| 13   | 1 | Rear Luggage Floor Panel Trim Board | \$   | <i>su</i> 378.00   |                   |
| 14   | 1 | Bootlid                             | \$   | <i>su</i> 973.00   | <i>}</i> <i>X</i> |
| 15   | 1 | Bootlid inner trim board            | \$   | <i>su</i> 400.00   |                   |
| 16   | 1 | Bootlid Weatherstrip                | \$   | <i>su</i> 344.28   |                   |
| 17   | 1 | Bootlid Lock - Top                  | \$   | <i>su</i> 466.56   |                   |
| 18   | 1 | Bootlid 'CHEVROLET' Badge           | \$   | <i>su</i> 120.62   |                   |
| 19   | 1 | Bootlid Logo                        | \$   | <i>su</i> 138.84   |                   |
| 20   | 1 | Bootlid 'EPICA LT' Badge            | \$   | <i>su</i> 119.84   |                   |
| 21   | 1 | Bootlid Reflector Centre            | \$   | <i>su</i> 217.97   |                   |
| 22   | 1 | Bootlid Reflector RH                | \$   | <i>su</i> 128.40   |                   |
| 23   | 1 | Bootlid Reflector LH                | \$   | <i>su</i> 128.40   |                   |
| 24   | 1 | Rear Tail Lamp RH                   | \$   | <i>su</i> 479.30   | <i>}</i>          |
| 25   | 1 | Rear Tail Lamp LH                   | \$   | <i>su</i> 479.30   |                   |
| 26   | 1 | Rear Exhaust Box (Muffler A-EXH,RR) | \$   | <i>su</i> 1,110.00 |                   |
| 27   | 1 | Rear Fender RH                      | \$   | <i>su</i> 1,145.00 |                   |
| 28   | 1 | Rear Fender Inner Trim RH           | \$   | <i>su</i> 418.44   |                   |
| 29   | 1 | Rear Fender LH                      | \$   | <i>su</i> 1,145.00 |                   |

**Trans-cab Auto Services Pte Ltd****AAD1809-080**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7693Z**

|    |   |                           |    |                           |
|----|---|---------------------------|----|---------------------------|
| 30 | 1 | Rear Fender Inner Trim LH | \$ | <i>Sn</i> 418.44 <i>X</i> |
|----|---|---------------------------|----|---------------------------|

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>12,707.43</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,270.74</b>  |
|              | <b>\$</b> | <b>11,436.69</b> |

**Special Nett**

|    |      |                                   |    |                           |
|----|------|-----------------------------------|----|---------------------------|
| 1  | 1Set | Bootlid inner trim board Clip     | \$ | <i>nn</i> 40.00 <i>X</i>  |
| 2  | 1Set | Rear Bumper Parking Sensor        | \$ | <i>Sn</i> 300.00 <i>X</i> |
| 3  | 1Set | Rear Bumper Fastener Clip         | \$ | <i>nn</i> 44.00           |
| 4  | 1Set | Rear Fender Inner Trim Clip LH    | \$ | <i>nn</i> 30.00           |
| 5  | 1Set | Rear Bumper End Dust Cover Clip   | \$ | <i>nn</i> 30.00           |
| 6  | 1    | Rear Exhaust Mounting             | \$ | <i>Sn</i> 300.00          |
| 7  | 2    | Rear Windscreen Sealant           | \$ | <i>nn</i> 80.00           |
| 8  | 1    | Rear Windscreen Inner Sponge Seal | \$ | <i>nn</i> 100.00          |
| 9  | 1    | Spare Tyre                        | \$ | <i>Sn</i> 180.00          |
| 10 | 1    | Spare Wheel Rim                   | \$ | <i>Sn</i> 126.74          |
| 11 | 1    | Rear boot sticker 'Trans-cab'     | \$ | <i>nn</i> 80.00           |
| 12 | 1    | Rear boot sticker '6555-3333'     | \$ | <i>nn</i> 80.00           |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>1,390.74</b> |
|--------------|-----------|-----------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>12,827.43</b> |
|--------------------|-----------|------------------|

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of  
Parts, Adjust And Realign The Same

|    |          |            |
|----|----------|------------|
| \$ | 3,500.00 | <i>200</i> |
|----|----------|------------|

To Check Electrical Lighting Concerned.

|    |        |            |
|----|--------|------------|
| \$ | 170.00 | <i>100</i> |
|----|--------|------------|

To Rust-Proofing Of The Affected Areas.

|    |                  |          |
|----|------------------|----------|
| \$ | <i>nn</i> 170.00 | <i>X</i> |
|----|------------------|----------|

Putty And Spray Painting Of The Affected Portion.

|    |          |            |
|----|----------|------------|
| \$ | 3,000.00 | <i>200</i> |
|----|----------|------------|

To reinstall rear bumper parking sensor.

|    |        |            |
|----|--------|------------|
| \$ | 170.00 | <i>600</i> |
|----|--------|------------|

**Trans-cab Auto Services Pte Ltd****AAD1809-080**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 7693Z**

To transfer of end panel fittings and conduct  
water seepage test.

\$ *nn* 170.00 X

To transfer of boot fittings and conduct water  
seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimmings,  
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To check steering geometry and computer wheel  
alignment

\$ *nn* 220.00 X

---

\$ **7,950.00**

---

**TOTAL** \$ **20,777.43**

---

**Repair Days (LUMP SUM)***10* DAYS*1 1/2 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: