

ASS. REC. BY:

REF: CS/FCL18010645/Atbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Lurene Jaw of FCL Date/Time: 12/09/2018 3:25pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 8570E Insured: SNB 2194E

at Workshop m/s Green Forest Tel: 9271 2214

of No. 8 Koki Bukit Ayer # 05-25

Policy No: Claim No: D18006604 MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 04/09/2018

CA / REV / REP. / REV 24 HRS '08'

H.O.D. Endorsement:

Date/Time: 12/09/2018 3:31pm Person Contacted: Onis Vehicle: ~~ID~~/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 8570E -X
	SNB 2194E - CS/INCORPORATION/Ch DA: 030809
13/9 -	Referent preli advise via email
	lump sum \$3200, 6days (Red. 7369; 69%)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 13 September 2018 5:00 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006604MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLW 8570E on 12/09/2018
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 12 September 2018 3:32 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006604MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 12 September, 2018 3:25 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006604MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

MOTOR SURVEY ASSIGNMENT

Date	05-09-2018	Our Ref No. D18006604MFSH
Accident Date	04-09-2018	Claim Type. Third Party
Insured Vehicle	SHB2194E	Third Party Vehicle. SLW8570E
Survey Location	No.8 Kaki Bukit Avenue 4 #05-25 Premier @ Kaki Bukit	
Contact Person.	CHRIS CHAN	
Contact No.	0/ 92712214	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GREEN FOREST AUTOMOBILE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 2921Z

Vehicle Details

Vehicle No: SLW8570E
Vehicle to be Exported: Yes
Intended Deregistration Date: 11 Sep 2018
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8L SUNROOF ALLOY WHEEL AT
Primary Colour: White
Manufacturing Year: 2008
Engine No: R18A1380095
Chassis No: JHMRN688095200759
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$27,948.00
Original Registration Date: 27 Mar 2009
First Registration Date: 27 Mar 2009
Transfer Count: 1
Actual ARF Paid: \$27,948.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Mar 2019
PARF Rebate Amount: \$13,974.00

Intended COE Rebate Details

COE Expiry Date: 26 Mar 2019
COE Category: B - Car (1601cc & above)
COE Period (Years): 10
QP Paid: \$5,001.00
COE Rebate Amount: \$270.00
Total Rebate Amount: \$14,244.00

The information contained herein is correct as at 11 Sep 2018

OK

6 months +



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2921Z
Vehicle Details	
Vehicle No.:	SLW8570E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L SUNROOF ALLOY WHEEL AT
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	R18A13800953
Chassis No.:	JHMRN68809S200969
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$27,948.00
Original Registration Date:	27 Mar 2009
First Registration Date:	27 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$27,948.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2019
PARF Rebate Amount:	\$13,974.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$5,001.00
COE Rebate Amount:	\$268.00
Total Rebate Amount:	\$14,242.00

The information contained herein is correct as at 12 Sep 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Price Range
 Depreciation
 2009
 Vehicle Type

[Advanced Search](#)

Used Car Comparison

--- Comparing 3 Vehicles ---

Honda Stream 1.8A RSZ

Honda Stream 1.8A X

Honda Stream 1.8A RSZ

[Back to search result](#)

CAR DETAILS				
Price	\$15,800	\$19,800	\$21,500	-
Instalment	\$3,714	\$1,574	\$1,292	-
Registration Date	08-Jan-2009	25-Jun-2009	14-Sep-2009	-
Manufactured	2008	2008	2008	-
Mileage	105,673 km	140,000 km	-	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,799 cc	1,799 cc	1,799 cc	-
Road Tax	\$978 /yr	\$978 /yr	\$978 /yr	-
Power	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)	-
Curb Weight	1,370 kg	1,350 kg	1,370 kg	-
Features	1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Paddle Shifters, Sunroof, Auto Climatic Aircon Control, Knockdown Rear Seats.	1.8L I-VTEC 16 Valves DOHC Engine, 5 Speed Automatic Transmission, SRS Airbags, ABS.	1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Paddle Shifters, Sunroof, Auto Climatic Aircon Control, Knockdown Rear Seats.	-
Accessories	Sport Rims, Touchscreen Audio System, Tweeter Speakers, Roof Mount Monitor, Electric Retractable Side Mirrors With Indicator, Leather Seats.	Auto Climatic Aircon, Premium Leather Seats, Sports Rims, Reverse Sensors, DVD Player, Knockdown Rear Seats.	Paddle Shifter, Leather Seats, Sports Rims, Reverse Camera, Touch Screen DVD Audio Player, Auto Retractable Side Mirrors, Knockdown Seats.	-
Description	Very Low Mileage! Extended Warranty, Servicing And Grooming Package Available! Professional Evaluation Services Provided! Well Taken Care Stylish MPV, View And Test Drive It To Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come To Our Aircon Showroom To Appreciate It In Pristine Condition Now, Don't Miss It!	5 Years New COE At \$36,800. Immaculate Condition. View To Appreciate. No More Repairs Needed. Comes With 1 Year Engine And Gearbox Protection Shield. Loan Up To 90%. Down Payment As Low As \$3k. High Approval Rate. High Trade In. Please Call Or SMS Now For Enquiries And Viewing Appointment.	Well Maintained By Single Owner. All Wear And Tear Done Up. Interior And Exterior Well Kept Good To Last Another 5 Or 10 Years Coe. Famous Honda Spacious And Reliability. STA Grading, 6 Months Free Servicing With Reputable Workshop For A Peace Of Mind. Flexible Low Down Payment Scheme Available. Call Our Friendly Sales Consultant Now Today For Viewing / Test Drive!	-
COE	\$1,551	\$14,840	\$19,629	-
OMV	\$23,621	\$21,196	\$21,945	-
ARF	\$17,656	\$21,196	\$21,945	-
Depreciation	-	\$11,790 /yr	\$10,500 /yr	-
No. of Owners	4	2	1	-
Type of Vehicle	MPV	MPV	MPV	-
Category	PARF Car	PARF Car	PARF Car, Premium Ad Car	-
Availability	Available	Available	Available	-

SELLER INFORMATION

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

MIDVIEW MOTORS PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TP 1st Cap.
Perise.

18th JANUARY 2017

Accident date: 04th SEPTEMBER 2018

Estimated repair cost for vehicle no: SLW8570E HONDA STREAM 1.8 A '09

S/n	Qty	Items	U/price	Amount
				\$1,171.30 903
1	1	Rear Boot Lid <i>Dented</i>		\$50.10 +
2	1	Rear Boot Lid Emblem Logo <i>nt m</i>		\$31.60 ✓
3	1	Rear Boot Lid Stream Logo <i>nt m</i>		\$50.00 +
4	1	Rear Boot Lid Number Plate <i>2 n p</i>		\$120.20 +
5	2	Rear Boot Lid Number Plate Lamp <i>nt m</i>	\$60.10	\$155.00 ✓
6	1	Rear Boot Lid Windscreen Seal <i>nt m</i>		\$189.00 ✓
7	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$165.00 +
8	1	Rear Boot Lid Inner Rubber <i>nt m</i>		\$341.00 +
9	1	Rear Boot Lid Inner Trim Board <i>nt m</i>		\$904.80 +
10	2	Rear tail lamp <i>nt m</i>	\$452.40	\$22.00 +
11	4	Rear tail lamp clips <i>nt m</i>	\$5.50	\$980.00 688.90
12	1	Rear Bumper <i>Debond</i>		\$168.00 74.
13	2	Rear Bumper Side Bracket <i>nt m</i>	\$84.00	\$65.00 30
14	10	Rear Bumper Clips <i>nt m</i>	\$6.50	\$68.00 +
15	1	Rear Bumper Towing Cover <i>nt m</i>		\$350.00 200 (sw)
16	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 +
17	1	rear bumper lower cover <i>nt m</i>		\$306.70 ✓
18	1	Rear End Panel Outer <i>Dented</i>		\$221.50 +
19	1	Rear End Panel Inner <i>nt m</i>		\$156.20 +
20	1	Rear End Panel Top Garnish <i>nt m</i>		\$260.00 +
21	2	Rear Floor Panel Top Cover <i>nt m</i>	\$130.00	\$250.00 +
22	1	Rear Floor Panel Sealant <i>2</i>		\$226.70 +
23	1	Rear Floor Panel Inner Garnish <i>nt m</i>		\$250.00 +
24	1	Rear Floor Panel Top Trim		\$866.90 +
25	1	Rear Exhaust		

Subtotal :- \$7,749.00

Labour charges

To remove & re-fix rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & re-fix cushion	\$120.00 60
To remove & re-fix rear exhaust	\$250.00 +
To remove & re-fix reverse sensor	\$100.00 50
To Check Wiring System	\$60.00 30
Tuff Kote	\$120.00 50
Panel beating	1960 \$1,000.00 800
Spray painting	\$1,000.00 800

Subtotal :- \$2,820.00

Total :- \$10,569.00

total: 4062.08
L/S: 3.2K ✓

06 days -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118016645/Atbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-10-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2194E	Veh. Inspected	SLW 8570E
Policy No.		Coverage (\$)	0.00
Claim No.	D18006604MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	12/09/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMRN68809S200969	Colour	WHITE
Odometer	282021	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/09/2018	Inspection Date	12/09/2018
Survey held at	GREEN FOREST AUTOMOBILE 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 8570E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	1,171.30	903.00
1	REAR BOOT LID EMBLEM LOGO	NOT NECESSARY	50.10	-
1	REAR BOOT LID STREAM LOGO	NECESSARY	31.60	31.60
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$60.10	NOT NECESSARY	120.20	-
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	155.00	155.00
1	REAR BOOT LID INNER LOCK	DAMAGED	189.00	189.00
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	165.00	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	341.00	-
2	REAR TAIL LAMP @\$452.40	NOT NECESSARY	904.80	-
4	REAR TAIL LAMP CLIPS @\$5.50	NOT NECESSARY	22.00	-
1	REAR BUMPER	DEFORMED	980.00	688.90
2	REAR BUMPER SIDE BRACKET @\$84.00	NECESSARY	168.00	74.00
10	REAR BUMPER CLIPS @\$6.50	NECESSARY	65.00	30.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	68.00	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	380.00	-
1	REAR END PANEL OUTER	DENTED	306.70	306.70
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	221.50	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	156.20	-
2	REAR FLOOR PANEL TOP COVER @\$130.00	NOT NECESSARY	260.00	-
1	REAR FLOOR PANEL SEALANT	NOT NECESSARY	250.00	-
1	REAR FLOOR PANEL INNER GARNISH	NOT NECESSARY	226.70	-
1	REAR FLOOR PANEL TOP TRIM	NOT NECESSARY	250.00	-
1	REAR EXHAUST	NOT NECESSARY	866.90	-
	LESS 20% DISCOUNT		-	-475.64
			7,399.00	1,902.56
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GUM (SN)	NECESSARY	50.00	50.00
			400.00	250.00
	LABOUR	NOT NECESSARY		
	TO REMOVE & RE0FIX REAR WINDSCREEN.		120.00	120.00
	TO REMOVE & RE-FIX CUSHION.		120.00	60.00
	TO REMOVE & RE-FIX REAR EXHAUST.		250.00	-
	TO REMOVE & RE-FIX REVERSE SENSOR.		100.00	50.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TUFF KOTE.		120.00	50.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER.		1,000.00	800.00
SPRAY PAINTING.	1,000.00	800.00		
		2,770.00	1,910.00	
GRAND TOTAL			10,569.00	4,062.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/FCI18016645/Atbn2

MARKET VALUE: \$17,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,244.00=NETT VALUE: \$3,256.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.