

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E

AAD1809-051

Not Authorised
Reserve B4 paint @1775.00

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 62E

WDD2120012B222270

MERCEDES BENZ

E220 CDI

7.9.2018

AXA**PART****LIST**

1	1	Front Fender RH	\$	<i>N</i>	2,900.00	X
2	1	Front Fender LEDGE RH	\$	<i>Sn</i>	108.00	X
3	1	Front Door RH	\$	<i>N</i>	3,680.00	X
4	1	Front Door mirror assy RH	\$	<i>CM</i>	1,750.00	✓
5	1	Front Door LEDGE RH	\$	<i>nn</i>	360.00	} X
6	1	Front Door outer handle seal front	\$	<i>Sn</i>	406.22	
7	1	Front Door hinge - top RH	\$	<i>N</i>	236.00	
8	1	Front Door hinge bottom RH	\$	<i>N</i>	236.00	
9	1	Front Door check / arrestor RH	\$	<i>Sn</i>	168.00	
10	1	Rocker Panel RH	\$	<i>N</i>	1,870.00	
11	1	Rear Door RH	\$	<i>N</i>	3,680.00	
12	1	Rear Door LEDGE RH	\$	<i>Sn</i>	340.00	
13	1	Rear Door outer handle seal front RH	\$	<i>Sn</i>	406.22	
14	1	Rear Door hinge bottom RH	\$	<i>Sn</i>	236.00	
15	1	Rear Door hinge top RH	\$	<i>N</i>	236.00	
16	1	Rear Fender RH	\$	<i>N</i>	3,620.00	}
17	1	Rear lamp	\$	<i>Sn</i>	1,040.00	
18	1	Rear Bumper	\$	<i>N</i>	2,760.00	
19	1	Rear Bumper Side Retainer Bracket	\$	<i>N</i>	176.00	
			\$		24,208.44	
TOTAL			\$		2,420.84	
10%			\$		21,787.60	

Trans-cab Auto Services Pte Ltd

AAD1809-051

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E**Specical Nett**

1SET	Rear Bumper Fastener Clip	\$	nn	120.00	} X
1SET	Rocker panel Fastener Clip	\$	nn	80.00	
1	Door corporate sticker	\$	nn	160.00	
1SET	Door LEDGE Clip FTR LH	\$	nn	120.00	
1SET	Door LEDGE Clip RR LH	\$	nn	120.00	
2	Rear Windscreen selant	\$	nn	160.00	
1	Windscreen Moulding	\$	nn	240.00	

TOTAL	\$	500.00
--------------	-----------	---------------

TOTAL PARTS	\$	11,393.80
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And Renewal
Of Parts, Adjust And Realign The Same

\$	3,500.00	80%
----	----------	-----

To Rust-Proofing Of The Affected Areas.

\$	nn	170.00	X
----	----	--------	---

To Check Electrical Lighting Concerned.

\$	170.00	20%
----	--------	-----

To Remove And Refit Interior Fittings,
Trimings, Garnish, Fittings And Other, to
Enable Repair.

\$	nn	380.00	X
----	----	--------	---

To Transfer Of Fender Fittings, Attachment
And Perform Water Seepage Test.

\$	nn	170.00	X
----	----	--------	---

To Check Steering Geometry And Computer
Wheel Alignment.

\$	nn	220.00	X
----	----	--------	---

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	100%
----	----------	------

Trans-cab Auto Services Pte Ltd

AAD1809-051

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E

To Transfer Of Door Fittings, Attachment And
Perform Water Seepage Test.

\$

na 170.00 X

To Remove And Refit Rear W/Screen Glass
To Facilitate Bodywork Repair.

\$

na 170.00 X

TOTAL	\$	8,150.00
--------------	-----------	-----------------

Over All Total	\$	19,543.80
-----------------------	-----------	------------------

REPAIR DAYS (PART-BY-PART)~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: