



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

	Repair Estimates	SL	S 653 Z		
oarts	(a) Cost / List Price Items	\$	2,075.50		
	Plus/Less 25%	\$	518.88		
	Total of Cost / List	\$	1,556.63		
	(b) Nett Price Items				
	Less				
	Total of Nett Item				
	(c) Special Nett Items	\$	200.00		
Total	Parts Cost	\$	1,756.63		
Labo	ur	\$	1,620.00		
Total		\$	3,376.63		
Na	ame of Surveyor	:			
C	ompany	:			
Sı	urvey conducted on	:		atat	
<u>R</u>	emarks By Surveyor				
(а	a) The repair of this vehicle is	authorized /	is not authorized until furthe	er notice.	
(b	(b) Recommended Days of Repair :day(s)				
(c	c) Resurvey	:	Required / Not Required		
(0	d) Excess	:\$			
(€	e) Signature of surveyor	:		Date:	



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts	S	pa	re	Pa	rts
-------------	---	----	----	----	-----

Vehicle No. :	SLS 653 Z	Submit By	:	Carmen Lim
Make & Model:	TOYOTA PRIUS	Year Manufacture	:	2017
Chassis No :	JTDKB3FU003569718	Fngine No.	•	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	
2	Rear bumper	1	\$497.50		
3	Rear bumper clip	10	\$40.00		
4	Rear bumper side retainer LH	1	\$112.70		
5	Rear bumper side retainer RH	1	\$112.70		
6	Rear bumper reinforcement	1	\$398.90		
7	Rear bumper lower garnish centre	1	\$582.60		
8	Rear bumper lower garnish LH	1	\$149.70		
9	Rear bumper lower garnish RH	1	\$149.70		
10	Rear bumper tow cover	1	\$31.70		
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle	e No. :		SLS 653 Z	Submit By	:Ca	rmen Lim
Make	& Model :	_	TOYOTA PRIUS	Year of Manufactu	ire :	2017
S/No			Labour Description	on	Esimated Price	Adjusted Price
1	TO RENE	W D	AMAGED PARTS & KNOC	K OUT ACCIDENT		
	REPAIR A	REA	A. (REAR BUMPER,END PA	ANEL)	\$600.00	y y
2	TO PUTTY	۲, R	ESPRAY PAINT FOR AFFE	ECTED ACCIDENT		
	REPAIR A	REA	A. (REAR BUMPER,END P.	ANEL)	\$600.00	
3	To check v	wirin	g		\$50.00	
4	To remove	e & r	efit reverse sensor		\$120.00	
5	To tuff coa	at			\$100.00	
6	To remove	e & r	efit spare tyre, spare tyre b	oard, carpet trim		
	to assist w				\$150.00	
			· p		,,	
					1	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

arorodalo.	
and the second s	ACCIDENT STATEMENT
Date Of Report	02/08/2018 20:33
Date Of Accident	02/08/2018 14:00
Exact Location Of Accident	JUNCTION OF SERANGOON ROAD AND BALESTIER ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLS653Z
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	TOYOTA

PRIUS HYBRID 1.8 CVT Model

Exact Purpose for which vehicle was being used at

time of accident

HIRE & REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No. Please state action to be taken PRIVATE HIRE Vehicle Category

Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

YES Fleet Policy

A29069766MKF Policy Number

Cover Note Number

Driver

LOH KELVIN Name of Driver S7600183I NRIC No 01/01/1976 Date Of Birth **INDOOR** Occupation 29/12/2000 Date Of Driving Pass

17 YEARS AND 7 MONTHS **Driving Experience**

Gender MALE

(LOCAL) +65-88627681 Mobile Number

Fax Number

Contact Number

EMail Address NOEMAIL Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

ОИ

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

2

Number of Passengers (Including Driver) Passenger 1

NAME:

: P1

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS WAITING TRAFFIC LIGHT AT JUNCTION OF SERANGOON ROAD AND BALESTIER ROAD. SUDDENLY VEHICLE B COLLIDED ONTO MY REAR SIDE OF VEHICLE. NO INJURY INVOLVED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

RETRIEVING

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

NISSAN/ NV350 PANEL VAN 2.5 5AT 5DR EURO V

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LOW CHIN YONG, JARON

NRIC/Passport Number

Contact Number

90056374

Address


Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 14

No. Of Passenger (Including Driver)



Sketch Plan #2 Pg. 1

CCIDENT STATEMENT (2000 characters)	
I WAS WAITING TRAFFIC LIGHT AT JU BALESTIER ROAD, SUDDENLY VEHIC VEHICLE, NO INJURY INVOLVED.	NCTION OF SERANGOON ROAD AND LE B COLLIDED ONTO MY REAR SIDE OF
Taxi Voucher No.:	
DECLARATION I/We declare that the above particulars & information provides	ded above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER - WONG JUN KEAT	226s
MARS Officer	
Job Complete Date/Time	Registered Owner or Driver's Signature Date/Time:
2 August 2018 at 5:37 PM	2 August 2018 at 5:37 PM