

ASS. REC. BY:

REF: CS/FCL8016666/Tcd307

Special Instruction:

SUVA/01

ASSIGNMENT (Office)From (Person): Harminder of FCL Date/Time: 12/09/2018 15:57pm

Estimated Cost: _____ Bill to: _____

DDX TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKH 7344P Insured: _____at Workshop m/s: Borneo motor Tel: 9347 6178of 2 Pondok CrescentPolicy No: _____ Claim No: D18006762MTBCSum Insured: _____ Excess: \$1500.00Make of Veh: _____ D.O.A. 03092018

(Client's Record) _____

CA / REV / REP. / REV 24 HRS 13092018Date/Time: 12/09/2018 5:11pm Person Contacted: Wally H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKH 7344P - NBM / PCL160D3305 / TI DUA: 19/02/2016
14/9/18	Revert to Harminder by email
14/9/18	Perce authorise repair from Serene by email
14/9/18	Informed Wally clA ex \$1500 by email

Q177400

Tanjim

REF:

FA

CS/FCU18016666/Tirb

ASSIGNMENT

From: Date: 13/09/2018

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKH 7344P

at Workshop n/s: Borneo Motor

of 2 Pandan Crescent

Insured

Policy No.

Claims No.

Sum Insured: Excess: \$ 1500.00

(Client's Record)

Make of Veh: Wally

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 180K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REY / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Wally

Veh No: SKH 7344P Yr Regn: 2013 Jan

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Lexus LS460L cc 4608

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 150866 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SKH 6L46F40504 7834

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R19

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A.

D.O.I.

Survey held at

Borneo Bank 13/9/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/3/19

Event to Wally \$ 17,609.80. Policy (Red 12,800.50, H22)

RECEIVED 02 APR 2019

Date/Time, File Pass to?

☐

Prel. Report

11

☐

Final Report

Date/Time, File Return to?

25

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee

Transportation

2 + 25 = 27

Phone

Cable

OSP

24/4/19

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: OD

Lump Sum / (B): \$ 17,609.80

20x15=300

170+300

50

50

28

658

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000108C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	12/09/2018	Our Ref No.	D18006762MFQC
Accident Date	08-09-2018	Claim Type	Own Damage
Insured Vehicle	SKH7344P	Third Party Vehicle	SKH7344P
Survey Location	BORNEO MOTORS (SINGAPORE) PTE LTD 2 PANDAN CRESCENT	Contact Person	WALLY TAN
Contact No.	66311388	Fax No.	0

Survey Type Revert for instructions - Est. COR
\$32,539.02

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person		Fax No.	68416315
Contact Number	62563561		

EXCESS APPLICATION FOR OWN DAMAGE CLAIM ADDITIONAL \$500.00 FOR INSURED VEHICLE INSTALLED WITH CNG TANKER

Basic	Y/I Driver	Total
\$1,500	\$0	\$1,500

Encl. Accident Reports & Estimate \$32,539.02

Cc : Workshop BORNEO MOTORS (SINGAPORE) PTE LTD Attention WALLY TAN

Officer Incharge SERENE

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 14 September 2018 3:17 PM
To: Wally Tan TCBC; SUR
Subject: SKH 7344P-DOA: 8/9/2018 (FCI OD)

Dear Wally,

As instructed by our client , please proceed to repair the insured vehicle **SKH 7344P based on surveyor's marking or which ever lower (Excess \$1500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler on behalf of Jannice

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Serene Ler <Serener@msfirstcapital.com.sg>
Sent: Friday, 14 September 2018 3:05 PM
To: Veron Chen (LKKAUTO); Harminder Kaur
Cc: SUR
Subject: RE: (Authorise to repair if in order) - OUR REF D18/6762M/PTE/SL, SKH 7344P

Dear Veron,

We refer to your email below of even date.

Please go ahead to authorize repairs at COR of not more than \$25,811.10 (\$27,311.10 less Excess \$1,500).

PRELIMINARY ADVICE OF VEHICLE NO. SKH 7344P

We thank you for your instruction on 12/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/9/2018 at the premises of M/s BORNEO MOTORS (S) PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$30,410.30
Revised Estimate Amount	: S\$15,181.40
"Check" Items Amount	: S\$12,129.70
Total	: S\$27,311.10
Market Value	: S\$180,000.00
LTA Reimbursement Value	: S\$126,322.00
Nett Value	: S\$53,678.00

Regards,
Serene Ler
Motor Claims

MS First Capital Insurance Limited

A Member of **MS&AD** Insurance Group

36 Robinson Road, City House, #16-01 | Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Motor Claims: motor_claims@msfirstcapital.com.sg | Website: www.msfirstcapital.com.sg

*With effect from 15 January 2018, we will be known as **MS First Capital Insurance Limited**. Our new website will be www.msfirstcapital.com.sg.

With immediate effect, my email address will change to Serener@msfirstcapital.com.sg.

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Friday, September 14, 2018 11:54 AM
To: Harminder Kaur <Harminder@msfirstcapital.com.sg>

Cc: Serene Ler <SereneLer@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OUR REF D18/6762M/PTE/SL, SKH 7344P

Dear Harminder,

Enclosed preliminary revised of vehicle SKH 7344P
Date of survey: 13/9/2018
Number of days : 8 days

We have Not authorise repair.

Kindly let us have your approval please.

Best Regards,

Veron Chen | Case Handler on behalf of Jannice

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 12 September 2018 5:14 PM

To: 'Harminder Kaur' <Harminder@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Serene Ler' <SereneLer@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: OUR REF D18/6762M/PTE/SL

Dear Harminder,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Harminder Kaur [mailto:Harminder@msfirstcapital.com.sg]

Sent: Wednesday, 12 September, 2018 4:55 PM

To: assignments@lkkauto.com

Cc: Serene Ler <SereneLer@msfirstcapital.com.sg>

Subject: OUR REF D18/6762M/PTE/SL

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly forward us your report by email only to Surveyor@msfirstcapital.com.sg within the next 14 days.

Thank you.

Best Regards,
Harminder Kaur
Motor Claims

MS First Capital Insurance Ltd

A Member of **MS&AD** Insurance Group



Change of email address

harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 14 September 2018 11:54 AM
To: 'Harminder Kaur'
Cc: 'Serene Ler'; SUR
Subject: RE: OUR REF D18/6762M/PTE/SL, SKH 7344P
Attachments: MARK EST.pdf; PRELI ADVISED.pdf

Dear Harminder,

Enclosed preliminary revised of vehicle SKH 7344P

Date of survey: 13/9/2018

Number of days : 8 days

We have Not authorise repair.

Kindly let us have your approval please.

Best Regards,

Veron Chen | Case Handler on behalf of Jannice

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 12 September 2018 5:14 PM
To: 'Harminder Kaur' <Harminder@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OUR REF D18/6762M/PTE/SL

Dear Harminder,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Harminder Kaur [<mailto:Harminder@msfirstcapital.com.sg>]
Sent: Wednesday, 12 September, 2018 4:55 PM
To: assignments@lkkauto.com
Cc: Serene Ler <Serener@msfirstcapital.com.sg>
Subject: OUR REF D18/6762M/PTE/SL

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly forward us your report by email only to Surveyor@msfirstcapital.com.sg within the next 14 days.

Thank you.

Best Regards,
Harminder Kaur
Motor Claims

MS First Capital Insurance Ltd

A Member of **MS&AD** Insurance Group



Change of email address

harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX.: (065) 62564315

Your ref: D18006762MFQC

Our ref: CS/FCI18016666/T1rb

Date: 14/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKH 7344P


We thank you for your instruction on 12/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/9/2018 at the premises of M/s BORNEO MOTORS (S) PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$30,410.30
Revised Estimate Amount	: S\$15,181.40
"Check" Items Amount	: S\$12,129.70
Total	: S\$27,311.10
Market Value	: S\$180,000.00
LTA Reimbursement Value	: S\$126,322.00
Nett Value	: S\$53,678.00

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/Present Status:

Damages Consistent
Repair Cost Economical

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4088M
Vehicle Details	
Vehicle No.:	SKH7344P
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS LS460L AUTO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	1UR0311170
Chassis No.:	JTHGL46F405047834
Maximum Power Output:	280.0 kW (375 bhp)
Open Market Value:	\$124,762.00
Original Registration Date:	11 Jan 2013
First Registration Date:	11 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$124,762.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2023
PARF Rebate Amount:	\$87,333.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$97,000.00
COE Rebate Amount:	\$38,989.00
Total Rebate Amount:	\$126,322.00

The information contained herein is correct as at 14 Sep 2018

OK

TYPE OF CLAIM: ☐ OD ☒ OD/UL ☐ DS

MCA: 127

MOTOR ACCIDENT REPORT

Date Of Report: 11.9.18 Time: 1245 Date Of Accident: 8.9.18 Time: 1500

Exact Location Of Accident: Out of scot square into yellow box

Country/State of Loss: Singapore ☐ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKH 7344P Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 200004088M

Name Of Registered Owner: Excelfin Pta Ltd

Mobile Number: 88226581 Alternative No: Awan Email Address:

Vehicle Particulars

Manufacturer: Toyota ☐ Lexus ☒ Suzuki ☐ Hino ☐ Model: LS460Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: First Capital

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: D-18090063MF0C

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Iriawan Bin Nispan NRIC/ Passport / FIN No: S81092086

Date Of Birth: 23.3.1981 Occupation: Indoor ☐ Outdoor ☒Date Of Driving Pass: 11.10.2013 Gender: Male ☒ Female ☐

Mobile Number: 88226581 Fax No: Alternative No:

Address: 265B Punggol Way #02-334 Postal Code: 822265

Email Address:

Was driver an employee of the Insured's Company? Yes ☒ No ☐ State relationship of the driver with the insured: driver

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Head to rear

Number of Passengers in the above vehicle (Including Driver): / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐Was any foreign vehicle involved in this accident? No ☐ Yes ☐ Vehicle No: N/A Vehicle type:

Number of vehicles involved in the accident:

Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below

Witness Name: Contact No.: Email:

Was there any other vehicle or property damaged? No ☐ Yes ☒Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SHA 5975D Vehicle Make/Model/Colour: Taxi

Details Of Properties Damage in Accident:

Vehicle Category:

Name of Driver: Chan Hwee Hong

NRIC/Passport/FIN Number: S1229616I Contact Number: 96791248

Address: Postal Code:

Insurance Company Name:

Nature Of Damage: No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Handwritten signature: *M. L.*

Handwritten notes: *Scott Square*, *Tangs Plaza*

↑	↓	↓	↓	↗
				↘
				→
				→
				→

Handwritten labels: *SHA5975D*, *SHA7344P*

Describe Circumstances of the Accident

I was turning out of Scott Square into the yellow box, when the blue
combi taxi Sha 5975 D hit my rear left bumper and rim.
causing my bumper to crack out.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

CERTIFICATE OF INSURANCE

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
 Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980
 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy: : COMPANY CAR - FLEET
 Type of Cover: : Comprehensive
 Certificate No.: : D-18090053MFQC
 Vehicle No / Chassis No: : SKH7344P / JTHGL46F405047834
 Name of Insured: : EXCELFIN PTE LTD

Period Of Insurance: : 01.04.2018 to 31.03.2019
 Insured Estimated Value: : Market Value At Time Of Loss

Excess :
 SGD1,500.00 SECTION I
 COMPULSORY EXCESS OF ADDITIONAL SGD1,000.00 APPLIES TO :-
 (1) DRIVERS BELOW THE AGE OF 25 YEARS AND/OR
 (2) HAS LESS THAN 1 YEAR DRIVING EXPERIENCE

Authorised Driver*
 ANY AUTHORISED DRIVERS

Persons or classes of persons entitled to drive*
 Any person who is driving on the Insured's order or with their permission.

ATTN: MR WALLY

VIA FAX: 6 476 62 47

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitations as to use*
 Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

MS First Capital Insurance Limited
 (Approved Insurers)

JENNY/B0020/MX4A

Issued at Singapore on 29.03.2018

Authorised Signature

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8109208G



Name

IRIAWAN BIN MISPAN

Race

JAVANESE

Date of Birth

23-03-1981

Sex

M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE

DRIVING LICENCE



License Number: S8109208G

Name

IRIAWAN BIN MISPAN

Birth Date: 23 Mar 1981

Issue Date: 04 Aug 2009



License No. S8109208G



Date of Validity

26-06-2007

APT BLK 285B PUNGGOL WAY #02-334
SINGAPORE 622895

S8109208G

18/02/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

- (A) Class 2B Motorcycles <= 249 CC
- (C) Class 2A Motorcycles between 250 CC and 499 CC
- (C) Class 2 Motorcycles > 499 CC
- Class 3A Motor cars without clutch pedals <= 2000 kg with <= 1 powerports, exclusive of the driver's and motor traction/braking without clutch pedals <= 2000 kg

VALID DATE

18 Apr 2009

15 Jun 2002

11 Oct 2013

04 Aug 2009

S8109208G

S / No. 9000180902



NP 435A

AUTHORIZATION LETTER

Date: 10.9.18To: First Capital

Cc: Borneo Motors (S) Pte Ltd (Wally Tan, wally.tan@borneomotors.com.sg)

Attn: To Whom It May Concern

Dear Sir / Madam,

RE: Authorization to Act on Behalf for Insurance Claims Documentation

I, (full name) Excelfin Pte Ltd NRIC No. 200004098 m hereby
authorized my relationship: driver (full name) Iniawan Bin Mispan
NRIC No. 98109208 G to exercise and execute to sign all / any necessary transaction
documentation pertaining to my registration vehicle number SKH 7344 P as I am
currently having tight official business schedules / away from Singapore on duty overseas travel.

Please do not hesitate to contact me should you require any further clarification on the above.

Thank You

Yours truly,

Signature:



Name :

DAVID BAN
Director

Contact No:

67314893

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail

First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877
Attn: Motor Claims Dept.

Account No

S1000005 / ICFICI

Document No

0

Document Date

12/09/2018

Customer Detail

M/s Excelfin Pte Ltd
50 Cuscaden Road
#08-01 Hpl House
Singapore 249724

Work: 67345250

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 SKH7344P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHGL46F405047834	1UR0311170	60	Wally Tan G H	10/09/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				80 . 100.00
2	B	BP-LAB TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW BOOT SHELL. (NETT)				? 816.00
3	B	BP-LAB REMOVE/REFIX REVERSE CAMERA. (NETT)				✓ 204.00
4	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)				✓ 204.00
5	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				✓ 204.00
6	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)				✓ 204.00
7	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.				? 816.00
8	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, L/R FENDER, L/R DOOR AND FIT NEW PARTS.				2448 3264.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of
Borneo Motors

Customer's Signature

Change Summary

Total

Less

Amount Due

Please acknowledge receipt of vehicle

Parts
Labour
Materials
Lubrication/Fluid
Others

Tanjong 67495749

Not Authorise.

Ex \$1500

Resurvey before part.

sur@lkhauto.com.

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE 12/09/2018

TIME 09:38

Acknowledged by Repairer

Signature:

Date:

Signature

FOR BORNEO MOTORS (SINGAPORE) PTE LTD

CUSTOMER



Borneo Motors

Nature Of Damage:

No. Of Passenger (Including Driver):

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005/ICFIC1	M/s Excelfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 12/09/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 SKH7344P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHGL46F405047834	IUR0311170	60	Wally Tan G H	10/09/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				80 100.00
2	B	BP-LAB TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW BOOT SHELL. (NETT)				W7 816.00
3	B	BP-LAB REMOVE/REFIX REVERSE CAMERA. (NETT)				✓ 204.00
4	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)				✓ 204.00
5	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				✓ 204.00
6	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)				✓ 204.00
7	B	BP-LAB REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.				W7 816.00
8	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, L/R FENDER, L/R DOOR AND FIT NEW PARTS.				✓ 2448 3264.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Not Authorise. Ex \$1500 Resurvey before paint. sure@lkanato.com. 8 days
			Amount Due

LOOK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE 12/09/2018

TIME 09:38

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

Signature:

Date:

VEHICLE NO SKH7344P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/s Excelfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 12/09/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 SKH7344P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHGL46F405047834	1U0311170	60	Wally Tan G H	10/09/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	300		✓	3500.00
10	2	BP-SLANT SUPPLY SEALANT (NETT)				100.00
11	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT. (NETT)				204.00
12	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)				204.00
13	S	BP-SUBLET TRANSFER L/R TYRE TO NEW WHEEL RIM AND BALANCING. (NETT)				102.00
14	1	L64401-50340 BOOT LID	1.00	1147.00		1147.00
15	2	L64571-50070 COVER, LUGGAGE COMPT R	1.00	99.10		99.10
16	3	L64572-50060 COVER, LUGGAGE COMPT L	1.00	104.30		104.30
17	4	L76801-50120 GARNISH SUB-ASSY,	1.00	244.80		244.80
18	5	L64726-50070 CLIP, LUGGAGE TRIM,	2.00	3.80		7.60
19	6	L76813-50020 GARNISH, BACK DOOR OUT 3	1.00	44.70		44.70
20	7	L76802-50020 C2 GARNISH SUB-ASSY,	1.00	1293.70		1293.70
21	8	L75441-50130 PLATE, LEXUS	1.00	77.70		77.70
22	9	L90975-02212 REAR BOOT LID EMBLEM,	1.00	62.70		62.70
23	0	L75443-50110 PLATE, LUGGAGE COMPT	1.00	77.70		77.70
24	1	L81581-50280 LENS & BODY, RR	1.00	726.90		726.90
25	2	L81591-50280 LENS & BODY, RR	1.00	726.90		726.90
26	3	L81551-50250 LENS & BODY, REAR RH	1.00	1149.00		1149.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 12/09/2018

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

TIME 09:38

VEHICLE NO SKH7344P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/s Excelfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 12/09/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 SKH7344P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHGL46F405047834	1U0311170	60	Wally Tan G H	10/09/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	4	L81561-50250 LENS & BODY, RR	1.00	1149.00		1149.00
28	5	L81496-50010 GUIDE, RR	2.00	3.30		6.60
29	6	L52562-50030 RETAINER, RR BUMPER R	1.00	91.00		91.00
30	7	L52563-50030 RETAINER, RR BUMPER, L	1.00	85.10		85.10
31	8	L52155-50070 SUPPORT, RR BUMPER RH	1.00	105.10		105.10
32	9	L52156-50060 SUPPORT, RR BUMPER LH	1.00	105.10		105.10
33	0	L52023-50090 REAR BFR REINFORCEMENT,	1.00	724.50		724.50
34	1	L52615-50080 ABSORBER, RR BUMPER	1.00	179.70		179.70
35	2	L52567-50040 RETAINER, BUMPER RR	1.00	110.90		110.90
36	3	L52568-50040 RETAINER, RR BUMPER	1.00	110.90		110.90
37	4	L52565-50070 RETAINER, BUMPER RR	1.00	291.30		291.30
38	5	L52566-50050 RETAINER, BUMPER RR	1.00	277.30		277.30
39	6	L52197-30040 BUMPER BRACKET,	2.00	7.50		15.00
40	7	L52581-30060 RR BUMPER PROTECTOR	2.00	3.10		6.20
41	8	L52159-50932 COVER, REAR BUMPER	1.00	1052.90		1052.90
42	9	L52165-50901 COVER, RR BUMPER UPP RH	1.00	19.90		19.90
43	0	L52166-50901 COVER, RR BUMPER,	1.00	19.90		19.90
44	1	L52161-50905 PIECE, RR BUMPER, RH	1.00	19.90		19.90
45	2	L52162-50905 PIECE, RR BUMPER, LH	1.00	19.90		19.90
46	3	L52169-50050 COVER, RR BUMPER LOWER	1.00	322.30		322.30

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 12/09/2018

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

TIME 09:38

VEHICLE NO SKH7344P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/s Excelfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 12/09/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 SKH7344P
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHGL46F405047834	1UR0311170	60	Wally Tan G H	10/09/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
47	4	L52535-28020 RETAINER, FR BUMPER SIDE	8.00	4.00		32.00 ✓
48	5	S52161-0K040 BUMPER CLIPS	6.00	4.00		24.00 ✓
49	6	L52106-50040 EXTENSION SUB-ASSY RH	1.00	230.00		230.00 ✓
50	7	L52107-50040 EXTENSION SUB-ASSY,	1.00	230.00		230.00 ✓
51	8	T90467-07201 CLIP	2.00	2.90		5.80 ✓
52	9	L81910-50010 REFLECTOR ASSY,	1.00	46.30		46.30 ✓
53	0	L81920-50010 REFLECTOR ASSY,	1.00	46.30		46.30 ✓
54	1	L89348-50020 RETAINER, ULTRASONIC	4.00	23.50		94.00 ✓
55	2	L89341-50060 J1 SENSOR, ULTRASONIC,	4.00	536.10		2144.40 ✓
56	3	L89348-50040 CLIP, ULTRASONIC	4.00	17.60		70.40 ✓
57	4	L82183-50030 WIRE, LUGGAGE ROOM 3	1.00	121.30		121.30 ✓
58	5	L88162-0W040 SENSOR, BLIND SPOT	2.00	1700.50 ✓		3401.00 ✓
59	6	L4261A-50161 WHEEL, DISC CHROME	1.00	3568.20		3568.20 ✓

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	30,410.30
	Please acknowledge receipt of vehicle	Parts 20,488.30	GST 7.00%	2,128.72
		Labour 9,820.00	Less	0.00
		Materials 102.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	32,539.02

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 12/09/2018
TIME 09:38

VEHICLE NO SKH7344P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Attn: Taufikh
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Page 5 of 5
Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/s Excelfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 29/03/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 :40D/SKH7344P/08091
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHGL46F405047834	1UR0311170	60	Wally Tan G H	10/09/2018	8.00	29/03/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:D-18090063MFOC ACC DATE:08.09.18 TOW/DRIVE IN:08.09.18 EXCESS:\$1500/- DATE-IN: DATE SURVEY:13.09.18 NO OF REPAIR DAYS: BY:TAUFIKH (LKK) AUTHORIZED ON:14.09.18				80.00
2	B	BP-LAB REMOVE/REFIX REVERSE CAMERA. (NETT)	*			204.00
3	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)	*			204.00
4	B	BP-LAB CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)	*			204.00
5	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)	*			204.00
6	B	BP-LAB REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, L/R FENDER, L/R DOOR AND FIT NEW PARTS.	*			2448.00
7	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			2450.00
8	B	BP-WA TO CARRY OUT WHEEL ALIGNMENT. (NETT)	18			204.00
9	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)	18			204.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKH7344P

CUSTOMER

DATE 29/03/2019
TIME 10:29

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR 8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/s Excellfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 29/03/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 :40D/SKH7344P/08091:

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHGL46F405047834	1UR0311170	60	Wally Tan G H	10/09/2018	8.00 29/03/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET TRANSFER L/R TYRE TO NEW WHEEL C25				102.00
		RIM AND BALANCING. (NETT) PO#4137				
11	V	EXC Excess element of insurance repair to be 88				-1500.00
		paid by the insured party				
12	1	L76802-50020 C2 GARNISH SUB-ASSY,	1.00	1293.70		1293.70
13	2	L75441-50130 PLATE, LUGGAGE	1.00	77.70		77.70
14	3	L90975-02212 EMBLEM, SYMBOL	1.00	62.70		62.70
15	4	L75443-50110 PLATE, LUGGAGE	1.00	77.70		77.70
16	5	L81561-50250 LENS & BODY, REAR COMBINATION	1.00	1149.00		1149.00
17	6	L52562-50030 R/REAR BUMPER RETAINER,	1.00	91.00		91.00
18	7	L52156-50060 L/REAR BUMPER SUPPORT,	1.00	105.10		105.10
19	8	L52568-50040 REAR BUMPER RETAINER,	1.00	110.90		110.90
20	9	L52565-50070 R/REAR SIDE BUMPER RETAINER,	1.00	291.30		291.30
21	0	L52566-50050 R/REAR SIDE BUMPER RETAINER,	1.00	277.30		277.30
22	1	L52197-30040 BRACKET, BUMPER	2.00	7.50		15.00
23	2	L52581-30060 PROTECTOR	2.00	3.10		6.20
24	3	L52159-50932 COVER, RR BUMPER	1.00	1052.90		1052.90
25	4	L52166-50901 COVER, RR BUMPER,	1.00	19.90		19.90
26	5	L52169-50050 REAR LWR BUMPER COVER,	1.00	322.30		322.30
27	6	L52535-28020 RETAINER, FR BUMPER SIDE	8.00	4.00		32.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 29/03/2019
TIME 10:29

VEHICLE NO SKH7344P

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

CUSTOMER

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/s Excelfin Pte Ltd 50 Cuscaden Road #08-01 Hpl House Singapore 249724 Work: 67345250
	Document No 0	
	Document Date 29/03/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	AEZGHW	L4	USF41R	11/01/2013	SKH7344P	150866	15994 :40D/SKH7344P/080911

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHGL46F405047834	1UR0311170	60	Wally Tan G H	10/09/2018 8.00	29/03/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	7	S52161-0K040 BUMPER PIECE,	6.00	4.00		24.00
29	8	L89348-50020 RETAINER, ULTRASONIC	4.00	23.50		94.00
30	9	L89348-50040 CLIP, ULTRASONIC	4.00	17.60		70.40
31	0	L52615-50080 REAR BUMPER ABSORBER,	1.00	179.70		179.70
32	1	L52563-50030 L/REAR BUMPER RETAINER,	1.00	85.10		85.10
33	2	L52155-50070 R/REAR BUMPER SUPPORT,	1.00	105.10		105.10
34	3	L52106-50040 R/REAR BUMPER EXTENSION,	1.00	230.00		230.00
35	4	L52107-50040 L/REAR BUMPER EXTENSION,	1.00	230.00		230.00
36	5	L64726-50070 CLIP, LUGGAGE TRIM,	2.00	3.80		7.60
37	6	L81496-50010 GUIDE, RR	2.00	3.30		6.60
38	7	L52165-50901 COVER, RR BUMPER UPP RH	1.00	19.90		19.90
39	8	L88162-0W040 SENSOR, BLIND SPOT	1.00	1700.50		1700.50
40	9	L4261A-50161 WHEEL, DISC CHROME	1.00	3568.20		3568.20

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	16,109.80
	Please acknowledge receipt of vehicle	Parts 11,305.80	GST 7.00%	1,127.69
		Labour 6,202.00		
		Materials 102.00	Less	0.00
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	17,237.49

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 29/03/2019
TIME 10:29

VEHICLE NO SKH7344P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

17609.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016666/T1cd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-04-2019	
			Code : FCI2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKH 7344P
Policy No. D-18090063MFQC		Coverage (\$)		0.00
Claim No. D18006762MFQC		Excess (\$)		1,500.00
Assign From HARMINDER KAUR		Assign Date		12/09/2018
2. Vehicle Particulars & Condition				
Make & Model TOYOTA LEXUS LS460L		c.c		4608
Engine No. HIDDEN		Year of Reg.		2013
Chassis No. JTHGL46F405047834		Colour		BLUE
Odometer 150866		Steering		IN ORDER
Brakes IN ORDER		Modification		SPORTS RIM
General GOOD				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R19	YOKOHAMA	6 mm	
L/H Front Tyre	245/45 R19	YOKOHAMA	6 mm	
R/H Rear Tyre	245/45 R19	YOKOHAMA	6 mm	
L/H Rear Tyre	245/45 R19	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date 08/09/2018		Inspection Date 13/09/2018		
Survey held at BORNEO MOTORS (S) PTE LTD				
2 PANDAN CRESCENT				
SINGAPORE 128462				
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT.				
B) THE MARKET VALUE IS S\$180,000.00 (EST. AVERAGE)				
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 7344P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	80.00
1	SEALANT (SN)	NOT NECESSARY	100.00	-
1	BOOT LID (SN)	TO REPAIR SEE LABOUR	1,147.00	-
1	COVER, LUGGAGE COMPT R (SN)	NOT NECESSARY	99.10	-
1	COVER, LUGGAGE COMPT L (SN)	NOT NECESSARY	104.30	-
1	GARNISH SUB-ASSY (SN)	NOT NECESSARY	244.80	-
2	CLIP, LUGGAGE TRIM @\$3.80 (SN)	NECESSARY	7.60	7.60
1	GARNISH, BACK DOOR OUT 3 (SN)	NOT NECESSARY	44.70	-
1	GARNISH SUB-ASSY (SN)	CRACKED	1,293.70	1,293.70
1	PLATE, LEXUS (SN)	NECESSARY	77.70	77.70
1	REAR BOOT LID EMBLEM (SN)	NECESSARY	62.70	62.70
1	PLATE, LUGGAGE COMPT (SN)	NECESSARY	77.70	77.70
1	LENS & BODY, RR (SN)	NOT NECESSARY	726.90	-
1	LENS & BODY, RR (SN)	NOT NECESSARY	726.90	-
1	LENS & BODY, REAR RH (SN)	NOT NECESSARY	1,149.00	-
1	LENS & BODY, RR (SN)	CRACKED	1,149.00	1,149.00
2	GUIDE, RR @\$3.30 (SN)	NECESSARY	6.60	6.60
1	RETAINER, RR BUMPER R (SN)	NECESSARY	91.00	91.00
1	RETAINER, RR BUMPER, L (SN)	NECESSARY	85.10	85.10
1	SUPPORT, RR BUMPER RH (SN)	NECESSARY	105.10	105.10
1	SUPPORT, RR BUMPER LH (SN)	NECESSARY	105.10	105.10
1	REAR BPR REINFORCEMENT (SN)	NOT NECESSARY	724.50	-
1	ABSORBER, RR BUMPER (SN)	MISSING	179.70	179.70
1	RETAINER, BUMPER RR (SN)	NOT NECESSARY	110.90	-
1	RETAINER, RR BUMPER (SN)	MISSING	110.90	110.90
1	RETAINER, BUMPER RR (SN)	MISSING	291.30	291.30
1	RETAINER, BUMPER RR (SN)	MISSING	277.30	277.30
2	BUMPER BRACKET @\$7.50 (SN)	NECESSARY	15.00	15.00
2	RR BUMPER PROTECTOR @\$3.10 (SN)	NECESSARY	6.20	6.20
1	COVER, REAR BUMPER (SN)	DEFORMED	1,052.90	1,052.90

Report Ref No. CS/FCI18016666/T1cd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER, RR BUMPER UPP RH (SN)	MISSING	19.90	19.90
1	COVER, RR BUMPER (SN)	MISSING	19.90	19.90
1	PIECE, RR BUMPER, RH (SN)	NOT NECESSARY	19.90	-
1	PIECE, RR BUMPER, LH (SN)	NOT NECESSARY	19.90	-
1	COVER, RR BUMPER LOWER (SN)	CUT	322.30	322.30
8	RETAINER, FR BUMPER SIDE @\$4.00 (SN)	NECESSARY	32.00	32.00
6	BUMPER CLIPS @\$4.00 (SN)	NECESSARY	24.00	24.00
1	EXTENSION SUB-ASSY RH (SN)	BENT	230.00	230.00
1	EXTENSION SUB-ASSY (SN)	BENT	230.00	230.00
2	CLIP @\$2.90 (SN)	NOT NECESSARY	5.80	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	46.30	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	46.30	-
4	RETAINER, ULTRASONIC @\$23.50 (SN)	NECESSARY	94.00	94.00
4	SENSOR, ULTRASONIC @\$536.10 (SN)	NOT NECESSARY	2,144.40	-
4	CLIP, ULTRASONIC @\$17.60 (SN)	NECESSARY	70.40	70.40
1	WIRE, LUGGAGE ROOM 3 (SN)	NOT NECESSARY	121.30	-
2	SENSOR, BLIND SPOT @\$1700.50 (SN)	NOT WORKING-1PC ONLY	3,401.00	1,700.50
1	WHEEL, DISC CHROME (SN)	CUT	3,568.20	3,568.20
			20,688.30	11,385.80
	LABOUR			
	TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW BOOT SHELL.	NOT NECESSARY	816.00	-
	REMOVE / REFIX REVERSE CAMERA.		204.00	204.00
	REMOVE / REFIX REAR BUMPER LOWER EXTENSION.		204.00	204.00
	CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.		204.00	204.00
	REMOVE / REFIX REVERSE SENSORS.		204.00	204.00
	REMOVE / REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR.	NOT NECESSARY	816.00	-
	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, L/R FENDER, L/R DOOR AND FIT NEW PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID.		3,264.00	2,448.00

Report Ref No. CS/FCI18016666/T1cd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		3,500.00	2,450.00
	TO CARRY OUT WHEEL ALIGNMENT.		204.00	204.00
	TO RESET ECU AND REPROGRAMME.		204.00	204.00
	TRANSFER L/R TYRE TO NEW WHEEL RIM AND BALANCING.		102.00	102.00
			9,722.00	6,224.00
GRAND TOTAL			30,410.30	17,609.80
RECOMMENDED COST OF REPAIRS				17,609.80
LESS EXCESS				-1,500.00
NETT LIABILITY				16,109.80

Report Ref No. CS/FCI18016666/T1cd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.