

ASS. REC. BY:

REF:

CS/msh18016667 / (Gsbm2) Special Instruction:

SURVEYOR:

Mummen

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

msh

Date/Time:

12/09/2018 4:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 5165U

Insured:

SLC 8430G

at Workshop m/s

FDK Automobile

Tel:

8101 6895

of

39 Woodlands Close Mega #05-12

Policy No:

A28758058AVW

Claim No:

569952

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 1wpi

17/09/2018

H.O.D. Endorsement:

Date/Time:

12/09/2018 4:54pm

Person Contacted:

Hazel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 5165U - X
	SLC 8430G - X
19/09/18	@ 15.15 pm. revised ZA to Elaine Ngu via mummen.
26/09/18	Confirmed P/P \$2,705.50 @ 5 days with X6 &
	(\$9,829.50 Red - 78%)

REF:

MSG.

C1065K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 5165U

at Workshop m/s FDK Automobile.

of 39 Woodlands Close Mega #05-12. 5737856

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$21K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKS565U

Yr Regn:

(2022)
12 Feb 2007

Type: M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c 1339

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMF036206S 204775

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: 205 / 55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

17-09-18

Survey held at

w/s

12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit \$3500

RECEIVED 20 SEP 2018

Date/Time, File Pass to?

26/09/18

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS: SI

Photos

Others

TOTAL

200
10

210

Report Format:

Lump Sum / I.B.I: (\$) 2,705.50 P/A

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 19 Sep 2018

Preliminary Advice

Insured Vehicle No	: SLC8430G	Accident Date	: 07/09/2018
TP Vehicle No	: SKS5165U	Assignment Date	: 12/09/2018
Make	: HONDA CIVIC	Est. Duration of Repair	: 5 - 6 days
Date of Inspection	: 17/09/2018		
Inspection At	: Fdk Automobile & Leasing Services Pte Ltd (HQ) 39 WOODLANDS CLOSE MEGA @ WOODLANDS, #05-12 Singapore 737856		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,720.00
Revised Amount	:S\$	5,180.00
Check Items (Estimated)	:S\$	4,370.00
Total	:S\$	9,550.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018		12 Sep 2018 16:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ANG KWANG MOH, ID: S1509254H, Tel: +6596555192, Email: serco88@gmail.com								
Main Claimant:	FDK AUTOMOBILE & LEASING SERVICES PTE LTD, Co. Reg. No.: 201611065K								
Vehicle Reg. No.:	SKS5165U	Date of Loss:	07/09/2018 16:00 - :59 [138 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569952	Policy/Cover Note No.:	A28758058AVW (Comprehensive) Coverage: 26/05/2018 - 25/05/2019						
Vehicle Reg. No. (Insured):	SLC8430G	Policy No. (Claimant):							
Repairer:	Fdk Automobile & Leasing Services Pte Ltd (HQ) 39 WOODLANDS CLOSE MEGA @ WOODLANDS, #05-12, 737856 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/09/2018]								
Driver/Custodian (Insured):	ANG KWANG MOH (56 / Male), NRIC: S1509254H, Tel: +6596555192								
Adj Asg. Remarks:	Liability 100%. Contact Person: Ms Hazel / 8101 6895. TP agree to use Naz from LKK.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Hazellea Bong <hazelleabong@gmail.com>
Sent: Wednesday, 26 September 2018 11:38 AM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: SKS 5165U (TP) SLC 8430G (OI) DOA : 07/09/2018

Hi Shirley,

Noted with thanks.

Regards,
Hazel Bong

On Wed, Sep 26, 2018 at 10:55 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Hazellea,

Final invoice and all supporting documents sent over to **MSIG Insurance (Singapore) Pte. Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazellea Bong [mailto:hazelleabong@gmail.com]
Sent: Wednesday, 26 September 2018 10:48 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SKS 5165U (TP) SLC 8430G (OI) DOA : 07/09/2018

Hi Shirley,

Acknowledged the mistake in finalised amount as mentioned. Confirm to the new finalised amount of \$2,705.50. Thanks.

Warmest Regards,

Hazel Bong

On 26 Sep 2018, at 10:43 AM, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Hazellea,

Kindly informed P/P finalised amount is \$ 2,705.50, apologize for making mistaken.

Please re-confirm.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazellea Bong [<mailto:hazelleabong@gmail.com>]
Sent: Wednesday, 26 September 2018 10:36 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SKS 5165U (TP) SLC 8430G (OI) DOA : 07/09/2018

Dear Shirley,

I confirm to the said finalised amount of \$2,705.20 and 5 days of repair. Thanks.

Please also confirm that I am able to submit my claims to MSIG.

Warmest Regards,

Hazel Bong

On 26 Sep 2018, at 10:21 AM, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Hazellea,

Please confirm finalised P/P amount \$ 2,705.20 and 5 repair days.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazellea Bong [<mailto:hazelleabong@gmail.com>]
Sent: Tuesday, 25 September 2018 9:34 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: SKS 5165U (TP) SLC 8430G (OI) DOA : 07/09/2018

Dear Shirley,

Attached are the photo of said vehicle before paint. Thanks.

<image001.jpg>

<image002.jpg>

<image003.jpg>

Warmest Regards,

Hazel Bong

On 21 Sep 2018, at 9:47 AM, Shirley Hiew (LKK Auto)
<ShirleyHiew@lkkauto.com> wrote:

Hi Hazellea,

Please send us resurvey before paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hazellea Bong [<mailto:hazelleabong@gmail.com>]

Sent: Thursday, 20 September 2018 11:46 AM

To: ShirleyHiew@lkkauto.com

Subject: Re: SKS 5165U (TP) SLC 8430G (OI) DOA : 07/09/2018

Dear Shirley,

Thanks for your email. Can I kindly confirm the said amount of \$3255.50 is the finalised amount and ready for submission to MSIG?

Warmest Regards,

Hazel Bong

On Thu, Sep 20, 2018 at 10:13 AM Shirley Hiew (LKK Auto)
<ShirleyHiew@lkkauto.com> wrote:

Hi Hazellea,

Enclosed herewith supplementary marking by Guo Qiang.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<ESTIMATE MARKED.pdf>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1065K

Vehicle Details

Vehicle No.: SKS5165U

Vehicle to be Exported: No

Intended Deregistration Date: 18 Sep 2018

Vehicle Make: HONDA

Vehicle Model: CIVIC IMA A

Primary Colour: Grey

Manufacturing Year: 2006

Engine No.: LDA21038191

Chassis No.: JHMFD36206S204775

Maximum Power Output: 70.0 kW (93 bhp)

Open Market Value: \$25,280.00

Original Registration Date: 12 Feb 2007

First Registration Date: 12 Feb 2007

Transfer Count: 2

Actual ARF Paid: \$17,696.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Feb 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,197.00

COE Rebate Amount: \$17,139.00

Total Rebate Amount: \$17,139.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Sep 2018

OK



FDK AUTOMOBILE & LEASING SERVICES PTE LTD

REF: 201800008
39 WOODLANDS CLOSE MEGA @ WOODLANDS
#05-12 S (737854)

Fabian Wong: 9191 6590
Daryl Wong: 9772 9498
Kenneth Wong: 9755 3198

Date: 15 September 2018

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
SINGAPORE 408933

ATTN: MOTOR CLAIM DEPT
TEL: 6256 3561
FAX: 6256 4315

YOUR REF NO:
CLAIM TYPE: THIRD PARTY CLAIM
ACCIDENT DATE:

NO	QUOTATION: 2018/0008
DATE	15/ 09/ 2018
POICY NO	5087677106-02
VEHICLE REG NO	SKS5165U
MAKE/ MODEL	HONDA CIVIC 1.3 IMA (A)
CHASSIS NO	JHMFD36206S204775
ENGINE NO	LDA21038191/ MF51050538
REG. DATE	12 FEBURARY 2007

Estimate Repair Cost to Vehicle NO.: SKS5165U

	Description	Quantity	Unit Price (\$\$)	Amount (\$\$)
WORKSHOP 1 - REPAIR				
1	Rear Bumper / <i>re</i>	1	350.00	350.00 /
2	Rear Boot + Cover / <i>bt</i>	1	550.00	550.00 /
3	High Voltage Hybrid Battery Box <i>X NN</i>	1	3310.00	3310.00
4	Rear Reinforcement Bar <i>X NN</i>	1	700.00	700.00
5	Left Rear Bumper Bracket set <i>X NN</i>	1	80.00	80.00
6	Right Rear Bumper Bracket set <i>X NN</i>	1	80.00	80.00
7	Reverse Sensor Accessory <i>/ dm</i>	<i>2</i> 1	150.00	300.00 <i>400 600</i>
8	Panel Beating	1	1000.00	1000.00
9	Wiring Check	1	50.00	50.00

rear end panel \$600. ? (300.5 490)

10	Panel Bearing at Tyre Region <i>B</i>	1	300.00	300.00	200
11	Labour <i>X NN</i>	10 days	200.00	2000.00	
WORKSHOP 2 - SPRAY PAINT					800
12	Spray Paint	1	1000.00	1000.00	
14	Labour <i>X NN</i>	5 days	200.00	1000.00	
TOTAL:				\$10,720.00	

MAKE ALL CHEQUE PAYABLE TO FDK AUTOMOBILE & LEASING SERVICES PTE LTD

5-6 Days.
P/P ~~1 week in repair~~
After repair.

Signature
19/9/18

Signature

Authorized Signature

Gino Qiang - 82880282.

17/9/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**FDK AUTOMOBILE & LEASING SERVICES PTE LTD**

UEN: 201611065K

39 WOODLANDS CLOSE MEGA @ WOODLANDS

#05-12 S (737856)

Fabian Wong: 9191 6590

Daryl Wong: 9772 9698

Kenneth Wong: 9755 3198

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: 18 September 2018

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
SINGAPORE 408933

ATTN: GUO QIANG/ MOTOR CLAIM
DEPT
TEL: 6256 3561
FAX: 6256 4315

YOUR REF NO:
CLAIM TYPE: THIRD PARTY CLAIM
ACCIDENT DATE: 07/ 09/ 2018 18:50 HRS

NO	QUOTATION: 2018/0011
DATE	18/ 09/ 2018
POICY NO	5087677106-02
VEHICLE REG NO	SKS5165U
MAKE/ MODEL	HONDA CIVIC 1.3 IMA (A)
CHASSIS NO	JHMF36206S204775
ENGINE NO	LDA21038191/ MF51050538
REG. DATE	12 FEBURARY 2007

Supplementary Estimated Cost of Repair to Vehicle NO.: SKS5165U

	Description	Quantity	Unit Price (S\$)	Amount (S\$)
WORKSHOP 1 - REPAIR				
1	Rear End Panel <i>X bus repair</i>	1	350.00	350.00
2	Boot Lock <i>/ BT</i>	1	68.00	68.00
3	Boot Rubber <i>/ Twi</i>	1	62.50	62.50
4	Honda Civic Logo <i>/ S</i>	1	25.00	25.00
5	Honda Civic Emblem <i>/ S</i>	1	30.00	30.00
6	Honda Civic Hybrid Emblem <i>X NN</i>	1	39.50	39.50
7	Rear End Panel Garnish <i>/ Re</i>	1	40.00	40.00
8	Labour <i>X NN</i>	6 days	200.00	1200.00
TOTAL:				\$1,815.00

Carve Qrf.

Total: ~~3255.5~~
2705.5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016667/GSBN2

Date: 27/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28758058AVW
Claimant Vehicle No :	SKS5165U	Insured Vehicle No :	SLC8430G
Date of Loss:	07/09/2018	Nature of Claim:	TP
		Claim No:	569952

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS5165U	Engine No:	LDA21038191
Make & Model:	HONDA CIVIC, 1.3 IMA (A)	Chassis No:	JHMFD36206S204775
Reg. Date:	12/02/2007 (Man. Year: 2006)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,985.00	1,275.50	4,709.50	78.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,550.00	1,430.00	5,120.00	78.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	12,535.00	2,705.50	9,829.50	78.42

INSPECTION

Date of Assignment:	12/09/2018	
Date Inspected:	17/09/2018	Inspected At:
		Fdk Automobile & Leasing Services Pte Ltd (HQ)
		39 WOODLANDS CLOSE MEGA @
		WOODLANDS, #05-12
		Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2018)
Parts:	143	HONDA CIVIC 1.3 IMA (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS5165U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	350.00 FS	*350.00 FS
2	1		*REAR BOOT + COVER	Bent	550.00 FS	*550.00 FS
3	1		*HIGH VOLTAGE HYBRID BATTERY BOX	Not Necessary	3,310.00 FS	*- FS
4	1		*REAR REINFORCEMENT BAR	Not Necessary	700.00 FS	*- FS
5	1		*LEFT REAR BUMPER BRACKET SET	Not Necessary	80.00 FS	*- FS
6	1		*RIGHT REAR BUMPER BRACKET SET	Not Necessary	80.00 FS	*- FS
7	1		*REVERSE SENSOR ACCESSORY (2 Pcs)	Damaged (1 Pc only)	300.00 FS	*150.00 FS
8	1		*REAR END PANEL	Repair	350.00 FS	*- FS
9	1		*BOOT LOCK	Bent	68.00 FS	*68.00 FS
10	1		*BOOT RUBBER	Twisted	62.50 FS	*62.50 FS
11	1		*HONDA CIVIC LOGO	Necessary	25.00 FS	*25.00 FS
12	1		*HONDA CIVIC EMBLEM	Necessary	30.00 FS	*30.00 FS
13	1		*HONDA CIVIC HYBRID EMBLEM	Not Necessary	39.50 FS	*- FS
14	1		*REAR END PANEL GARNISH	Deformed	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,985.00	1,275.50
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	400.00
2	WIRING CHECK	New	50.00	30.00
3	PANEL BEARING AT TYRE REGION	New	300.00	200.00
4	LABOUR	New	2,000.00	-
5	SPRAY PAINT	New	1,000.00	800.00
6	LABOUR	New	1,000.00	-
7	LABOUR	New	1,200.00	-
Gross Labour Cost (S\$)			6,550.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >