

ASS. REC. BY:

REF: CS/TII/8016672 (Gvb02) Special Instruction:

ASSIGNMENT (Office)

Supervisor:

From (Person): Gabriel Wai of TII Date/Time: 12/09/2018 9:33am

Estimated Cost: Bill to:

OD /  TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SK 8938B Insured: SHC 3583D

at Workshop m/s: Ching Leung Motor Tel: 6483 3119

of: Bk 10 AMK Ind Park 2A #03-15

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 10/09/2018

CA / REV / REP. / REV 24 HRS '13p' 13-09-2018 @ after 11am H.O.D. Endorsement:

Date/Time: 12/09/2018 4:29pm Person Contacted: Mr. Lee Vehicle:  IN /  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SK 8938B - X
	SHC 3583D - CS/TII/8016672 / Kyu3g2 Dof: 23-12-2016

Surround

XHL.

REF: III

48428

ASSIGNMENT

(-2021)

From: \_\_\_\_\_ Date: 13092018

Estimated Cost: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 8938B

at Workshop m/s: Chiang Leong

of: Btk 10 Amk nd Park IA # 03-15

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SLK 8938B Yr Regn: 29 Aug 2006

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Altis c.c 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 1634361 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR0538EC 107130704

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD  AirRm or \_\_\_\_\_

Tyre Size: F: 185/70 R14

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO /  YOKO or \_\_\_\_\_

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 13-09-18

Survey held at: w/s 1pm

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

After 11am

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$19K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR- Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
13/9	offer lee \$3250 but he don't accept. He said charge to PRS. \$3000 - \$4000
14/9/18	GUO Qiang confirmed LS \$3250 (Red 3643-08, 508)

17/9/2018

RECEIVED 10 SEP 2018

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 17/9 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 3250/-)

Days Of Repair: 6

Resurvey No. of Trip: -

Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech. Invs (\$ )  Weekend (\$ )

Survey Fee: \_\_\_\_\_

Transportation: 250

S + PRS: SI \_\_\_\_\_

Photos: \_\_\_\_\_

Others: 10

TOTAL: 260

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 12 September 2018 9:33 AM  
**To:** accident@kscgp.com; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** motor@kscgp.com; Sundari Nagarajan - III  
**Subject:** RE: 2nd Notice to Conduct Pre-Repair Survey - III Ref: SHC 3583D Our ref: SGK 8938B/CL/sy/wl  
**Attachments:** SGK8938B GIA\_20180911133238.pdf; 1st PRS.PDF

*pending wksp details*

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGK8938B and let us have your report urgently.

This claim will be handled by Ms Sundari.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

**From:** accident@kscgp.com [mailto:accident@kscgp.com]  
**Sent:** 11 September, 2018 6:37 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** motor@kscgp.com  
**Subject:** 2nd Notice to Conduct Pre-Repair Survey - III Ref: SHC 3583D Our ref: SGK 8938B/CL/sy/wl

Dear Sirs,

We refer to the matter above and your email of even date.

Please see enclosed our 2nd Notice to Conduct Pre-Repair Survey.

Thank you.

Regards,

Wei Lin

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**To:** [accident@kscgp.com](mailto:accident@kscgp.com)

**Cc:** [motor@kscgp.com](mailto:motor@kscgp.com)

**Sent:** Tue, 11 Sep 2018 06:23:28 +0000

**Subject:**

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

**From:** [accident@kscgp.com](mailto:accident@kscgp.com) [<mailto:accident@kscgp.com>]

**Sent:** 11 September, 2018 1:39 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Cc:** [motor@kscgp.com](mailto:motor@kscgp.com)

**Subject:** Notice to Conduct Pre-Repair Survey - Your insured's vehicle: SHC 3583D Our ref: SGK 8938B/CL/sy/wl

Dear Sirs,

Please find enclosed herein the Notice to conduct Pre-Repair Survey, for your attention and necessary action.

Thank you.

Regards,

Wei Lin

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708  
Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4842Z

### Vehicle Details

Vehicle No.:	SGK8938B
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4601698
Chassis No.:	MR053ZEC107130704
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,498.00
Original Registration Date:	29 Aug 2006
First Registration Date:	29 Aug 2006
Transfer Count:	0
Actual ARF Paid:	\$17,048.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	28 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,759.00
COE Rebate Amount:	\$15,219.00
<b>Total Rebate Amount:</b>	<b>\$15,219.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Sep 2018

OK

# 長隆汽車服務

## CHIANG LEONG MOTOR VEHICLE SPRAY PAINTING

10 Ang Mo Kio Industrial Park 2A #03-15 AMK Autopoint Singapore 568047


Tel : 9662 0782 Fax : 6483 1392

Business regn no : 204106-00A

### ESTIMATE

India International Insurance Pte Ltd

Date : 11 Sep 2018  
 Vehicle No: SGK 8938 B  
 Make/Model: Toyota Altis



Qty	Parts And Labour Detail		\$
	List Items:		
1	rear bootlid - BT		715.90
2	bootlid lamp X NH		191.20
1	Toyota emblem - ACC		36.20
1	Altis emblem		36.90
1	Toyota logo X NH		41.20
1	1.6 E emblem - ACC		32.60
1	VVT-I emblem		33.70
1	rear bumper cover - Re		455.90
2	rear bumper brackets X NH		117.80
2	rear bumper side retainer - Re		57.80
7	rear bumper clips - ACC		29.40
2	tail lamp assy - ACC		999.70
2	tail lamp panel X NH		599.60
1	rear end panel - BT		499.85
1	end panel plastic garnish - Re		195.95
1	weather strip - Twi		165.95
1	spare tire floor board X Repair		956.70
		25%	2394.45
		Less 20%	1033.27
		Parts Total	1795.84

Qty	Nett items:		\$
1	reverse sensor - PM		250.00
1	rear number plate - cut		50.00
			300.00

Labour-charges:	\$
To remove damaged parts and attachments, panelbeat/weld rear floorboard, end panel, refit replaced items	950.00
To remove upholstery to enable repairs/refit spare tire floor board	80.00
To apply sealant and waterproofing on rear end panel and s/tire floor board	120.00
To check wiring function	60.00
To spray paint affected areas	1250.00
	2460.00

60 days -  
 Lump sum repair.  
 After repair photos.  
 13/9/18.  
 Gao Qiang - 82880282

Total 4065.84  
 net%: 7250

6893.08



## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18016672/GVBN2

Date: 24/09/2018

**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SGK8938B	Insured Vehicle No :	SHC3583D
Date of Loss:	10/09/2018	Nature of Claim:	TP
		Claim No:	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SGK8938B	Engine No:	3ZZ4601698
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107130704
Reg. Date:	29/08/2006 (Man. Year: 2006)	Odometer:	164361 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/70R14	Rear Tyre Size:	185/70R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,433.08	2,035.84	2,397.24	54.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	2,030.00	430.00	17.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,893.08</b>	<b>4,065.84</b>	<b>2,827.24</b>	<b>41.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,893.08</b>	<b>3,250.00</b>	<b>3,643.08</b>	<b>52.85</b>

**INSPECTION**

Date of Assignment:	12/09/2018	
Date Inspected:	13/09/2018	Inspected At:
		Chiang Leong Motor Vehicle Spray Painting (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A #03-15 AMK AUTOPOINT Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2018)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGK8938B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	715.90 FL	*610.00 FL
2	2		*BOOTLID LAMP	Not Necessary	191.20 FL	*- FL
3	1		*TOYOTA EMBLEM	Necessary	36.20 FL	*36.20 FL
4	1		*ALTIS EMBLEM	Necessary	36.90 FL	*36.90 FL
5	1		*TOYOTA LOGO	Not Necessary	41.20 FL	*- FL
6	1		*1.6 E EMBLEM	Necessary	32.60 FL	*32.60 FL
7	1		*VVT-I EMBLEM	Necessary	33.70 FL	*33.70 FL
8	1		*REAR BUMPER COVER	Deformed	455.90 FL	*455.90 FL
9	2		*REAR BUMPER BRACKETS	Not Necessary	117.80 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINERS	Deformed	57.80 FL	*57.80 FL
11	7		*REAR BUMPER CLIPS	Necessary	29.40 FL	*29.40 FL
12	2		*TAIL LAMP ASSY	Cracked	999.70 FL	*440.90 FL
13	2		*TAIL LAMP PANEL	Not Necessary	599.60 FL	*- FL
14	1		*REAR END PANEL	Bent	499.85 FL	*499.85 FL
15	1		*END PANEL PLASTIC GARNISH	Deformed	195.95 FL	*70.90 FL
16	1		*WEATHER STRIP	Twisted	165.95 FL	*90.30 FL
17	1		*SPARE TIRE FLOOR BOARD	Repair	956.70 FL	*- FL
18	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
19	1		*REAR NUMBER PLATE	Cut	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,466.35</b>	<b>2,634.45</b>
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,033.27	598.61
<b>Total Parts (\$\$)</b>	<b>4,433.08</b>	<b>2,035.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS,PANELBEAT/WELD REAR FLOORBOARD,END PANEL,REFIT REPLACED ITEMS	New	950.00	800.00
2	TO REMOVE UPHOLSTERY TO ENABLE REPAIRS/REFIT SPARE TIRE FLOOR BOARD	New	80.00	60.00
3	TO APPLY SEALANT AND WATERPROOFING ON REAR END PANEL AND S/TIRE FLOOR BOARD	New	120.00	40.00
4	TO CHECK WIRING FUNCTION	New	60.00	30.00
5	TO SPRAY PAINT AFFECTED AREAS	New	1,250.00	1,100.00
<b>Gross Labour Cost (S\$)</b>			<b>2,460.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >