

Indra
- 13/9/18
(Thursday)
LKK @ 11:00



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 570 E

Not Authorized
Resurvey B & paint

| | | | |
|------------------|-----------------------------|----|----------|
| Parts | (a) Cost / List Price Items | \$ | 3,944.40 |
| | Plus/Less 25% | \$ | 986.10 |
| | Total of Cost / List | \$ | 2,958.30 |
| | (b) Nett Price Items | | |
| | Less | | |
| | Total of Nett Item | | |
| | (c) Special Nett Items | \$ | 245.00 |
| Total Parts Cost | | \$ | 3,203.30 |
| Labour | | \$ | 1,870.00 |
| Total | | \$ | 5,073.30 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 13/9/18 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is Not authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 03 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : sc Date: 13/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Prepare Parts

| | | | |
|----------------|-------------------|--------------------|-------------------|
| Vehicle No. : | SLN 570 E | Submit By : | Carmen Lim |
| Make & Model : | TOYOTA PRIUS | Year Manufacture : | 2017 |
| Chassis No. : | JTDKB3FU703555881 | Engine No. : | |

Cost / List

| i/No. | Part Description | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|--|-----|------------|-------|-------------------------|
| 1 | Front number plate <i>NC</i> | 1 | \$45.00 | S.N | ✓ |
| 2 | Front number plate garnish <i>SN</i> | 1 | \$129.00 | | X |
| 3 | Front bumper | 1 | \$450.80 | | ? |
| 4 | Front bumper clip | 10 | \$40.00 | | ? |
| 5 | Front bumper reinforcement - upper <i>NC</i> | 1 | \$711.50 | | X |
| 6 | Front bumper reinforcement - lower <i>NC</i> | 1 | \$245.30 | | X |
| 7 | Front bumper side retainer RH <i>SN</i> | 1 | \$107.20 | | X |
| 8 | Front bumper side retainer LH <i>SN</i> | 1 | \$107.20 | | X |
| 9 | Front bumper upper grille <i>SN</i> | 1 | \$321.90 | | X |
| 10 | Front bumper emblem | 1 | \$87.10 | | ? |
| 11 | Reverse sensor <i>SN</i> | 1 | \$200.00 | S.N | X |
| 12 | Rear bumper | 1 | \$497.50 | | ? |
| 13 | Rear bumper clip | 10 | \$40.00 | | ? |
| 14 | Rear bumper side retainer LH <i>SN</i> | 1 | \$112.70 | | X |
| 15 | Rear bumper side retainer RH <i>SN</i> | 1 | \$112.70 | | X |
| 16 | Rear bumper reinforcement <i>NC</i> | 1 | \$398.90 | | ? |
| 17 | Rear bumper lower garnish centre <i>Red / Wt</i> | 1 | \$582.60 | | ✓ |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | | | | | |
| 22 | | | | | |
| 23 | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

