SINRT

60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6362 3422 Fax: 65 6368 7420

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/	Duty Officer at Accident Reporting Cen	tre
Reg. No. : SHD 6394H	Ref. No. TAX	X9 /18 /2026
Make / Model : TOYOTA PRIUS	8	Reg. Date : 15/02/2012
Name of Driver : TAN KOK WAH		
Date/Time of Accident : 07/09/2018 1	9:38	The damages on the Taxi are as
Surveyer is Required?	YES / NO	indicated in the following diagram :
If Yes, VICOM / LKK / LH Teo / A	AIS (Please circle one)	Front
Taxi is Towed Back?	YES / NO	
Replacement Taxi Issued ?	YES / NO	
Accident Repair Job Card No. : 24097	7872	
Special Instruction to ARC, if any :		
		Rear
Signed :	Date	e :
Section B - To be Completed by Service Advisor	, Accident Repair Centre	
Chassis No : KPTV0B1FSCP066707	7 Mileage	:
Date Prepared :	Repair (Completed date/time:
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 1,014.00	\$
Total Spray Painting Charges:	\$ 1,126.00	\$
Total Material Charges:	\$ 3,286.82	\$
Other Charges :	\$ 600.00	\$
TOTAL :	\$ 6,026.82	\$ ()
No. of Repair Days :	[6	1 3
Signature : Pres	pared by: FOO	Adjusted by:
	11/09/2018 11:20	
Continuo Taba Complete III de la constante III	1. U. 18	
Section C - To be Completed by Admin Assistant,		
500000 500000 0000000 0000000000000000	oice No.	Invoice Date
Signed :	Date	:

Ref. No. TAX 9 / 18 / 2026

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR REAR PORTION	1014.00	300		
Total Labour	\$ 1,014.00	\$		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	473.00	200
TO RESPRAY REAR PANEL	180.00	?
TO RESPRAY TAIL GATE	473.00	200
Total Spray Painting & Panel Beating	\$ 1,126.00	\$

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20
TO WASH AND VACUUM	60.00	×nn
TO TRANSFER REAR TAILGATE MECHANISM	120.00	Xnn
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	XVU
TO REPLACE SUNDRY PARTS	100.00	XON
Total Other Costs	\$ 600.00	\$

Part 4 - Spare Parts / Material Usage

Reservation No	:

Page (1)

	To be completed by Servic	e Advis	or, ARC				Surveyor A
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
7881A21000	Rear Bumper Assy	1	925.27	10%	832.74	1	/CLA
	REAR BUMPER CLIP	6	4.25	10%	22.95	1	/ nec
7882121000	ABSORBER ENERGY RR BUMPER	1	111.73	10%	100.56	/	?
7883021000	BEAM ASSY-IMPACT RR BUMPER	1	513.97	10%	462.57	1	?
8390221100	LAMP ASSY, REFLEX REFLECTOR RH	1	10.52	10%	9.47	1	3
	REVERSE SENSOR	1	165.10	10%	148.59	/	XSUL
7978021000	MUD GUARD-RR RH	1	17.08	10%	15.37	1	FN
6401121000	PNL ASSY-T/GATE	1	1355.08	10%	1219.57	1	XR
7141021000	LATCH ASSY, T/GATE	1	59.98	10%	53.98	1	?
7141521000	STRIKER ASSY, T/GATE	1	9.89	10%	8.90	1	?
6617403093	Handle assy-T/gate O/S	1	14.16	10%	12.74	1	?
7963021002	Garnish assy-T/gate ctr	1	300.19	10%	270.17	1	ż
7145021001	WEATHER STRIP T/GATE OPENING	1	97.67	10%	87.90	1	?
7934021001	RUBBERSEAL GLASS RR QTR	2	11.04	10%	19.87	1	KAN
	SEALANT W/SCREEN	2	37.00	0%	74.00	1	Xnn
	EMBLEM REAR	1	48.94	10%	44.05	/	TALC
	SMRT LOGO	1	7.80	0%	7.80	1	MIC
	STICKER PRESTIGE	1	60.00	0%	60.00	/	MONC /M
	REAR NUMBER PLATE	1	15.00	0%	15.00	/	Kna
	REAR NUMBER PLATE FRAME	1	35.00	0%	35.00	/	XM
8360221201	COMBI LAMP ASYS-RR T/GATE RH	1	288.57	10%	259.71	1	V 5/10
	PANEL END INNER	1	239.33	10%	215.40	1	2
	PANEL END OUTER	1	105.74	10%	95.17	1	?
4006314	SEALANT SIKAFLEX	1	37.00	0%	37.00	/	7
	TOTAL MATERIALS L	the R • To re UMPt&M	Auto Consult epairer of the survey before/a survey before/a prices are sub	e following fter spray p part(s) duri	g: ainting faresurvey		3,286.82
	NAZ LKK	Parts Third	prices are sub party survey is legal modification	ect to confi	rmation out Prejudice" I	basis	5,200.0

NAZ LKK 11/9/18 1105 LIJ 30 Ays AFTEL FERON PHOP

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

FR-AS-ARC-02 Rev 6