

60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6362 3422 Fax: 65 6368 7420

## **SMRT Accident Taxi Repair Estimates**

| Section A - To be completed by Claims Advisor/Duty  |                                     |                                      |
|---|-------------------------------------|--------------------------------------|
| Reg. No. : SHD 6214U                                | Ref. No. TAX                        | 9 / 18 / 2043                        |
| Make / Model : TOYOTA PRIUS                         |                                     | Reg. Date : 24/06/2016               |
| Name of Driver : HAN MIN KWANG                      |                                     |                                      |
| Date/Time of Accident : 11/09/2018 12:15            | 5                                   | The damages on the Taxi are as       |
| Surveyer is Required ?                              | YES / NO                            | indicated in the following diagram : |
| If Yes, VICOM / LKK / LH Teo / AIS                  | (Please circle one)                 | Front                                |
| Taxi is Towed Back?                                 | YES / NO                            |                                      |
| Replacement Taxi Issued ?                           | YES / NO                            |                                      |
| Accident Repair Job Card No. : 24097898             | 3                                   |                                      |
| Special Instruction to ARC, if any :                |                                     |                                      |
|   |                                     | Rear                                 |
|   |                                     |                                      |
|   |                                     |                                      |
| Signed :  | Date                                | 1400                                 |
| Section B - To be Completed by Service Advisor, Acc | cident Repair Centre                |                                      |
| Chassis No : JTDKN36U005768165                      | Mileage                             | : <u></u>                            |
| Date Prepared :                                     | Repair Co                           | ompleted date/time:                  |
| Summary of Repair Estimates                         |                                     |                                      |
|   | Quotation from ARC                  | Adjusted by Surveyor, if applicable  |
| Total Labour Charges :                              | \$ 676.00                           | \$                                   |
| Total Spray Painting Charges :                      | \$ 756.00                           | \$                                   |
| Total Material Charges :                            | \$ 1,380.38                         | \$                                   |
| Other Charges :                                     | \$ 240.00                           |                                      |
|   |                                     | \$                                   |
| TOTAL :   | \$ 3,052.38                         | ( )                                  |
| No. of Repair Days :                                | [ 5                                 | 1 2                                  |
| Signature : Prepared                                | by: FOO                             | Adjusted by:                         |
|   | 13/09/2018 08:50                    |                                      |
| Section C - To be Completed by Admin Assistant, Acc | cident Repair Centre, Upon Completi | on of Repair                         |
| QN No. Invoice                                      |                                     | Invoice Date                         |
| Signed :  | Date                                |                                      |
| olgiled .   | Date                                |                                      |

Ref. No. TAX 9 / 18 / 2043

## Part 1 - Labour Works

| Job Scope            | Quotation from ARC | Adjusted by Surveyor, if applicable |  |  |
|----------------------|--------------------|-------------------------------------|--|--|
| TO REPAIR LH PORTION | _676.00            | 400                                 |  |  |
|                      |                    |                                     |  |  |
|                      |                    |                                     |  |  |
|                      |                    |                                     |  |  |
|                      |                    |                                     |  |  |
| Tetallahaus          |                    |                                     |  |  |
| Total Labour         | \$ 676.00          | \$                                  |  |  |

## Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO RESRAY REAR DOOR LH               | 378.00             | 206                                 |
| O RESPRAY REAR FENDER LH             | 378.00             | 200                                 |
|                                      |                    |                                     |
|                                      |                    |                                     |
|                                      |                    |                                     |
| Total Spray Painting & Panel Beating | \$ 756.00          | \$                                  |

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION     | 80.00              | ×nn                                 |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00             | 40                                  |
| TO WASH AND VACUUM                      | 60.00              | Xnn                                 |
|   |                    |                                     |
|   |                    |                                     |
|   |                    |                                     |
|   |                    |                                     |
|   |                    |                                     |
| Total Other Costs                       | \$ 240.00          | \$                                  |

Part 4 - Spare Parts / Material Usage

| Reservation | No: |  |
|-------------|-----|--|
|-------------|-----|--|

Page (1)

|             | To be completed by Service   | e Adviso | r, ARC              |     |                     |                             | Surveyor A                                   |
|-------------|--|----------|---------------------|-----|---------------------|-----------------------------|--|
| Part Number | Parts Description  |          | Qty List Price (\$) |     | Final Price<br>(\$) | Repair (R)<br>Replace ( / ) | Not given (x)<br>Repair (R)<br>Replace ( / ) |
| 67004-47080 | DOOR RR/LH   | 1        | 954.50              | 25% | 715.88              | 1                           | 2R   |
|             | PIXEL STICKER  | 1        | 60.00               | 0%  | 60.00               | 1                           | / rec  |
| 61602-47091 | FENDER RR/LH   | 1        | 766.80              | 25% | 575.10              | 7                           | XR   |
|             | STICKER DECAL 6555 8888  | 1        | 21.60               | 0%  | 21.60               | 1                           | /rec   |
|             | STICKER SMRT LOGO  | 1        | 7.80                | 0%  | 7.80                | 1                           | /ree   |
|             |  |          |                     |     |                     |                             |  |
|             |  |          |                     |     |                     |                             |  |
|             | NAZ CKIC   |          |                     |     |                     |                             |  |
|             | 13/9/18 1015   |          |                     |     |                     |                             |  |
|             | Ste CIP  |          |                     |     |                     |                             |  |
|             | 2 DAYS   |          |                     |     |                     |                             |  |
|             | AFTER PERME PLYOTO   |          |                     |     |                     |                             |  |
|             |  |          |                     |     |                     |                             |  |
|             |  |          |                     |     |                     |                             |  |
|             | LKK Auto Consultants hence notifine Repairer of the following:  To resurvey before/after spray painting To display damaged part(s) during resure Parts prices are subject to confirmation Third party survey is on a "Without Prejute Party survey is on a "Without Party survey survey is on a "Without Party | vey      |                     |     |                     |                             |  |
|             | No illegal modification(s) is allowed     Supplementary item(s) must be resurvey     le subject to final approval from insurance  Acknowledged by Repairer   |          |                     |     |                     |                             |  |
|             | Signature:   |          |                     |     |                     |                             |  |
|             |  |          |                     |     |                     |                             |  |
|             |  |          |                     |     |                     |                             |  |
| 7 - 1       |  |          |                     |     |                     |                             |  |
|             | TOTAL MATERIALS  |          |                     |     | \$                  |                             | 1,380.3                                      |