

REC. BY: \_\_\_\_\_ REF: CS/CT18016716/Ktbn2 Special Instruction: \_\_\_\_\_

Survivor Mei Man ASSIGNMENT (Office)

From (Person): Elaine Cheng of CU Date/Time: 13/09/2018 1135AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SN 7500L Insured: GBF 345A

at Workshop m/s Lai Huet Cheng Kee Tel: 6453 8110

of 160 Sin Ming Dr #04-01

Policy No: DmCV SN 3015371802 Claim No: SN 18D 0447C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11-09-2018

(Client's Record) 17-09-2018

CA / REV / REP. / REV 24 HRS

Date/Time: 13/09/2018 11-41am Person Contacted: Jenny H.O.D. Endorsement: \_\_\_\_\_

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SN 7500L - X</u>
	<u>GBF 345A - X</u>
	<u>Part by Part \$1696.31, 3 days (Red: 63; 0.05%)</u>

REF:

CT

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 7500L

at Workshop m/s Lai Huat (Mong Kee)

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 7500L Yr Regn: 05 / 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra 1591

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

17702

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM110 841 CM14 U368150

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

2 mm

R/Bal.

2 mm

L/Bal.

2 mm

L/Bal.

2 mm

D.O.A.

11/19/18

D.O.I.

17/19/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

OPC

Date / Time

Action / Instruction

18/9 File pass to Customer

RECEIVED 15 OCT 2018

Date/Time, File Pass to?



Preli. Report

1) 15/10 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Report Format: TP

Lump Sum / I.B. (\$) 1696.31

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018 Sandback Est	12 Sep 2018 15:51 S\$1,759.31	13 Sep 2018 11:35 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:	<b>A TEAM LANDSCAPE CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201101215Z		
Main Claimant:	<b>TAN KUANG HUA</b> , ID: S0164147F		
Vehicle Reg. No.:	<b>SLN7500L</b>	Date of Loss:	11/09/2018 13:00 - :59 [15 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM18D04417C02</b>	Policy/Cover Note No.:	DMCVSN3015371802
Vehicle Reg. No. (Insured):	<b>GBF345A</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 24/09/2018]		
Adj Asg. Remarks:	EST \$1882.46, CASE WITH SJE.		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

**Denise Tay (LKKAUTO)**

---

**From:** Jenny Lim <jenny.lim@laihuat.com.sg>  
**Sent:** Thursday, 11 October 2018 11:50 AM  
**To:** Kenneth Kong (LKKAUTO)  
**Cc:** SUR  
**Subject:** Finalisation - SLN 7500L / Hyundai Elantra  
**Attachments:** SLN 7500L.pdf; IMG\_8212.jpg; IMG\_8213.jpg; IMG\_8214.jpg; IMG\_8215.jpg; IMG\_8220.jpg; IMG\_8221.jpg; IMG\_8222.jpg

Dear Sir

For your confirmation, please:

- Parts: \$ 978.00
  - SN: \$ 180.00
  - L&P: \$ 538.31
- Sub-total: \$1,696.31 / 3 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Monday, 15 October 2018 2:48 PM  
**To:** Jenny Lim; Kenneth Kong (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: Finalisation - SLN 7500L / Hyundai Elantra

Dear Jenny,

Confirm at \$1,696.31 / 3 days.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jenny Lim <jenny.lim@laihuat.com.sg>  
**Sent:** Thursday, 11 October 2018 11:50 AM  
**To:** Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** Finalisation - SLN 7500L / Hyundai Elantra

Dear Sir

For your confirmation, please:

- Parts: \$ 978.00
- SN: \$ 180.00
- L&P: \$ 538.31

**Sub-total: \$1,696.31 / 3 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267

# 來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity  
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722  
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg  
UEN: 199407592C

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	69811
Policy No:		Date of Loss:	11/09/2018
Vehicle Reg. No.:	SLN7500L	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Vehicle Reg. Date:	17/05/2017
Vehicle Colour:	WHITE		
Engine No:	G4FGGU041669	Chassis No:	KMHD84CMHU366150
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / JASON TAN		

COST OF CLAIMS	Amount
Parts	978.00
Miscellaneous Items	180.00
Labour	601.31
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>1,759.31</b>
<b>+ GST 7.00% (S\$)</b>	<b>123.15</b>
<b>Nett Amount (S\$)</b>	<b>1,882.46</b>

This claim is handled by: JASON TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 12 Sep 2018)**Parts:** 143      HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SLN7500L/12/09/2018 15:51**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BADGE "HYUNDAI"	0.00	0.00	nll ✓ 35.00 F
2	1	NA	*BADGE MODEL	0.00	0.00	nll ✓ 28.00 F
3	1	NA	*BOOTLID	0.00	0.00	BT ✓ 510.00 F
4	1	NA	*REAR BUMPER	0.00	0.00	cm ✓ 215.00 F
5	1	NA	*REAR BUMPER SPOILER	0.00	0.00	BT ✓ 140.00 F
6	1	NA	*S EMBLEM	0.00	0.00	nll ✓ 50.00 F

F=Franchise part.

**Total Parts (S\$)****978.00**

Lai Huat (Meng Kee) Motor Pte Ltd/SLN7500L/12/09/2018 15:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	SUNDRY PARTS	nee 100.00
2	1	WEEKEND CAR SEAL	nee 80.00
Sub Total (S\$)			180.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	281.40
2	Total Paint Materials	New	109.91
3	Total Panel/Mechanical Labour	New	147 210.00
Gross Labour Cost (S\$)			601.31

Lai Huat (Meng Kee) Motor Pte Ltd/SLN7500L/12/09/2018 15:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



**LAI HUAT (MENG KEE)  
MOTOR PTE LTD  
SIN MING INDUSTRIAL  
ESTATE SECTOR A  
BLK 21 #01-58  
SINGAPORE 575679**

**Claim Reference:**  
**Assessment Number: LHM61195**  
**Version: LAIHUATM/1**  
**Date Calculated: 12/09/2018 07:26**

**Full Report - V1**  
**Registration: SLN 7500L**  
**Printed: 12/09/2018 14:27**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	11/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP-GBF 345A	Quote Due Date:	
Other Reference:	TP CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HYUNDAI
Model:	Elantra
Sub Model:	BASE MODEL
Model Sheet Number:	3092 01
Registration:	SLN 7500L
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

FROM 06/2016	AUTO AIR CON
LED HEADLAMP	FOG LAMPS
REAR PARKING SYSTEM	1.6 LTR 94 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE

*Not Authorised  
1.3.1  
Resurvey by paint  
4 days*

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	12/09/2018
Pre-Accident Damage:	

Tyres Condition:  
Tread Depth LHF:  
Tread Depth LHR:  
Damage Areas:

Tread Depth RHF:  
Tread Depth RHR:  
Direction of Impact:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61195



Version: LAIHUATM/1

Date Calculated: 12/09/2018 07:26

Full Report - V1

Registration: SLN 7500L

Printed: 12/09/2018 14:27



## Addresses

## Cost Summary

Total Labour	\$491.40
Total Paint/Material	\$109.91
Total Parts	\$978.00
Total of Additional Costs	\$180.00
Excess:	TBA
Grand Total Exc GST:	\$1,759.31
7 % GST:	\$123.15
Grand Total Inc GST:	\$1,882.46

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR

Price/Dent = \$42.00/HR

### Repair /

### Guide Number Repair Details

	WU	Cost Price (\$)
86520R00 RENEW REAR BUMPER	9.0	37.80
INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS		
69200R00 RENEW BOOTLID	11.0	46.20
1000 TRANSFER PARKING SENSOR	5 10.0*	42.00
1000 TRASNFER REVERSING CAMERA	5 10.0*	42.00
2640 REPAIR REAR BUMPER SUPPORT	5 10.0*	42.00

### LABOUR COST

Total Work Units	50.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	5.0HRS	\$210.00
Paint Labour	6.7HRS	\$281.40
Total Labour	11.7HRS	\$491.40

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2931	BOOTLID NEW PART PAINTING	12.0	
2583	REAR BUMPER NEW PART PAINT K1R	8.0	
2640	REAR BUMPER SUPPORT SURFACE PAINT	5.0	
2681	L/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0	
2682	R/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0	
2683	L/R INN PARKING SENSSURFACE PAINT PLAST.	3.0	
2684	R/R INN PARKING SENSSURFACE PAINT PLAST.	3.0	

### LABOUR COST - PAINT

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHM61195**

**Version: LAIHUATM/1**

**Date Calculated: 12/09/2018 07:26**

**Full Report - V1**

**Registration: SLN 7500L**

**Printed: 12/09/2018 14:27**

<b>TIME(PAINT)</b>	<b>37.0</b>	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	67.0	
Total Paintwork Labour	6.7HRS	\$281.40
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		\$29.93
New Part Painting - Plastic K1R		\$35.42
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$5.48
Surface Paint Plastic		\$1.48
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$109.91
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$109.91

## PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3015	1	BADGE "HYUNDAI"	86321F2000		0%	35.00*
3014	1	BADGE MODEL	86315F2000		0%	28.00*
2931	1	BOOTLID	69200F2010		0%	510.00*
2583	1	REAR BUMPER	86610F2010		0%	215.00*
2593	1	REAR BUMPER SPOILER	86612F2000		0%	140.00*
1000	1	S EMBLEM	Renew		0%	50.00*
f: OEM Parts			Sub Total			\$978.00
g: Original			Sundry Parts	(Fixed)		\$0.00
h: Secondhand			<b>Total Parts</b>			<b>\$978.00</b>
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
WEEKEND CAR SEAL SPECIALIST	0%	\$80.00
SUNDRY PARTS SPECIALIST		\$100.00
<b>Total Extras</b>		<b>\$180.00</b>

## Final Calculation

<b>Total Parts</b>	<b>\$978.00</b>
<b>Labour</b>	
Total Panel/Mechanical	\$210.00
Total Paintwork	\$281.40
<b>Total Labour</b>	<b>\$491.40</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$180.00
<b>Total of Additional Costs</b>	<b>\$180.00</b>
<b>Total Paint/Material Costs</b>	<b>\$109.91</b>
<b>Grand Total Excludes GST</b>	<b>\$1,759.31</b>
GST @ 7 %	\$123.15
<b>Grand Total Includes GST</b>	<b>\$1,882.46</b>

**LAI HUAT (MENG KEE) MOTOR PTE LTD**

**Claim Reference:**

**Assessment Number: LHM61195**

**Version: LAIHUATM/1**

**Date Calculated: 12/09/2018 07:26**

---

**Full Report - V1**

**Registration: SLN 7500L**

**Printed: 12/09/2018 14:27**

**Assessment Notes**

---

K7

**LAI HUAT (MENG KEE)  
MOTOR PTE LTD  
SIN MING INDUSTRIAL  
ESTATE SECTOR A  
BLK 21 #01-58  
SINGAPORE 575679**

**Claim Reference:**  
**Assessment Number: LHM61195**  
**Version: LAI HUAT/1**  
**Date Calculated: 11/10/2018 04:44**

**Full Report - V1**  
**Registration: SLN 7500L**  
**Printed: 11/10/2018 11:44**

---

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	11/09/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	TP-GBF 345A	Quote Due Date:	
Other Reference:	TP CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HYUNDAI
Model:	Elantra
Sub Model:	BASE MODEL
Model Sheet Number:	3092 01
Registration:	SLN 7500L
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

FROM 06/2016	AUTO AIR CON
LED HEADLAMP	FOG LAMPS
REAR PARKING SYSTEM	1.6 LTR 94 KW
TWO COAT METALLIC	PREPARE OFF VEHICLE

---

**Vehicle Condition**



**Vehicle Status**

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	12/09/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**  
**Assessment Number:** LHM61195  
**Version:** LAI HUAT/1  
**Date Calculated:** 11/10/2018 04:44

**Full Report - V1**  
**Registration:** SLN 7500L  
**Printed:** 11/10/2018 11:44



## Addresses

## Cost Summary

Total Labour	\$428.40
Total Paint/Material	\$109.91
Total Parts	\$978.00
Total of Additional Costs	\$180.00
Excess:	TBA
Grand Total Exc GST:	\$1,696.31
7 % GST:	\$118.74
Grand Total Inc GST:	\$1,815.05

## Repair Information

### LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR  
 Price/Dent = \$42.00/HR

### Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
86520R00	RENEW REAR BUMPER INCLUDES: R + R OUTER TAIL LAMPS AND NECESSARY ATTACHED PARTS	9.0	37.80
69200R00	RENEW BOOTLID	11.0	46.20
1000	TRANSFER PARKING SENSOR	5.0*	21.00
1000	TRASNFER REVERSING CAMERA	5.0*	21.00
2640	REPAIR REAR BUMPER SUPPORT	5.0*	21.00
<b>LABOUR COST</b>			
	<b>Total Work Units</b>	35.0	
	<b>Corrosion Protection External Labour</b>	0.0HRS	0.00
	<b>Corrosion Protection Internal Labour</b>	0.0HRS	0.00
	<b>Sub Total</b>	3.5HRS	\$147.00
	<b>Paint Labour</b>	6.7HRS	\$281.40
	<b>Total Labour</b>	10.2HRS	\$428.40

### PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
2931	BOOTLID NEW PART PAINTING	12.0	
2583	REAR BUMPER NEW PART PAINT K1R	8.0	
2640	REAR BUMPER SUPPORT SURFACE PAINT	5.0	
2681	L/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0	
2682	R/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0	
2683	L/R INN PARKING SENSSURFACE PAINT PLAST.	3.0	
2684	R/R INN PARKING SENSSURFACE PAINT PLAST.	3.0	

### LABOUR COST - PAINT

# LAI HUAT (MENG KEE) MOTOR PTE LTD

**Claim Reference:**

**Assessment Number: LHM61195**

**Version: LAI HUAT/1**

**Date Calculated: 11/10/2018 04:44**

**Full Report - V1**

**Registration: SLN 7500L**

**Printed: 11/10/2018 11:44**

<b>TIME(PAINT)</b>	<b>37.0</b>	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	67.0	
Total Paintwork Labour	6.7HRS	\$281.40
<b>MATERIAL COST - PAINT</b>		<b>Cost Price</b>
New Part Painting		\$29.93
New Part Painting - Plastic K1R		\$35.42
Material-Constant Main Work Metal		\$28.60
Surface-/Blend Paint		\$5.48
Surface Paint Plastic		\$1.48
Material-Const Main Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$109.91
Pearlescent Uplift @ 0.0%		\$0.00
<b>Total Paint Material Cost</b>		<b>\$109.91</b>

## PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
3015	1	BADGE "HYUNDAI"	86321F2000		0% 35.00*
3014	1	BADGE MODEL	86315F2000		0% 28.00*
2931	1	BOOTLID	69200F2010		0% 510.00*
2583	1	REAR BUMPER	86610F2010		0% 215.00*
2593	1	REAR BUMPER SPOILER	86612F2000		0% 140.00*
1000	1	S EMBLEM	Renew		0% 50.00*
f: OEM Parts			Sub Total		\$978.00
g: Original			Sundry Parts	(Fixed)	\$0.00
h: Secondhand			<b>Total Parts</b>		<b>\$978.00</b>
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

Description	Betterment	Price
WEEKEND CAR SEAL SPECIALIST	0%	\$80.00
SUNDRY PARTS SPECIALIST		\$100.00
<b>Total Extras</b>		<b>\$180.00</b>

## Final Calculation

<b>Total Parts</b>	<b>\$978.00</b>
<b>Labour</b>	
Total Panel/Mechanical	\$147.00
Total Paintwork	\$281.40
<b>Total Labour</b>	<b>\$428.40</b>
<b>Additional Costs</b>	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$180.00
<b>Total of Additional Costs</b>	<b>\$180.00</b>
<b>Total Paint/Material Costs</b>	<b>\$109.91</b>
<b>Grand Total Excludes GST</b>	<b>\$1,696.31</b>
GST @ 7 %	\$118.74
<b>Grand Total Includes GST</b>	<b>\$1,815.05</b>



**LAI HUAT (MENG KEE) MOTOR PTE LTD**

**Claim Reference:**

**Full Report - V1**

**Assessment Number: LHM61195**

**Registration: SLN 7500L**

**Version: LAI HUAT/1**

**Printed: 11/10/2018 11:44**

**Date Calculated: 11/10/2018 04:44**

---

**Assessment Notes**

---



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016716/KTBN2

Date: 16/10/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3015371802
Claimant Vehicle No :	SLN7500L	Insured Vehicle No :	GBF345A
Date of Loss:	11/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04417C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLN7500L	Engine No:	G4FGGU041669
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU366150
Reg. Date:	17/05/2017 (Man. Year: 2017)	Odometer:	17702 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 8 mm	Rear Left Side:	Nexen 8 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	978.00	978.00	0.00	0.00
Miscellaneous Items	180.00	180.00	0.00	0.00
Labour	601.31	538.31	63.00	10.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,759.31</b>	<b>1,696.31</b>	<b>63.00</b>	<b>3.58</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>123.15</b>	<b>118.74</b>	<b>4.41</b>	<b>3.58</b>
<b>Nett Amount (\$\$)</b>	<b>1,882.46</b>	<b>1,815.05</b>	<b>67.41</b>	<b>3.58</b>

## INSPECTION

Date of Assignment:	13/09/2018	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	17/09/2018	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2018)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN7500L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BADGE "HYUNDAI"	Necessary	35.00 F	*35.00 F
2	1	NA	*BADGE MODEL	Necessary	28.00 F	*28.00 F
3	1	NA	*BOOTLID	Bent	510.00 F	*510.00 F
4	1	NA	*REAR BUMPER	Cracked	215.00 F	*215.00 F
5	1	NA	*REAR BUMPER SPOILER	Bent	140.00 F	*140.00 F
6	1	NA	*S EMBLEM	Necessary	50.00 F	*50.00 F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>978.00</b>	<b>978.00</b>
--------------------------	---------------	---------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	<b>SUNDRY PARTS</b> (NECESSARY)	100.00	100.00
2	1	<b>WEEKEND CAR SEAL</b> (NECESSARY)	80.00	80.00
<b>Sub Total (S\$)</b>			<b>180.00</b>	<b>180.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	281.40	281.40
2	Total Paint Materials	New	109.91	109.91
3	Total Panel/Mechanical Labour	New	210.00	147.00
<b>Gross Labour Cost (S\$)</b>			<b>601.31</b>	<b>538.31</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;