

ASS. REC. BY:

REF:

CS/CT113016717/Ksbez

Special Instruction:

Supervisor

Kineth

ASSIGNMENT (Office)

Mumeta

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

13/01/2018 11:18am

Estimated Cost:

Bill to:

OD / TP / WS / TE RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 2785D

Insured:

BBH 2014G

at Workshop m/s

Cheng Hoe

Tel:

6755 6142

of

Bik 1019 Yishun Ind Park A # 01-374

Policy No:

OMCVSN 30129 01800

Claim No:

SHM18D04354CD

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

H.O.D. Endorsement:

Date/Time:

13/01/2018 11:56am

Person Contacted:

Efeeda

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 2785D - X

BBH 2014G - X

C/L By @3200a Confirm Efeeda

ASS. REC. BY:

REF: 072 /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKD 2785D

Yr Regn:

11 / 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

c.c.

1591

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

117039

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM140C 810MBU128582

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brakes:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/9/18

D.O.A.

14/9/18

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/9

File pass to Carhena

11/10/18

Confirmed L/S \$ 3200/- @ 1 days with Kennedy
(\$ 1.324.55 Red - 29%)

RECEIVED 11 JAN 2019

11/1/2019

Date/Time, File Pass to?

11/01/19



: Prel. Report



: Final Report

1) Typing

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

220

Transportation:

S - RS - SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

TOTAL

220

Report Format:

Lump Sum / I.B.I: (\$ 3,200/- L/S

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 12 Sep 2018 Sendback Est | 12 Sep 2018 16:43 S\$4,524.55 | 13 Sep 2018 11:18 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS | | | | | | | | | |
| Insured: | TENG SHENG KOREAN CUISINE, Co. Reg. No.: 53119472L | | | | | | | | |
| Main Claimant: | TAN HEE BOEY DALVIN | | | | | | | | |
| Vehicle Reg. No.: | SKD2785D | Date of Loss: | 10/09/2018 19:00 - :59 [81 Months and 25 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / SNM18D04354C02 | Policy/Cover Note No.: | DMCVSN3022901800 | | | | | | |
| Vehicle Reg. No. (Insured): | GBH2014G | Policy No. (Claimant): | | | | | | | |
| | | Excess: | \$50.00 | | | | | | |
| Repairer: | Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142 | | | | | | | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018] | | | | | | | | |
| Driver/Custodian (Insured): | ZHANG BAOSHENG (/ Male), Tel: +6591117604 | | | | | | | | |
| Adj Asg. Remarks: | EST \$4841.27, CASE WITH SJE. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | | | | | | |
| View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | | | | | | | | |
| View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------------|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 5735F |
| Vehicle Details | |
| Vehicle No.: | SKD2785D |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 11 Sep 2018 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | FD I30 CW 1.6 A |
| Primary Colour: | White |
| Manufacturing Year: | 2011 |
| Engine No.: | G4FCBU283329 |
| Chassis No.: | KMHDC81DMBU128582 |
| Maximum Power Output: | 89.7 kW (120 bhp) |
| Open Market Value: | \$13,091.00 |
| Original Registration Date: | 16 Nov 2011 |
| First Registration Date: | 16 Nov 2011 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$13,091.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 15 Nov 2021 |
| PARF Rebate Amount: | \$8,509.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 15 Nov 2021 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$55,997.00 |
| COE Rebate Amount: | \$17,794.00 |
| Total Rebate Amount: | \$26,303.00 |

The information contained herein is correct as at 11 Sep 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------|
| Date Of Report | 11/09/2018 15:26 |
| Date Of Accident | 10/09/2018 19:25 |
| Exact Location Of Accident | PIE TOWARDS BKE |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKD2785D |
| Insured/Policyholder | |
| Name Of Registered Owner | TAN HEE BOEY DALVIN |
| NRIC No | S2015735F |
| Email Address | DALVINTAN@SIM.EDU.SG |
| Mobile Phone No | (LOCAL) +65-96786939 |
| Alternative Phone No | OTHERS-96786939 |

Vehicle Particulars

| | |
|--|-----------------|
| Manufacturer | HYUNDAI |
| Model | FD I30 CW 1.6 A |
| Exact Purpose for which vehicle was being used at time of accident | PTE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5052147051-06 |
| Cover Note Number | 16/11/17 - 15/11/18 |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | TAN HEE BOEY DALVIN |
| NRIC No | S2015735F |
| Date Of Birth | 16/10/1949 |
| Occupation | INDOOR |
| Date Of Driving Pass | 27/11/1974 |
| Driving Experience | 43 YEARS AND 9 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-96786939 |
| Fax Number | |
| Contact Number | OTHERS-96786939 |
| EMail Address | DALVINTAN@SIM.EDU.SG |

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

| | |
|---|---|
| Name | TAN HEE BOEY DALVIN |
| Approximate Age | 68 |
| Injuries Sustain | PAIN AT HEAD, NECK , UPPER BACK & GIDDINESS |
| Injured person in which vehicle? | SKD2785D |
| Were seat belts worn? | |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | BLK 358 WOODLANDS AVE 5 #08-376 |
| Postcode | 730358 |

| | |
|---|---------------------------------|
| Address | BLK 358 WOODLANDS AVE 5 #08-376 |
| Postcode | 730358 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | YES |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|--|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | WOODLANDS WEST NPC |
| Police Station Address | ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: - FAX NO: |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER POLICE REPORT.


Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------------|
| Vehicle Registration Number | GBH2014G |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | ZHANG BOSHENG |
| NRIC/Passport Number | S8772832C |
| Contact Number | 91117604 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ATTACHED TO POLICE REPORT

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 11/9/18

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature] 11/9/18
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

GIARMC SketchPlanForm, V3 () Claim Own Policy (✓) Claim Third Party () Reporting Only
 () Claim OD/TP at other workshop ()

MT 1011086

SKETCH PLAN

VEHICLE NO.: SKD 2785D
INSURER : NTUC
DATE & TIME: 10/09/18 19.25P

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 11/9/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE POLICE FORCE

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999



T/20180911/2061

1 of 3

Report No. T/20180911/2061

REPORT OF A TRAFFIC ACCIDENT

| | | | | |
|--|------------|--|------------------------------|--------------------------|
| Date/Time Report Made: 11/09/2018 12:35 | | Vide Report No.: | | Station Diary No.: 39 |
| Informant Details | | | | |
| Name of Informant: TAN HEE BOEY DALVIN | | Address: APT BLK 358 WOODLANDS AVENUE 5 #08-376 SINGAPORE 730358 | | |
| ID Type / ID No.: NRIC-NO / S2015735F | | Contact No.: Home/Office: Mobile: 96786939 | | |
| Nationality: SINGAPORE CITIZEN | | Email: | | |
| Sex: Female | Age: 68 | Date of Birth: 16/10/1949 | Type of Informant: Driver | |
| Race: Chinese | | Language: English | Institution / School Name: | |
| Occupation: EXECUTIVE ASSISTANT | | Driving Licence Information: Class: Date of Expiry: | | |

| | | | | |
|---|---------------|--------------------|--|-------------------------------------|
| General Information on the Accident | | | | |
| Type of Accident: | Injury Others | Drink Drive: No | Date/Time of Accident: 10/09/2018 19:25 | Type of Location: |
| Location: Along Road 1 PAN ISLAND EXPRESSWAY BUKIT TIMAH EXPRESSWAY Near BKE exit | | | | |
| Weather: | | Road Surface: | Road Speed Limit: | |
| Traffic Flow: | | Traffic Control: | Traffic Volume: | |
| Type of Collision: | | | | Anyone conveyed by ambulance: No |

| Details of Vehicle Involved | | | | | | |
|------------------------------------|------|---------|-----------------|-------|------------------|-------|
| Vehicle No. | Type | Make | Model | Color | Damage | Other |
| GBH2014G | Van | | | | Slightly Damaged | 0 |
| SKD2785D | Car | HYUNDAI | FD I30 CW 1.6 A | White | Slightly Damaged | 0 |

| Details of Vehicle Insurance | | | | |
|-------------------------------------|--|---------------|----------------|-------------|
| Vehicle No. | Insurance Company | Policy No. | Effective Date | Expiry Date |
| SKD2785D | NTUC Income Insurance Co-Operative Limited | 5052147051-06 | 16/11/2017 | 15/11/2018 |



**SINGAPORE
POLICE FORCE**



T/20180911/2081

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

2 of 3

Report No. T/20180911/2081

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|-------------------------|--|-----------------------------------|
| Any Pedestrian Involved: No | | | |
| No. of Pedestrians Injured: NIL | | Use of Pedestrian Crossing: NA | |
| Name | Zhang Bosheng | ID No. | S8772832C |
| Related Vehicle | GBH2014G (Van) | Contact No. | 91117604 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Name | TAN HEE BOEY DALVIN | ID No. | S2015735F |
| Related Vehicle | SKD2785D (Car) | Contact No. | 96786939 |
| Hospital/Clinic | MOUNT ALVERNIA HOSPITAL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | 10/09/2018 | Date Discharge | 10/09/2018 |
| No. of Days granted Medical Leave | 04 | Degree of Injury | Slight |

Brief Details.

On 10/09/2018 at about 1925hrs, I was driving along PIE after work. I was on the leftmost lane heading towards BKE. Near the BKE exit, there was a jam thus I stopped my vehicle behind the queue and waited. Suddenly I felt a strong impact from the rear of my vehicle. I alighted from my vehicle to make a check and discovered that a Van had collided onto the rear of my car. I then approached the van driver and he admitted that he was in the wrong and we both exchanged particulars. Due to the accident I suffered pain at my head, neck and upper back and giddiness. My car's rear bumper and trunk were damaged and is unable to close properly. I was given 4 days MC by Mount Alvernia Hospital and was advised by my insurance company to lodge a traffic accident report.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999



T/20180911/2061

3 of 3

Report No. T/20180911/2061

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 NOR RUDIEMAN BIN ABDUL RAHMAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 SITIMARSITA BINTE BOHARI

Contact No.: 65476219

Signature Of Informant:

[Handwritten Signature]

Date/Time:
11/09/2018 12:35

Classification Of Case:

SN 127

Authentication Stamp
NP168



Signature :

Singapore Police Force

CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761

SKD 2785D
TP/china

Claim Reference:
Assessment Number: CSKD2785
Version: CHENGHOE/1
Date Calculated: 12/09/2018 09:35

Full Report - V1
Registration: SKD2785D
Printed: 12/09/2018 16:36

Summary Information

Claim

| | | | |
|-----------------------|--------------------------------|----------------------------|------------|
| Location: | Singapore (SG) | Currency: | SGD |
| Printed by: | CHENG HOE MOTOR PTE LTD | Date of Incident: | 10/09/2018 |
| Authorisation Status: | Interim | Able to Authorise Repairs: | TBA |
| Work Provider: | China Taiping Insurance (S) Pt | Repairs Authorised: | TBA |
| Claim Reference: | | Estimated Repair Time: | |
| Policy Number: | TP/CHINA | Quote Due Date: | |
| Other Reference: | | Actual Repair Days: | |
| Third Party: | | Parts Ordered Date: | |
| Insured Amount: | | Hire Car Start: | |
| Under Warranty: | | Hire Car End: | |
| Warranty Expired: | | Vehicle Collected: | |

Vehicle Details

Vehicle

| | |
|---------------------|-------------------|
| Manufacturer: | HYUNDAI |
| Model: | I30 |
| Sub Model: | BASE MODEL |
| Model Sheet Number: | 3024 01 |
| Registration: | SKD2785D |
| Registration Month: | November |
| Registration Year: | 2011 |
| VIN Number: | KMHDC81DMBU128582 |
| Manufacture Year: | 2011 |
| Odometer: | Not Known |
| Colour: | |
| Engine Number: | G4FCBU283329 |
| Fuel Level: | % |

Model Specs

| | |
|----------------------|---------------------|
| FROM 01/2011 | AIR CONDITIONING |
| EMISSION STD EC 2000 | 1.6 LTR 89/90KW |
| POWER STEERING | COMBI |
| TWO COAT METALLIC | PREPARE OFF VEHICLE |

Not Authorised
1/1 Surp @ ?
Resurvey After Paint
6 days

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Severity of Impact:
Vehicle Status on
Inspection:

Date of Inspection:


Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

LIK Auto Consultants hence notify
the Repairer of the following:
To resurvey before spray painting
To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
Third party surp 12/09/2018 Prejudice basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

CHENG HOE MOTOR PTE LTD**Claim Reference:****Assessment Number: CSKD2785****Version: CHENGHOE/1****Date Calculated: 12/09/2018 09:35****Full Report - V1****Registration: SKD2785D****Printed: 12/09/2018 16:36**

All

**Addresses****Repairer**

Name : CHENG HOE MOTOR PL

Address :

BLK 1019 YISHUN IND PARK A

#01-374

Post Code : 768761

Cost Summary

| | |
|---------------------------|------------|
| Total Labour | \$1,373.40 |
| Total Paint/Material | \$251.15 |
| Total Parts | \$2,325.00 |
| Total of Additional Costs | \$575.00 |
| Excess: | TBA |
| Grand Total Exc GST: | \$4,524.55 |
| 7 % GST: | \$316.72 |
| Grand Total Inc GST: | \$4,841.27 |

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR****Price/Dent = \$42.00/HR****Repair /****Guide Number Repair Details**

| | | WU | Cost Price (\$) |
|-----------|--------------------------------------|-----------|------------------------|
| 86520R00 | R + R REAR BUMPER | 8.0 | 33.60 |
| | INCLUDES: R + R TAILLAMPS AND NUMBER | | |
| | PLATE LAMP | | |
| 73700R00 | RENEW TAILGATE | 33.0 | 138.60 |
| | INCLUDES: R + R TAILGATE, | | |
| | CONVERT ATTACHED PARTS, RENEW IF | | |
| | NECESSARY | | |
| 87160R00 | R + R BOOT LID SEAL | 2.0 | 8.40 |
| 81214R00 | R + R TAILGATE LOCK PLATE | 2.0 | 8.40 |
| NO NUMBER | RENEW REAR CLOSING PANEL | 48.0 | 201.60 |
| 85875R00 | R + R L/R SILL MOULDING | 2.0 | 8.40 |
| 85875R0R | R + R R/R SILL MOULDING | 2.0 | 8.40 |
| 85850R00 | R + R L/UPPER C-PILLAR TRIM | 3.0 | 12.60 |
| 85850R0R | R + R R/UPPER C-PILLAR TRIM | 3.0 | 12.60 |
| 85770R00 | R + R REAR END PANEL TRIM | 2.0 | 8.40 |
| 85731R00) | R + R LEFT BOOT TRIM | 1.0 | 4.20 |
| 85731R0R) | R + R RIGHT BOOT TRIM | 1.0 | 4.20 |
| 85710R00 | R + R BOOT CARPET | 2.0 | 8.40 |
| 3151 | REMOVE AND REFIT REAR SCREEN | 20.0* ✓ | 84.00 |

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSKD2785

Version: CHENGHOE/1

Date Calculated: 12/09/2018 09:35

Full Report - V1

Registration: SKD2785D

Printed: 12/09/2018 16:36

| | | | | |
|------|------------------------|---|--------------------|-------|
| 3481 | REPAIR L/R SIDE PANEL | 5 | 10.0* | 42.00 |
| 3482 | REPAIR R/R SIDE PANEL | 5 | 10.0* | 42.00 |
| 3900 | REPAIR BOOZFLOOR | 5 | 10.0* | 42.00 |
| 3991 | REPAIR L/R SIDE MEMBER | | 10.0* ? | 42.00 |
| 3992 | REPAIR R/R SIDE MEMBER | | 10.0* ? | 42.00 |

LABOUR COST

| | | |
|--------------------------------------|---------|------------|
| Total Work Units | 179.0 | |
| Corrosion Protection External Labour | 0.0HRS | 0.00 |
| Corrosion Protection Internal Labour | 0.0HRS | 0.00 |
| Sub Total | 17.9HRS | \$751.80 |
| Paint Labour | 14.8HRS | \$621.60 |
| Total Labour | 32.7HRS | \$1,373.40 |

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

| Guide Number | Description | WU | Cost Price (\$) |
|--------------|--------------------------------------|------|-----------------|
| | - TWO COAT METALLIC | | |
| | - PREPARE OFF VEHICLE | | |
| 2640 | REAR BUMPER SUPPORT SURFACE PAINT | 4.0 | |
| 2711 | REAR PANEL NEW PART PAINTING | 16.0 | |
| 2931 | BOOTLID/TAI LGATE NEW PART PAINTING | 15.0 | |
| 2583 | REAR BUMPER COVER NEW PART PAINT K1R | 13.0 | |
| 2985 | TRIM CPL NEW PART PAINT K1R | 3.0 | |
| 3481 | L/R SIDE PANEL REPAIR PAINTING >50% | 21.0 | |
| 3482 | R/R SIDE PANEL REPAIR PAINTING >50% | 21.0 | |
| 3900 | BOOZFLOOR SURFACE PAINT | 9.0 | |
| 3951 | L/BOOT FLOOR EXT SURFACE PAINT | 4.0 | |
| 3959 | CTR BOOT CROSSMEMBERSURFACE PAINT | 4.0 | |
| 3991 | L/R SIDE MEMBER SURFACE PAINT | 4.0 | |
| 3992 | R/R SIDE MEMBER SURFACE PAINT | 4.0 | |

LABOUR COST - PAINT

| | | |
|------------------------------------|---------|----------|
| TIME(PAINT) | 118.0 | |
| Preparation Main Work Plastic | 5.0 | |
| Preparation Main Work Metal | 25.0 | |
| Preparation Work Multi Layer Paint | 0.0 | |
| Total Work Units (10WU/HR) | 148.0 | |
| Total Paintwork Labour | 14.8HRS | \$621.60 |

MATERIAL COST - PAINT

| | |
|------------------------------------|------------|
| | Cost Price |
| New Part Painting | \$58.23 |
| New Part Painting - Plastic K1R | \$67.41 |
| Material-Constant Main Work Metal | \$28.60 |
| Surface-/Blend Paint | \$37.35 |
| Repair Painting | \$50.56 |
| Material-Const Main Work Plastic | \$9.00 |
| Total Excluding Pearlescent Uplift | \$251.15 |
| Pearlescent Uplift @ 0.0% | \$0.00 |
| Total Paint Material Cost | \$251.15 |

PARTS

| Guide No. | Qty | Description | Part Number | Supplier | Bet. | Price (\$) |
|-----------|-----|---------------------|--------------|----------|------|------------|
| 3020 | 1 | BADGE MODEL | 863102L300 | | 0% | 21.00* ✓ |
| 5009 | 1 | BOOT TRAY | 857502L510WK | | 0% | 140.00* ✓ |
| 2977 | 1 | BOOT/TAI LGATE LOCK | 812302L200 | | 0% | 90.00* ✓ |

Price Valid: 01/06/2015

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSKD2785

Version: CHENGHOE/1

Date Calculated: 12/09/2018 09:35

Full Report - V1

Registration: SKD2785D

Printed: 12/09/2018 16:36

| | | | | | | | |
|---------------|---|----------------------|------------------|---------|-----|------------|---|
| 2944 | 1 | BOOT/TAILGATE SEAL | 873212L200 | 0% | RM | 55.00* | ✓ |
| 2931 | 1 | BOOTLID/TAILGATE | 737002L220 | 0% | R1 | 500.00* | ✓ |
| 3167 | 2 | CLIP FASTENING | 871143K000 | 0% | | 0.00F | |
| 5007 | 1 | L/BOOT TRAY | 857502L600WK | 0% | RM | 110.00* | ✓ |
| 3281 | 1 | L/R LAMP ASSY | 924012L110 | 0% | CRM | 190.00* | ✓ |
| 4907 | 1 | LOWER TAILGATE TRIM | 817502L200WK | 0% | D11 | 130.00* | ✓ |
| 3013 | 1 | MANUFACTURER BADGE | 86335H1020 | 0% | RM | 25.00* | ✓ |
| 5008 | 1 | R/BOOT TRAY | 857502L700WK | 0% | CRM | 110.00* | ✓ |
| 3282 | 1 | R/R LAMP ASSY | 924022L110 | 0% | CRM | 190.00* | ✓ |
| 2583 | 1 | REAR BUMPER COVER | 866102L310 | 0% | Rm | 200.00* | ✓ |
| 2640 | 1 | REAR BUMPER SUPPORT | 866312L300 | 0% | | 0.00F | |
| 1000 | 1 | REAR BUMPER TOW CVR | Renew | 0% | RM | 7.00* | ✓ |
| 2644 | 1 | REAR IMPACT DAMPER | 866202L300 | 0% | CRM | 75.00* | ✓ |
| 3015 | 1 | REAR MANUFACT BADGE | 863402L100 | 0% | RM | 20.00* | ✓ |
| 4985 | 1 | REAR OUTER PANELLING | 857702L500WK | 0% | Rm | 42.00* | ✓ |
| 2711 | 1 | REAR PANEL | 691002L210 | 0% | R1 | 145.00* | ✓ |
| 3160 | 1 | REAR SCREEN BOND KIT | KNGKW12 | 0% | | 0.00F | |
| 3163 | 1 | REAR SCREEN FIX SET | USE SINGLE PARTS | 0% | | 0.00 | |
| 3165 | 7 | REAR SCREEN SPACER | 861143D000 | 0% | | 0.00F | |
| 1000 | 1 | REINFORCEMENT | Renew | 0% | CRM | 125.00* | ✓ |
| 2985 | 1 | TRIM CPL | 873702L300 | 0% | RM | 50.00* | ✓ |
| f: OEM Parts | | | Saving | | | \$194.61 | |
| g: Original | | | Sub Total | | | \$2,225.00 | |
| h: Secondhand | | | Sundry Parts | (Fixed) | | \$100.00 | |
| p: Parallel | | | Total Parts | | | \$2,325.00 | |
| x: Exchange | | | | | | | |

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

| Description | | Betterment | Price | |
|---------------------|------------|------------|----------|------------|
| REAR W/S GUM | SPECIALIST | 0% | RM | \$40.00 ✓ |
| REAR NO. PLATE | SPECIALIST | | R1 | \$35.00 ✓ |
| 1SET REVERSE CAMERA | SPECIALIST | 0% | RM | \$300.00 ✓ |
| 1SET REVERSE SENSOR | SPECIALIST | | CM | \$200.00 ✓ |
| Total Extras | | | \$575.00 | |

Final Calculation

| | | | |
|------------------------------|------------|------------|---------|
| Total Parts | \$2,325.00 | | |
| Labour | | | |
| Total Panel/Mechanical | \$751.80 | 604.80 | |
| Total Paintwork | \$621.60 | 538.00 | |
| Total Labour | | \$1,373.40 | |
| Additional Costs | | | |
| Corr Prot Materials External | \$0.00 | | |
| Corr Prot Materials Internal | \$0.00 | | |
| Cost of Specialist | \$575.00 | 275 275 | |
| Total of Additional Costs | | \$575.00 | |
| Total Paint/Material Costs | | \$251.15 | 246.62 |
| Grand Total Excludes GST | | \$4,524.55 | 4039.47 |
| GST @ 7 % | | \$316.72 | |
| Grand Total Includes GST | | \$4,841.27 | |

CHENG HOE MOTOR PTE LTD

Claim Reference:

Full Report - V1

Assessment Number: CSKD2785

Registration: SKD2785D

Version: CHENGHOE/1

Printed: 12/09/2018 16:36

Date Calculated: 12/09/2018 09:35

Assessment Notes

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2018)

Parts: 143 HYUNDAI 130 1.6 (FD) DOHC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SKD2785D/12/09/2018 16:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|----------|-----------------------|-------|-------|-----------|
| 1 | 1 | NA | *BADGE MODEL | 0.00 | 0.00 | *21.00 F |
| 2 | 1 | NA | *BOOT TRAY | 0.00 | 0.00 | *140.00 F |
| 3 | 1 | NA | *BOOT/TAILGATE LOCK | 0.00 | 0.00 | *90.00 F |
| 4 | 1 | NA | *BOOT/TAILGATE SEAL | 0.00 | 0.00 | *55.00 F |
| 5 | 1 | NA | *BOOTLID/TAILGATE | 0.00 | 0.00 | *500.00 F |
| 6 | 1 | NA | *CLIP FASTENING | 0.00 | 0.00 | *- F |
| 7 | 1 | NA | *L/BOOT TRAY | 0.00 | 0.00 | *110.00 F |
| 8 | 1 | NA | *L/R LAMP ASSY | 0.00 | 0.00 | *190.00 F |
| 9 | 1 | NA | *LOWER TAILGATE TRIM | 0.00 | 0.00 | *130.00 F |
| 10 | 1 | NA | *MANUFACTURER BADGE | 0.00 | 0.00 | *25.00 F |
| 11 | 1 | NA | *R/BOOT TRAY | 0.00 | 0.00 | *110.00 F |
| 12 | 1 | NA | *R/R LAMP ASSY | 0.00 | 0.00 | *190.00 F |
| 13 | 1 | NA | *REAR BUMPER COVER | 0.00 | 0.00 | *200.00 F |
| 14 | 1 | NA | *REAR BUMPER SUPPORT | 0.00 | 0.00 | *- F |
| 15 | 1 | NA | *REAR BUMPER TOW CVR | 0.00 | 0.00 | *7.00 F |
| 16 | 1 | NA | *REAR IMPACT DAMPER | 0.00 | 0.00 | *75.00 F |
| 17 | 1 | NA | *REAR MANUFACT BADGE | 0.00 | 0.00 | *20.00 F |
| 18 | 1 | NA | *REAR OUTER PANELLING | 0.00 | 0.00 | *42.00 F |
| 19 | 1 | NA | *REAR PANEL | 0.00 | 0.00 | *145.00 F |
| 20 | 1 | NA | *REAR SCREEN BOND KIT | 0.00 | 0.00 | *- F |
| 21 | 1 | NA | *REAR SCREEN FIX SET | 0.00 | 0.00 | *- F |
| 22 | 1 | NA | *REAR SCREEN SPACER | 0.00 | 0.00 | *- F |
| 23 | 1 | NA | *REINFORCEMENT | 0.00 | 0.00 | *125.00 F |
| 24 | 1 | NA | *TRIM CPL | 0.00 | 0.00 | *50.00 F |

F=Franchise part.

Total Parts (S\$) **2,225.00**

Cheng Hoe Motor Pte Ltd/SKD2785D/12/09/2018 16:43. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items


| No | Qty | Particulars | Amount |
|----------------------------|-----|---------------------|---------------|
| Miscellaneous Items | | | |
| 1 | 1 | 1SET REVERSE CAMERA | 300.00 |
| 2 | 1 | 1SET REVERSE SENSOR | 200.00 |
| 3 | 1 | REAR NO.PLATE | 35.00 |
| 4 | 1 | REAR W/S GUM | 40.00 |
| 5 | 1 | SUNDRY PARTS | 100.00 |
| Sub Total (S\$) | | | 675.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|-------------------------|-------------------------------|----------|-----------------|
| <u>Labour Items</u> | | | |
| 1 | Total Paint Labour | New | 621.60 |
| 2 | Total Paint Materials | New | 251.15 |
| 3 | Total Panel/Mechanical Labour | New | 751.80 |
| Gross Labour Cost (S\$) | | | 1,624.55 |

Cheng Hoe Motor Pte Ltd/SKD2785D/12/09/2018 16:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

| | | | |
|-------------------------------|----------------------------------|--------------------|-------------------|
| Claim Type: | THIRD PARTY | Ref. No: | TP/CHINA |
| Policy No: | | Date of Loss: | 10/09/2018 |
| Vehicle Reg. No.: | SKD2785D | Driveable? | |
| Party At Fault: | UNKNOWN | | |
| Driver (TP): | TAN HEE BOEY DALVIN | Driver (Insured): | ZHANG BAOSHENG |
| Make/Model: | HYUNDAI 130, 1.6 (FD) DOHC (A) | Vehicle Reg. Date: | 16/11/2011 |
| Vehicle Colour: | WHITE | | |
| Engine No: | G4FCBU283329 | Chassis No: | KMHDC81DMBU128582 |
| Odometer: | 0 KM | | |
| Paint Type: | | | |
| Total Loss? | NO | | |
| Est. Duration of Repair (day) | 0 | | |
| Description of Accident/Loss | REFER TO GIA ATTACHED | | |
| Present Location: | CHENG HOE MOTOR PTE LTD (YISHUN) | | |

| COST OF CLAIMS | Amount |
|---------------------------|-----------------|
| Parts | 2,225.00 |
| Miscellaneous Items | 675.00 |
| Labour | 1,624.55 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (\$\$) | 4,524.55 |
| + GST 7.00% (\$\$) | 316.72 |
| Nett Amount (\$\$) | 4,841.27 |

This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: CSKD2785
Version: LKKAUTOC/3
Date Calculated: 11/01/2019 02:25

Full Report - V1
Registration: SKD2785D
Printed: 11/01/2019 10:28

Summary Information

Claim

| | | | |
|-----------------------|--------------------------------|----------------------------|------------|
| Location: | Singapore (SG) | Currency: | SGD |
| Printed by: | LKK AUTO | Date of Incident: | 10/09/2018 |
| Authorisation Status: | Interim | Able to Authorise Repairs: | TBA |
| Work Provider: | China Taiping Insurance (S) Pt | Repairs Authorised: | TBA |
| Claim Reference: | | Estimated Repair Time: | |
| Policy Number: | TP/CHINA | Quote Due Date: | |
| Other Reference: | | Actual Repair Days: | |
| Third Party: | | Parts Ordered Date: | |
| Insured Amount: | | Hire Car Start: | |
| Under Warranty: | | Hire Car End: | |
| Warranty Expired: | | Vehicle Collected: | |

Vehicle Details

Vehicle

| | |
|---------------------|-------------------|
| Manufacturer: | HYUNDAI |
| Model: | i30 |
| Sub Model: | BASE MODEL |
| Model Sheet Number: | 3024 01 |
| Registration: | SKD2785D |
| Registration Month: | November |
| Registration Year: | 2011 |
| VIN Number: | KMHDC81DMBU128582 |
| Manufacture Year: | 2011 |
| Odometer: | Not Known |
| Colour: | |
| Engine Number: | G4FCBU283329 |
| Fuel Level: | % |

Model Specs

| | |
|----------------------|---------------------|
| FROM 01/2011 | AIR CONDITIONING |
| EMISSION STD EC 2000 | 1.6 LTR 89/90KW |
| POWER STEERING | COMBI |
| TWO COAT METALLIC | PREPARE OFF VEHICLE |

Vehicle Condition

Vehicle Status

| | | |
|-------------------------|-------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact: | |
| Steering: | Vehicle Status on Inspection: | |
| Brakes Pedal Travel: | Date of Inspection: | 12/09/2018 |
| Place of Inspection: | | |
| Pre-Accident Damage: | | |
| Tyres Condition: | Tread Depth RHF: | |
| Tread Depth LHF: | Tread Depth RHR: | |
| Tread Depth LHR: | Direction of Impact: | |
| Damage Areas: | | |

Claim Reference:

Full Report - V1


Assessment Number: CSKD2785

Registration: SKD2785D


Version: LKKAUTOC/3

Printed: 11/01/2019 10:28

Date Calculated: 11/01/2019 02:25



All



Addresses

Repairer

Name : CHENG HOE MOTOR PL

Address :

BLK 1019 YISHUN IND PARK A

#01-374

Post Code : 768761

Cost Summary

| | |
|---------------------------|------------|
| Total Labour | \$1,192.80 |
| Total Paint/Material | \$246.67 |
| Total Parts | \$2,325.00 |
| Total of Additional Costs | \$275.00 |
| Excess: | TBA |
| Grand Total Exc GST: | \$4,039.47 |
| 7 % GST: | \$282.76 |
| Grand Total Inc GST: | \$4,322.23 |

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR

Price/Dent = \$42.00/HR

Repair /

| Guide Number | Repair Details | WU | Cost Price (\$) |
|--------------|--|-------|-----------------|
| 86520R00 | R + R REAR BUMPER INCLUDES: R + R TAILLAMPS AND NUMBER PLATE LAMP | 8.0 | 33.60 |
| 73700R00 | RENEW TAILGATE INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY | 33.0 | 138.60 |
| 87160R00 | R + R BOOT LID SEAL | 2.0 | 8.40 |
| 81214R00 | R + R TAILGATE LOCK PLATE | 2.0 | 8.40 |
| NO NUMBER | RENEW REAR CLOSING PANEL | 48.0 | 201.60 |
| 85875R00 | R + R L/R SILL MOULDING | 2.0 | 8.40 |
| 85875R0R | R + R R/R SILL MOULDING | 2.0 | 8.40 |
| 85850R00 | R + R L/UPPER C-PILLAR TRIM | 3.0 | 12.60 |
| 85850R0R | R + R R/UPPER C-PILLAR TRIM | 3.0 | 12.60 |
| 85770R00 | R + R REAR END PANEL TRIM | 2.0 | 8.40 |
| 85731R00) | R + R LEFT BOOT TRIM | 1.0 | 4.20 |
| 85731R0R) | R + R RIGHT BOOT TRIM | 1.0 | 4.20 |
| 85710R00 | R + R BOOT CARPET | 2.0 | 8.40 |
| 3151 | REMOVE AND REFIT REAR SCREEN | 20.0* | 84.00 |
| 3481 | REPAIR L/R SIDE PANEL | 5.0* | 21.00 |
| 3482 | REPAIR R/R SIDE PANEL | 5.0* | 21.00 |

Claim Reference:

Full Report - V1

Assessment Number: CSKD2785

Registration: SKD2785D

Version: LKKAUTOC/3

Printed: 11/01/2019 10:28

Date Calculated: 11/01/2019 02:25

| | | | |
|--------------------|--------------------------------------|---------|------------|
| 3900 | REPAIR BOOTFLOOR | 5.0* | 21.00 |
| LABOUR COST | | | |
| | Total Work Units | 144.0 | |
| | Corrosion Protection External Labour | 0.0HRS | 0.00 |
| | Corrosion Protection Internal Labour | 0.0HRS | 0.00 |
| | Sub Total | 14.4HRS | \$604.80 |
| | Paint Labour | 14.0HRS | \$588.00 |
| | Total Labour | 28.4HRS | \$1,192.80 |

| PAINT WORK | | Time Basis 10 WU = 1 HR. Price = \$42.00/HR | |
|------------------------------|--------------------------------------|---|-----------------|
| Guide Number | Description | WU | Cost Price (\$) |
| | - TWO COAT METALLIC | | |
| | - PREPARE OFF VEHICLE | | |
| 2640 | REAR BUMPER SUPPORT SURFACE PAINT | 4.0 | |
| 2711 | REAR PANEL NEW PART PAINTING | 16.0 | |
| 2931 | BOOTLID/TAILGATE NEW PART PAINTING | 15.0 | |
| 2583 | REAR BUMPER COVER NEW PART PAINT K1R | 13.0 | |
| 2985 | TRIM CPL NEW PART PAINT K1R | 3.0 | |
| 3481 | L/R SIDE PANEL REPAIR PAINTING >50% | 21.0 | |
| 3482 | R/R SIDE PANEL REPAIR PAINTING >50% | 21.0 | |
| 3900 | BOOTFLOOR SURFACE PAINT | 9.0 | |
| 3951 | L/BOOT FLOOR EXT SURFACE PAINT | 4.0 | |
| 3959 | CTR BOOT CROSSMEMBERSURFACE PAINT | 4.0 | |
| LABOUR COST - PAINT | | | |
| | TIME(PAINT) | 110.0 | |
| | Preparation Main Work Plastic | 5.0 | |
| | Preparation Main Work Metal | 25.0 | |
| | Preparation Work Multi Layer Paint | 0.0 | |
| | Total Work Units (10WU/HR) | 140.0 | |
| | Total Paintwork Labour | 14.0HRS | \$588.00 |
| MATERIAL COST - PAINT | | | Cost Price |
| | New Part Painting | | \$58.23 |
| | New Part Painting - Plastic K1R | | \$67.41 |
| | Material-Constant Main Work Metal | | \$28.60 |
| | Surface-/Blend Paint | | \$32.87 |
| | Repair Painting | | \$50.56 |
| | Material-Const Main Work Plastic | | \$9.00 |
| | Total Excluding Pearlescent Uplift | | \$246.67 |
| | Pearlescent Uplift @ 0.0% | | \$0.00 |
| | Total Paint Material Cost | | \$246.67 |

PARTS

| | | | | Price Valid: 01/06/2015 | |
|-----------|-----|--------------------|--------------|-------------------------|------------|
| Guide No. | Qty | Description | Part Number | Supplier | Price (\$) |
| 3020 | 1 | BADGE MODEL | 863102L300 | | 21.00* |
| 5009 | 1 | BOOT TRAY | 857502L510WK | | 140.00* |
| 2977 | 1 | BOOT/TAILGATE LOCK | 812302L200 | | 90.00* |
| 2944 | 1 | BOOT/TAILGATE SEAL | 873212L200 | | 55.00* |
| 2931 | 1 | BOOTLID/TAILGATE | 737002L220 | | 500.00* |
| 3167 | 2 | CLIP FASTENING | 871143K000 | | 0.00F |
| 5007 | 1 | L/BOOT TRAY | 857502L600WK | | 110.00* |
| 3281 | 1 | L/R LAMP ASSY | 924012L110 | | 190.00* |

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: CSKD2785

Registration: SKD2785D

Version: LKKAUTOC/3

Printed: 11/01/2019 10:28

Date Calculated: 11/01/2019 02:25

| | | | | | |
|---------------|---|----------------------|------------------|---------|-------------------|
| 4907 | 1 | LOWER TAILGATE TRIM | 817502L200WK | 0% | 130.00* |
| 3013 | 1 | MANUFACTURER BADGE | 86335H1020 | 0% | 25.00* |
| 5008 | 1 | R/BOOT TRAY | 857502L700WK | 0% | 110.00* |
| 3282 | 1 | R/R LAMP ASSY | 924022L110 | 0% | 190.00* |
| 2583 | 1 | REAR BUMPER COVER | 866102L310 | 0% | 200.00* |
| 2640 | 1 | REAR BUMPER SUPPORT | 866312L300 | 0% | 0.00F |
| 1000 | 1 | REAR BUMPER TOW CVR | Renew | 0% | 7.00* |
| 2644 | 1 | REAR IMPACT DAMPER | 866202L300 | 0% | 75.00* |
| 3015 | 1 | REAR MANUFACT BADGE | 863402L100 | 0% | 20.00* |
| 4985 | 1 | REAR OUTER PANELLING | 857702L500WK | 0% | 42.00* |
| 2711 | 1 | REAR PANEL | 691002L210 | 0% | 145.00* |
| 3160 | 1 | REAR SCREEN BOND KIT | KNGKW12 | 0% | 0.00F |
| 3163 | 1 | REAR SCREEN FIX SET | USE SINGLE PARTS | 0% | 0.00 |
| 3165 | 7 | REAR SCREEN SPACER | 861143D000 | 0% | 0.00F |
| 1000 | 1 | REINFORCEMENT | Renew | 0% | 125.00* |
| 2985 | 1 | TRIM CPL | 873702L300 | 0% | 50.00* |
| f: OEM Parts | | Saving | | | \$194.61 |
| g: Original | | Sub Total | | | \$2,225.00 |
| h: Secondhand | | Sundry Parts | | (Fixed) | \$100.00 |
| p: Parallel | | Total Parts | | | \$2,325.00 |
| x: Exchange | | | | | |

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

| Description | | Betterment | Price |
|---------------------|------------|------------|-----------------|
| REAR W/S GUM | SPECIALIST | 0% | \$40.00 |
| REAR NO. PLATE | SPECIALIST | | \$35.00 |
| 1SET REVERSE | SPECIALIST | 0% | \$200.00 |
| SENSOR | | | |
| Total Extras | | | \$275.00 |

Final Calculation

| | | |
|-----------------------------------|----------|-------------------|
| Total Parts | | \$2,325.00 |
| Labour | | |
| Total Panel/Mechanical | \$604.80 | |
| Total Paintwork | \$588.00 | |
| Total Labour | | \$1,192.80 |
| Additional Costs | | |
| Corr Prot Materials External | \$0.00 | |
| Corr Prot Materials Internal | \$0.00 | |
| Cost of Specialist | \$275.00 | |
| Total of Additional Costs | | \$275.00 |
| Total Paint/Material Costs | | \$246.67 |
| Grand Total Excludes GST | | \$4,039.47 |
| GST @ 7 % | | \$282.76 |
| Grand Total Includes GST | | \$4,322.23 |

Assessment Notes

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: CSKD2785

Registration: SKD2785D

Version: LKKAUTOC/3

Printed: 11/01/2019 10:28

Date Calculated: 11/01/2019 02:25

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 12 Sep 2018 Sendback Est | 12 Sep 2018 16:43 \$4,524.55 | 13 Sep 2018 11:18 Edit Adj Rpt | \$43,200.00 Edit Estimates | \$43,200.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS

| | | | |
|-----------------------------|---|------------------------|--|
| Insured: | TENG SHENG KOREAN CUISINE, Co. Reg. No.: 53119472L | | |
| Main Claimant: | TAN HEE BOEY DALVIN | | |
| Vehicle Reg. No.: | SKD2785D | Date of Loss: | 10/09/2018 19:00 - :59 [81 Months and 25 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / SNM18D04394C02 | Policy/Cover Note No.: | DMCVSN3022901800 |
| Vehicle Reg. No. (Insured): | GBH2014G | Policy No. (Claimant): | |
| | | Excess: | \$0.00 |
| Repairer: | Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/09/2018] | | |
| Driver/Custodian (Insured): | ZHANG BAOSHENG (/ Male), Tel: +6591117604 | | |
| Adj Asg. Remarks: | EST \$4841.27, CASE WITH SJE. | | |

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)




































There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

SKD2785D (SNM18D04394C02)
[GBH2014G]
TP
TAN HEE BOEY DALVIN
Sep 10 2018 7:00PM
[TENG SHENG KOREAN CUISINE]
Cheng Hoe Motor Pte Ltd

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 12/09/18 16:43 | Repairer Estimates |  Load HTML | |
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 11/01/19 11:11 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 11/01/19 11:11 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 11/01/19 11:11 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--|-------------------------------------|
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 35 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 11/01/19 11:15 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | Cheng Hoe Motor Pte Ltd (Yishun) | Thumbnail | Print |
| 1 | 12/09/18 16:40 | E-filed GIA report |  Load PDF | |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 13/09/18 11:17 | OI GIA |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured. | | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | | |
| Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016717/KSBE2

Date: 14/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3022901800

Claimant Vehicle
No: SKD2785DInsured Vehicle
No: GBH2014G

Date of Loss: 10/09/2018

Nature of Claim: TP

Claim
No: SNM18D04394C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD2785D

Make & Model: HYUNDAI 130, 1.6 (FD) DOHC (A)

Engine No: G4FCBU283329

Reg. Date: 16/11/2011 (Man. Year: 2011)

Chassis No: KMHDC81DMBU128582

Colour: Metallic Pearl White

Odometer: 117039 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 185/65R15

Rear Tyre Size:

185/65R15

Front Left Side: Michelin 8 mm

Rear Left Side:

Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side:

Michelin 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 2,225.00 | 2,225.00 | 0.00 | 0.00 |
| Miscellaneous Items | 675.00 | 375.00 | 300.00 | 44.44 |
| Labour | 1,624.55 | 1,439.47 | 185.08 | 11.39 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,524.55 | 4,039.47 | 485.08 | 10.72 |
| Approved Total (Overridden) (S\$) | | 3,200.00 | | |
| (S\$) | 4,524.55 | 3,200.00 | 1,324.55 | 29.27 |
| + GST 7.00/7.00% (S\$) | 316.72 | 224.00 | 92.72 | 29.28 |
| Nett Amount (S\$) | 4,841.27 | 3,424.00 | 1,417.27 | 29.27 |

INSPECTION

Date of Assignment: 13/09/2018 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 14/09/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 14 Jan 2019) |
| Parts: 143 | HYUNDAI 130 1.6 (FD) DOHC (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKD2785D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------|----------------|------------|-----------|
| 1 | 1 | NA | *BADGE MODEL | Necessary | 21.00 F | *21.00 F |
| 2 | 1 | NA | *BOOT TRAY | Dented/Cracked | 140.00 F | *140.00 F |
| 3 | 1 | NA | *BOOT/TAILGATE LOCK | Dented | 90.00 F | *90.00 F |
| 4 | 1 | NA | *BOOT/TAILGATE SEAL | Necessary | 55.00 F | *55.00 F |
| 5 | 1 | NA | *BOOTLID/TAILGATE | Bent | 500.00 F | *500.00 F |
| 6 | 1 | NA | *CLIP FASTENING (NPA) | Not Necessary | 0.00 F | *- F |
| 7 | 1 | NA | *L/BOOT TRAY | Dented | 110.00 F | *110.00 F |
| 8 | 1 | NA | *L/R LAMP ASSY | Cracked | 190.00 F | *190.00 F |
| 9 | 1 | NA | *LOWER TAILGATE TRIM | Distorted | 130.00 F | *130.00 F |
| 10 | 1 | NA | *MANUFACTURER BADGE | Necessary | 25.00 F | *25.00 F |
| 11 | 1 | NA | *R/BOOT TRAY | Cracked | 110.00 F | *110.00 F |
| 12 | 1 | NA | *R/R LAMP ASSY | Cracked | 190.00 F | *190.00 F |
| 13 | 1 | NA | *REAR BUMPER COVER | Buckled | 200.00 F | *200.00 F |
| 14 | 1 | NA | *REAR BUMPER SUPPORT (NPA) | Not Necessary | 0.00 F | *- F |
| 15 | 1 | NA | *REAR BUMPER TOW CVR | Dented | 7.00 F | *7.00 F |
| 16 | 1 | NA | *REAR IMPACT DAMPER | Cracked | 75.00 F | *75.00 F |
| 17 | 1 | NA | *REAR MANUFACT BADGE | Necessary | 20.00 F | *20.00 F |
| 18 | 1 | NA | *REAR OUTER PANELLING | Dented | 42.00 F | *42.00 F |
| 19 | 1 | NA | *REAR PANEL | Bent | 145.00 F | *145.00 F |
| 20 | 1 | NA | *REAR SCREEN BOND KIT (NPA) | Not Necessary | 0.00 F | *- F |
| 21 | 1 | NA | *REAR SCREEN FIX SET (NPA) | Not Necessary | 0.00 F | *- F |
| 22 | 1 | NA | *REAR SCREEN SPACER (NPA) | Not Necessary | 0.00 F | *- F |
| 23 | 1 | NA | *REINFORCEMENT | Cracked | 125.00 F | *125.00 F |
| 24 | 1 | NA | *TRIM CPL | Warped | 50.00 F | *50.00 F |

F=Franchise part.

| | | |
|--------------------------|-----------------|-----------------|
| Total Parts (S\$) | 2,225.00 | 2,225.00 |
|--------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|--------------------------------------|---------------|---------------|
| Miscellaneous Items | | | | |
| 1 | 1 | 1SET REVERSE CAMERA (Serviceable) | 300.00 | 0.00 |
| 2 | 1 | 1SET REVERSE SENSOR (Cracked) | 200.00 | 200.00 |
| 3 | 1 | REAR NO.PLATE (Bent) | 35.00 | 35.00 |
| 4 | 1 | REAR W/S GUM (Necessary) | 40.00 | 40.00 |
| 5 | 1 | SUNDRY PARTS (Necessary) | 100.00 | 100.00 |
| Sub Total (S\$) | | | 675.00 | 375.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|-------------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | Total Paint Labour | New | 621.60 | 588.00 |
| 2 | Total Paint Materials | New | 251.15 | 246.67 |
| 3 | Total Panel/Mechanical Labour | New | 751.80 | 604.80 |
| Gross Labour Cost (S\$) | | | 1,624.55 | 1,439.47 |

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >