

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 25 Sep 2018

Preliminary Advice

Vehicle No	: SLE1493K	Accident Date	: 30/08/2018
Make	: VOLKSWAGEN GOLF	Policy No.	: DMPCSN3078531701
Assignment Date	: 13/09/2018	Excess	: S\$1,000.00
Date of Inspection	: 18/09/2018	Est. Duration of Repair	: 10 days
Inspection At	: Chai Motor Workshop Sdn Bhd (HQ) No 3, Jalan Bertam 8, Taman Daya, 81100 Johor Bahru, Johor Darul Takzim		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	58,300.65
Revised Amount	:S\$	48,577.55
Check Items (Estimated)	:S\$	6,818.10
Total	:S\$	55,395.65

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	15,000.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,000.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST NOT EXCEEDING \$35,000.00 ON LUMP SUM BASIS.