

12/17/80

ASS. REC. BY:

REF: C/TPD18016728/Z

Special Instruction:

SUBJECT:

ASSIGNMENT (Office)

From (Person): Kamallah Kawi

of SPF

Date/Time: 13/9/2018

Estimated Cost:

Bill to:

OD/TP/WSTP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 1293U

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000000485

Claim No: TP/1P/51609/2018

Sum Insured:

Excess:

Make of Veh.
(Client's Record)

D.O.A 8/9/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SJX 1293U-X

530/9

⑥ SJX 1293 U

6 vehicles

Rohaizal (LKKAuto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Thursday, 13 September 2018 11:22 AM
To: Rohaizal (LKKAuto)
Cc: Bryan Ang (LKKAuto); SPF-TP FAIT
Subject: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 6 vehicles below:

a) a) Case IAFP-IB-20180911 - Mechanical Inspection of Motorcycle, JQP 6420 (TP/IP/49129/2018)

On 30 August 2018 (Thursday) at 7.37 a.m., the Deceased was riding his motorcycle with his pillion, his wife along Ayer Rajah Expressway towards Marine Coastal Expressway L/P 244 on lane 4 of 4 lanes, near L/P 244, the Deceased collided onto the rear of the Involved Party's motorcycle and lost control of his motorcycle. The Deceased was pronounced dead at scene at 7.57 a.m. by the attending paramedic, SS Yap.

Vehicle to be inspected: JQP 6420 – Rider (Deceased)

IO In-Charge: IO Clarence Lim

b) Case IAFP-IB-20180911 - Mechanical Inspection of Motorcycle, JRY 6722 (TP/IP/49129/2018)

On 30 August 2018 (Thursday) at 7.37 a.m., the Involved Party was riding along the said location on lane 4 of 4 lanes and traffic ahead on lane 4 were clear when he felt an impact on his rear. After the impact, the Involved Party saw a motorcycle on his right side very close to his motorcycle, almost touching the other motorcycle while the Involved Party was trying to prevent himself from falling. The Involved Party then lost control of his motorcycle and skidded. The Involved Party was also conveyed to National University Hospital by ambulance and he was conscious. He sustained abrasions and was discharged on the same day with 7 days of MC.

Vehicle to be inspected: JRY 6722 – Rider (Involved Party)

IO In-Charge: IO Clarence Lim

c) Case IAFP-IB-20180911 - Mechanical Inspection of Motor bus, PC 3156 J (TP/IP/48921/2018)

On 29 August 2018, sometime before 6.05 p.m., the Deceased was riding motorcycle along Pasir Panjang Road towards West Coast Highway while the Involved Party (driving motor bus PC 3156 J) was travelling on the opposite direction towards Telok Blangah Road. The Involved Party made a right turn at the junction of Harbour Drive, resulting in a collision (head to side) with the Deceased, who was travelling straight.

Vehicle to be inspected: PC 3156 J - Driver (Involved Party)

IO In-Charge: SIO Farhan

d) Case IAFP-IB-20180911 - Mechanical Inspection of Tipper Truck, XE 694 L (TP/IP/48837/2018)

On 29 August 2018, the involved Party driving tipper truck (XE 694 L) along the compound of a company (HSC Pipeline Engineering Pte Ltd) of unit number 36. Upon reaching the exit of the unit, the truck stopped to give way for vehicles along Sungei Kadut Avenue to clear. As the truck moved forward, the Deceased cycled in front of the truck from the left to right of the driver's perspective. The Deceased was hit and believed to been run over by the front right tyre of the tipper truck.

Vehicle to be inspected: XE 694 L - Driver (Involved Party)

IO In-Charge: SIO Farhan

- e) **Case IAFP-IB-20180911 - Mechanical Inspection of Motorcycle, FBA 2368 Y (TP/IP/51609/2018)**
- f) **Case IAFP-IB-20180911 - Mechanical Inspection of Motor Car, SJX1293U (TP/IP/51609/2018)**

On 8 September 2018 (Saturday) at about 2.12 p.m., it was revealed that the Deceased was travelling ahead of the Witness and they were on their way to Johor Bahru, Malaysia. While travelling along BKE (Woodlands) near the 9.5 km marker, on lane 1 of the 3 lanes road, the Deceased collided into the rear portion of the Involved Party's motor car. Due to the collision, the Deceased and his motorcycle fell to the left and landed in between lanes 1 and 2. As a result of the accident, the Deceased was conveyed in a critical condition to Khoo Teck Puat Hospital. On the same day at 3.24 p.m., the Deceased succumbed to his injuries and was pronounced dead by Dr Yuen in the said hospital.

Vehicles to be inspected: Motorcycle, FBA 2368 Y - Rider (Deceased)

Vehicles to be inspected: Motor Car, SJX1293U - Driver (Involved Party)

IO In-Charge: IO Kamaliah

- 2. These request has been approved by my management.
- 3. Thank you Sirs.

Cc: Bryan Ang (LKK) & FAIT Team, fyip

Best regards,

Kamaliah Kamis (Miss)
Investigation Officer | Fatal Accident Investigation Team
Traffic Police | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."