

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9547A**AAD1809-078***Not Auth'd**11 Sep 819506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9547A

KL1LA69RJB123834

CHEVROLET

EPICA 2.0

10.9.2018

*Ath.***PART****LIST**

1	1	Rear Bumper	\$	<i>Bu</i>	1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>Bu</i>	239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i>	260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>Sn</i>	68.76	X
5	1	Rear Bumper Side Retainer LH	\$	<i>cm</i>	68.76	✓
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i>	119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>Bu</i>	119.74	✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i>	93.00	} X
9	1	Rear End Panel Outer	\$	<i>R</i>	623.76	
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i>	263.84	
11	1	Rear Luggage Floor Panel	\$	<i>R</i>	973.00	
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i>	63.50	
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i>	378.00	
14	1	Bootlid	\$	<i>R</i>	973.00	
15	1	Bootlid inner trim board	\$	<i>Sn</i>	400.00	
16	1	Bootlid Weatherstrip	\$	<i>Sn</i>	344.28	
17	1	Bootlid Lock - Top	\$	<i>R</i>	466.56	
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>ra</i>	120.62	} X
19	1	Bootlid Logo	\$	<i>ra</i>	138.84	
20	1	Bootlid 'EPICA LT' Badge	\$	<i>ra</i>	119.84	
21	1	Bootlid Reflector Centre	\$	<i>Sn</i>	217.97	
22	1	Bootlid Reflector RH	\$	<i>Sn</i>	128.40	
23	1	Bootlid Reflector LH	\$	<i>Sn</i>	128.40	
24	1	Rear Tail Lamp RH	\$	<i>Sn</i>	479.30	
25	1	Rear Tail Lamp LH	\$	<i>cm</i>	479.30	✓
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i>	1,110.00	X
27	1	Rear Fender RH	\$	<i>R</i>	1,145.00	X
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i>	418.44	X
29	1	Rear Fender LH	\$	<i>R</i>	1,145.00	X

Trans-cab Auto Services Pte Ltd**AAD1809-078**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9547A

30	1	Rear Fender Inner Trim LH	\$	sn 418.44X
----	---	---------------------------	----	------------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	sn 40.00 X
2	1Set	Rear Bumper Parking Sensor	\$	sn 300.00 X
3	1Set	Rear Bumper Fastener Clip	\$	na 44.00 ✓
4	1Set	Rear Fender Inner Trim Clip LH	\$	na 30.00
5	1Set	Rear Bumper End Dust Cover Clip	\$	na 30.00
6	1	Rear Exhaust Mounting	\$	sn 300.00
7	2	Rear Windscreen Sealant	\$	na 80.00
8	1	Rear Windscreen Inner Sponge Seal	\$	na 100.00
9	1	Spare Tyre	\$	sn 180.00
10	1	Spare Wheel Rim	\$	sn 126.74
11	1	Rear boot sticker 'Trans-cab'	\$	na 80.00
12	1	Rear boot sticker '6555-3333'	\$	na 80.00

TOTAL	\$	1,390.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,827.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	2001
----	----------	------

To Check Electrical Lighting Concerned.

\$	170.00	201
----	--------	-----

To Rust-Proofing Of The Affected Areas.

\$	na 170.00	X
----	-----------	---

Putty And Spray Painting Of The Affected Portion.

\$	3,000.00	2001
----	----------	------

To reinstall rear bumper parking sensor.

\$	170.00	601
----	--------	-----

Trans-cab Auto Services Pte Ltd**AAD1809-078**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9547A

To transfer of end panel fittings and conduct
water seepage test. \$ *nn* 170.00 X

To transfer of boot fittings and conduct water
seepage test. \$ *nn* 170.00 X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 X

\$ **7,950.00**

TOTAL \$ 20,777.43

Repair Days (LUMP SUM)~~10 DAYS~~*2 day,*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: