

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 572P**AAD1809-093**

Not Authored
11 Supp @ 6050/-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 572P

VF1ABL15AUC278385

RENAULT

LATITUDE

10.9.2018

AIG**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Br</i> 1,108.46	✓
\$	<i>Br</i> 768.84	✓
\$	<i>Sn</i> 113.47	X
\$	<i>Sn</i> 135.97	X
\$	<i>Sn</i> 44.99	X
\$	<i>Sn</i> 43.61	X
\$	<i>Sn</i> 135.97	X
\$	<i>Sn</i> 44.99	X
\$	<i>Sn</i> 43.61	X
\$	<i>Br</i> 777.52	✓
\$	<i>R</i> 225.95	X
\$	<i>R</i> 225.95	X
\$	<i>Br</i> 2,872.68	✓
\$	<i>Sn</i> 470.06	X
\$	<i>Sn</i> 323.05	X
\$	<i>Sn</i> 493.35	X
\$	<i>Sn</i> 493.35	X
\$	<i>Br</i> 225.36	✓
\$	<i>Br</i> 225.36	✓
\$	<i>Sn</i> 276.08	} X
\$	<i>Sn</i> 276.08	
\$	<i>R</i> 367.84	
\$	<i>R</i> 367.84	
\$	<i>Sn</i> 586.45	
\$	<i>Sn</i> 168.13	
\$	<i>R</i> 202.67	
\$	<i>R</i> 74.40	
\$	<i>Sn</i> 50.52	
\$	<i>Sn</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1809-093**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 572P

30	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
31	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
32	1	WHEELARCH REAR RH	\$	Sm	543.47	X
33	1	TAILLAMP RH	\$	ngun Sm	552.55	X
34	1	TAILLAMP PANEL RH	\$	R	986.70	X
35	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	X
36	1	OUTER PANEL REAR (End Panel)TRIM	\$	nc	404.56	X
37	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
38	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
39	1	EXHAUST REAR	\$	R	7,489.05	X
40	1	EXHAUST CAP REAR	\$	Sm	230.49	X
41	1	WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	X
42	1	CHASSIS PANEL REAR RH L70Y	\$	R	3,766.43	X

TOTAL	\$	38,264.16
10%	\$	3,826.42
	\$	34,437.74

Specical Nett

1	1SET	PARKING AID	\$	Sm	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nc	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nc	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	nc	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	nc	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	nc	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X

Trans-cab Auto Services Pte Ltd**AAD1809-093**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 572P

18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 X
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 X
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00 ✓
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 X
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 X
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00 X
25	1 SPARE TYRE	\$	<i>sn</i> 330.00 X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 36,662.76****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>500</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>400</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>300</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>600</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>600</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1809-093**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 572P

To supply and re-do rear luggage floor panel insulation padding.

\$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X**TOTAL \$ 12,540.00****Over All Total \$ 49,202.76****(LUMP SUM)****Repair Days**~~20 DAYS~~*2 1/2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: