

22/03/2007

ASS. REC. BY:

REF:

CS/FCL18016744/Kvbz

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of

FCL

Date/Time: 13/09/2018 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 199U

Insured:

SHA 2136D

at Workshop m/s

Trans Cab

Tel:

of

No. 2 AMK S1 63

Policy No:

Claim No:

D18006788MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

14.09.2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate            |
|-----------|--------------------------------------------|
|           | SHD 199U - CS / AXA 16011999 / K2b352      |
|           | SHA 2136D - X                              |
|           |                                            |
| 17/9/18   | Email preli revised to FCI                 |
| 25/10/18  | Final fig \$ 6177.90 (Red 31,543.73, 8490) |

DLA: 250616

REF: FA

## ASSIGNMENT

From:

Date:

14092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHD 199U

at Workshop n/s

Trans Cab

of

No. 2 Amk St 63

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.21

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 199U

Yr Regn:

03 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

C.C.

1995

Colour:

m White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

361993

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 282378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/19/18

D.O.I.

14/19/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

ols body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/9 File pass to Carman

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

25/10 - typist

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

CWS

Lump Sum / I.B.I. (\$

6177.90

Survey Fee:

Transportation:

S + RS: SI

Photos:

Others:

27x15 = 405

170 + 405

50

50

16

TOTAL

25/10/18

691



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006788MFSH

Our ref: CS/FCI18016744/Kvb

Date : 17/9/2018

The Motor Claims Department  
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 199U**


We thank for your instruction on 13/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/9/2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

|                          |                |
|--------------------------|----------------|
| Workshop Estimate Amount | : S\$37,721.63 |
| Revised Estimate Amount  | : S\$6,177.90  |
| "Check" Items Amount     | : S\$          |
| Market Value             | : S\$          |
| LTA Reimbursement Value  | : S\$          |
| Nett Value               | : S\$          |

**Description of Damage:**

The vehicle sustained damages at the o/s body



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

Kenneth Kong  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                           |                              |                                     |
|---------------------------|------------------------------|-------------------------------------|
| <b>Date</b>               | 13-09-2018                   | <b>Our Ref No.</b> D18006788MFSH    |
| <b>Accident Date</b>      | 12-09-2018                   | <b>Claim Type.</b> Third Party      |
| <b>Insured Vehicle</b>    | SHA2136D                     | <b>Third Party Vehicle.</b> SHD199U |
| <b>Survey Location</b>    | NO. 2 ANG MO KIO STREET 63   |                                     |
| <b>Contact Person.</b>    | CANDY KONG                   |                                     |
| <b>Contact No.</b>        | 62876666/ 0                  | <b>Fax No.</b> 62571330             |
| <b>Survey Type</b>        | WITHOUT PREJUDICE:           |                                     |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD |                                     |
| <b>Contact Person</b>     | NA                           | <b>Fax No.</b> 68416315             |
| <b>Contact Number.</b>    | NA                           |                                     |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                 |                                |
|--------------------------|---------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | TRANS-CAB AUTO SERVICES PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                              | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | KARENT                          |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 17 September 2018 2:42 PM  
**To:** 'Claim Workflow System'  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18006788MFSH/1, SHD 199U  
**Attachments:** SHD 199U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 199U  
Date of survey: 14/9/2018  
Number of days : 5 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 13 September 2018 4:43 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18006788MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 13 September, 2018 4:06 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); KARENTAN@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18006788MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note:** All the accident reports are uploaded into CWS for your perusal.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 25 October 2018 11:08 AM  
**To:** 'Ng Wai Yin'; 'calvin.er'  
**Cc:** jasminetan@transcab.com.sg; SUR  
**Subject:** SHD 199U-DOA: 12/9/2018 (FIRST CAPITAL TP)  
**Attachments:** MARKING.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Please submit \$6177.90 before GST @ 5 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHD199U

Vehicle to be Exported: Yes

Intended Deregistration Date: 12 Sep 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002956

Chassis No.: VF1ABL15AUC282378

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 22 Mar 2016

First Registration Date: 22 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Mar 2024

PARF Rebate Amount: \$14,998.00

**Intended COE Rebate Details**

COE Expiry Date: 21 Mar 2024

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$39,633.00

COE Rebate Amount: \$27,367.00

**Total Rebate Amount: \$42,365.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Sep 2018

OK

**Trans-cab Auto Services Pte Ltd**

AAD1809-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD 199U**

*Not Notarised*  
*Resurvey Bk paint* \$6177.90

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

**SHD 199U**

VF1ABL15AUC282378

RENAULT

LATITUDE

12.9.2018

**FCIL**

| PART |                              | LIST |               |
|------|------------------------------|------|---------------|
| 1    | FENDER PANEL FRT RH          | \$   | R 783.83 X    |
| 1    | WHEELARCH FRT RH             | \$   | Sn 278.84 X   |
| 1    | FENDER BRACKET LOWER RH      | \$   | Sn 15.79 X    |
| 1    | FENDER INSULATOR RH          | \$   | Sn 130.84 X   |
| 1    | DOOR PANEL FRT RH            | \$   | B 2,844.66 ✓  |
| 1    | DOOR HINGE UPPER RH          | \$   | R 261.28      |
| 1    | DOOR HINGE LOWER RH          | \$   | R 300.55      |
| 1    | DOOR CHECK FRT RH            | \$   | Sn 194.77 } X |
| 1    | DOOR LOCK FRT RH             | \$   | R 908.75      |
| 1    | DOOR CATCH FRT RH            | \$   | R 131.23      |
| 1    | DOOR HANDLE OUTER FRT RH     | \$   | Sn 477.76     |
| 1    | DOOR HANDLE COVER FRT RH     | \$   | Sn 13.22      |
| 1    | DOOR HANDLE MODULE FRT RH    | \$   | Sn 133.60     |
| 1    | DOOR REGULATOR FRT RH        | \$   | R 505.19 ✓    |
| 1    | DOOR REGULATOR MOTOR FRT RH  | \$   | Sn 796.46 ✓   |
| 1    | DOOR REGULATOR GUIDE FRT RH  | \$   | Sn 120.97     |
| 1    | DOOR PANEL REAR RH           | \$   | R 2,844.66    |
| 1    | DOOR GUIDE REAR RH           | \$   | Sn 176.82     |
| 1    | DOOR HINGE UPPER RH          | \$   | R 274.50      |
| 1    | DOOR HINGE LOWER RH          | \$   | R 300.55      |
| 1    | DOOR CHECK REAR LH/RH L70Y   | \$   | Sn 203.06 } X |
| 1    | DOOR LOCK REAR RH            | \$   | R 908.75      |
| 1    | DOOR HANDLE OUTER REAR RH    | \$   | Sn 126.49     |
| 1    | DOOR HANDLE CAP REAR RH      | \$   | Sn 35.52      |
| 1    | DOOR HANDLE SEAL REAR RH     | \$   | Sn 7.89       |
| 1    | DOOR HANDLE COVER REAR RH    | \$   | Sn 13.22      |
| 1    | DOOR HANDLE MODULE REAR RH   | \$   | Sn 133.60     |
| 1    | DOOR REGULATOR REAR RH       | \$   | R 1,135.10    |
| 1    | DOOR REGULATOR MOTOR REAR RH | \$   | Sn 893.75     |
| 1    | DOOR REGULATOR NUT REAR L70Y | \$   | Sn 12.43      |

**Trans-cab Auto Services Pte Ltd****AAD1809-111**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 199U**

|   |                                      |    |          |   |   |
|---|--------------------------------------|----|----------|---|---|
| 1 | DOOR REGULATOR MOTOR SCREW REAR L70Y | \$ | 6.31     | } | X |
| 1 | DOOR FINISHER REAR RH                | \$ | 423.10   |   |   |
| 1 | DOOR MOULDING REAR RH                | \$ | 176.82   |   |   |
| 1 | DOOR MOULDING CLIP L70Y              | \$ | 5.92     |   |   |
| 1 | DOOR MOULDING SCREW L70Y             | \$ | 6.91     |   |   |
| 1 | DOOR CASING REAR RH                  | \$ | 1,509.06 |   |   |
| 1 | DOOR WATER SHIELD REAR RH            | \$ | 30.39    |   |   |
| 1 | DOOR CASING CLIP                     | \$ | 12.63    |   |   |
| 1 | DOOR CASING LIGHT L70Y               | \$ | 48.74    |   |   |
| 1 | DOOR FINISHER INNER REAR RH          | \$ | 323.44   |   |   |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | 46.97    |   |   |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | 20.33    |   |   |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | 20.33    |   |   |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | 20.33    |   |   |
| 1 | DOOR GRAB HANDLE REAR RH             | \$ | 210.96   |   |   |
| 1 | DOOR BLIND REAR RH                   | \$ | 741.80   |   |   |
| 1 | DOOR WHEATHESTRIIP REAR RH           | \$ | 410.66   |   |   |
| 1 | DOOR SEAL REAR RH                    | \$ | 162.02   |   |   |
| 1 | DOOR GLASS RUNNER SEAL REAR RH       | \$ | 229.31   |   |   |
| 1 | DOOR WAIST SEAL OUTER REAR RH        | \$ | 334.69   |   |   |
| 1 | DOOR WAIST SEAL INNER REAR RH        | \$ | 115.64   |   |   |
| 1 | FENDER PANEL REAR RH                 | \$ | 3,299.13 | } | X |
| 1 | FENDER PANEL INNER TRIM REAR         | \$ | 671.45   |   |   |
| 1 | WHEELARCH REAR RH                    | \$ | 543.47   |   |   |
| 1 | DOOR MIRROR ASSY RH                  | \$ | 1,483.40 |   |   |
| 1 | ROCKER PANEL INNER GARNISH RH        | \$ | 466.51   | } | X |
| 1 | ROCKER PANEL INNER RH                | \$ | 1,024.79 |   |   |
| 1 | ROCKER PANEL CENTER RH               | \$ | 990.25   |   |   |

|    |                  |
|----|------------------|
| \$ | <b>28,299.44</b> |
|----|------------------|

|        |                 |
|--------|-----------------|
| 10% \$ | <b>2,829.94</b> |
|--------|-----------------|

|    |                  |
|----|------------------|
| \$ | <b>25,469.50</b> |
|----|------------------|

**Specical Nett**

|      |                               |    |       |   |
|------|-------------------------------|----|-------|---|
| 1SET | FRAME FULL SUPPORT PANEL CLIP | \$ | 70.00 | X |
| 2    | FRAME FULL SUPPORT PANEL NUT  | \$ | 20.00 | X |
| 2    | FRAME FULL SUPPORT PANEL STUD | \$ | 30.00 | X |

**Trans-cab Auto Services Pte Ltd**

AAD1809-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 199U**

|                    |                                |           |                              |
|--------------------|--------------------------------|-----------|------------------------------|
| 1SET               | WHEELARCH CLIP FRT LH          | \$        | <i>un</i> 30.50 <i>X</i>     |
| 1                  | FRONT DOOR STICKER 'Trans-cab' | \$        | <i>un</i> 80.00 <i>6000</i>  |
| 1                  | FRONT DOOR STICKER 'Chassis'   | \$        | <i>un</i> 300.00 <i>1500</i> |
| 1                  | DOOR CHECK BOLT                | \$        | <i>sn</i> 22.69              |
| 1                  | DOOR GUIDE SCREW               | \$        | <i>sn</i> 10.85              |
| 1                  | DOOR HINGE BOLT                | \$        | <i>sn</i> 10.85              |
| 1                  | DOOR HINGE NUT RH              | \$        | <i>sn</i> 14.60              |
| 1                  | DOOR CHECK BOLT                | \$        | <i>sn</i> 22.69              |
| 1                  | DOOR CHECK NUT                 | \$        | <i>sn</i> 3.75               |
| 1                  | DOOR LOCK SCREW L70Y           | \$        | <i>sn</i> 6.12               |
| 1                  | DOOR CATCH SCREW L70Y          | \$        | <i>sn</i> 10.06              |
|                    |                                |           | <i>11</i>                    |
| <b>TOTAL</b>       |                                | <b>\$</b> | <b>632.13</b>                |
| <b>TOTAL PARTS</b> |                                | <b>\$</b> | <b>26,101.63</b>             |

**LABOUR**

|                                                                                                                           |    |                           |
|---------------------------------------------------------------------------------------------------------------------------|----|---------------------------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,500.00 <i>6000</i>      |
| Putty and spray painting of the affected portion.                                                                         | \$ | 4,200.00 <i>6600</i>      |
| To rust-proofing of the affected areas.                                                                                   | \$ | 170.00 <i>600</i>         |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00 <i>800</i>         |
| To check steering geometry and computer wheel alignment                                                                   | \$ | <i>un</i> 220.00 <i>X</i> |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | <i>un</i> 170.00 <i>X</i> |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00 <i>200</i>         |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | <i>un</i> 380.00 <i>X</i> |

**Trans-cab Auto Services Pte Ltd**

AAD1809-111

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 199U

|                                                                                                                     |    |        |      |
|---------------------------------------------------------------------------------------------------------------------|----|--------|------|
| To transfer of front door fittings, attachment and perform water seepage test.                                      | \$ | 380.00 | 602  |
| To dismantle advertisement sticker                                                                                  | \$ | 170.00 | nn X |
| Towing Fees.                                                                                                        | \$ | 120.00 | nn X |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. | \$ | 380.00 | nn X |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                     | \$ | 380.00 | nn X |

**TOTAL \$ 11,620.00****Over All Total \$ 37,721.63**

61

**PART-BY-PART (REPAIR DAY)****15 DAYS**

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                              |                            |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|--|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                              | Ref : CS/FCI18016744/Kvbn2 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                              | Date : 30-10-2018          |  |  |
|                                                                                                                                                                                        |                                                                              | Code : FCI2                |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                              |                            |                                                                                     |  |
| Insured Veh.                                                                                                                                                                           | SHA 2136D                                                                    | Veh. Inspected             | SHD 199U                                                                            |  |
| Policy No.                                                                                                                                                                             |                                                                              | Coverage (\$)              | 0.00                                                                                |  |
| Claim No.                                                                                                                                                                              | D18006788MFSH                                                                | Excess (\$)                | 0.00                                                                                |  |
| Assign From                                                                                                                                                                            | KARENT                                                                       | Assign Date                | 13/09/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                              |                            |                                                                                     |  |
| Make & Model                                                                                                                                                                           | RENAULT LATITUDE (A)                                                         | c.c                        | 1995                                                                                |  |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                       | Year of Reg.               | 2016                                                                                |  |
| Chassis No.                                                                                                                                                                            | VF1ABL15AUC282378                                                            | Colour                     | METALLIC WHITE / RED                                                                |  |
| Odometer                                                                                                                                                                               | 361993                                                                       | Steering                   | IN ORDER                                                                            |  |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                     | Modification               | NIL                                                                                 |  |
| General                                                                                                                                                                                | GOOD                                                                         |                            |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                              |                            |                                                                                     |  |
|                                                                                                                                                                                        | Size                                                                         | Make                       | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                   | GITI                       | 7 mm                                                                                |  |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                   | GITI                       | 7 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                   | GITI                       | 7 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                   | GITI                       | 7 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                              |                            |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.                                                                                                                                         |                                                                              |                            |                                                                                     |  |
| DAMAGES SEE DETAILS.                                                                                                                                                                   |                                                                              |                            |                                                                                     |  |
| <b>5. General Information</b>                                                                                                                                                          |                                                                              |                            |                                                                                     |  |
| Accident Date                                                                                                                                                                          | 12/09/2018                                                                   | Inspection Date            | 14/09/2018                                                                          |  |
| Survey held at                                                                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                            |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                              |                            |                                                                                     |  |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                            |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                              |                            |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                              | 5 Working Days             |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 199U

| Qty                         | Description of Parts        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                             |                      |                           |                   |
| 1                           | FENDER PANEL FRT RH         | TO REPAIR SEE LABOUR | 783.83                    | -                 |
| 1                           | WHEELARCH FRT RH            | SERVICEABLE          | 278.84                    | -                 |
| 1                           | FENDER BRACKET LOWER RH     | SERVICEABLE          | 15.79                     | -                 |
| 1                           | FENDER INSULATOR RH         | SERVICEABLE          | 130.84                    | -                 |
| 1                           | DOOR PANEL FRT RH           | BENT                 | 2,844.66                  | 2,844.66          |
| 1                           | DOOR HINGE UPPER RH         | TO REPAIR SEE LABOUR | 261.28                    | -                 |
| 1                           | DOOR HINGE LOWER RH         | TO REPAIR SEE LABOUR | 300.55                    | -                 |
| 1                           | DOOR CHECK FRT RH           | SERVICEABLE          | 194.77                    | -                 |
| 1                           | DOOR LOCK FRT RH            | TO REPAIR SEE LABOUR | 908.75                    | -                 |
| 1                           | DOOR CATCH FRT RH           | TO REPAIR SEE LABOUR | 131.23                    | -                 |
| 1                           | DOOR HANDLE OUTER FRT RH    | SERVICEABLE          | 477.76                    | -                 |
| 1                           | DOOR HANDLE COVER FRT RH    | SERVICEABLE          | 13.22                     | -                 |
| 1                           | DOOR HANDLE MODULE FRT RH   | SERVICEABLE          | 133.60                    | -                 |
| 1                           | DOOR REGULATOR FRT RH       | BENT                 | 505.19                    | 505.19            |
| 1                           | DOOR REGULATOR MOTOR FRT RH | JAMMED               | 796.46                    | 796.46            |
| 1                           | DOOR REGULATOR GUIDE FRT RH | SERVICEABLE          | 120.97                    | -                 |
| 1                           | DOOR PANEL REAR RH          | TO REPAIR SEE LABOUR | 2,844.66                  | -                 |
| 1                           | DOOR GUIDE REAR RH          | SERVICEABLE          | 176.82                    | -                 |
| 1                           | DOOR HINGE UPPER RH         | TO REPAIR SEE LABOUR | 274.50                    | -                 |
| 1                           | DOOR HINGE LOWER RH         | TO REPAIR SEE LABOUR | 300.55                    | -                 |
| 1                           | DOOR CHECK REAR LH/RH L70Y  | SERVICEABLE          | 203.06                    | -                 |
| 1                           | DOOR LOCK REAR RH           | TO REPAIR SEE LABOUR | 908.75                    | -                 |
| 1                           | DOOR HANDLE OUTER REAR RH   | SERVICEABLE          | 126.49                    | -                 |
| 1                           | DOOR HANDLE CAP REAR RH     | SERVICEABLE          | 35.52                     | -                 |
| 1                           | DOOR HANDLE SEAL REAR RH    | SERVICEABLE          | 7.89                      | -                 |

Report Ref No. CS/FCI18016744/Kvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

| Qty | Description of Parts                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|----------------------|---------------------------|-------------------|
| 1   | DOOR HANDLE COVER REAR RH            | SERVICEABLE          | 13.22                     | -                 |
| 1   | DOOR HANDLE MODULE REAR RH           | SERVICEABLE          | 133.60                    | -                 |
| 1   | DOOR REGULATOR REAR RH               | TO REPAIR SEE LABOUR | 1,135.10                  | -                 |
| 1   | DOOR REGULATOR MOTOR REAR RH         | SERVICEABLE          | 893.75                    | -                 |
| 1   | DOOR REGULATOR NUT REAR L70Y         | SERVICEABLE          | 12.43                     | -                 |
| 1   | DOOR REGULATOR MOTOR SCREW REAR L70Y | SERVICEABLE          | 6.31                      | -                 |
| 1   | DOOR FINISHER REAR RH                | SERVICEABLE          | 423.10                    | -                 |
| 1   | DOOR MOULDING REAR RH                | SERVICEABLE          | 176.82                    | -                 |
| 1   | DOOR MOULDING CLIP L70Y              | NOT NECESSARY        | 5.92                      | -                 |
| 1   | DOOR MOULDING SCREW L70Y             | NOT NECESSARY        | 6.91                      | -                 |
| 1   | DOOR CASING REAR RH                  | SERVICEABLE          | 1,509.06                  | -                 |
| 1   | DOOR WATER SHIELD REAR RH            | SERVICEABLE          | 30.39                     | -                 |
| 1   | DOOR CASING CLIP                     | NOT NECESSARY        | 12.63                     | -                 |
| 1   | DOOR CASING LIGHT L70Y               | SERVICEABLE          | 48.74                     | -                 |
| 1   | DOOR FINISHER INNER REAR RH          | SERVICEABLE          | 323.44                    | -                 |
| 1   | DOOR FINISHER BRACKET INNER REAR RH  | TO REPAIR SEE LABOUR | 46.97                     | -                 |
| 1   | DOOR FINISHER BRACKET INNER REAR RH  | TO REPAIR SEE LABOUR | 20.33                     | -                 |
| 1   | DOOR FINISHER BRACKET INNER REAR RH  | TO REPAIR SEE LABOUR | 20.33                     | -                 |
| 1   | DOOR FINISHER BRACKET INNER REAR RH  | TO REPAIR SEE LABOUR | 20.33                     | -                 |
| 1   | DOOR GRAB HANDLE REAR RH             | SERVICEABLE          | 210.96                    | -                 |
| 1   | DOOR BLIND REAR RH                   | SERVICEABLE          | 741.80                    | -                 |
| 1   | DOOR WEATHERSTRIP REAR RH            | SERVICEABLE          | 410.66                    | -                 |
| 1   | DOOR SEAL REAR RH                    | SERVICEABLE          | 162.02                    | -                 |
| 1   | DOOR GLASS RUNNER SEAL REAR RH       | SERVICEABLE          | 229.31                    | -                 |
| 1   | DOOR WAIST SEAL OUTER REAR RH        | SERVICEABLE          | 334.69                    | -                 |
| 1   | DOOR WAIST SEAL INNER REAR RH        | SERVICEABLE          | 115.64                    | -                 |
| 1   | FENDER PANEL REAR RH                 | TO REPAIR SEE LABOUR | 3,299.13                  | -                 |
| 1   | FENDER PANEL INNER TRIM REAR         | SERVICEABLE          | 671.45                    | -                 |
| 1   | WHEELARCH REAR RH                    | SERVICEABLE          | 543.47                    | -                 |

Report Ref No. CS/FCI18016744/Kvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts                                                                                                                                                                                                                                                                                                | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | DOOR MIRROR ASSY RH                                                                                                                                                                                                                                                                                                 | SERVICEABLE          | 1,483.40                  | -                 |
| 1   | ROCKER PANEL INNER GARNISH RH                                                                                                                                                                                                                                                                                       | SERVICEABLE          | 466.51                    | -                 |
| 1   | ROCKER PANEL INNER RH                                                                                                                                                                                                                                                                                               | TO REPAIR SEE LABOUR | 1,024.79                  | -                 |
| 1   | ROCKER PANEL CENTER RH                                                                                                                                                                                                                                                                                              | BENT                 | 990.25                    | 990.25            |
|     | LESS 10% DISCOUNT                                                                                                                                                                                                                                                                                                   |                      | -2,829.94                 | -513.66           |
|     |                                                                                                                                                                                                                                                                                                                     |                      | 25,469.50                 | 4,622.90          |
|     | <b>SPECIAL NETT ITEMS</b>                                                                                                                                                                                                                                                                                           |                      |                           |                   |
| 1   | SET FRAME FULL SUPPORT PANEL CLIP (SN)                                                                                                                                                                                                                                                                              | NOT NECESSARY        | 70.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL NUT (SN)                                                                                                                                                                                                                                                                                   | NOT NECESSARY        | 20.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL STUD (SN)                                                                                                                                                                                                                                                                                  | NOT NECESSARY        | 30.00                     | -                 |
| 1   | SET WHEELARCH CLIP FRT LH (SN)                                                                                                                                                                                                                                                                                      | NOT NECESSARY        | 30.50                     | -                 |
| 1   | FRONT DOOR STICKER "TRANS-CAB" (SN)                                                                                                                                                                                                                                                                                 | NECESSARY            | 80.00                     | 60.00             |
| 1   | FRONT DOOR STICKER "CHASSIS" (SN)                                                                                                                                                                                                                                                                                   | NECESSARY            | 300.00                    | 15.00             |
| 1   | DOOR CHECK BOLT (SN)                                                                                                                                                                                                                                                                                                | SERVICEABLE          | 22.69                     | -                 |
| 1   | DOOR GUIDE SCREW (SN)                                                                                                                                                                                                                                                                                               | SERVICEABLE          | 10.85                     | -                 |
| 1   | DOOR HINGE BOLT (SN)                                                                                                                                                                                                                                                                                                | SERVICEABLE          | 10.85                     | -                 |
| 1   | DOOR HINGE NUT RH (SN)                                                                                                                                                                                                                                                                                              | SERVICEABLE          | 14.60                     | -                 |
| 1   | DOOR CHECK BOLT (SN)                                                                                                                                                                                                                                                                                                | SERVICEABLE          | 22.69                     | -                 |
| 1   | DOOR CHECK NUT (SN)                                                                                                                                                                                                                                                                                                 | SERVICEABLE          | 3.75                      | -                 |
| 1   | DOOR LOCK SCREW L70Y (SN)                                                                                                                                                                                                                                                                                           | SERVICEABLE          | 6.12                      | -                 |
| 1   | DOOR CATCH SCREW L70Y (SN)                                                                                                                                                                                                                                                                                          | SERVICEABLE          | 10.06                     | -                 |
|     |                                                                                                                                                                                                                                                                                                                     |                      | 632.11                    | 75.00             |
|     | <b>LABOUR</b>                                                                                                                                                                                                                                                                                                       |                      |                           |                   |
|     | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }                                                                                                                                                                                           |                      | 4,500.00                  | 600.00            |
|     | INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK FRT RH,DOOR CATCH FRT RH,DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK REAR RH,DOOR REGULATOR REAR RH,DOOR FINISHER BRACKET INNER REAR RH,FENDER PANEL REAR RH AND ROCKER PANEL INNER RH. } |                      | -                         | -                 |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty | Description of Parts                                                                                                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                   |               | 4,200.00                  | 660.00            |
|     | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                             |               | 170.00                    | 60.00             |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.                     |               | 380.00                    | 80.00             |
|     | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                            | NOT NECESSARY | 220.00                    | -                 |
|     | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.                                                                    | NOT NECESSARY | 170.00                    | -                 |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                             |               | 170.00                    | 20.00             |
|     | TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                    | NOT NECESSARY | 380.00                    | -                 |
|     | TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                      |               | 380.00                    | 60.00             |
|     | TO DISMANTLE ADVERTISEMENT STICKER.                                                                                 | NOT NECESSARY | 170.00                    | -                 |
|     | TOWING FEES.                                                                                                        | NOT NECESSARY | 120.00                    | -                 |
|     | TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. | NOT NECESSARY | 380.00                    | -                 |
|     | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.                                     | NOT NECESSARY | 380.00                    | -                 |
|     |                                                                                                                     |               | 11,620.00                 | 1,480.00          |
|     | <b>GRAND TOTAL</b>                                                                                                  |               | <b>37,721.61</b>          | <b>6,177.90</b>   |
|     | <b>RECOMMENDED COST OF REPAIRS</b>                                                                                  |               |                           | <b>6,177.90</b>   |

Report Ref No. CS/FCI18016744/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.