

ASS. REC. BY:

REF:

CS/FL218016765/Kltb

n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): (WS Luene Jaw) of FCL Date/Time: 13092018 2114pm

Estimated Cost: Bill to:

OD / ~~IT~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6880B Insured: SHC 7297D

at Workshop m/s Premier Tel: 6544 6689

of 23 Changi South Ave 2 #03-02

Policy No: Claim No: D18006755 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 10092018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wpi

H.O.D. Endorsement:

Date/Time: 13092018 2147pm Person Contacted: Vincent Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6880B - X
	SHC 7297D - NA / msh 16021004 / H4
18/9/18 @ 5.12pm	revised to Luene by email.

Date: 03-11-16



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006755MFSH

Date: 18 September 2018

Our Ref: CS/FCI18016765/K1tb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6880B

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/09/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,728.70</u>
Revised Estimate Amount	: <u>S\$ 1,025.40</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	11-09-2018	Our Ref No. D18006755MFSH
Accident Date	10-09-2018	Claim Type. Third Party
Insured Vehicle	SHC7297D	Third Party Vehicle. SHC6880B
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 18 September 2018 5:12 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006755MFSH/1
Attachments: CSFCI18016765K1tb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHC 6880B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 13 September 2018 2:47 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006755MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 13 September, 2018 2:14 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006755MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	02 Sep 2015 / 07:58:55	Receipt No.:	AACCK001-AX239-150902-000017
Asset Type:	Vehicle	Transaction Amount:	\$69,132.00
Asset ID:	SHC6880B	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150902075855258942		

Vehicle No.:	SHC6880B
Vehicle Type:	H1D - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	02 Sep 2015
Original Registration Date:	02 Sep 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5621884
Engine No.:	D4FDEH313437
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,156.00
Minimum PARF Benefit:	\$12,971.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	02 Sep 2015 07:58:55
COE No.:	2015090201003470M
COE Expiry Date:	01 Sep 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$47,373.00
Lifespan Expiry Date:	01 Sep 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

17-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6880 B

1 pc	Rear bumper <i>x repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>— m</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>x m</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>x m</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>x m</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>x m</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>x m</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>x m</i>	\$	36.00
1 pc	Rear bumper n/s reflector <i>x m</i>	\$	46.00
1 pc	Rear n/s wheel cover @ \$116.00 <i>x m</i>	\$	116.00
<i>Rear n/s fender x repair</i>		\$	2,023.00
Less 10%		\$	202.30
		\$	1,820.70

S/NETT

1 set	Rear bumper clips <i>x m</i>	\$	48.00
1 pc	Rear n/s fender sticker <i>— m</i>	\$	60.00
Sundry		\$	50.00 <i>20 net</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs		\$	180.00 <i>x m</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of rear n/s fender, end panel etc		\$	850.00 <i>400</i>
To putty and spray painting on rear bumper, rear n/s fender, end panel <i>x</i>		\$	600.00 <i>360</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>x m</i>
		\$	3,728.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalra
17/9/18 1320h
30yr.
45
After Repair photo




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016765/K1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7297D	Veh. Inspected	SHC 6880B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006755MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	13/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5621884	Colour	SILVER	
Odometer	357240	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/09/2018	Inspection Date	17/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6880B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
1	REAR BUMPER N/S REFLECTOR	SERVICEABLE	46.00	-
1	REAR N/S WHEEL COVER	SERVICEABLE	116.00	-
1	REAR N/S FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-202.30	-20.60
			1,820.70	185.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			158.00	80.00
LABOUR				
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF REAR N/S FENDER, END PANEL ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, END PANEL.		600.00	360.00

Report Ref No. CS/FC118016765/K1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,750.00	760.00
GRAND TOTAL			3,728.70	1,025.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CS/FC18016765/K1tbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.