

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Ou	r [₹	2	F٠
$\mathcal{O}_{\mathbf{u}}$		N	_	١.

Type of Claim : THIF	RD PARTY	Vehicle No. :	SJV3482M
		Make & Model :	MERZ BENZ E250CGI
		Year of Manufacture :	2009
		Chassis No.	WDD2073472F029058
Ins Company :Ale	G VS EQ	Engine No. :	27186030019726
Excess :		Policy No. :	2100187191
Date of Accident :2	4/08/18	Time of Accident :	1310
Suggested Days of Repair :		In-house Vehicle Assesso	<u>or</u>
Repair Estimates		Case Owner :	BRENDA
De-t- (-) O(1) (-) D' (-)	.	Signature :	pullularities
Parts (a) Cost / List Price Items Plus/Less	\$ 1,622.00 \$ 243.30 \$ 1,865.30 \$ - \$ 1,865.30 \$ 1,220.00 \$ 3,085.30	Contact No 63837890 – Rohani braddell cr@sparkcarcare.c 63837730 – Brenda Ng braddell cr@sparkcarcare.c 63837362 - Andrew braddell operation@spareca 63838115 – William War braddell operation@spareca	om 63837656 - Ngo arcare.cc braddell_operation@spareca
Name of Surveyor	:		
Company			
Survey conducted on	•	at	
Remarks By Surveyor			
(a) The repair of this vehicle is a	authorized / is not auth	orized until further notice.	
(b) Recommended Days of Rep			
(c) Resurvey	: Required / No	t Required	
(d) Excess	:\$		
(e) Signature of surveyor	•	Date:	
VACCEDENT REPAIR ESTIMATESUS			

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	;	SJV3482M	Case Owner	;	BRENDA	
Make & Model	:	MERZ BENZ E250C	Year Manufacture	:	2009	
Chassis No	:	WDD2073472F029058	Engine No	:	27186030019726	
Sales Order	:		Supplier	:		
Order By	:		Type of Claim	:	THIRD PARTY	

S/No	Part Description	QTY		Cost	List	Nett		Disposition By
		<u> </u>	<u> </u>	Price	Price	Price	S/N	Surveyor
1	FRONT FENDER - LH	1	\$	580.00				
2	FRONT BUMPER - LH	1	\$	820.00				
3	FRONT BUMPER RETAINER – LH	1	\$	12.00				
4	FRT BUMPER CHROME MOULDING – LH	1	\$	53.00				
5	FRT BUMPER PARKING SENSOR -LH	1	\$	150.00				
6	FRT BUMPER PARKING SENSSOR SEAL – LH	1	\$	7.00				
7	FRT BUMPER PARKING SENSOR COVER – LH	1		TBA				
8	0	1						
9	0	1						
10	0	1						
11	0	1						
12	0	1						
13	0	1						
14	0	0						
15	0	0						
16	0	0						
17	0	0						
18	0	0						
19	0	0						
20	0	0						
21	0	0						
22	0	0						
23	0	0						
24	0	0						
25	0	0			***************************************			
26	0	0						
27	0	0		-				
	0	0						
	0	0						
30	0	0						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

<u>Labour</u>

Vehicle No.	:	SJV3482M	Case Owner	;	BRENDA
Make & Model	:	MERZ BENZ E250CGI	Year of Manufacture		2009

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO KNOCK,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH	\$500.00	
	FRONT LH FENDER , FRONT BUMPER AND AFFECTED AREA.		
2	TO PUTTY AND RESPRAY FRONT LEFT FENDER AND FRONT BUMPER	\$600.00	
	AND AFFECTED AREA		
3	TO CHECK WIRING AND INSTALL PARKING SENSOR	\$120.00	
		Ψ120.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.