

REC BY:

REF: CS/CT118016773/Tit b n2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Name

From (Person):

Jowyn Tay

of

CT

Date/Time: 13/09/2018 2pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 6470R

Insured:

S6D 50B

at Workshop m/s

Borneo Motor

Tel:

of

2 Pandan Crescent

Policy No:

DMPCSN 3049251700

Claim No:

SNM18D04387C02

Sum Insured:

Excess:

D.O.A.

05/09/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

17/09/2018 @ 9am - 2pm

I.O.D. Endorsement:

Date/Time:

13/09/2018 215pm

Person Contacted:

Thomas

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 6470R - CCE/AT/118000608 / Aed557
	S6D 50B - X
	Part by Part \$4,226.46. (Red: 2631; 38%)

POA: 08/01/2018

Signature: *Tan Jiah*

REF: *CT*


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: *SKV 6470R*
at Workshop m/s: *Borneo Motor*
of *2 Pandan Crescent*
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record) _____
Make of Veh: _____

Rear - 2pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *Thomson* Vehicle: IN / OUT

Veh No: *SKV 6470R* Yr Regn: *2015 Sep*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
Make: *Toyota Veloz* C.C. *2444*
Colour: *Silver* A/C: Insured / Std / NI / NA
Sp Reading: *132696* T/Radio: Insured / Std / NI / NA
Eng/No: *STNGF3DH308002322*
C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *235/50R18*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: *6* mm R/Bal. *6* mm
R/Bal. *6* mm L/Bal. *6* mm
L/Bal. *6* mm D.O.I. *12/9/18 @ 1330*
D.O.A. _____
Survey held at: *Borneo Pandan*
Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

RECEIVED 12 OCT 2018

Date/Time: File Pass to? _____
1) *12/10 Typist* ☐ : Preli. Report
Date/Time: File Return to? _____ ☒ : Final Report

Days Of Repair: *5*
Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS: _____
Photos: _____
Others: _____

Report Format: *TP*
Lump Sum / (B): (\$ *4226.46*)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018		13 Sep 2018 14:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All	
[Created by insurer] CLAIM SUBFOLDER DETAILS					
Insured:		CHENG HAI LENG, ID: S1627594H			
Main Claimant:		LIN WENSEN			
Vehicle Reg. No.:		SKV6470R	Date of Loss:	09/09/2018 11:00 - :59	
Claim Type:		TP / SNM18D04387C02	Policy/Cover Note No.:	DMPCSN3049251700 (Comprehensive)	
Vehicle Reg. No. (Insured):		SGD50B	Policy No. (Claimant):		
			Excess:	S\$0.00	
Repairer:		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857			
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/09/2018]			
Adj Asg. Remarks:		EST \$7337.48, CASE WITH SJE.			
			View All	Compose Case Mail	
ASSOCIATED MAIL RECEIVED					
There are no mail for this case.					
ALL ASSOCIATED TASKS					
View All Search Tasks Create New Task Complete Assigned By Completed On Created On Done?					
Due Date	Priority	Type	Task Group	Subject	Handler
No results.					

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 12 October 2018 10:49 AM
To: Thomas Pang PTCBC; Taufikh (LKKAUTO); SUR; Admin A
Subject: RE: FINALIZE REPORT FOR SKV6470R

Dear Thomas,

Confirm final figure at \$4226.46(before GST), 5 working days

Please submit all documents to China Tai Ping

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>

Sent: Friday, 21 September 2018 4:36 PM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: FINALIZE REPORT FOR SKV6470R

Dear Taufikh,

Attach finalize report for your perusal. 05 working days.

Thank you

Regards

thomas

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



UCC

Borneo Motors (Singapore) Pte Ltd
Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No.	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Lin Wensen 71 Jurong West Central 3 #14-17 Singapore 648335 Mobile: 93881029
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	NFXLK E1	AGH30R	28/09/2015	SKV6470R	0	35044	72/DS/SKV6470R
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTNGF3DH308002322	2ARH622066	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: TP VEH: SGD50B DATE OF ACC: 09.09.2018			net ✓	50. 100.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N ETT)			✓	169.50
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET T)			✓	115.26
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)			✓	169.50
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS			✓ 1356	2034.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS <i>plink end panel.</i>			✓ 1668	2224.00
7	1	T52159-58922 COVER, RR BUMPER	1.00	591.30		591.30
8	2	S52161-OK040 PIECE, RR BUMPER	10.00	4.00		40.00
9	3	T52164-58040 B0 PLATE, RR BUMPER, LH	1.00	19.90		19.90
10	4	T52155-58050 SUPPORT, RR BUMPER	1.00	95.90		95.90
11	5	T52155-58060 SUPPORT, RR BUMPER	1.00	101.20		101.20
12	6	T52156-58030 SUPPORT, RR BUMPER	1.00	95.90		95.90
13	7	T52156-58040 SUPPORT, RR BUMPER	1.00	101.20		101.20
14	8	T89341-58081 B0 SENSOR, ULTRASONIC,	2.00	390.50		781.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: 10/09/2018
Time: 14:57

VEHICLE NO: SKV6470R

Tan Kah 92495749.
WP
6 days
sur @ LKK auto on 19/9/18
Resurvey before print
17/9/18 @ 1330.

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

3773804

3773804



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Lin Wensen 71 Jurong West Central 3 #14-17 Singapore 648335 Mobile: 93881029	
		Document No		
		Document Date		
		0		
		10/09/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	NFXLK E1	AGH30R	28/09/2015	SKV6470R	0	35044	72/DS/SKV6470R
Chassis No		Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTNGF3DH308002322		2ARH622066	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
15	9	T89348-12020	CLIP, ULTRASONIC	4.00	8.00		32.00
16	0	T75441-58090	PLATE, BACK DOOR	1.00	66.90		66.90
17	1	S81920-OK010	REFLECTOR ASSY, REFL	1.00	58.90		58.90
18	2	T89997-30100	ANTENNA, ELECTRICAL	1.00	61.00		61.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.							

For & on behalf of Borneo Motors	Customer's Signature	Change Summary		Total	6,857.46
	Please acknowledge receipt of vehicle	Parts	2,045.20	GST 7.00%	480.02
		Labour	4,812.26	Less	0.00
		Materials	0.00		
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	7,337.48

PLEASE TEAR ALONG PERFORATED LINE

3773805

3773805

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 10/09/2018
TIME 14:57

VEHICLE NO SKV6470R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 21/09/2018	Mr Lin Wensen 71 Jurong West Central 3 #14-17 Singapore 648335 Mobile: 93881029

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	NFXLK E1	AGH30R	28/09/2015	SKV6470R	125698	35044	72/DS/SKV6470R
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTNGF3DH308002322	2ARH622066	60	Thomas Pang W T	17/09/2018	8.00	21/09/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY TP INS: CHINA TAIPING TP VEH: SGD50B DATE OF ACC: 09.09.2018 BY: LKK-TAUFIKH @ 17.09.2018 05 WORKING DAYS				50.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N	*			169.50
3	B	ETT) CHECK WIRING AND CONDUCT WATER TEST (NET	*			115.26
4	B	BP-LAB T) TO RESET ECU AND REPROGRAMME (NETT)	18			169.50
5	B	BP-LAB REPLACE ACC DAMAGED PARTS	*			1356.00
6	B	AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	*			1668.00
7	1	BP-RES RESPRAY ACC AFFECTED AREAS	1.00	591.30		591.30
8	2	T52159-58922 COVER, RR BUMPER	10.00	4.00		40.00
9	3	S52161-OKO40 PIECE, RR BUMPER	1.00	66.90		66.90
		T75441-58090 PLATE, BACK DOOR				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 698.20 Labour 3,528.26 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	4,226.46
			GST 7.00% 295.85
			Less 0.00
			Amount Due 4,522.31

3766237

3766237

21/09/2018
14:35

SKV6470R

WORKSHOP



Borneo Moto

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18016773/T1TBN2

Date: 15/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3049251700
Claimant Vehicle No :	SKV6470R	Insured Vehicle No :	SGD50B
Date of Loss:	09/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04387C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV6470R	Engine No:	2ARH622066
Make & Model:	TOYOTA VELLFIRE, 2.5 (A)	Chassis No:	JTNGF3DH308002322
Reg. Date:	28/09/2015 (Man. Year: 2015)	Odometer:	132696 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R18	Rear Tyre Size:	235/50R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,145.20	748.20	1,397.00	65.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,712.26	3,478.26	1,234.00	26.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,857.46	4,226.46	2,631.00	38.37
+ GST 7.00/7.00% (\$\$)	480.02	295.85	184.17	38.37
Nett Amount (\$\$)	7,337.48	4,522.31	2,815.17	38.37

INSPECTION

Date of Assignment:	13/09/2018		
Date Inspected:	17/09/2018	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Oct 2018)
 Parts: M1-MPV TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKV6470R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,RR BUMPER	Deformed	591.30 FS	*591.30 FS
2	10		*PIECE,RR BUMPER	Necessary	40.00 FS	*40.00 FS
3	1		*PLATE,RR BUMPER,LH	Not Necessary	19.90 FS	*- FS
4	1		*SUPPORT,RR BUMPER	Not Necessary	95.90 FS	*- FS
5	1		*SUPPORT,RR BUMPER	Not Necessary	101.20 FS	*- FS
6	1		*SUPPORT,RR BUMPER	Not Necessary	95.90 FS	*- FS
7	1		*SUPPORT,RR BUMPER	Not Necessary	101.20 FS	*- FS
8	2		*SENSOR,ULTRASONIC	Not Necessary	781.00 FS	*- FS
9	4		*CLIP,ULTRASONIC	Not Necessary	32.00 FS	*- FS
10	1		*PLATE,BACK DOOR	Necessary	66.90 FS	*66.90 FS
11	1		*REFLECTOR ASSY,REFL	Not Necessary	58.90 FS	*- FS
12	1		*ANTENNA ELECTRICAL	Not Necessary	61.00 FS	*- FS
13	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
Total Parts (S\$)					2,145.20	748.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	169.50	169.50
2	CHECK WIRING AND CONDUCT WATER TEST	New	115.26	115.26
3	TO RESET ECU AND REPROGRAMME	New	169.50	169.50
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	2,034.00	1,356.00
5	RESPRAY ACC AFFECTED AREAS	New	2,224.00	1,668.00
Gross Labour Cost (S\$)			4,712.26	3,478.26

Report was unsubmitted during this print-out.

< END OF ESTIMATES >