

22/03/2002

ASS. REC. BY:

REF: CS/CT118016776/Tlvber

Special Instruction:

Surveyor:

**ASSIGNMENT (Office)**

Medmen

From (Person):

Irene Tay

of

CTL

Date/Time:

13/09/18 1.46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S6C 2388U

Insured:

SLP 9876D

at Workshop m/s

Cycle & Carriage

Tel:

91865113

of

188 Pandan Loop

Policy No:

DMP/CSN1742651801

Claim No:

SNM18D 04380C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08092018

(Client's Record)

17092018 @ Office 10am

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13/09/2018 2.11pm

Person Contacted:

Kerlyn


Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	S6C 2388U - CS/AXA10007758/UHC3K2 DIA: 170412
	SLP 9876D - NA/CTL17013751/13 DCA: 170417
8/10/18	Final fig \$ 7398.48 (Red 2494.02, 2570)

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SGC 2388U  
 at Workshop m/s Cycle & Carriage  
 of 188 Pandan Loop.  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)

Make of Veh: \_\_\_\_\_  
After loan.  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: Kerlyn Vehicle: IN / OUT

Veh No: SGC 2388U Yr Regn: 2012, May.  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mercedes Benz C/C: 1796  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 212365 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDD2040472A70704  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 275/45R18  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm

D.O.A. \_\_\_\_\_ D.O.I. 17/9/18  
 Survey held at 188 Pandan Loop  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.  
 Rebate: \$57,098

Date / Time	Action / Instruction

RECEIVED 8 OCT 2018

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 Date/Time, File Return to?  
 1) \_\_\_\_\_  
 2) 8/10 - typist  
 Report Format : men men  
 Lump Sum / I.B.I: (\$) 7398.48

Days Of Repair: 6  
 Resurvey No. of Trip: -  
 Add Fee:  Site Insp (\$) )  
 Interview (\$) )  
 Tech. Invs (\$) )  
 Weekend (\$) )  
 Survey Fee: 220  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		13 Sep 2018 13:46 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by insurer\]](#)

Insured:	<b>CHUNG MUN KIT (ZENG WENJIE)</b> , ID: S7577229G		
Main Claimant:	<b>YEOW ENG FOO</b> , ID: S6871583J		
Vehicle Reg. No.:	<b>SGC2388U</b>	Date of Loss:	08/09/2018 14:00 - :59
Claim Type:	<b>TP / SNM18D04380C02</b>	Policy/Cover Note No.:	DMPCSN1742651801 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLP9876D</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Cycle &amp; Carriage Industries Pte Ltd (Pandan Loop)</b> 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Final Rpt</b> due 24/09/2018]		
Adj Asg. Remarks:	EST \$10,584.98, CASE WITH SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/09/2018 16:54
Date Of Accident	08/09/2018 14:30
Exact Location Of Accident	SLIP RD CTE (CITY) TWDS ANG MO KIO AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC2388U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEOW ENG FOO
NRIC No	S6871583J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94799057
Alternative Phone No	OFFICE-94799057

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C250
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA228951
Cover Note Number	

### Driver

Name of Driver	YEOW ENG FOO
NRIC No	S6871583J
Date Of Birth	01/04/1968
Occupation	INDOOR
Date Of Driving Pass	20/09/2002
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94799057
Fax Number	
Contact Number	OFFICE-94799057
EEmail Address	NOEMAIL

Address	BLK 704 HOUGANG AVE 2 #01-211
Postcode	530704
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I STOPPED MY CAR AT THE JUNCTION OF SLIP RD CTE (CITY) TWDS ANG MO KIO AVE 5. AS I STOPPED FOR AWHILE AS IT WAS RED LIGHT, CAR B (SLP9876D) CAME FROM REAR DID NOT MANAGE TO STOP ON TIME AND COLLIDED ONTO MY REAR PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP9876D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUNG MUN KIT
NRIC/Passport Number	S7577229G
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time 10/09/2018 1409

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

**Kerlyn Ong Kai Li**  
DID : 6771 4420 HP : 9186 5113  
Email : kerlyn.ong@cyclecarriage.com.sg  
Rep.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Name: KERLYN ONG  
Customer Service Centre - Pandan Loop  
NRIC/FIN No.:

SKETCH PLAN



A: SGC 2388U

B: SLP 9876D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I STOPPED MY CAR (SGC2388U) AT THE JUNCTION OF SLIP ROAD CTE (CITY) TWD ANG MO KIO AVE 5. AS I STOPPED FOR AWHILE AS IT WAS RED LIGHT, VEHICLE B (SLP9876D) CAME FROM REAR DID NOT MANAGE TO STOP ON TIME AND COLLIDED ONTO MY REAR PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

**Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.**

(Please contact your insurance company for any further details)

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time 10/09/2018 1409

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

**Kerlyn Ong Kai Li**  
DID : 6771 4420 HP : 9186 5113  
Email : kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

\_\_\_\_\_  
Reporting Centre Personnel's  
Name: KERLYN  
NRIC/FIN No.:



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC2388U

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 26779  
Reg No/Reg Date SGC2388U / 24/05/2012  
Date In/Mileage / 0  
Chassis No WDD2040472A708744  
Engine No 27186030472287  
Make/Model MB/C 250 CGI SEDAN W204  
Colour/Trim 021 197 Obsidian B1/ 042 224 Leather Cas

Table with 5 columns: Account No, Terms, Date/Time Printed, CSE, Operator. Row 1: WC000668, Credit, 10/09/2018/ 17:43, K0, 301 / Kerlyn Ong

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like Z REQUEST, M BPNSUN, A BPILAB, A BPIRES, A BPILAB, M BOOT LID, etc. Includes handwritten notes and checkmarks.

Confirmed & accepted by

Kerlyn Ong Kal Li  
DID: 6771 4420 HP: 9186 5113  
Email: kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC2388U

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information

WIP No 26779  
Reg No/Reg Date SGC2388U / 24/05/2012  
Date In/Mileage / 0  
Chassis No WDD2040472A708744  
Engine No 27186030472287  
Make/Model MB/C 250 CGI SEDAN W204  
Colour/Trim 021 197 Obsidian B1/ 042 224 Leather Cas

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	10/09/2018/ 17:43	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REAR BUMPER SIDE STABILITY	2.00	36.21	00.00	72.42
M LH/ REAR BUMPER BRACKET	1.00	14.94	00.00	14.94
M RH/ REAR BUMPER BRACKET	1.00	14.94	00.00	14.94

net 7 72.42  
net 7 14.94  
net 7 14.94

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tanpin 97495749  
'up'  
17/9/18 @ 1450  
sur @ (Kuantan)  
6 days.  
19/9/18

Confirmed & accepted by

**Kerlyn Ong Kai Li**  
DID : 6771 4420 HP : 9186 5113  
Email : kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

Nett	9,892.50
7% GST on	9892.50
<b>Total Payable</b>	<b>10,584.98</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-B500111-X

TAX INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909  Contact No 62222366	Cust No/Name /Yeow Eng Foo Reg No/Reg Date SGC2388U / 24/05/2012 Date In/Mileage 17/09/2018/ 212365 Chassis No WDD2040472A708744 Engine No 27186030472287 Make/Model MB/C 250 CGI SEDAN W204 Colour/Trim 021 197 Obsidian Bl/ 042 224 Leather Cas



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WC000668	Credit	27/09/2018/ 13:46	K0	301 / Kerlyn Ong	26779	28146463

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
Z REQUEST Customer Request			F.O.C.
M BPNSUN POLICY NO/ACC DATE : VA1/GA228951 // 08/09/2018 DRIVE IN/TP VEHICLE NO. : 10/09/2018 // SLP9876D - CHINA DATE IN/DATE SURVEY: 17/09/2018 1450 // LKK - TAUFIKH BY/AUTHORIZED ON : 14/09/2018 // CHINA - IRENE			
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO		0.10	380.00
A BPILAB STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			1920.00
A BPIRES TO RESPRAY REAR BOOT LID AND REAR BUMPER			1200.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT			120.00
X BOOT LID	1.00	1610.28	1610.28
X BOOT LID SEAL	1.00	165.74	165.74
X BOOT LID UPPER STOP BUFFER	2.00	9.41	18.82
X BOOT LID PLUG	2.00	0.92	1.84
X REAR MERCEDES STAR	1.00	46.63	46.63
X SEALING GROMMET	3.00	1.81	5.43
X REAR BUMPER	1.00	1448.64	1448.64
X LH/ REAR BUMPER CHROME MOULDING	1.00	132.56	132.56
X CTR/ REAR BUMPER CHROME MOULDING	1.00	186.40	186.40
X RH/ REAR BUMPER CHROME MOULDING	1.00	132.56	132.56
X LH/ REAR BUMPER BRACKET	1.00	14.94	14.94
X RIVETED NUT	4.00	3.66	14.64

Parts	3,778.48	Nett	7,398.48
Labour	3,620.00	7% GST on	517.89
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	7,916.37
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	0.00	Total Due	7,916.37
Total(w/o GST)	7,398.48		

Payment should be made strictly by cash, NETS or credit cards. Thank you.  
Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2018		13 Sep 2018 13:46 <a href="#">Edit Adj Rpt</a>	<b>S\$7,398.48</b> <a href="#">Edit Estimates</a>	<b>S\$7,398.48</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float:right">[Created by insurer]</span>									
Insured:	<b>CHUNG MUN KIT (ZENG WENJIE)</b> , ID: S7577229G								
Main Claimant:	<b>YEOW ENG FOO</b> , ID: S6871583J								
Vehicle Reg. No.:	<b>SGC2388U</b>	Date of Loss:	08/09/2018 14:00 - :59 [75 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04380C02</b>	Policy/Cover Note No.:	DMPCSN1742651801 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLP9876D</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Cycle &amp; Carriage Industries Pte Ltd (Pandan Loop)</b> 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 24/09/2018]								
Adj Asg. Remarks:	EST \$10,584.98, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right"><a href="#">View All</a>   <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float:right"><a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SGC2388U (SNM18D04380C02)  
[SLP9876D]  
TP  
YEOW ENG FOO  
Sep 8 2018 2:00PM  
[CHUNG MUN KIT (ZENG WENJIE)]  
Cycle & Carriage Industries Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>	
<b>Assessment Reports</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 15:26	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 15:26	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	10/09/18 15:26	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	10/09/18 15:26	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
4	10/09/18 15:26	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
5	10/09/18 15:26	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
6	10/09/18 15:26	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
7	10/09/18 15:26	<b>TP DAMAGE PHOTO</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
8	10/09/18 15:26	<b>TP DAMAGE PHOTO</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
9	10/09/18 15:26	<b>TP DAMAGE PHOTO</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/09/18 13:45	<b>EMAIL FM C&amp;C</b>	Load PDF	<input type="checkbox"/>
2	13/09/18 13:45	<b>REPAIR EST WITH TP GIA</b>	Load PDF	<input type="checkbox"/>
3	13/09/18 13:45	<b>OI GIA</b>	Load PDF	<input type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 15:25	<b>Sketch Plan</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	10/09/18 15:25	<b>Sketch Plan #2</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	10/09/18 15:25	<b>Sketch Plan #3</b> <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
<b>Relabel/Reorder</b>				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/10/18 10:37	<b>General View</b>	Load PDF	<input type="checkbox"/>

## Linked Accident Report Documents

			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>	
<b>Assessment Reports</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 15:26	<b>Accident Statement</b>	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 15:26	<b>Accident Photo</b>	Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
				<input checked="" type="checkbox"/>
2	10/09/18 15:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	10/09/18 15:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	10/09/18 15:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	10/09/18 15:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	10/09/18 15:26	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	10/09/18 15:26	TP DAMAGE PHOTO	Load JPG	<input checked="" type="checkbox"/>
8	10/09/18 15:26	TP DAMAGE PHOTO	Load JPG	<input checked="" type="checkbox"/>
9	10/09/18 15:26	TP DAMAGE PHOTO	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	10/09/18 15:25	Sketch Plan <small>Click here &amp; type to add comment...</small>	Load JPG	<input checked="" type="checkbox"/>
2	10/09/18 15:25	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	10/09/18 15:25	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI18016776/T1VBE2  
**Date:** 11/10/2018

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN1742651801	
Claimant Vehicle No: SGC2388U	Insured Vehicle No: SLP9876D	
Date of Loss: 08/09/2018	Nature of Claim: TP	Claim No: SNM18D04380C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGC2388U</b>		
Make & Model:	MERCEDES-BENZ C250, 2.0 AMG LINE (R18 LED SR) (A)	Engine No:	27186030472287
Reg. Date:	24/05/2012 (Man. Year: 2012)	Chassis No:	WDD2040472A708744
Colour:	Black	Odometer:	212365 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,192.50	3,778.48	1,414.02	27.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	3,620.00	1,080.00	22.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,892.50</b>	<b>7,398.48</b>	<b>2,494.02</b>	<b>25.21</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>692.48</b>	<b>517.89</b>	<b>174.59</b>	<b>25.21</b>
<b>Nett Amount (S\$)</b>	<b>10,584.98</b>	<b>7,916.37</b>	<b>2,668.61</b>	<b>25.21</b>

#### INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	17/09/2018 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	6.0 days	

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)	
<b>Parts:</b> 143	MERCEDES-BENZ C250 2.0 AMG LINE (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b> (Unsubmitted, no print-code for SGC2388U)		
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,610.28 FS	*1,610.28 FS
2	1		*BOOT LID SEAL	Necessary	165.74 FS	*165.74 FS
3	2		*BOOT LID UPPER STOP BUFFER	Necessary	18.82 FS	*18.82 FS
4	2		*BOOT LID LOWER STOP BUFFER	Not Necessary	14.18 FS	*- FS
5	2		*BOOT LID PLUG	Necessary	1.84 FS	*1.84 FS
6	1		*BOOT LID LOCK	Not Necessary	285.68 FS	*- FS
7	1		*C250 EMBLEM	Not Necessary	81.03 FS	*- FS
8	1		*REAR MERCEDES STAR	Necessary	46.63 FS	*46.63 FS
9	3		*SEALING GROMMET	Necessary	5.43 FS	*5.43 FS
10	1		*REAR BUMPER	Cracked	1,448.64 FS	*1,448.64 FS
11	2		*REAR SENDER UNIT	Not Necessary	690.12 FS	*- FS
12	1		*LH / REAR BUMPER CHROME MOULDING	Necessary	132.56 FS	*132.56 FS
13	1		*CTR / REAR BUMPER CHROME MOULDING	Cut	186.40 FS	*186.40 FS
14	1		*RH / REAR BUMPER CHROME MOULDING	Necessary	132.56 FS	*132.56 FS
15	1		*CTR / REAR BUMPER REINFORCEMENT	Not Necessary	135.13 FS	*- FS
16	1		*LH / BASIC MOUNTING FOR BUMPER	Not Necessary	67.58 FS	*- FS
17	1		*RH / BASIC MOUNTING FOR BUMPER	Not Necessary	67.58 FS	*- FS
18	2		*REAR BUMPER SIDE STABILITY	Not Necessary	72.42 FS	*- FS
19	1		*LH / REAR BUMPER BRACKET	Necessary	14.94 FS	*14.94 FS
20	1		*RH / REAR BUMPER BRACKET	Necessary	14.94 FS	*14.64 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 5,192.50 3,778.48**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO	New	380.00	380.00
2	STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	2,400.00	1,920.00
3	TO RESPRAY REAR BOOT LID AND REAR BUMPER	New	1,800.00	1,200.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>4,700.00</b>	<b>3,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >