M. Contla			MENT (Office)	
From (Person	: Christina Wang	of _	prou	Date/Time: 13092018 9.01Gr
Estimated Co	S/TP RES/OD RES/		Bill to:	
To Inspect V	S/TP RES / OD RES / I	CBB 87444	i CS	Insured: XX INTE
at Workshop	m/s_	KKIM HIN A	nto	Tel: 6452 7018
of	81k	160 Sin 1	CU# YING DING	Tel: 6452 7018
	827450516TMV		Claim No:	569931
Sum Insured	•			
Make of Veh (Client's Recon	d)			D.O.A. 04072018
CA / REV	/ REP. / REV 24 HRS			H.O.D. Endorsement:
	13092018 951am		Shuman	Vehicle DY/OUT
	Action/Instruction (√) Estima	te	4.1
Date/Time				8
Date/Time	6BB 87447 - X			
Date/Time	X) 1476 - CS/W	184 18011722	Mich	DUA: CHUSIS
Date/Time				

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adi Submitter	d Ins Auth	'ed Status		
Main	10 Sep 2018 16:22 Sendback Est	10 Sep 2018 16:27 \$\$16,164.93	13 Sep 2018 09:01 Assign		They bearing the	ins recti	New Assi Cancel (
	Main	Refe	rence	Claim	Details	Doc	cuments	Show All	
CLAIM SI	JBFOLDER DETAI	II S				Marie Company			
Insured:	OLDEN DE IN	COLC.	SERVICES PTE	ITD Co Doo	N 0				
Main Claim	nant:		BUILDING PRO			2000145210			
		MARVEST	DOILDING PROI	DOCIS PIE LIL	, Co. Reg. No.:		04/00/2040 44 0		
Vehicle Re	g. No.:	GBB874	4A	Date o	f Loss:	1		/2018 11:00 - :59 lonths and 9 Days From LTA late (Man Yr)]	
Claim Type	e:	TP / 569	932	Policy/Cover Note No.: B27450516TMV Coverage: 13/0		B27450516TMV (0 Coverage: 13/02/ 12/02/2019			
Vehicle Reg. No. (Insured):		XD147E	XD147E		Policy No. (Claimant):		A28806552MKC		
					Excess:		JAINSC COODDS		
Repairer:		K Kim Hir 64527018	Auto Pte Ltd (H	Q) 160 Sin Ming	Drive #02-20, S	in Ming AutoCit	y, 575722 Sin Mi	ng - Tel:	
Handling I	nsurer:	MSIG Ins	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Christina Wong - 6 1311]					na Wong - 6643	
Claimant's	Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (F	Q) - Tel: +65 68	327 7888			
Adjuster:			MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 14/09/2018]						
Adj Asg. Re	emarks:	Car in, sur	Car in, survey by today. on WP. Please contact us ASAP if you cannot attend this assignment. Liability 100%. Contact Person: Wong Shu Man / 6452 7018.						
ASSOCIA	TED MAIL RECEIV	/ED				Vie	ew All Com	pose Case Mail	
There are r	no mail for this case								
F									
_	CIATED TASKS				View All Sea	arch Tasks	Create New Task	Complete	
Due Dat	e Priority T	ype Task Grou	up Subject	Handler	Assigned By	Completed	On Create	d On Done?	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Mobile Number

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	07/09/2018 10:39
Date Of Accident	04/09/2018 11:10
Exact Location Of Accident	GUL WAY
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBB8744A
Insured/Policyholder	
Name Of Registered Owner	HARVEST BUILDING PRODUCTS PTE LTD
Co Reg No	200914531R
Email Address	LILIAN.FOO@HBP.COM.SG
Mobile Phone No	(LOCAL) +65-96447794
Alternative Phone No	OFFICE-63622608
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	DYNA 150 MANUAL 3SEATER-3.0 D (M)
Exact Purpose for which vehicle was being use time of accident	ed at
Are you claiming under your own insurance pol for repair to your vehicle?	licy NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28806552MKC
Cover Note Number	
Driver	
Name of Driver	LIM JIT SENG
NRIC No	S6822975H
Date Of Birth	17/06/1968
Occupation	INDOOR
Date Of Driving Pass	18/08/1988
Driving Experience	30 YEARS AND 0 MONTHS
Gender	MALE

(LOCAL) +65-94874026

NOEMAIL

BLK 417 ANG MO KIO AVE 10 Address

#09-1011

Postcode 560417

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions AFTER RAIN

Road Surface DAMP

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

Passenger 1

YES

NO

2

YES Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NAME:

: WORKER

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes.Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY: Police Station Address

SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera?

NO

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

XD147E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM JIT SENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBB8744A

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN			
	[20]		
	TAP	A.	GBB 8744A
		6	
		B:	XD 147E
		Palak	
	14 1 1 1 1	Gul Way	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 19	Please	refer to	polize	report
			1	

DECLARATION

I/We declare the foregoing particulars are true in exery respect.

(X)

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:

7/9 @ 10 An

Police Report Pg. 1





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20180905/2110

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/09/2018 16:21		Vide Report No.:	Station Diary No.		
Informa	nt's Partic	ulars		· 14 (1984年) 18 (1984年) 19 (1984年) 18 (1984年)	
Name of LIM JIT	f Informant: SENG		Address: 417 ANG MO KIO AVE HEARTLANDS SINGA	ENUE 10 #09-1011 TECK GHEE APORE 560417	
	/ ID No.: O / S68229	75H	Contact No.: Home/Office: Mobile: 94874026		
National SINGAP	ity: ORE CITIZ	EN	Email:		
Sex: Male	Age: 50	Date of Birth: 17/06/1968	Type of Informant: Driver		
Race: Chinese		Language: English	Institution / School Name:		
Occupation: DRIVER		Driving Licence Inform Class: 3	ation: Date of Expiry:		

General Infor	mation of the Accident			
Type of Accident:	Injury Conveyed By Ambuland	Drink be Drive: No	Date/Time of Accident: 04/09/2018 11:10	Type of Location:
Location: Along Road 1 GUL WAY				
Weather:	Ro	oad Surface:	R	oad Speed Limit:
Traffic Flow:	Tr	affic Control:	Tr	raffic Volume:
Type of Collis	ion:		ar	nyone conveyed by nbulance: es

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBB8744A	Lorry			8		1
XD147E						0

Police Report Pg. 2





T/20180905/2110

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20180905/2110

2 of 3

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION

I WAS GOING STRAIGHT ON THE 2-LANE 2-WAY ROAD WITH 1 PASSENGER. I WAS GOING STRAIGHT WHEN SUDDENLY A LORRY(XD147E) CAME OUT FROM A FACTORY ON MY LEFT. THE LORRY WANTED TO TURN RIGHT. I COULD NOT STOP IN TIME AND COLLIDED INTO THE RIGHT SIDE OF THE LORRY. POLICE AND AMBULANCE CAME. MY PASSENGER AND I WAS CONVEYED TO NG TENG FONG GENERAL HOSPITAL WHERE I WAS DISCHARGED THE SAME DAY AND RECEIVED 6-DAYS MC.

Police Report Pg. 3





Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20180905/2110

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Records TP / MUHAMMAD SYUKRI BIN A		Signature Of Informant:
Signature Of Interpreter: Not applicable		Date/Time: 05/09/2018 16:21
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED SUFIA Contact No.: 65476367	N BIN SUDIN	Classification Of Case:
Authentication Stamp NP168	Signature:	FULICI FUREE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: Vehicle Details	4531R	
Vehicle No.:	GBB8744A	
Vehicle to be Exported:	No	
Intended Deregistration Date:	07 Sep 2018	
Vehicle Make:	TOYOTA	
Vehicle Model:	DYNA 150 MANUAL 3SEATER	
Primary Colour:	White	
Manufacturing Year:	2010	
Engine No.:	1KD2002141	
Chassis No.:	JTFAT35Y50K201237	
Maximum Power Output:	€	
Open Market Value:	\$24,970.00	
Original Registration Date:	26 Aug 2010	
First Registration Date:	26 Aug 2010	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$1,249.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	•	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	25 Aug 2020	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	10	
QP Paid:	\$31,689.00	
COE Rebate Amount:	\$6,227.00	
Total Rebate Amount:	\$6,227.00	

The information contained herein is correct as at 07 Sep 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	4531R
Vehicle Details	
Vehicle No.:	GBB8744A
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	1KD2002141
Chassis No.:	JTFAT35Y50K201237
Maximum Power Output:	
Open Market Value:	\$24,970.00
Original Registration Date:	26 Aug 2010
First Registration Date:	26 Aug 2010
Transfer Count:	0
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	·*
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Aug 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,689.00
COE Rebate Amount:	\$6,167.00
Total Rebate Amount:	\$6,167.00

The information contained herein is correct as at 14 Sep 2018

OK



K.KIM HIN AUTO PTE LTD 160 Sin Ming Drive #02-20 Sin Ming AutoCity Singapore 575722

Claim Reference:

Assessment Number: KKHM0022

Version: K.KIMHIN/1

Date Calculated: 10/09/2018 09:10

Full Report - V1

Registration: GBB8744A

Printed: 10/09/2018 16:10

SGD

TBA

04/09/2018

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

SANDRA KHONG Interim

MSIG Insurance

(Singapore) Pte

True

TOYOTA

Dyna

Y1N 03

GBB8744A

Not Known

1KD2002141

White

%

JTFAT35Y50K201237

150

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Repairs Authorised:

Estimated Repair Time: Quote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start:

Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model:

Model Sheet Number: Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Model Specs

FROM 12/2010 SINGLE CAB

TWO COAT PEARL/MICA

AIR CONDITIONING 3.0 LTR 80KW

Severity of Impact: Vehicle Status on

Inspection:

Date of Inspection:

10/09/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

Claim Reference:


Assessment Number: KKHM0022


Version: K.KIMHIN/1

Date Calculated: 10/09/2018 09:10

Full Report - V1 Registration: GBB8744A

Printed: 10/09/2018 16:10





Addresses

Cost Summary

Total Labour	\$2,665.00
Total Paint/Material	\$232.87
Total Parts	\$10,953.06
Total of Additional Costs	\$2,314.00
Excess:	TBA
Grand Total Exc GST:	\$16,164.93
7 % GST:	\$1,131.55
Grand Total Inc GST:	\$17,296,48

Repair Information

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR		
		Price/Der	nt = \$50.00/HR
Repair /			
	er Repair Details	wu	Cost Price (\$)
	RENEW L/F CAB BRACKET	5.0	25.00
	RENEW L/F CAB BRACKET	5.0	25.00
	RENEW R/F CAB BRACKET	5.0	25.00
NO NUMBER	R + R CAB	30.0	150.00
NO NUMBER	RENEW FRONT PANEL	60.0	300.00
NO NUMBER	R + R BADGE "DYNA"	2.0	10.00
520011)	R + R FRONT BUMPER	4.0	20.00
520011)	RENEW FRONT BUMPER (REMOVED)	2.0	10.00
751011	R + R RADIATOR GRILLE	2.0	10.00
810051)	R + R LEFT HEADLAMP	1.0	5.00
	(RADIATOR GRILLE REMOVED)		
810051)	R + R RIGHT HEADLAMP	1.0	5.00
	(RADIATOR GRILLE REMOVED)		
810151A	ADJUST HEADLAMPS	3.0	15.00
NO NUMBER	R + R L/F LOWER CLOSING PANEL	1.0	5.00
NO NUMBER	R + R R/F LOWER CLOSING PANEL	1.0	5.00
NO NUMBER	R + R L/LOWER PROTECTING COVER	2.0	10.00
NO NUMBER	R + R R/LOWER PROTECTING COVER	2.0	10.00
851061)	R + R FRONT WASHER NOZZLE/S	1.0	5.00
554011)	R + R WINDSCREEN	14.0	70.00
, , , , , , , , , , , , , , , , , , ,	INCLUDES: R + R SUN VISORS, UPPER FRONT		
	PANEL AND A-PILLAR TRIMS		
670051)	R + R LEFT FRONT DOOR	6.0	30.00
NO NUMBER	R + R L/F STEP	3.0	15.00
752051	R + R LEFT MIRROR	4.0	20.00
670051)	R + R RIGHT FRONT DOOR	6.0	30.00
NO NUMBER	R + R R/F STEP BOARD	3.0	15.00
743201)	DETACH + REFIT HEADLINING	4.0	20.00

Claim Reference:

Full Report - V1

Assessment Number: KKHM0022

Registration: GBB8744A

Version: K.KIMHIN/1

Printed: 10/09/2018 16:10

Date Calculated: 10/09/2018 09:10

NO NUMBER NO NUMBER 870031) 870151 NO NUMBER 550451) 550451) NO NUMBER 850161) 850171) 160011)	R + R HEATING CPL R + R BLOWER (HEATER REMOVED) R + R EVAPORATOR R + R INSTRUMENT PANEL RENEW INSTRUMENT PANEL (REMOVED)	2.0 2.0 12.0 5.0 4.0 9.0 4.0 2.0 1.0 1.0	10.00 10.00 60.00 25.00 20.00 45.00 20.00 10.00 5.00 50.00
572-272-1970av	EXPANSION TANK, BLEED COOLING SYSTEM		
160011)	RENEW RADIATOR (RADIATOR REMOVED)	1.0	5.00
463011)	R + R BOOSTER	3.0	15.00
461101)	R + R BRAKE MASTER CYLINDER	2.0	10.00
	INCLUDES: BLEED BRAKE SYSTEM		
442151 ZAX		2.0	10.00
441101	R + R STEERING WHEEL	2.0	10.00
NO NUMBER		5.0	25.00
444401)	R + R POWER STEERING RACK	18.0	90.00
881151 ZAX		8.0	40.00
002889 ZAX		7.0	35.00
0911	REPAIR L/OUTER A-PILLAR	30.0* 20	150.00
0912	REPAIR R/OUTER A-PILLAR	30.0* 20	150.00
3000	REPAIR FRAME CPL	30.0* 20	150.00
3010	REPAIR FRONT CROSSMEMBER	15.0* (0.	75.00
LAB	OUR COST		
	Total Work Units	372.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	37.2HRS	\$1,860.00
	Paint Labour	16.1HRS	\$805.00
	Total Labour	53.3HRS	\$2,665.00

PAINT W	ORK Time Basis 10	WU = 1 HR. Pric	ce = \$50.00/HR
Guide Nu	mber Description	wu	Cost Price (\$)
	- TWO COAT PEARL/MICA		
281	FRONT BUMPER NEW PART PAINTING	12.0	
414	FRONT LOWER PANEL NEW PART PAINTING	19.0	
418	UPPER FRONT PANEL NEW PART PAINTING	8.0	
885	L/F UPPER END PANEL NEW PART PAINTING	6.0	
886	R/F UPPER END PANEL NEW PART PAINTING	6.0	
889	L/F LOWER END PANEL NEW PART PAINTING	6.0	
890	R/F LOWER END PANEL NEW PART PAINTING	6.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	16.0	
1482	RIGHT FRONT DOOR NEW PART PAINTING	16.0	
410	GRILLE NEW PART PAINT K1R	5.0	

Claim Reference:

Assessment Number: KKHM0022

Version: K.KIMHIN/1

Date Calculated: 10/09/2018 09:10

Full Report - V1

Registration: GBB8744A Printed: 10/09/2018 16:10

L/OUTER A-PILLAR REPAIR PAINTING >50%	15.0	
R/OUTER A-PILLAR REPAIR PAINTING >50%	15.0	
FRONT CROSSMEMBER SURFACE PAINT	5.0	
LABOUR COST - PAINT		
TIME(PAINT)	135.0	
Preparation Main Work Metal	21.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	161.0	
Total Paintwork Labour	16.1HRS	\$805.00
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$161.32
New Part Painting - Plastic K1R		\$11.81
Surface-/Blend Paint		\$4.98
Repair Painting		\$27.66
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$232.87
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$232.87
	R/OUTER A-PILLAR REPAIR PAINTING >50% FRONT CROSSMEMBER SURFACE PAINT LABOUR COST - PAINT TIME(PAINT) Preparation Main Work Metal Preparation Comp. Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour MATERIAL COST - PAINT New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint Repair Painting Material-Const Main Work Metal Material-Const Comp. Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0%	R/OUTER A-PILLAR REPAIR PAINTING >50% FRONT CROSSMEMBER SURFACE PAINT LABOUR COST - PAINT TIME(PAINT) Preparation Main Work Metal Preparation Comp. Work Plastic Preparation Work Multi Layer Paint Total Work Units (10WU/HR) Total Paintwork Labour MATERIAL COST - PAINT New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint Repair Painting Material-Const Main Work Metal Material-Const Comp. Work Plastic Total Excluding Pearlescent Uplift Pearlescent Uplift @ 0.0%

PARTS						
				Price Valid:	01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER / BT	52101 25912		0%	/ 165.00*
385/	1	UPP RAD GRILLE SEAL	53119 37080B0		0%	/ 30.00*
410/	1	Capille a Asia	53114 37010		0%	/ 165.00*
414/	1	FRONT LOWER PANEL	55711 37051		0%	× 340.00*
417	1	END MOULDING / SCR	53928 37011		0%	110.00*
418	1	UPPER FRONT PANEL / PACE	55078 37070		0%	/ 110.00*
481/	1	BADGE / We	75315 37011		0%	/ 35.00*
484	1	BADGE MODEL / NC	75311 37130		0%	/ 35.00*
561	1	LEFT HEADLAMP ASSY / 0.5	81170 37171		0%	/ 215.00*
562	1	RIGHT HEADLAMP ASSY/15	81130 37170		0%	/ 215.00*
563	1	L/HEADLAMP TRIM / (81193 37050		0%	/ 25.00*
564 /	1	R/HEADLAMP TRIM / MIS	81193 37050		0%	/ 25.00*
887	1	L/END MOULDING	53922 25011		0%	/ 60.00*
888	1	R/END MOULDING	53921 25011		0%	/ 60.00*
889	1		4 53802 37021		0%	/ 85.00*
890 /	1	R/F LOWER END PANEL /	53801 37021		0%	/ 85.00*
1401	1	WINDSCREEN - CAM	56111 37120		0%	/ 485.00*
1410	1	WINDSCREEN SEAL	56121 25040		0%	/ 100.00*
1450 ×	1	WIPER MOTOR X NN	85070 25080		0%	₹ 385.00*
1453 /	1	L/F WIPER ARM	85221 37150		0%	/65.00 *
1454 /	1	R/F WIPER ARM	85211 37070		0%	65.00*
1457 /	1	L/F WIPER BLADE /	85222 37141		0%	60.00*
1458	1	R/F WIPER BLADE	85212 37081		0%	60.00*
1469×	1	WIPER LINKAGE X	85150 37090		0%	¥145.00*
2205 ×	1	L/F STEP X	J 51772 37131		0%	J115.00*
2206>	1	R/F STEP 🗸	51771 25021		0%	√115.00*
2560>	1	INSTRUMENT SUPPORT X	55330 37025		0%	♦ 290.00*
2759 / 6	1	L/F SUPPORT BRACKET V/	51702 25060		0%	220.00 *
2760 / 4	1	R/F SUPPORT BRACKET 2/	51701 25110		0%	220.00*
		. 1	RT			18
			1.(

Claim Reference:

Assessment Number: KKHM0022

Version: K.KIMHIN/1

Date Calculated: 10/09/2018 09:10

Full Report - V1

Registration: GBB8744A Printed: 10/09/2018 16:10

×1		
2771 1 L/CAB ATTACHMENT 1 57224 37011	0%	420.00*
2811 CONTROL ROD X 54915 37090		320.00*
3307 / 1 BRAKE MASTER CYL 7 47201 25270		185.00*
3737 1 L/F WASHER JET X 5 N N 85381 37030	0%	20.00*
3738 1 R/F WASHER JET X 1 85381 37030		20.00*
4331 1 • INSTRUMENT PANEL 7.704 55301 37012		/ 320.00*
4415 1 HEATER BLOWER CPL 7 87130 37151	/scra 0%	/ 480.00*
4451 1 DEVAPORATOR CPL 2 88510 25090	, 10 N	/ 650.00*
7301 1 POWER STEERING 705380 26061	. 0%	390.00*
7369 1 COLUMN TUBE/SPINDLE 7 45210 37190		350.00*
7505 1 & BRAKE POWER CONTROL 3 44610 25310	/ 100	/ 390.00*
7761 1 RADIATOR 16400 30230	0%	550.00*
7767 X 1 RADIATOR SHROUD * NV16711 30010	0%	110.00*
7793 1 FAN 16361 67020	0%	85.00*
7801 1 FAN CLUTCH 16210 30011	. 0%	195.00*
1000 1 FRT GRILLE CLIP / NC 8PCSX \$1.80	0%	/ 14.40*
1000 1 WIPER ARM CAP CVR /MIS Renew	0%	/ 15.00*
1000 / 1 ♣ FRT CABIN MOUNTING X 2PCS X\$115	0%	/230.00*
1000 1 RR CABIN MOUNTING Y 2PCS X \$220	0%	440.00*
1000 X 1 FRT BRAKE PIPE A SUN 2PCS X \$85	0%	170.00*
1000 1 FRT CLUCTH PIPE 💉 / Renew	0%	85.00*
f: OEM Parts Pub To		\$9,524.40
	Jp From Cost (15 %)	\$1,428.66
	y Parts (Fixed)	\$0.00
DO SERVICIONES CONTROL	Parts	\$10,953.06
x: Exchange		
NB - COLOUR CODED ITEMS/TRIM - P	ART NUMBERS MAY DIFFER	
Extras		

Extras			
Description	Betterment		Price
AUDATEX FEE ATSPECIALIST	0%		\$42.00
FRONT NUMBER SPECIALIST			\$40.00
PLATE / Cut			
ERP BRACKET / LASPECIALIST	0%		\$26.00
AIR CON GAS / SPECIALIST			\$120.00
FRT ADS STICKER ASPECIALIST	. 0%		\$350.00
FRT DR ROC STICKER\$25 X 2PCS			\$50.00
BRAKE OIL / MC 2LITRES X \$	18 0%		\$36.00
AIR CON ASSY MISPECIALIST	others and		\$1,500.00
FRT PANEL INN & SPECIALIST	0%		\$150.00
INSUL			
/ MCC.	Total Extras		\$2,314.00
Final Calculation	130		
Total Parts	EAST WITH		\$10,953.06
Labour			
Total Panel/Mechanical	bns	\$1,860.00	
Total Paintwork	Wheeling and a	\$805.00	
Total Labour			\$2,665.00
Additional Costs	editermin		
Corr Prot Materials External		\$0.00	1
Corr Prot Materials Internal		\$0.00	
Cost of Specialist		\$2,314.00	- ad
Total of Additional Costs		1-1 1100	\$2,314.00
			, -,

Claim Reference:

Full Report - V1

Assessment Number: KKHM0022

Registration: GBB8744A

Version: K.KIMHIN/1

Printed: 10/09/2018 16:10

Date Calculated: 10/09/2018 09:10

\$232.87

Grand Total Excludes GST GST @ 7 %

\$16,164.93 \$1,131.55

Grand Total Includes GST

Total Paint/Material Costs

\$17,296.48

Assessment Notes

17479.18

MDays.

Lungson report

After report phos.

Ano Oup-82880262 13/9/18.

> LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before after spray painting
- . To display damaged part(s) during resurvey.
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K.KIM HIN AUTO PTE LTD 160 Sin Ming Drive #02-20 Sin Ming AutoCity Singapore 575722

Claim Reference:

Assessment Number: KKHM0022

Version: K.KIMHIN/4

Date Calculated: 23/11/2018 03:22

Full Report - V1

Registration: GBB8744A

Printed: 23/11/2018 11:22

AIR CONDITIONING

TWO COAT PEARL/MICA

TACHOMETER

3.0 LTR 80KW

SGD

TBA

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference: Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG) SANDRA KHONG

Interim

MSIG Insurance (Singapore) Pte

True

TOYOTA

Y1N 03 **GBB8744A**

Dyna

150

Currency:

Date of Incident:

04/09/2018 Able to Authorise Repairs: TBA

Repairs Authorised:

Estimated Repair Time: Quote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start:

Hire Car End: Vehicle Collected:

Model Specs

FROM 12/2010

REAR HEATER

DRIVER AIRBAG

SINGLE CAB

Vehicle Details

Vehicle Manufacturer:

Model: Sub Model:

Model Sheet Number: Registration:

Registration Month:

Registration Year:

VIN Number:

Colour:

Engine Number:

Fuel Level:

Odometer:

JTFAT35Y50K201237

Not Known White

1KD2002141

Vehicle Condition

Vehicle Status Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

10/09/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

Claim Reference:


Assessment Number: KKHM0022


Version: K.KIMHIN/4

Date Calculated: 23/11/2018 03:22

Full Report - V1 Registration: GBB8744A

Printed: 23/11/2018 11:22





Addresses

Cost Summary

Total Labour	\$2,375.00
Total Paint/Material	\$227.89
Total Parts	\$6,329.40
Total of Additional Costs	\$814.00
Excess:	TBA
Grand Total Exc GST:	\$9,746.29
7 % GST:	\$682.24
Grand Total Inc GST:	\$10,428.53

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR

Repair Information LABOUR

		Price/Der	nt = \$50.00/HR
Repair /			
Guide Numbe	er Repair Details	wu	Cost Price (\$)
NO NUMBER	R + R DUMPING LINKAGE	9.0	45.00
NO NUMBER	RENEW L/F CAB BRACKET	5.0	25.00
NO NUMBER	RENEW R/F CAB BRACKET	5.0	25.00
NO NUMBER	R + R CAB	30.0	150.00
NO NUMBER	RENEW FRONT PANEL	60.0	300.00
NO NUMBER	R + R BADGE "DYNA"	2.0	10.00
520011)	R + R FRONT BUMPER	4.0	20.00
520011)	RENEW FRONT BUMPER (REMOVED)	2.0	10.00
751011	R + R RADIATOR GRILLE	2.0	10.00
810051)	R + R LEFT HEADLAMP	1.0	5.00
	(RADIATOR GRILLE REMOVED)		
810051)	R + R RIGHT HEADLAMP	1.0	5.00
	(RADIATOR GRILLE REMOVED)		
810151A	ADJUST HEADLAMPS	3.0	15.90
NO NUMBER	R + R L/F LOWER CLOSING PANEL	1.0	5.00
NO NUMBER	R + R R/F LOWER CLOSING PANEL	1.0	5.00
554011)	R + R WINDSCREEN	14.0	70.00
	INCLUDES: R + R SUN VISORS, UPPER FRONT		
	PANEL AND A-PILLAR TRIMS		
670051)	R + R LEFT FRONT DOOR	6.0	30.00
752051	R + R LEFT MIRROR	4.0	20.00
670051)	R + R RIGHT FRONT DOOR	6.0	30.00
NO NUMBER	RENEW FRONT CROSSMEMBER	25.0	125.00
743201)	DETACH + REFIT HEADLINING	4.0	20.00
	INCLUDES: R + R INSIDE MIRROR, PILLAR		
	TRIMS AND SEAT BELTS		
NO NUMBER	R + R L/F LOWER DOOR SEAL	2.0	10.00
NO NUMBER	R + R R/F LOWER DOOR SEAL	2.0	10.00

Claim Reference:

Full Report - V1 Registration: GBB8744A Assessment Number: KKHM0022

Printed: 23/11/2018 11:22

Version: K.KIMHIN/4

Date Calculated: 23/11/2018 03:22

870031)	R + R HEATING CPL	12.0	60.00
870151		5.0	25.00
NO NUMBER		4.0	20.00
550451)	R + R INSTRUMENT PANEL	9.0	45.00
550451)	RENEW INSTRUMENT PANEL (REMOVED)	4.0	20.00
NO NUMBER		2.0	10.00
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	5.00
850171)	R + R WIPER LINKAGE	1.0	5.00
002019)	DRAIN + REFILL COOLANT	3.0	15.00
463011)	R + R BOOSTER	3.0	15.00
461101)	R + R BRAKE MASTER CYLINDER	2.0	10.00
	INCLUDES: BLEED BRAKE SYSTEM		
442151 ZAX	R + R STEERING SHAFT	2.0	10.00
441101	R + R STEERING WHEEL	2.0	10.00
NO NUMBER	DETACH + REFIT STEERING SPINDLE	5.0	25.00
881151 ZAX	R + R CONDENSER	8.0	40.00
002889 ZAX	DRAIN AND REFILL AIR CONDITIONING	7.0	35.00
0911	REPAIR L/OUTER A-PILLAR	20.0*	100.00
0912	REPAIR R/OUTER A-PILLAR	20.0*	100.00
3000	REPAIR FRAME CPL	20.0*	100.00
	BOUR COST		
	Total Work Units	319.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	31.9HRS	\$1,595.00
	Paint Labour	15.6HRS	\$780.00
	Total Labour	47.5HRS	\$2,375.00

PAINT WORK Time Basis 1		0 WU = 1 HR. Price =	\$50.00/HR
Guide Number Description WU		Cost Price (\$)	
	- TWO COAT PEARL/MICA		
281	FRONT BUMPER NEW PART PAINTING	12.0	
414	FRONT LOWER PANEL NEW PART PAINTING	19.0	
418	UPPER FRONT PANEL NEW PART PAINTING	8.0	
885	L/F UPPER END PANEL NEW PART PAINTING	6.0	
886	R/F UPPER END PANEL NEW PART PAINTING	6.0	
889	L/F LOWER END PANEL NEW PART PAINTING	6.0	
890	R/F LOWER END PANEL NEW PART PAINTING	6.0	
1481	LEFT FRONT DOOR NEW PART PAINTING	16.0	
1482	RIGHT FRONT DOOR NEW PART PAINTING	16.0	
410	GRILLE NEW PART PAINT K1R	5.0	
911	L/OUTER A-PILLAR REPAIR PAINTING >50%	15.0	
912	R/OUTER A-PILLAR REPAIR PAINTING >50%	15.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	130.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	156.0	
	Total Paintwork Labour	15.6HRS	\$780.00
	MATERIAL COST - PAINT		Cost Price

Claim Reference:

Assessment Number: KKHM0022

Version: K.KIMHIN/4

Date Calculated: 23/11/2018 03:22

Full Report - V1
Registration: GBB8744A

Printed: 23/11/2018 11:22

New Part Painting	\$161.32
New Part Painting - Plastic K1R	\$11.81
Repair Painting	\$27.66
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$227.89
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$227.89

PARTS				Price	e Valid: 01/06/2015
Guide N	o.Otv	Description	Part Number Supp	olier E	Bet. Price (\$)
281	1	FRONT BUMPER	52101 25912	0	% 165.00 *
385	1	UPP RAD GRILLE SEAL	53119 37080B0		30.00
410	1	GRILLE	53114 37010	0	% 165.00 *
414	1	FRONT LOWER PANEL	55711 37051	0	340.00
417	1	END MOULDING	53928 37011	C	% 110.00 *
418	1	UPPER FRONT PANEL	55078 37070	0	% 110.00 *
481	1	BADGE	75315 37011	C	35.00
484	1	BADGE MODEL	75311 37130	0	% 35.00 *
561	1	LEFT HEADLAMP ASSY	81170 37171	C	% 215.00 °
562	1	RIGHT HEADLAMP ASSY	81130 37170		% 215.00°
563	1	L/HEADLAMP TRIM	81193 37050		0% 25.00 °
564	1	R/HEADLAMP TRIM	81193 37050		25.00
887	1	L/END MOULDING	53922 25011		60.00
888	1	R/END MOULDING	53921 25011		0% 60.00°
889	1	L/F LOWER END PANEL	53802 37021		0% 85.00 °
890	1	R/F LOWER END PANEL	53801 37021		% 85.00°
1401	1	WINDSCREEN	56111 37120		0% 485.00°
1410	1	WINDSCREEN SEAL	56121 25040		0% 100.00
		L/F WIPER ARM	85221 37150		0% 65.00
1453 1454	1	R/F WIPER ARM	85211 37070		0% 65.00
1454		L/F WIPER BLADE	85222 37141		60.00
	1	R/F WIPER BLADE	85212 37081		0% 60.00
1458			51702 25060		0% (220.00
2759	1	L/F SUPPORT BRACKET	51701 25110		0% / 220.00
2760	1	R/F SUPPORT BRACKET BT	54801 25052		0% (A) 560.00°
2812	1	SITT I LINKAGE	51211 25100		
3010	1	FRONT CROSSMEMBER	55301 37012B0		0% (A) 115.00 320.00
4331	1	INSTRUMENT PANEL	83800 25A20		0% (Å)520.00°
4366	1	COMBI INSTRUMENT			0% 480.00
4415	1		87130 37151		650.00
4451	1	EVAPORATOR CPL	88510 25090		0% / 390.00°
7505	1	BRAKE POWER CONTROL	44610 25310		0% / 14.40
1000	1	FRT GRILLE CLIP	8PCSX \$1.80		0% 15.00
1000	1	WIPER ARM CAP CVR	Renew		
1000	1	FRT CABIN MOUNTING	2PCS X\$115		230.00
f: OEM P			Sub Total	. (0.0/)	\$6,329.40
g: Origin		1 30 5	Mark Up From Co		\$0.00
h: Secon			Sundry Parts	(Fixed)	\$0.00
p: Paralle	el		Total Parts		\$6,329.40

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Claim Reference:

Assessment Number: KKHM0022

Version: K.KIMHIN/4

Assessment Notes

Date Calculated: 23/11/2018 03:22

Full Report - V1 Registration: GBB8744A

Printed: 23/11/2018 11:22

	Description		Betterment		Price
	AUDATEX FEE	SPECIALIST	0%		\$42.00
	FRONT NUMBER	SPECIALIST			\$40.00
	PLATE		00/		\$26.00
	ERP BRACKET	SPECIALIST	0%		
	AIR CON GAS	SPECIALIST			\$120.00
	FRT ADS STICKER	SPECIALIST	0%		\$350.00
	FRT DR ROC STICKE				\$50.00
	BRAKE OIL	2LITRES X \$18	0%		\$36.00
	FRT PANEL INN INSUL	SPECIALIST			\$150.00
	111002		Total Extras		\$814.00
Final C	alculation				
Total Pa					\$6,329.40
Labour					
	Total Panel/Mechanical			\$1,595.00	
	Total Paintwork			\$780.00	
Total La	bour				\$2,375.00
	al Costs				
	Corr Prot Materials Extern	nal		\$0.00	
	Corr Prot Materials Intern	nal		\$0.00	
	Cost of Specialist			\$814.00	
Total of	Additional Costs				\$814.00
Total Pa	int/Material Costs				\$227.89
	otal Excludes GST				\$9,746.29
	GST @ 7 %				\$682.24
	otal Includes GST				\$10,428.53

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRACK	ING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	A	dj Submitted	Ins Auth'ed	111111111111111111111111111111111111111	
	10 Sep 2018 16:22 Sendback Est	10 Sep 2018 16:27 S\$16,164.93	13 Sep 2018 09:01 Edit Adj Rpt	S\$9,700.00 Edit Estimates	1	\$9,700.00 View Rpt		Report Cancel	for Survey
	lain	Refere	ence	Claim Deta	ails		Document	s	Show All
CLAIM SU	SFOLDER DETA	ILS	A STATE OF THE PARTY OF						
Insured:	HENG LIM S	ERVICES PTE LTD	Co. Reg. No.: 0						
Main Claimant:	HARVEST BU	JILDING PRODUC	TS PTE LTD, Co	. Reg. No.: 20091	4531F	2			
Vehicle Reg. No.:	GBB8744A	(p		Date of I	.oss:	04/09/2018 1: [96 Months an		n LTA Reg Date (Man Yr)]
Claim Type:	TP / 56993	2		Policy/Co Note No.		B27450516TM Coverage: 13/			
Vehicle Reg. No. (Insured):	XD147E			Policy No (Claiman		A28806552MKC			
				Excess:					
Repairer:	K Kim Hin A	uto Pte Ltd (HQ)	160 Sin Ming Drive	#02-20, Sin Ming	Auto	City, 575722 S	in Ming - Tel:	64527018	
Handling Insurer:	MSIG Insura	nce (Singapore)	Pte. Ltd. (HQ) -	Tel: +65 6827 788	8 [Handled by Ch	ristina Wong	- 6643 1311]	
Claimant's Insurer:		ince (Singapore)		DESCRIPTION SCALE	177				
Adjuster:		nsultants Pte Ltd							
Adj Asg. Remarks:	Car in, survey Shu Man / 64	by today. on WP. 52 7018.	Please contact us	ASAP if you cannot	atter	nd this assignm	ent. Liability 1	00%. Contact Pe	rson: Wong
ASSOCIAT	ED MAIL RECE	IVED					Vie	ew All Compo	se Case Mail
There are no	mail for this cas	se.						=======================================	
ALL ASSO	CIATED TASKS	∃			v	/iew All Sear	rch Tasks C	Create New Task	Complete
Due Date	Priority	Type Task Gro	up Subject	Handler A	ssign	ed By Co	ompleted On	Created O	n Done?

Merimen e-Claims Page 1 of 4

Claim Documents

GBB8744A (569932)

[XD147E]

TP

HARVEST BUILDING PRODUCTS PTE LTD

Sep 4 2018 11:00AM

[HENG LIM SERVICES PTE LTD]


K Kim Hin Auto Pte Ltd

Ass	sessment Reports		1 per p	page 🔻	~
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Prin
1	07/09/18 17:04	Accident Statement	0	Load HTM	
2	10/09/18 16:27	Repairer Estimates	0	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Prin
1	12/09/18 10:25	Accident Statement From:SC - Reg. No: XD147E, Claimant: HENG LIM SERVICES PTE LTD	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	29/05/19 11:01	Adjuster Immediate Advice	0	Load HTM	
Dhe	otos/Images		2 nor 1	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per	Thumbnail	+
1	23/05/19 16:39	General View	0	Load JPG	V
2	23/05/19 16:39	General View	0	Load JPG	V
3		General View	0	Load JPG	V
	23/05/19 16:39	General View	0	Load JPG	₹
4	23/05/19 16:39				-
5	23/05/19 16:39	General View	0	Load JPG	V
6	23/05/19 16:39	General View	0	Load JPG	∀
7	23/05/19 16:39	General View	0	Load JPG	<u>~</u>
8	23/05/19 16:39	General View	0	Load JPG	₹
9	23/05/19 16:39	General View	0	Load JPG	✓
10	23/05/19 16:39	General View	0	Load JPG	✓
11	23/05/19 16:39	General View	0	Load JPG	~
12	23/05/19 16:39	General View	0	Load JPG	V
13	23/05/19 16:39	General View	0	Load JPG	✓
14	23/05/19 16:39	General View	0	Load JPG	V
15	23/05/19 16:39	General View	0	Load JPG	V
16	23/05/19 16:39	General View	0	Load JPG	~
17	23/05/19 16:39	General View	0	Load JPG	V
18	23/05/19 16:39	General View	0	Load JPG	V
19	23/05/19 16:39	General View	0	Load JPG	V
20	23/05/19 16:39	General View	0	Load JPG	V
21	23/05/19 16:39	General View	0	Load JPG	V
22	23/05/19 16:39	General View	0	Load JPG	V
23	150 15 CAN CONTROL OF	General View	0	Load JPG	V
1000	23/05/19 16:39			J 7955-2	_
24	23/05/19 16:39	General View	0	Load JPG Load JPG	₹ V
25	23/05/19 16:39	General View	0		-
26	23/05/19 16:39	General View	0	Load JPG	V
27	23/05/19 16:39	General View	0	Load JPG	V
28	23/05/19 16:39	General View	0	Load JPG	V
29	23/05/19 16:39	General View	0	Load JPG	V

Ass	essment Reports		1 per page 🗸] V
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail Load JPG	
30	23/05/19 16:39	General View		\ <u>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</u>
1	23/05/19 16:39	General View	1 Load JPG	4
2	23/05/19 16:39	General View	1 Load JPG	V
3	23/05/19 16:39	General View	1 Load JPG	V
4	23/05/19 16:39	General View	1 Load JPG	~
5	23/05/19 16:39	General View	1 Load JPG	V
86	23/05/19 16:39	General View	1 Load JPG	4
37	23/05/19 16:39	General View	Load JPG	V
8	24/05/19 08:57	General View	Load JPG	5
19	24/05/19 08:57	General View	1 Load JPG	-
0	24/05/19 08:57	General View	Load JPG	5
1	24/05/19 08:57	General View	Load JPG	Į.
2	24/05/19 08:57	General View	Load JPG	5
3	24/05/19 08:57	General View	Load JPG	5
4	24/05/19 08:57	General View	1 Load JPG	6
5	24/05/19 08:57	General View	1 Load JPG	5
6	24/05/19 08:57	General View	1 Load JPG	6
7	24/05/19 08:57	General View	1 Load JPG	6
200	CONSTRUCTOR AND CONTROL	Contraction (1994) Contraction		6
8	24/05/19 08:57	General View	1 Load JPG	_
19	24/05/19 08:57	General View	1 Load JPG	<u> </u>
0	24/05/19 08:57	General View	1 Load JPG	5
1	24/05/19 08:57	General View	1 Load JPG	5
52	24/05/19 08:57	General View	1 Load JPG	5
3	24/05/19 08:57	General View	1 Load JPG	6
4	24/05/19 08:57	General View	1 Load JPG	5
55	24/05/19 08:57	General View	Load JPG	<u>-</u>
6	24/05/19 08:57	General View	Load JPG	5
7	24/05/19 08:57	General View	1 Load JPG	5
8	24/05/19 08:57	General View	1 Load JPG	5
9	24/05/19 08:57	General View	Load JPG	5
50	24/05/19 08:57	General View	1 Load JPG	5
51	24/05/19 08:57	General View	■ Load JPG	
52	24/05/19 08:57	General View	1 Load JPG	Q
3	24/05/19 08:57	General View	1 Load JPG	6
4	24/05/19 08:57	General View	Load JPG	
5	24/05/19 08:57	General View	Load JPG	T-
6	24/05/19 08:57	General View	1 Load JPG	-
7	24/05/19 08:57	General View	Load JPG	5
_	24/05/19 08:57	General View	Load JPG Load JPG	5
8	The state of the s		1 Load JPG	2
9	24/05/19 08:57	General View	1 Load JPG	2
0	24/05/19 08:57	General View		_
1	24/05/19 08:57	General View	Load JPG	<u>-</u>
2	24/05/19 08:57	General View	1 Load JPG	5
3	24/05/19 08:57	General View	1 Load JPG	5
4	24/05/19 08:57	General View	1 Load JPG	5
5	24/05/19 08:57	General View	1 Load JPG	5
6	24/05/19 08:57	General View	1 Load JPG	5
7	24/05/19 08:57	General View	1 Load JPG	_
8	24/05/19 08:57	General View	1 Load JPG	5
79	24/05/19 08:57	General View	Load JPG	5

Ass	essment Reports		1 per p	page 🔻	V
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
80	24/05/19 08:57	General View	0	Load JPG	✓
81	24/05/19 08:57	General View	0	Load JPG	V
82	24/05/19 08:57	General View	0	Load JPG	☑
83	24/05/19 08:57	General View	Ð	Load JPG	✓
84	24/05/19 08:57	General View	0	Load JPG	V
85	24/05/19 08:57	General View	0	Load JPG	✓
86	24/05/19 08:57	General View	0	Load JPG	V
87	24/05/19 08:58	Photo After Spray	0	Load JPG	V
88	24/05/19 08:58	Photo After Spray	0	Load JPG	✓
89	24/05/19 08:58	Photo After Spray	0	Load JPG	✓
90	24/05/19 08:58	Photo After Spray	0	Load JPG	✓
Dog	cumentation		1 per	page 🔻	V
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	10/09/18 16:27	AUDATEX	0	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/09/18 14:38	TP said vehicle is in, to survey vehicle tomorrow on 13.09.18	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/05/19 09:40	Supplementary	0	Load PDF	

Linked Accident Report Documents



Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18016778/GCD3E2

Date:

30/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B27450516TMV

Claimant Vehicle

Date of Loss:

GBB8744A

Insured Vehicle No:

XD147E

No:

04/09/2018

Nature of Claim:

TP

Claim No: 569932

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBB8744A

Make & Model:

TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) Engine No:

1KD2002141

355929 km

Reg. Date:

26/08/2010 (Man. Year: 2010)

Chassis No: Odometer:

JTFAT35Y50K201237

Colour: Engine Capacity:

2982 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

195 R15

Rear Tyre Size:

155 R12 (D)

Front Left Side: Front Right Side: Bridgestone 5 mm Bridgestone 5 mm

Rear Left Side: Rear Right Side: Bridgestone 5/5 mm Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,953.06	6,329.40	4,623.66	42.21
Miscellaneous Items	2,314.00	814.00	1,500.00	64.82
Paintwork Materials	232.87	227.89	4.98	2.14
Labour	1,860.00	1,595.00	265.00	14.25
Paintwork Labour	805.00	780.00	25.00	3.11
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,164.93	9,746.29	6,418.64	39.71
Approved Total (Overridden) (S\$)		9,700.00		
(S\$)	16,164.93	9,700.00	6,464.93	39.99
+ GST 7.00/7.00% (S\$)	1,131.55	679.00	452.55	39.99
Nett Amount (S\$)	17,296.48	10,379.00	6,917.48	39.99

INSPECTION

Date of Assignment:

13/09/2018 Present Location:

K Kim Hin Auto Pte Ltd (HQ)

Date Inspected:

13/09/2018 Inspected At:

K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair:

9.0 days

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	се				
Part Source	:	(Last Synchronised: 30 May 2019)			
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted	I, no print-code for GBB8744A)			
Validity:	These estimate numbers with	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

Qty Pa	art No.	Particulars	Condition	Repairer's	Amount
1		*SPARE PARTS		10,953.06 F	*5,134.40 F
1		*SHIFT LINKAGE	Bent	-	*560.00 F
1		*FRONT CROSSMEMBER	Bent	-	*115.00 F
1		*HEATER BLOWER CPL	Cracked		*520.00 F
anchise par	rt.		Total Parts (S\$)	10,953.06	6,329.40
	1 1 1 1	Qty Part No. 1 1 1 1 anchise part.	1 *SPARE PARTS 1 *SHIFT LINKAGE 1 *FRONT CROSSMEMBER 1 *HEATER BLOWER CPL	1 *SPARE PARTS 1 *SHIFT LINKAGE Bent 1 *FRONT CROSSMEMBER Bent 1 *HEATER BLOWER CPL Cracked	1 *SPARE PARTS 10,953.06 F 1 *SHIFT LINKAGE Bent - 1 *FRONT CROSSMEMBER Bent - 1 *HEATER BLOWER CPL Cracked - anchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mat	erials				
1	1	PAINT/MATERIAL COSTS		232.87	227.89
Mis	cellar	neous Items			
2	1	COST OF SPECIALIST		2,314.00	814.00
			Sub Total (S\$)	2,546.87	1,041.89

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Pair	twork Labour			
1	PAINTWORK	New	805.00	780.00
Lab	our Items			
2	PANEL/MECHANICAL	New	1,860.00	1,595.00
		Gross Labour Cost (S\$)	2,665.00	2,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >