

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2018)**Parts:** 144 MERCEDES-BENZ A200 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SCU2221U)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CON CONDENSER / Cut	0.00	0.00	*1,100.00 F
2	1		*RADAR SENSOR / NW	0.00	0.00	*1,170.00 F
3	1		*RADAR SENSOR BRACKET / 22	0.00	0.00	*25.00 F
4	1		*CROSS MEMBER COVER / Cut	0.00	0.00	*68.00 F
5	1		*REAR BUMPER LOWER UNDER COVER BRACKET X NW	0.00	0.00	*95.00 F
6	1		*FRONT GRILLE OUTER GARNISH / CRA	0.00	0.00	*120.00 F

F=Franchise part.

Sub Total (\$\$)	2,578.00
- Add. Disc. on L,N Items 10.00% (\$\$)	257.80
Total Parts (\$\$)	2,320.20

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS2483
10%, 234.7

1345.80