

Surveyor:

WAPUS

DOI:

ASSIGNMENT

13/9/18

Date/Time:

13/9/18

Registered in Merimen:

14/9/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SIL 7562S

Name of Insured:

TA PINT & DRIVE P/L

Insured Tel No.:

HP:

Claim No.:

Policy No.:

099994608

Make / Model:

7. Vios

Excess Sec II :SS

D.O.A.:

12/9/18

Place of Accident:

AYE 774AS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Kwok Chiu Ping

Driver Tel No.:

96812402

(VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SLV 7234M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

18/9/18

SLV 7234M - X ;

SIL 7562S - CS/PU150 (1083/Gy60.10A3/10/10)

28-9-18

4VC OI 2ND A: - 09. @ 11AM CALLED - NO ANSWER

5-10-18

@ 502PM CALLED - NO ANSWER.

CHAIN COLLISION.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

21/5-10-18

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PDR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

15-10-18

Confirm with:

JOHNSON

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

286(ii)

Email

Call

Repair Cost:

S\$

3,210

Loss of Rental (LOR):

S\$

780

(4.5 days)

X120

Loss of Use (LOU):

S\$

-

(\$ x days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost:

S\$

-

Total:

S\$

3,997.49

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,997.49

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N/A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N/A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ANW

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLV 7234m

at Workshop m/s Tashm

of _____

Insured: SJL 75625

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 286.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LTA 22791

Vehicle: IN / OUT

Date: _____ Person Contacted: 32576

Date / Time Action / Instruction

17/9/18 see inst. 1 p21/1/2023

car found 1/5 @ 3000. m/s Cayman.

Veh No: SLV 7234m Yr Regn: 1, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prima Mover /

Truck / Trailer or CA /

Make: Honda stream c.c. 1799

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 112197 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN 61053586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 12/9/18 D.O.I. 13/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



Date of Accident : 12 September 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Nur Azera Binte Johana

Date : 14 September 2018

Chassis No : RN61053586

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>50450</i>	\$ 903.20
02	1 pc	tailgate lid lock <i>0/HW1</i>	\$ 109.40
03	1 pc	tailgate lid lock stricker <i>11</i>	\$ 27.50
04	1 pc	tailgate lid weatherstrip <i>7W1</i>	\$ 121.60
05	1 pc	tailgate lid inner trimboard <i>CNE</i>	\$ 141.00
06	1 pc	tailgate lid inner closing garnish <i>11</i>	\$ 25.00
07	2 pc	tailgate lid rubber stopper @ \$12.50 <i>11</i>	\$ 25.00
08	2 pc	tailgate lid absorber stay @ \$118.60 <i>11</i>	\$ 237.20
09	1 pc	tailgate lid stream badge <i>MC</i>	\$ 31.60
10	1 pc	tailgate lid outer garnish <i>11</i>	\$ 162.80
11	1 pc	tailgate lid outer garnish emblem badge <i>11</i>	\$ 21.90
12	1 pc	rear windshield glass weatherstrip <i>MC</i>	\$ 65.00
13	2 pc	rear license plate lamp @ \$32.80 <i>11</i>	\$ 65.60
14	1 pc	rear end panel <i>R</i>	\$ 306.70
15	1 pc	rear end panel inner trim <i>11</i>	\$ 116.70
16	1 pc	rear bumper <i>713</i>	\$ 588.90
17	2 pc	rear bumper side retainer @ \$19.40 <i>3af</i>	\$ 38.80
18	2 pc	rear bumper side holder @ \$10.00 <i>11</i>	\$ 20.00
19	8 pc	rear bumper clips @ \$3.90 <i>MC</i>	\$ 31.20
20	1 pc	rear bumper tow cover <i>HW1</i>	\$ 13.90
21	1 pc	rear bumper screw <i>11</i>	\$ 16.00
22	1 pc	n/s rear lamp <i>CNE</i>	\$ 385.50
23	3 pc	rear lamp clip holder @ \$7.00 <i>11</i>	\$ 21.00
		Less 20 %	\$ 3,475.50
			\$ 695.10
			\$ 2,780.40
		<u>SPECIAL NETT ITEMS</u>	
24	1 pc	rear windshield glass sealant <i>MC</i>	\$ 180.00
25	1 pc	rear windshield glass sponge <i>MC</i>	\$ 100.00
26	1 pc	rear license plate <i>11</i>	\$ 60.00
27	1 pc	back off camera lens <i>11</i>	\$ 380.00
28	1 pc <i>set</i>	rear bumper parking sensor <i>short</i>	\$ 450.00
			\$ 1,170.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To remove and refit rear windscreen glass.	\$ 180.00
02		To rust-proofing of the affected areas.	\$ 150.00



陳林瑞峰私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJL7562S
Date of Accident : 12 September 2018

Miss Nur Azera Binte Johana

Date : 14 September 2018

Estimate To Repair SLV7234M - Honda Stream 1.8A

Chassis No : RN61053586

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 160.00
04		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
05		To reinstall of rear bumper parking sensor.	\$ 120.00
06		To check electrical lighting concerned.	\$ 60.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
08		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,820.00
		Total	\$ 6,770.40

80
60
40
30
550
600
1540

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1944.08
S.N-270
Labour-1540
3754.08
202
3003.24



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SJL7562S
Date of Accident : 12 September 2018

Miss Nur Azera Binte Johana

Date : 13 September 2018

Estimate To Repair SLV7234M - Honda Stream 1.8A
Chassis No : RN61053586

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid <i>10/6/00</i>	\$ 0.00
02	1 pc	tailgate lid lock <i>50/100</i>	\$ 0.00
03	1 pc	tailgate lid lock stricker <i>11X</i>	\$ 0.00
04	1 pc	tailgate lid weatherstrip <i>721</i>	\$ 0.00
05	1 pc	tailgate lid inner trimboard <i>CRA</i>	\$ 0.00
06	1 pc	tailgate lid inner closing garnish <i>11X</i>	\$ 0.00
07	2 pc	tailgate lid rubber stopper @ \$.00 <i>11X</i>	\$ 0.00
08	2 pc	tailgate lid absorber stay @ \$.00 <i>11X</i>	\$ 0.00
09	1 pc	tailgate lid stream badge <i>11</i>	\$ 0.00
10	1 pc	tailgate lid outer garnish <i>11</i>	\$ 0.00
11	1 pc	tailgate lid outer garnish emblem badge <i>11X</i>	\$ 0.00
12	1 pc	rear windshield glass weatherstrip <i>11</i>	\$ 0.00
13	2 pc	rear license plate lamp @ \$.00 <i>11X</i>	\$ 0.00
14	1 pc	rear end panel <i>11X</i>	\$ 0.00
15	1 pc	rear end panel inner trim <i>11X</i>	\$ 0.00
16	1 pc	rear bumper <i>113</i>	\$ 0.00
17	2 pc	rear bumper side retainer @ \$.00 <i>11</i>	\$ 0.00
18	2 pc	rear bumper side holder @ \$.00 <i>11X</i>	\$ 0.00
19	8 pc	rear bumper clips @ \$.00 <i>11</i>	\$ 0.00
20	1 pc	rear bumper tow cover <i>11</i>	\$ 0.00
21	1 pc	rear bumper screw <i>11X</i>	\$ 0.00
22	1 pc	n/s rear lamp <i>CRA</i>	\$ 0.00
23	3 pc	rear lamp clip holder @ \$.00 <i>11X</i>	\$ 0.00
		Less 20 %	\$ 0.00
<u>SPECIAL NETT ITEMS</u>			
24	1 pc	rear windshield glass sealant <i>11 40</i>	\$ 180.00
25	1 pc	rear windshield glass sponge <i>11 30</i>	\$ 100.00
26	1 pc	rear license plate <i>11X</i>	\$ 60.00
27	1 pc	back off camera lens <i>11X</i>	\$ 380.00
28	1 pc	rear bumper parking sensor <i>11 200</i>	\$ 450.00
			\$ 1,170.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear windscreen glass. <i>120</i>	\$ 180.00
02		To rust-proofing of the affected areas. <i>50</i>	\$ 150.00



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJL7562S
Date of Accident : 12 September 2018

Miss Nur Azera Binte Johana

Date : 13 September 2018

Estimate To Repair SLV7234M - Honda Stream 1.8A
Chassis No : RN61053586

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 160.00
04		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
05		To reinstall of rear bumper parking sensor.	\$ 120.00
06		To check electrical lighting concerned.	\$ 60.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
08		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,820.00
		Total	\$ 3,990.00

80
60
50
30
150
600

ACKNOWLEDGEMENT: The repairer hereby notify the insurance company of the following:

- The repairer will perform spray painting
- The repairer will perform during resurvey
- The repairer is subject to confirmation
- The repairer is on a "Without Prejudice" basis
- No warranty/indemnity is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Inchcape
Pre-Owned

**WIDE RANGE OF PRE-OWNED
TOYOTA AND OTHER CARS
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRES

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Undriven 03/2018 Mazda 3 @ \$79K 100% Zero Downpayment



No Hidden Cost! \$0 Down
Payment. Cash Less Than
\$2500. \$790 Monthly. Call Now
Privilege Group Pte StarAd



Post an Ad

Advertiser Login

Ways of Selling

« Back (1 2 3 4 5 6) Next »

Sort by

Browse by Category

ADVANCE

107 vehicles

honda stream

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mi
		Any	Any	> 10 year(s) old	Any	
Search Selection	honda stream					



Honda Stream 1.8A X (COE till 08/2023)

\$32,800

\$6,700 /yr

07-Aug-2008

1,799 cc

\$2000 Down Payment, Lowest Monthly From \$638 Onwards. Low Interest At 3.18% Per Annum By GV Cars Financing. Warranty By GV In House Workshop. New 2k Metallic Paint/6 Mths R...

\$2000 Downpayment Monthly From \$638 Onwards. Lowest 3.18%P.A@GV Cars Financing
GV Credit Pte Ltd

Posted: 14-Sep-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A RSZ (COE till 08/2023)

\$33,800

\$6,900 /yr

08-Aug-2008

1,799 cc

\$2000 Down Payment, Lowest Monthly From \$638 Onwards. Low Interest At 3.18% Per Annum By GV Cars Financing. Warranty By GV In House Workshop. New 2k Metallic Paint/6 Mths R...

\$2000 Downpayment Monthly From \$638 Onwards. Lowest 3.18%P.A@GV Cars Financing
GV Credit Pte Ltd

Posted: 14-Sep-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A (COE till 08/2023)

\$32,800

\$6,660 /yr

18-Aug-2008

1,799 cc

\$2000 Down Payment, Lowest Monthly From \$638 Onwards. Low Interest At 3.18% Per Annum By GV Cars Financing. Warranty By GV In-House Workshop. New \$2k Metallic Paint/6 Month...

\$2000 Downpayment Monthly From \$638 Onwards. Lowest 3.18%P.A@GV Cars Financing
GV Credit Pte Ltd

Posted: 14-Sep-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda



Honda Stream 1.8A X (New 5-yr COE)

\$31,800

\$6,360 /yr

03-Jul-2008

1,799 cc

3 Months Engine/Gearbox Warranty From Our In-house Workshop, Stabilizer Link Replaced And Valve Cover Gask...
Warranty From Our In House Workshop, Good Condition, Accident Free...

1payment Monthly From \$558 Onwards. Low 3.18%, In-House Warranty / Loan.

ad: 14-Sep-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3251E

Vehicle Details

Vehicle No.:	SLV7234M
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	R18A1759993
Chassis No.:	RN61053586
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,471.00
Original Registration Date:	24 Jan 2008
First Registration Date:	24 Jan 2008
Transfer Count:	1
Actual ARF Paid:	\$19,219.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Jan 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,136.00
COE Rebate Amount:	\$22,791.00
Total Rebate Amount:	\$22,791.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Sep 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP018092018
Your Ref SJL 75628

Date 21-09-2018

WITHOUT PREJUDICE

Claims Department - Executive in charge MS JOY IRENE
40 LKR CCB/A1418016700/Uja3
ALG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SLV 7234M & SJL 75628

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / _____ copies of photographs _____
☒ Original Tax-invoice number TP018/021 ☒ Original rental invoice number 17181343
☒ SAS / AS & IS / police report ☐ police result
☒ Certificate Of Insurance NRUE INCOME ☒ Vehicle search result
☐ Authorization to act ☐ _____

*Survey under insurance instruction / Independent surveyor / No survey.

a) Cost of repair (inclusive GST)	\$ <u>3,210.00</u>
b) Survey fees / Photographs as per request	\$ _____
c) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
d) Loss of hire / use / repair / earnings / rental fees	\$ <u>1,530.10</u>
e) Scene photographs	\$ _____
f) Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ _____
g) _____	\$ _____
Total	\$ <u>4,747.59</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlmotor.com.sg / sam@tlmotor.com.sg / johnson.chua@tlmotor.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18016788/Uja3

05 October 2018

SG RENT & DRIVE PTE LTD
210 TURF CLUB ROAD
#A12-A27
THE GRANDSTAND
SINGAPORE (287995)

Dear Sir/Madam,

ACCIDENT INVOLVING SJL 7562S / SLV 7234M / OTHERS ON 12/09/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Joy Irene
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: joyirene@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Nur Azera Binte Johana ("the third party claimant")
of Block 443 Hougang Avenue 3 #07-1581 S' 530443 (address),
owner of SLV7034M (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLV7034M that was
damaged pursuant to the accident which occurred on 10.09.2018 (date) along
AYE (location)
involving vehicle no/s SJL7562S ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 13th day of 09 (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,210.00 (Repair Cost), S\$780.00 (Loss of ~~Use~~/Rental) S\$7.49 (Disbursement) for vehicle no. SLV 7234M that was damaged pursuant to the accident which occurred on 12/09/2018 (date) along AYE (location) involving vehicle no/s SIL 7562S. This is pursuant to the inspection conducted on 13/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NUR AZERA BINTE JOHANA ("the third party claimant") of vehicle no. SLV 7234M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".



We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLV 7234M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15th (day) of October (month) 2018 (year)

 cks
Signed by appointed surveyor

 
Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0918/021

(Please quote our reference number TP018092018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


Nur Azera Binte Johana

Date: 21/09/2018

Vehicle No: SLV7234M
Model: HONDA STREAM 1.8 A

Description	Amount
To lump sum repair as recommended by surveyor.	\$3,000.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$3,007.00
Add 7% GST	\$210.49
Total	\$3,217.49


Tan Lim Motor Pte Ltd

Bill To: NUR AZERA BINTE JOHANA (C/O TAN LIM MOTOR PTE LTD)
BLK 443 HOUGANG AVENUE 8
#07-1581
SINGAPORE 530443

Tax Invoice : 17181343
Date : 19 SEP 2018
Agreement No. : ST7115

Vehicle No	Description	Total Amount
SJR5026E	Mitsubishi Grandis 2.4L Sports-Gear Rental Charges From 13-09-2018 to 19-09-2018 6.5 days @ \$220.00 per day	SGD 1,430.00

PAID
20 SEP 2018
BY: Cash

Sub-Total 1,430.00
Add: GST (7.00%) 100.10
Amount Payable (SGD) 1,530.10

SINGAPORE DOLLAR: ONE THOUSAND FIVE HUNDRED THIRTY AND CENTS TEN ONLY.

Cheque should be crossed "A/C Payee Only" and made payable to GLOBAL ADVANCE LEASING.

Please write your invoice number on the reverse side of the cheque.

Payment should be made within 7 days from invoice.

Interest at 24% per annum on overdue account.

For bill enquiry, please call 6100 0425 / 9018 0988

**GLOBAL ADVANCE LEASING**

Biz Reg: 852935825E
 GST Reg No: 200408785W
 C/o 51 Delfu Lane 10 S1539216
 Tel: 610006AL

Agreement: 7115

Vehicle No SJR 5026 E		Make & Model Nit. Cronos		Date 13.09.2018
Hirer Name Nur Azera Birte Johana Address 443 Hanyang Avenue 8 #07-1581 S (530443) Contact Person _____ Tel 94597823		Class 2 / 2A / 2B / 3 / 4 / 5 Check Out / Check In Date Out 13.09.2018 Time Out 1215 Ls KM Out 195350 PETROL E 1/4 1/2 3/4 F Date In 19.09.2018 Time In 1510 Ls KM In 195704 PETROL E 1/4 1/2 3/4 F		
1st Driver Name Siti Nur Aziefalyana Birte Johana Address As above (H/P) 81808459 (O) _____ (H) _____ Passport/IRIC No S9711002 F Nationality Singapore Driving Licence No _____ Driving Exp 1 yr 5 mths Country of Issue Singapore Expiry Date Unlimited		Mode of Payment Cash / Cheque / Company Billing / Credit Card / Others Cheque / Card Details: _____ Expiry Date: _____		
Additional Driver Name _____ Address _____ (H/P) _____ (O) _____ (H) _____ Passport/IRIC No _____ Nationality _____ Driving Licence No _____ Driving Exp _____ yrs Country of Issue _____ Expiry Date _____		Rental Charges 6.5 Day/s @ \$ 220.00 /day \$ 1430.00 _____ Week/s @ \$ _____ /week \$ _____ _____ Month/s @ \$ _____ /month \$ _____ SUBTOTAL \$ _____ CDW @ \$ _____ \$ _____ PAI @ \$ _____ \$ _____ Petrol Top Up \$ _____ Delivery / Collection fee \$ _____ Misc \$ 100.10 Misc \$ _____ Less _____ Pre-Payment / Deposit (S\$ _____) Misc (S\$ _____) Total Due \$ 1530.10		
Non Waiverable Excess The Hirer acknowledges that collision damage excess per accident applies. \$2,500.00 (Capex Use) + \$2,500.00 (Capex Use) \$2,500.00 (Capex Use) + \$2,500.00 (Capex Use) X _____		Collision Damage Waiver (CDW) The Hirer may limit his liability for any damage arising from collision to \$ _____ by purchasing CDW and paying the specified sum. X _____		
Personal Accident Insurance (PAI) PAI may be purchased at a premium specified herein. The Hirer acknowledges that the insurance is written by an independent insurance company and acknowledges that he has received, read and understood the policy conditions relating to the same. X _____		Charges Subject to Final Audit Refundable Deposit Deposit \$ _____ Date of Refund _____ Refund Acknowledgement X _____		
Special Instructions _____ _____ _____		For Official Use Invoice No 1181343 Date 19.09.2018 Receipt No _____ Date _____		

Important Notes

- Rental Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the owner.
- Only persons authorised by Global Advance Leasing may drive the vehicle.
- All parking and traffic violations are the responsibility of the Hirer. An Administrative charge will be levied on any traffic violations redirected.
- The Hirer shall be liable for excess charges for any late return at the rate shown per hour or per day.
- In the event of accident, the Hirer shall report to the rental office immediately.

I/We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have been made on the applicable credit card charge slip.

X _____
 (Hirer's signature)

X _____
 (Additional Driver's signature)

X _____
 (Global Advance Leasing)

Enquire Vehicle & Owner Information (Vehicle No. SJL7562S As At 12 Sep 2018 / 17:30:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: TLM(CAYMEN)SLV7234M

Current Owner Details

Owner ID Type: Company

Owner ID: 201806696W

Owner Name: SG RENT & DRIVE PTE. LTD.

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.: 210

Registered Street Name: TURF CLUB ROAD

Registered Unit No.: # A - 27

Registered Building Name: THE GRANDSTAND

Registered Postal Code: 287995

Current Vehicle Details

Vehicle No.: SJL7562S

Make Description/Model: TOYOTA / VIOS E AUTO

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Sep 2018 Edit Reg		13 Sep 2018 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SG RENT & DRIVE PTE LTD , Co. Reg. No.: 201806696W									
Main Claimant: NUR AZERA BINTE JOHANA , ID: S8633251E									
Vehicle Reg. No.: SLV7234M		Date of Loss: 12/09/2018 17:00 - :59 [127 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3691710542SG		Policy/Cover Note No.: 0999994608 (Third Party Only)							
Vehicle Reg. No. (Insured): SJL7562S		Policy No. (Claimant): 509835966							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (17/09/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV7234M (3691710542SG)
[SJL7562S]
TP
NUR AZERA BINTE JOHANA
Sep 12 2018 5:00PM
[SG RENT & DRIVE PTE LTD]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit		
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	14/09/18 09:13	Chassis Number													1	Load JPG	<input checked="" type="checkbox"/>	
2	14/09/18 09:13	Odometer Reading													1	Load JPG	<input checked="" type="checkbox"/>	
3	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
4	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
5	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
6	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
7	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
8	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
9	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
10	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
11	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
12	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
13	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
14	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
15	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
16	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
17	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
18	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
19	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
20	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
21	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
22	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
23	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
24	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
25	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
26	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
27	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
28	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
29	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
30	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
31	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
32	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
33	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	
34	14/09/18 09:13	General View													1	Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
60	14/09/18 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/18 09:03	TP ESTIMATE - MARKED	 Load PDF	
2	22/10/18 10:26	WORKSHOP INVOICE	 Load PDF	
3	22/10/18 10:26	AUTHORISATION TO ACT FORM	 Load PDF	
4	22/10/18 10:26	Release Voucher	 Load PDF	
5	22/10/18 10:26	LETTER TO OI	 Load PDF	
6	22/10/18 10:26	LTA SEARCH	 Load PDF	
7	22/10/18 10:26	RENTAL RECEIPT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/09/18 10:09	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJL7562S (Insd veh)	Model:	HONDA STREAM 1.8 (A)
	SLV7234M (TP veh)		
Date of Accident:	12/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	7,244.33	
Final Repair Cost	: \$	3,210.00	
Loss of Use	: \$	_____ days at \$0.00 per day	
Rental (if any)	: \$	780.00 6.50 days	
LTA / GIA Search Fee	: \$	7.49	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	3,997.49	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	3,997.49
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

22 Oct
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016788/UJA3Q2

Date: 22/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994608

Claimant Vehicle No: SLV7234M

Insured Vehicle No: SJL7562S

Date of Loss: 12/09/2018

Nature of Claim: TP

Claim No: 3691710542SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV7234M

Make & Model: HONDA STREAM, 1.8 (A)

Engine No: R18A1759993

Reg. Date: 24/01/2008 (Man. Year: 2007)

Chassis No: RN61053586

Colour: White

Odometer: 112197 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,950.40	2,214.08	1,736.32	43.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,540.00	1,280.00	45.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,770.40	3,754.08	3,016.32	44.55
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	6,770.40	3,000.00	3,770.40	55.69
+ GST 7.00/7.00% (S\$)	473.93	210.00	263.93	55.69
Nett Amount (S\$)	7,244.33	3,210.00	4,034.33	55.69
+ Car Rental (6.5 x S\$120.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,997.49		

INSPECTION

Date of Assignment: 13/09/2018

Date Inspected: 13/09/2018 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
51 Defu Lane 10
Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	903.20 FL	*903.20 FL
2	1		*TAILGATE LID LOCK	Dented / Twisted	109.40 FL	*109.40 FL
3	1		*TAILGATE LID LOCK STRIKER	Not Necessary	27.50 FL	*- FL
4	1		*TAILGATE LID WEATHERSTRIP	Twisted	121.60 FL	*121.60 FL
5	1		*TAILGATE LID INNER TRIMBOARD	Cracked	141.00 FL	*141.00 FL
6	1		*TAILGATE LID INNER CLOSING GARNISH	Not Necessary	25.00 FL	*- FL
7	2		*TAILGATE LID RUBBER STOPPER	Not Necessary	25.00 FL	*- FL
8	2		*TAILGATE LID ABSORBER STAY	Not Necessary	237.20 FL	*- FL
9	1		*TAILGATE LID STREAM BADGE	Necessary	31.60 FL	*31.60 FL
10	1		*TAILGATE LID OUTER GARNISH	Not Necessary	162.80 FL	*- FL
11	1		*TAILGATE LID OUTER GARNISH EMBLEM BADGE	Not Necessary	21.90 FL	*- FL
12	1		*REAR WINDSHIELD GLASS WEATHERSTRIP	Necessary	65.00 FL	*65.00 FL
13	2		*REAR LICENSE PLATE LAMP	Not Necessary	65.60 FL	*- FL
14	1		*REAR END PANEL	Repair	306.70 FL	*- FL
15	1		*REAR END PANEL INNER TRIM	Not Necessary	116.70 FL	*- FL
16	1		*REAR BUMPER	Distorted	588.90 FL	*588.90 FL
17	2		*REAR BUMPER SIDE RETAINER	Bent	38.80 FL	*38.80 FL
18	2		*REAR BUMPER SIDE HOLDER	Not Necessary	20.00 FL	*- FL
19	8		*REAR BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
20	1		*REAR BUMPER TOW COVER	Twisted	13.90 FL	*13.90 FL
21	1		*REAR BUMPER SCREW	Not Necessary	16.00 FL	*- FL
22	1		*N/S REAR LAMP	Cracked	385.50 FL	*385.50 FL
23	3		*REAR LAMP CLIP HOLDER	Not Necessary	21.00 FL	*- FL
24	1		*REAR WINDSHIELD GLASS SEALANT	Necessary	180.00 FS	*40.00 FS
25	1		*REAR WINDSHIELD GLASS SPONGE	Necessary	100.00 FS	*30.00 FS
26	1		*REAR LICENSE PLATE	Not Necessary	60.00 FS	*- FS
27	1		*BACK OFF CAMERA LENS	Not Necessary	380.00 FS	*- FS
28	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,645.50	2,700.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	695.10	486.02
Total Parts (\$\$)	3,950.40	2,214.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	50.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	160.00	80.00
4	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	150.00	60.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,000.00	550.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,820.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >