

15/5/2010

INS. CASE OWNER:

#00 JUMM

CC 6/AIG1301

6801

Aish S3

LKK:

IDAC:

Surveyor:

Adrian

DOI:

12/11/18

Date / Time:

12/11/18

Registered in Merimen:

12/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCV 8000X

Name of Insured:

MICHAEL TAN YONG SHAN.

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

7/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

RYAN TAN YE KAI

Driver Tel No.:

(V/L/YES/NO)

Claim No.:

ANU667401056

Policy No.:

700452619-0Y

Make / Model:

E1A

Place of Accident:

BUP NEAR EXIT 14A

OI GIA REPORT:

YES / NO

Insured Liability:

Final ? Yes / No


SCV 8000X

SUDENA

SHC 8641C

INSRS:
WSP:
Tel:
Liability:
RMKS:

n

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
12/11/18	Non-Reporting ltr (1st):	
7/11	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

Date/Time

12/11/18
7/11

SUDENA - 4

SCV 8000X - 4

3 vehicles chain collision oio last vehicle.

30-11-18

TRANSFER: THIN2 TO JOY

19-12-18

LOD IN.
FOR MANDATE

29/01/2020 - AIG APPROVED MANDATE
 02/02/2020 - GENIO 1st OFFER TO TP
 TP ACCEPTED OFFER.
 ALL DOCS IN ORDER.
 TO close.

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: 121	SS 19,368.23 (10 days) Reduction: 31 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 02/02/20	Confirm with: SUMINI
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 28	Email ☐ Call ☐
Repair Cost:	SS 19,368.23	If NO or B 28, Ass. Lia: 100
Loss of Rental (LOR):	SS 1,000.00 10 days X 2100	(3 JBM-G-C, OIO UBT)
Loss of Use (LOU):	SS - (S x days)	
Loss of Income (LOI):	SS - (S x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]	
GLA/LTA Search	SS 7.41	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	
Legal Cost:	SS -	
Total:	SS 20,375.63 Global Sum SS: 18,600.00	
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 18,600.00	Name 1: ACE AUTO SOLUTION
Payee 2: (Strike if N.A.)	SS -	Name 2: -
Payee 3: (Strike if N.A.)	SS -	Name 3: -

1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: \$320.00

COPY SENT
2/3/2020

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLD52AYr Regn: 2016 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Orlando c.c 1362

Colour:

Black

A/C: Insured / Std / NI / NA

Sp.Reading

51090

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

K21YA1589GK341924Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

13/09/18

Survey held at

Acc Auto SolutionDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG.16-10-18 1B1 \$ 19,368.23CRAB: 98,047.69/31.1)MV: 72KPV: 50KNett: 22K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + R.S. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/AIG18016801/Aub3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 14-09-2018	
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCV 8000X	Veh. Inspected	SLD 521A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/09/2018	Inspection Date	13/09/2018	
Survey held at	ACE AUTO SOLUTION 23 KAKI BUKIT AVE 4, #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2335Z

Vehicle Details

Vehicle No.: SLD521A
Vehicle to be Exported: Yes
Intended Deregistration Date: 10 Sep 2018
Vehicle Make: CHEVROLET
Vehicle Model: ORLANDO 1.4AT TURBO
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: A14NET160880145
Chassis No.: KL1YA7589GK341924
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$16,195.00
Original Registration Date: 31 May 2016
First Registration Date: 31 May 2016
Transfer Count: 0
Actual ARF Paid: \$16,195.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 May 2026
PARF Rebate Amount: \$12,146.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$49,000.00
COE Rebate Amount: \$37,830.00
Total Rebate Amount: \$49,976.00

The information contained herein is correct as at 10 Sep 2018

Depreciation per month: \$740

3 months = \$2220

Market value \$7020

minus Rebate Amount \$49976

\$27044

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Orlando 1.4A Turbo LS

Price Range

Depreciation

2016

Vehicle Type

Advanced Search

Home » Used Cars » Car House Pte Ltd » Chevrolet Orlando 1.4A Turbo LS

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Chevrolet Orlando 1.4A Turbo LS

Overview

Financial

Accessories

Similar

Research

Photos

Map

CAR HOUSE PTE LTD



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$74,800

Depreciation \$8,920 /yr

View models with similar depreciation

Reg Date 24-Feb-2016

(7yrs 5mths 13days COE left)

Manufactured 2015

Mileage 49,980 km (19.6k /yr)

Transmission Auto

Engine Cap 1,362 cc

Road Tax \$604 /yr

Power 103.0 kW (138 bhp)

View specs of the Chevrolet Orlando (2011-2018)

Curb Weight 1,650 kg

Features DOHC ECOTEC Turbocharged Engine, 6 Speed Auto Transmission, Front Wheel Drive, Ventilated Brakes Disc.

Accessories Quality Audio System, GPS Navigation, Bluetooth, Full Leather Seats, Halogen Headlights, Reverse Camera, Retractable Side Mirrors, Full Airbags, Etc.

Description Special Loan Offer At 1.99%! Best Selling MPV! Plenty Of Space, Full Features, Quality Interiors, Smooth And Comfortable Drive With Turbo Power, Fuel Efficiency EcoTech! Everything That You And Your Family Want For In An MPV! Fully Agent Serviced And Under Warranty. Best Value For Money, Low Depreciation! High Loan With Low Down Payment Available. Trade-In Welcome! Hurry Call Now! GST Included.

COE \$51,000

OMV \$16,562

ARF \$16,562

Dereg Value \$50,469 as of today (change)

No. of Owners 1

Type of Veh MPV

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note



Seller Information

Company

Car House Pte Ltd

» dealer's pricelist

» 48 vehs sold | 44 vehs available

Address

210 Turf Club Road Lot B27

Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

64666220

Contact Person(s)

Shah	97308666
Frankie Chen	97281121
Darren Yeo	86088466
May Chan	96150834

Vehicle Number Plates

BUY & SELL

Your AUSPICIOUS & UNIQUE Vehicle No.

Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!

Click here to see all Auspicious Numbers!

Tags: Chevrolet Orlando, 2016 Chevrolet Orlando, Chevrolet, Orlando, Used Chevrolet

Upfront Payment

[View More Financial Info](#)

Transfer Fee	\$25	?
Down Payment	\$22,440 (change)	Maximum 70% Loan ?
1st Instalment	\$753	?
Total Upfront Payment	\$23,218 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

[New car list](#) • [Used car list](#) • [Company profile](#)


Afraid of lemons? Request to have this car evaluated professionally.

Recommended for you

1-6 of 18



Chevrolet orlando



MCF checks out SEAT's award-winning range



Chevrolet releases details of the Orlando MPV



Lexus launches its all new UX compact SUV



Vehicle sales and transfers to go online



Hamilton Autohub Trusted Brand showcase

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

Take a position on cash and forward commodity CFDs with competitive spreads

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

New 5 Years Coe Renewal Toyota Wish 1.8A

\$2000 Downpayment Monthly
From \$638 Onwards. Lowest
3.18% P.A. @ Gv Cars Financing
Gv Credit Pte Ltd - StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category Save Search Print Sort by Date Posted 20 results/page

3 vehicles **Search** Orlando Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Orlando	Any	Any	2016	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----------

☐ **Chevrolet Orlando 1.4A Turbo LS** **\$68,500** **\$8,160 /yr** **26-Jan-2016** **1,362 cc** **42,700 km** **MPV** **Available**

1 Owner, Well Maintained, Accident Free, Spacious Car Suitable For Family, Bought Directly From Authorised Dealer.

Posted: 07-Sep-2016 Tags: 2016 Chevrolet Orlando, Chevrolet Orlando, Chevrolet, Orlando, Used Chevrolet

☐ **Chevrolet Orlando 1.4A Turbo LS** **\$76,900** **\$9,200 /yr** **25-Feb-2016** **1,362 cc** **36,000 km** **MPV** **Available**

Look No Further! Probably One Of The Most Reasonably Priced For The Family Minded Owner Who Prefers Wants A MPV That Have Style And Sportiness Of A SUV. Beautiful Grey 2016 Chevrolet Orlando 7 Seater...

Posted: 10-Sep-2016 Tags: 2016 Chevrolet Orlando, Chevrolet Orlando, Chevrolet, Orlando, Used Chevrolet

☐ **Chevrolet Orlando 1.4A Turbo LS** **\$78,000** **\$8,550 /yr** **18-Nov-2016** **1,362 cc** **18,000 km** **MPV** **Available**

AA Trust Certified Quality 1 Owner Vehicle! Dubbed The People Mover Equipped With A 1.4L Turbo Ensuring Enough Power For Your Long Trips Up North! Spacious Cabin To Take On Your Extended Family On Lon...

AA Trust Automotive

Posted: 01-Sep-2016 Tags: 2016 Chevrolet Orlando, Chevrolet Orlando, Chevrolet, Orlando, Used Chevrolet

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads 20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Orlando, Orlando Singapore, used Orlando Singapore, used Orlando, used vehicles Singapore or even buy used Orlando Singapore. We have new car dealers comprising parallel imports, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

SHORTLISTED HISTORY

Compare [4]

Repair Estimate

Date : 13/9/2018

Reference: SLD521A
 CHEVROLET
 Make: ORLANDO
 1.4AT TURBO

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLD521A
 CHASSIS NO.: KL1YA7589GK341924
 ENGINE NO. A14NET160880145

Name of insured : Ong See Ban
 Date of accident : 07/09/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET GRILLE <i>new</i>	\$ 371.00
2	1	FRT BUMPER <i>Rehnd</i>	\$ 1,406.00
3	1	FRT BUMPER TOW COVER <i>new</i>	\$ 75.00
4	1	FRT BUMPER LOGO <i>new</i>	\$ 158.00
5	1	FRT GRILLE MIDDLE <i>cracked.</i>	\$ 400.00
6	1	FRT NUMBER PLATE GARNISH <i>old</i>	\$ 95.00
7	1	FRT BUMPER LOWER <i>new</i>	\$ 516.00
8	1	FRT BUMPER LOWER GARNISH(silver colour) <i>Rehnd</i>	\$ 333.00
9	1	FRT GRILLE LOW <i>new</i>	\$ 311.00
10	1	RH HEADLAMP <i>green</i>	\$ 983.00
11	1	LH HEADLAMP	\$ 983.00
12	1	FRT SUPORT PANEL TOP CENTRE <i>new</i>	\$ 326.00
13	1	FRT BUMPER SIDE RETAINER LH, SUPPORT <i>green</i>	\$ 133.00
14	1	FRT BUMPER SIDE RETAINER RH, SUPPORT	\$ 133.00
15	1	FRT BUMPER BRACKET LH, GUIDE <i>green</i>	\$ 111.00
16	1	FRT BUMPER BRACKET RH, GUIDE	\$ 111.00
17	1	FRT BUMPER SPONGE <i>cracked.</i>	\$ 263.00
18	1	FRT BUMPER REINFORCEMENT, IMPACT BAR <i>Best</i>	\$ 927.00
19	1	LHR TAILLAMP <i>cracked</i>	\$ 629.00

20	1	LHR TAILLAMP PANEL <i>Repair</i>	\$ 180.00
21	1	RHR TAILLAMP <i>Not new</i>	\$ 629.00
22	1	RHR TAILLAMP PANEL <i>Repair</i>	\$ 180.00
23	1	REAR TAILGATE <i>Distorted</i>	\$ 1,850.00
24	1	REAR TAILGATE CHROME HANDLE <i>Not new</i>	\$ 290.00
25	1	CHEVROLET LETTERING	\$ 50.00
26	1	ORLANDO LETTERING	\$ 40.00
27	1	LS LETTERING	\$ 25.00
28	1	TURBO LETTERING	\$ 45.00
29	1	CHEVROLET EMBLEM	\$ 120.00
30	1	LHR TAILGATE LAMP <i>cracked</i>	\$ 290.00
31	1	RHR TAILGATE LAMP <i>Not new</i>	\$ 290.00
32	1	REAR WINDSCREEN WITH MOULDING <i>Not new</i>	\$ 698.00
33	1	REAR TAILGATE INNER TRIM <i>Deformed</i>	\$ 340.00
34	1	REAR TAILGATE INNER LH TRIM <i>Not new</i>	\$ 150.00
35	1	REAR TAILGATE INNER RH TRIM <i>Not new</i>	\$ 150.00
36	1	REAR TAILGATE WEATHERSTRIP <i>cut</i>	\$ 240.00
37	1	REAR TAIL LID LATCH <i>Bad</i>	\$ 220.00
38	1	REAR TAIL LID STRIKER <i>new</i>	\$ 80.00
39	1	REAR BUMPER STEP PLATE <i>Missing</i>	\$ 160.25
40	1	REAR BUMPER UPPER <i>Distorted</i>	\$ 1,467.00
41	1	REAR BUMPER LOWER	\$ 540.00
42	1	REAR BUMPER SILL PLATE(SILVER) <i>Deformed</i>	\$ 300.00
43	1	REAR BUMPER TOWING COVER <i>Deformed</i>	\$ 75.00
44	1	LHR BUMPER REFLECTOR <i>cracked</i>	\$ 95.00
45	1	RHR BUMPER REFLECTOR <i>Missing</i>	\$ 95.00
46	1	REAR REVERSE LIGHT AND BRAKE LIGHT <i>cracked</i>	\$ 401.00
47	1	REAR BUMPER CENTRE GUIDE	\$ 120.00
48	1	RHR BUMPER GUIDE, OTR	\$ 60.00
49	1	LHR BUMPER GUIDE, OTR	\$ 60.00
50	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 50.00
51	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00
52	1	REAR BUMPER ABSORBER <i>new</i>	\$ 190.00
53	1	REAR BUMPER BEAM <i>Bent</i>	\$ 743.00
54	1	REAR END PANEL TRIM <i>Deformed</i>	\$ 125.00
55	1	REAR END PANEL OUTER <i>Distorted</i>	\$ 680.00
56	1	REAR END PANEL INNER <i>Distorted</i>	\$ 470.00
57	1	TOOL BOX COVER <i>Deformed</i>	\$ 375.00
58	1	TOOL BOX COMPARTMENT <i>Deformed</i>	\$ 220.00

59	1	REVERSE SENSOR WIRING HARNESS <i>Not in</i>	\$ 325.00	<i>+</i>
60	1	RHR FENDER PROTECTOR <i>Not in</i>	\$ 113.00	<i>+</i>
61	1	LHR FENDER PROTECTOR <i>Not in</i>	\$ 113.00	<i>+</i>

14005.25

12604.73

Parts Total: \$ 20,958.25

Less 10%: \$ 2,095.83

Total: \$ 18,862.43

Labour

Labour Description

No. Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 600.00	<i>400</i>
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 600.00	<i>400</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	<i>✓</i>
4	To refocus headlamp	\$ 80.00	<i>+</i>

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 2,000.00	<i>1400</i>
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,200.00	<i>1000</i>
3	To conduct anti rust of under carriage tuff coat	\$ 80.00	<i>50</i>
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	<i>✓</i>
5	To remove and refix reverse sensor and conduct test	\$ 80.00	<i>50</i>
6	To remove and refix reverse camera and conduct test	\$ 80.00	<i>50</i>
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00	<i>✓</i>
8	To conduct water leakage test after repairs of vehicle	\$ 80.00	<i>+</i>
9	To remove and refix rear tail gate windscreen	\$ 120.00	<i>✓</i>

3610

Labour Total: \$ 5,060.00

Others

Other Description

No. Qty Price (SGD)

		<u>Front portion</u>	
1	1	Number plate with casement <i>cracked</i>	\$ 45.00
2	10	Front bumper clip <i>new</i>	\$ 65.00
3	5	Front support panel top garnish clip <i>new</i>	\$ 32.50
4	6	Front fender liner clip <i>Not in</i>	\$ 39.00

Rear portion

1	1	Rear number plate <i>lt</i>	\$	45.00	✓
2	10	Rear bumper clip <i>mu</i>	\$	65.00	30
3	6	Rear fender liner clips <i>mu</i>	\$	39.00	+
4	10	Rear end panel trim clip <i>mu</i>	\$	65.00	20
5	1	Reverse sensor (1 set) <i>Damaged</i>	\$	440.00	300
6	1	Rear reverse camera <i>mu</i>	\$	280.00	x.
7	1	Rear end panel insulation seal <i>mu</i>	\$	120.00	60
8	1	Rear floor panel insulation seal <i>mu</i>	\$	180.00	60
9	13	Tail gate inner trim board clip <i>mu</i>	\$	84.50	30.
10	1	Tailgate windscreen moulding <i>mu</i>	\$	120.00	✓
11	1	Tailgate windscreen sealant <i>mu</i>	\$	120.00	60
12	1	Tailgate windscreen solar film <i>mu</i>	\$	200.00	+

Other Total: \$ 1,940.00

GRAND TOTAL: \$ 25,862.43

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor
Suhaimi
HP : 9189 2617 Email - aceautosolution@gmail.com

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Supplementary : 2353.50

total: 19368.23

Finisition : Hitam

Ace Auto Solution

Registration number : 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : AIG Asia Pacific Insurance Pte. Ltd
78 SHENTON WAY
#07-16
SINGAPORE 079120

Invoice No: ACC-2015001
Invoice Date:

Vehicle No: SLD521A
Chasis No: KL1YA7589GK341924
Engine No: A14NET160880145

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
<u>1</u>	1	FRT BUMPER	\$ 1,406.00
<u>2</u>	1	FRT BUMPER LOGO	\$ 158.00
<u>3</u>	1	FRT GRILLE MIDDLE	\$ 400.00
<u>4</u>	1	FRT NUMBER PLATE GARNISH	\$ 95.00
<u>5</u>	1	FRT BUMPER LOWER GARNISH(silver colour)	\$ 333.00
<u>6</u>	1	FRT BUMPER SIDE RETAINER LH, SUPPORT	\$ 133.00
<u>7</u>	1	FRT BUMPER SIDE RETAINER RH, SUPPORT	\$ 133.00
<u>8</u>	1	FRT BUMPER BRACKET LH, GUIDE	\$ 111.00
<u>9</u>	1	FRT BUMPER BRACKET RH, GUIDE	\$ 111.00
<u>10</u>	1	FRT BUMPER SPONGE	\$ 263.00
<u>11</u>	1	FRT BUMPER REINFORCEMENT, IMPACT BAR	\$ 927.00
<u>12</u>	1	LHR TAILLAMP	\$ 629.00
<u>13</u>	1	REAR TAILGATE	\$ 1,850.00
<u>14</u>	1	CHEVROLET LETTERING	\$ 50.00
<u>15</u>	1	ORLANDO LETTERING	\$ 40.00
<u>16</u>	1	LS LETTERING	\$ 25.00
<u>17</u>	1	TURBO LETTERING	\$ 45.00
<u>18</u>	1	CHEVROLET EMBLEM	\$ 120.00
<u>19</u>	1	LHR TAILGATE LAMP	\$ 290.00
<u>20</u>	1	REAR TAILGATE INNER TRIM	\$ 340.00
<u>21</u>	1	REAR TAILGATE WEATHERSTRIP	\$ 240.00
<u>22</u>	1	REAR TAIL LID LATCH	\$ 220.00
<u>23</u>	1	REAR BUMPER STEP PLATE	\$ 160.25
<u>24</u>	1	REAR BUMPER UPPER	\$ 1,467.00
<u>25</u>	1	REAR BUMPER LOWER	\$ 540.00
<u>26</u>	1	REAR BUMPER SILL PLATE(SILVER)	\$ 300.00
<u>27</u>	1	REAR BUMPER TOWING COVER	\$ 75.00
<u>28</u>	1	LHR BUMPER REFLECTOR	\$ 95.00
<u>29</u>	1	RHR BUMPER REFLECTOR	\$ 95.00
<u>30</u>	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 401.00

31	1	REAR BUMPER CENTRE GUIDE	\$ 120.00
32	1	RHR BUMPER GUIDE, OTR	\$ 60.00
33	1	LHR BUMPER GUIDE, OTR	\$ 60.00
34	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 50.00
35	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00
36	1	REAR BUMPER BEAM	\$ 743.00
37	1	REAR END PANEL TRIM	\$ 125.00
38	1	REAR END PANEL OUTER	\$ 680.00
39	1	REAR END PANEL INNER	\$ 470.00
40	1	TOOL BOX COVER	\$ 375.00
41	1	TOOL BOX COMPARTMENT	\$ 220.00

Supplementary

42	1	LHR FENDER INNER TRIM <i>crushed</i>	\$ 450.00	✓
43	1	RHR FENDER INNER TRIM	\$ 450.00	✓
44	1	SPARE TYRE LIFTING MECHANISM <i>best</i>	\$ 420.00	✓
45	1	LHR FENDER LINER <i>Torn</i>	\$ 90.00	✓
46	1	CONDENSOR <i>Dented</i>	\$ 875.00	✓
47	1	RHF FOGLAMP <i>crushed</i>	\$ 330.00	✓

2615
2353.50

Total: \$ 16,620.25
Less 10%: \$ 1,662.03
Parts Total : \$ 14,958.23

Labour

No.		Price (SGD)
<u>Front portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 400.00
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 400.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>Rear portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 1,400.00
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,000.00
3	To conduct anti rust of under carriage tuff coat	\$ 50.00
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
5	To remove and refix reverse sensor and conduct test	\$ 50.00
6	To remove and refix reverse camera and conduct test	\$ 50.00
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
8	To remove and refix rear tail gate windscreen	\$ 120.00

Labour Total : \$ 3,610.00

Other

No.			Price (SGD)
Front portion			
1	1	Number plate with casement	\$ 45.00
2	10	Front bumper clip	\$ 30.00
Rear portion			
1	1	Rear number plate	\$ 45.00
2	10	Rear bumper clip	\$ 30.00
3	10	Rear end panel trim clip	\$ 20.00
4	1	Reverse sensor (1 set)	\$ 300.00
5	1	Rear end panel insulation seal	\$ 60.00
6	1	Rear flooe panel insulation seal	\$ 60.00
7	13	Tail gate inner trim board clip	\$ 30.00
8	1	Tailgate windscreen moulding	\$ 120.00
9	1	Tailgate windscreen sealant	\$ 60.00

Other Total : \$ 800.00

Total : \$ 19,368.23

Grand Total: \$ 19,368.23

Yours Faithfully,



Suhaimi
Service Executive
Tel: 9189 2617 Fax:6844 5185
Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice

Vic (LKKAUTO)

From: Foo, Chityan <Chityan.Foo@aig.com>
Sent: Friday, 15 February, 2019 11:30 AM
To: Joy Irene (LKKAUTO)
Cc: Admin A; Admin-D (LKKAUTO)
Subject: OUR REF: 9946634010SG; YOUR REF: CC6/AIG18016801/AJB3S2

Hi Irene,

We refer to the above matter

We seek your clarification on the replacement of the following parts:

- Front bumper side retainer LH, support
- Front bumper side retainer RH, support
- Front bumper bracket LH, Guide
- Front bumper bracket RH, Guide
- RHR bumper guide, OTR
- LHR bumper guide, OTR
- Rear bumper left centre guide, INR
- Rear bumper right centre guide, INR
- Spare tyre lifting mechanism 97-104.
- RHF foglamp 55-56
- Front grille middle 47-49

These are essential replacement parts which are riveted onto the body of the vehicle.

To remove these items, the rivets have to be damaged and most of the time while removing the rivets, the items are inadvertently damaged as well.

Please forward a copy of repair estimate before approval of mandate in merimen.

Jimmy Foo
AIG
Complex Claims Examiner
AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1945 | Fax +(65) 6835 7416

Chityan.foo@aig.com | www.aig.sg

From: Foo, Chityan
Sent: Monday, 11 February, 2019 9:39 AM
To: Admin A; 'Admin-D (LKKAUTO)'
Subject: OUR REF: 9946634010SG; YOUR REF: CC6/AIG18016801/AJB3S2

Hi LKK,

We refer to the above matter

Please assist to upload repair estimate from Ace Auto Solution into merimen.

Thank you.

Jimmy Foo
AIG
Complex Claims Examiner

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1945 | Fax +(65) 6835 7416

Chityan.foo@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SLD521A (9946634010SG)**
[SCV8000X]

TP

ONG SEE BAN

Sep 7 2018 7:00PM

[MICHAEL TAN YONG SIANG]

Ace Auto Solution (kaki Bukit)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 27/02/2020 10:34 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$18600.00) - SLD521A - Claim Handler: Foo, Chit Yan

Approved:18600.00:Pls negotiate at best from: \$18.2k to 18.6k (All-in). Subj to Final Repair Bill, Rental Bill & Agreement, GIA/LTA Search Bill in order.

...CLAIM SUBFOLDER...(Pending for Approval)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2018 Edit Reg		13 Sep 2018 00:00 Edit Adj Rpt	S\$19,368.22 Edit Estimates	S\$19,368.22 View Rpt		Pending for Approval Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MICHAEL TAN YONG SIANG, ID: S2604035C		
Main Claimant:	ONG SEE BAN, ID: S0152335Z		
Vehicle Reg. No.:	SLD521A	Date of Loss:	07/09/2018 19:00 - :59 [27 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9946634010SG	Policy/Cover Note No.:	2100453619 (Comprehensive) Coverage: 01/03/2018 - 28/02/2019
Vehicle Reg. No. (Insured):	SCV8000X	Policy No. (Claimant):	5080948148-02
		Excess:	
Repairer:	Ace Auto Solution (kaki Bukit) (HQ) 23 KAKI BUKIT AVE 4, #04-01 (SOUTH WING), 415933 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (27/02/2020): Alert - Adj Mandate Approved (S\$18600.00) - SLD521A - Claim Handler: Foo, Chit Y...
- AIG_SG_EXPRESS (01/07/2019): Alert - Adj Mandate Maintained - SLD521A - Claim Handler: Foo, Chit Yan

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLD521A (9946634010SG)**
[SCV8000X]
TP
ONG SEE BAN
Sep 7 2018 7:00PM
[MICHAEL TAN YONG SIANG]
Ace Auto Solution (kaki Bukit)

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Letters/Correspondences															1 per page ▾			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
															3 per page ▾			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	16/10/18 16:46		General View												1	Load JPG		☒		
2	16/10/18 16:46		General View												1	Load JPG		☒		
3	16/10/18 16:46		General View												1	Load JPG		☒		
4	16/10/18 16:46		General View												1	Load JPG		☒		
5	16/10/18 16:46		General View												1	Load JPG		☒		
6	16/10/18 16:46		General View												1	Load JPG		☒		
7	16/10/18 16:46		General View												1	Load JPG		☒		
8	16/10/18 16:46		General View												1	Load JPG		☒		
9	16/10/18 16:46		General View												1	Load JPG		☒		
10	16/10/18 16:46		General View												1	Load JPG		☒		
11	16/10/18 16:46		General View												1	Load JPG		☒		
12	16/10/18 16:46		General View												1	Load JPG		☒		
13	16/10/18 16:46		General View												1	Load JPG		☒		
14	16/10/18 16:46		General View												1	Load JPG		☒		
15	16/10/18 16:46		General View												1	Load JPG		☒		
16	16/10/18 16:46		General View												1	Load JPG		☒		
17	16/10/18 16:46		General View												1	Load JPG		☒		
18	16/10/18 16:46		General View												1	Load JPG		☒		
19	16/10/18 16:46		General View												1	Load JPG		☒		
20	16/10/18 16:46		General View												1	Load JPG		☒		
21	16/10/18 16:46		General View												1	Load JPG		☒		
22	16/10/18 16:46		General View												1	Load JPG		☒		
23	16/10/18 16:46		General View												1	Load JPG		☒		
24	16/10/18 16:46		General View												1	Load JPG		☒		
25	16/10/18 16:46		General View												1	Load JPG		☒		
26	16/10/18 16:46		General View												1	Load JPG		☒		
27	16/10/18 16:46		General View												1	Load JPG		☒		
28	16/10/18 16:46		General View												1	Load JPG		☒		
29	16/10/18 16:46		General View												1	Load JPG		☒		
30	16/10/18 16:46		General View												1	Load JPG		☒		
31	16/10/18 16:46		General View												1	Load JPG		☒		
32	16/10/18 16:46		General View												1	Load JPG		☒		

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	16/10/18 16:46	General View	 Load JPG	☒
34	16/10/18 16:46	General View	 Load JPG	☒
35	16/10/18 16:46	General View	 Load JPG	☒
36	16/10/18 16:46	General View	 Load JPG	☒
37	16/10/18 16:46	General View	 Load JPG	☒
38	16/10/18 16:46	General View	 Load JPG	☒
39	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
40	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
41	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
42	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
43	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
44	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
45	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
46	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
47	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
48	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
49	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
50	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
51	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
52	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
53	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
54	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
55	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
56	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
57	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
58	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
59	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
60	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
61	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
62	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
63	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
64	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
65	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
66	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
67	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
68	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
69	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
70	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
71	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
72	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
73	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
74	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
75	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
76	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
77	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
78	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
79	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
80	16/10/18 16:46	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
82	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
83	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
84	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
85	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
86	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
87	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
88	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
89	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
90	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
91	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
92	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
93	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
94	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
95	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
96	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
97	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
98	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
99	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
100	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
101	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
102	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
103	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
104	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
105	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
106	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
107	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
108	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
109	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
110	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
111	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
112	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
113	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
114	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
115	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
116	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
117	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
118	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
119	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
120	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
121	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
122	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
123	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
124	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
125	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
126	16/10/18 16:46	Reinspection Photo	 Load JPG	☒
127	16/10/18 16:46	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/09/18 15:44	TP GIA REPORT	Load PDF	
2	18/01/19 11:39	LETTER TO OI	Load PDF	
3	18/01/19 11:39	LTA SEARCH	Load PDF	
4	18/01/19 11:39	RENTAL RECEIPT	Load PDF	
5	16/10/19 18:00	TP ESTIMATE - MARKED	Load PDF	
6	02/03/20 08:55	EMAIL FROM TP	Load PDF	
7	05/03/20 09:37	LOD	Load PDF	
8	05/03/20 09:37	Authorisation to Act	Load PDF	
9	05/03/20 09:37	Release Voucher	Load PDF	
10	05/03/20 09:37	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/09/18 09:58	OI GIA REPORT	Load PDF	
2	17/02/20 11:36	Clear Report	Load DOCX	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCV8000X (Insd veh)	Model:	CHEVROLET ORLANDO 1.4
	SLD521A (TP veh)		TURBO (A)
Date of Accident:	07/09/2018		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$		28,215.92
Final Repair Cost	:	\$		18,600.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		10 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		18,600.00

Is Third Party Workshop GIA Registered?		☐ [] YES	☒ [X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Ace Auto Solution	: \$	18,600.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

05 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016801/AHS3S2

Date: 05/03/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100453619
Claimant Vehicle No :	SLD521A	Insured Vehicle No :	SCV8000X
Date of Loss:	07/09/2018	Nature of Claim:	TP
		Claim No:	9946634010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD521A	Engine No:	B14NET160880145
Make & Model:	CHEVROLET ORLANDO, 1.4 Turbo (A)	Chassis No:	KL1YA7589GK341924
Reg. Date:	31/05/2016 (Man. Year: 2016)	Odometer:	51090 km
Colour:	Black		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,155.92	15,758.22	7,397.70	31.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	3,610.00	1,450.00	28.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	28,215.92	19,368.22	8,847.70	31.36
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
	Nett Liability (S\$)	20,375.67		
	Global Sum Settlement (S\$)	18,600.00		

INSPECTION

Date of Assignment:	13/09/2018	
Date Inspected:	13/09/2018	Inspected At: Ace Auto Solution (kaki Bukit) (HQ) 23 KAKI BUKIT AVE 4, #04-01 (SOUTH WING) Singapore 415933
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

DIFFERENT BY 1 CENT. FINALIZE CONFIRMED AMOUNT \$19,368.23

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET GRILLE	Not Necessary	371.00 FL	*- FL
2	1		*FRT BUMPER	Deformed	1,406.00 FL	*1,406.00 FL
3	1		*FRT BUMPER TOW COVER	Not Necessary	75.00 FL	*- FL
4	1		*FRT BUMPER LOGO	Necessary	158.00 FL	*158.00 FL
5	1		*FRT GRILLE MIDDLE	Cracked	400.00 FL	*400.00 FL
6	1		*FRT NUMBER PLATE GARNISH	Deformed	95.00 FL	*95.00 FL
7	1		*FRT BUMPER LOWER	Not Necessary	516.00 FL	*- FL
8	1		*FRT BUMPER LOWER GARNISH (SILVER COLOUR)	Deformed	333.00 FL	*333.00 FL
9	1		*FRT GRILLE LOW	Not Necessary	311.00 FL	*- FL
10	1		*RH HEADLAMP	Not Necessary	983.00 FL	*- FL
11	1		*LH HEADLAMP	Not Necessary	983.00 FL	*- FL
12	1		*FRT SUPPORT PANEL TOP CENTRE	Not Necessary	326.00 FL	*- FL
13	1		*FRT BUMPER SIDE RETAINER LH, SUPPORT	Necessary	133.00 FL	*133.00 FL
14	1		*FRT BUMPER SIDE RETAINER RH, SUPPORT	Necessary	133.00 FL	*133.00 FL
15	1		*FRT BUMPER BRACKET LH, GUIDE	Necessary	111.00 FL	*111.00 FL
16	1		*FRT BUMPER BRACKET RH, GUIDE	Necessary	111.00 FL	*111.00 FL
17	1		*FRT BUMPER SPONGE	Cracked	263.00 FL	*263.00 FL
18	1		*FRT BUMPER REINFORCEMENT, IMPACT BAR	Bent	927.00 FL	*927.00 FL
19	1		*LHR TAILLAMP	Cracked	629.00 FL	*629.00 FL
20	1		*LHR TAILLAMP PANEL	Repair	180.00 FL	*- FL
21	1		*RHR TAILLAMP	Not Necessary	629.00 FL	*- FL
22	1		*RHR TAILLAMP PANEL	Repair	180.00 FL	*- FL
23	1		*REAR TAILGATE	Distorted	1,850.00 FL	*1,850.00 FL
24	1		*REAR TAILGATE CHROME HANDLE	Not Necessary	290.00 FL	*- FL
25	1		*CHEVROLET LETTERING	Necessary	50.00 FL	*50.00 FL
26	1		*ORLANDO LETTERING	Necessary	40.00 FL	*40.00 FL
27	1		*LS LETTERING	Necessary	25.00 FL	*25.00 FL
28	1		*TURBO LETTERING	Necessary	45.00 FL	*45.00 FL
29	1		*CHEVROLET EMBLEM	Necessary	120.00 FL	*120.00 FL
30	1		*LHR TAILGATE LAMP	Cracked	290.00 FL	*290.00 FL
31	1		*RHR TAILGATE LAMP	Not Necessary	290.00 FL	*- FL
32	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	698.00 FL	*- FL
33	1		*REAR TAILGATE INNER TRIM	Deformed	340.00 FL	*340.00 FL
34	1		*REAR TAILGATE INNER LH TRIM	Not Necessary	150.00 FL	*- FL
35	1		*REAR TAILGATE INNER RH TRIM	Not Necessary	150.00 FL	*- FL
36	1		*REAR TAILGATE WEATHERSTRIP	Cut	240.00 FL	*240.00 FL
37	1		*REAR TAIL LID LATCH	Damaged	220.00 FL	*220.00 FL
38	1		*REAR TAIL LID STRIKER	Not Necessary	80.00 FL	*- FL
39	1		*REAR BUMPER STEP PLATE	Missing	160.25 FL	*160.25 FL
40	1		*REAR BUMPER UPPER	Distorted	1,467.00 FL	*1,467.00 FL
41	1		*REAR BUMPER LOWER	Distorted	540.00 FL	*540.00 FL
42	1		*REAR BUMPER SILL PLATE (SILVER)	Deformed	300.00 FL	*300.00 FL
43	1		*REAR BUMPER TOWING COVER	Deformed	75.00 FL	*75.00 FL
44	1		*LHR BUMPER REFLECTOR	Cracked	95.00 FL	*95.00 FL
45	1		*RHR BUMPER REFLECTOR	Missing	95.00 FL	*95.00 FL
46	1		*REAR REVERSE LIGHT AND BRAKE LIGHT	Cracked	401.00 FL	*401.00 FL
47	1		*REAR BUMPER CENTRE GUIDE	Necessary	120.00 FL	*120.00 FL
48	1		*RHR BUMPER GUIDE, OTR	Necessary	60.00 FL	*60.00 FL
49	1		*LHR BUMPER GUIDE, OTR	Necessary	60.00 FL	*60.00 FL
50	1		*REAR BUMPER LEFT CENTRE GUIDE, INR	Necessary	50.00 FL	*50.00 FL
51	1		*REAR BUMPER RIGHT CENTRE GUIDE, INR	Necessary	50.00 FL	*50.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR BUMPER ABSORBER	Not Necessary	190.00 FL	*- FL
53	1		*REAR BUMPER BEAM	Bent	743.00 FL	*743.00 FL
54	1		*REAR END PANEL TRIM	Deformed	125.00 FL	*125.00 FL
55	1		*REAR END PANEL OUTER	Distorted	680.00 FL	*680.00 FL
56	1		*REAR END PANEL INNER	Distorted	470.00 FL	*470.00 FL
57	1		*TOOL BOX COVER	Deformed	375.00 FL	*375.00 FL
58	1		*TOOL BOX COMPARTMENT	Deformed	220.00 FL	*220.00 FL
59	1		*REVERSE SENSOR WIRING HARNESS	Not Necessary	325.00 FL	*- FL
60	1		*RHR FENDER PROTECTOR	Not Necessary	113.00 FL	*- FL
61	1		*LHR FENDER PROTECTOR	Not Necessary	113.00 FL	*- FL
62	1		*NUMBER PLATE WITH CASEMENT	Cracked	45.00 FS	*45.00 FS
63	10		*FRONT BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
64	5		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	32.50 FS	*- FS
65	6		*FRONT FENDER LINER CLIP	Not Necessary	39.00 FS	*- FS
66	1		*REAR NUMBER PLATE	Cut	45.00 FS	*45.00 FS
67	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
68	6		*REAR FENDER LINER CLIPS	Not Necessary	39.00 FS	*- FS
69	1		*REAR END PANEL TRIM CLIP	Necessary	65.00 FS	*20.00 FS
70	1		*SET REVERSE SENSOR	Damaged	440.00 FS	*300.00 FS
71	1		*REAR REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
72	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
73	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	180.00 FS	*60.00 FS
74	1		*TAIL GATE INNER TRIM BOARD CLIP	Necessary	84.50 FS	*30.00 FS
			13pcs			
75	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FS	*120.00 FS
76	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
77	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS
78	1		*LHR FENDER INNER TRIM	Cracked	450.00 FL	*450.00 FL
79	1		*RHR FENDER INNER TRIM	Cracked	450.00 FL	*450.00 FL
80	1		*SPARE TYRE LIFTING MECHANISM	Bent	420.00 FL	*420.00 FL
81	1		*LHR FENDER LINER	Torn	90.00 FL	*90.00 FL
82	1		*CONDENSOR	Dented	875.00 FL	*875.00 FL
83	1		*RHF FOGLAMP	Cracked	330.00 FL	*330.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	25,513.25	17,420.25
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,357.33	1,662.03
Total Parts (\$\$)	23,155.92	15,758.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	2,600.00	1,800.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.	New	1,800.00	1,400.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.	New	60.00	60.00
4	TO REFOCUS HEADLAMP.	New	80.00	0.00
5	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.	New	80.00	50.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.	New	80.00	50.00
7	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.	New	80.00	50.00
8	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.	New	80.00	80.00
9	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	New	80.00	0.00
10	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.	New	120.00	120.00
Gross Labour Cost (S\$)			5,060.00	3,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >