

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 13/9/2018

Reference: SLD521A
 CHEVROLET
 Make: ORLANDO
 1.4AT TURBO

To Whom It May Concern

Dear Sir,

TPAIG.
 Thin Thin.

RE: VEHICLE :SLD521A
CHASSIS NO.:KL1YA7589GK341924
ENGINE NO.A14NET160880145

Name of insured :Ong See Ban
 Date of accident.: 07/09/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET GRILLE <i>new</i>	\$ 371.00
2	1	FRT BUMPER <i>Rehnd</i>	\$ 1,406.00
3	1	FRT BUMPER TOW COVER <i>new</i>	\$ 75.00
4	1	FRT BUMPER LOGO <i>new</i>	\$ 158.00
5	1	FRT GRILLE MIDDLE <i>excluded.</i>	\$ 400.00
6	1	FRT NUMBER PLATE GARNISH <i>new</i>	\$ 95.00
7	1	FRT BUMPER LOWER <i>new</i>	\$ 516.00
8	1	FRT BUMPER LOWER GARNISH(silver colour) <i>Rehnd</i>	\$ 333.00
9	1	FRT GRILLE LOW <i>new</i>	\$ 311.00
10	1	RH HEADLAMP <i>new</i>	\$ 983.00
11	1	LH HEADLAMP	\$ 983.00
12	1	FRT SUPORT PANEL TOP CENTRE <i>new</i>	\$ 326.00
13	1	FRT BUMPER SIDE RETAINER LH, SUPPORT <i>new</i>	\$ 133.00
14	1	FRT BUMPER SIDE RETAINER RH, SUPPORT	\$ 133.00
15	1	FRT BUMPER BRACKET LH, GUIDE <i>new</i>	\$ 111.00
16	1	FRT BUMPER BRACKET RH, GUIDE	\$ 111.00
17	1	FRT BUMPER SPONGE <i>excluded.</i>	\$ 263.00
18	1	FRT BUMPER REINFORCEMENT, IMPACT BAR <i>Bent</i>	\$ 927.00
19	1	LHR TAILLAMP <i>combined</i>	\$ 629.00

20	1	LHR TAILLAMP PANEL <i>Repr</i>	\$ 180.00
21	1	RHR TAILLAMP <i>Not new</i>	\$ 629.00
22	1	RHR TAILLAMP PANEL <i>Repr</i>	\$ 180.00
23	1	REAR TAILGATE <i>Distorted</i>	\$ 1,850.00
24	1	REAR TAILGATE CHROME HANDLE <i>Not new</i>	\$ 290.00
25	1	CHEVROLET LETTERING	\$ 50.00
26	1	ORLANDO LETTERING	\$ 40.00
27	1	LS LETTERING	\$ 25.00
28	1	TURBO LETTERING	\$ 45.00
29	1	CHEVROLET EMBLEM	\$ 120.00
30	1	LHR TAILGATE LAMP <i>cracked</i>	\$ 290.00
31	1	RHR TAILGATE LAMP <i>Not new</i>	\$ 290.00
32	1	REAR WINDSCREEN WITH MOULDING <i>Not new</i>	\$ 698.00
33	1	REAR TAILGATE INNER TRIM <i>Deformed</i>	\$ 340.00
34	1	REAR TAILGATE INNER LH TRIM <i>Not new</i>	\$ 150.00
35	1	REAR TAILGATE INNER RH TRIM <i>Not new</i>	\$ 150.00
36	1	REAR TAILGATE WEATHERSTRIP <i>on it</i>	\$ 240.00
37	1	REAR TAIL LID LATCH <i>Repr</i>	\$ 220.00
38	1	REAR TAIL LID STRIKER <i>new</i>	\$ 80.00
39	1	REAR BUMPER STEP PLATE <i>Missing</i>	\$ 160.25
40	1	REAR BUMPER UPPER <i>Distorted</i>	\$ 1,467.00
41	1	REAR BUMPER LOWER	\$ 540.00
42	1	REAR BUMPER SILL PLATE(SILVER) <i>Repr</i>	\$ 300.00
43	1	REAR BUMPER TOWING COVER <i>Repr</i>	\$ 75.00
44	1	LHR BUMPER REFLECTOR <i>cracked</i>	\$ 95.00
45	1	RHR BUMPER REFLECTOR <i>Missing</i>	\$ 95.00
46	1	REAR REVERSE LIGHT AND BRAKE LIGHT <i>cracked</i>	\$ 401.00
47	1	REAR BUMPER CENTRE GUIDE <i>Repr</i>	\$ 120.00
48	1	RHR BUMPER GUIDE, OTR <i>Repr</i>	\$ 60.00
49	1	LHR BUMPER GUIDE, OTR	\$ 60.00
50	1	REAR BUMPER LEFT CENTRE GUIDE, INR <i>Repr</i>	\$ 50.00
51	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00
52	1	REAR BUMPER ABSORBER <i>new</i>	\$ 190.00
53	1	REAR BUMPER BEAM <i>Bent</i>	\$ 743.00
54	1	REAR END PANEL TRIM <i>Deformed</i>	\$ 125.00
55	1	REAR END PANEL OUTER <i>Distorted</i>	\$ 680.00
56	1	REAR END PANEL INNER <i>Distorted</i>	\$ 470.00
57	1	TOOL BOX COVER <i>Deformed</i>	\$ 375.00
58	1	TOOL BOX COMPARTMENT <i>Deformed</i>	\$ 220.00

59	1	REVERSE SENSOR WIRING HARNESS <i>Not new</i>	\$ 325.00	<i>x</i>
60	1	RHR FENDER PROTECTOR <i>Not new</i>	\$ 113.00	<i>+</i>
61	1	LHR FENDER PROTECTOR <i>Not new</i>	\$ 113.00	<i>+</i>

14005.25

12604.73

Parts Total: \$ 20,958.25
Less 10%: \$ 2,095.83
Total : \$ 18,862.43

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 600.00	<i>400</i>
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 600.00	<i>400</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	<i>✓</i>
4	To refocus headlamp	\$ 80.00	<i>x</i>

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 2,000.00	<i>1400</i>
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,200.00	<i>1000</i>
3	To conduct anti rust of under carriage tuff coat	\$ 80.00	<i>50</i>
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	<i>✓</i>
5	To remove and refix reverse sensor and conduct test	\$ 80.00	<i>50</i>
6	To remove and refix reverse camera and conduct test	\$ 80.00	<i>50</i>
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00	<i>✓</i>
8	To conduct water leakage test after repairs of vehicle	\$ 80.00	<i>x</i>
9	To remove and refix rear tail gate windscreen	\$ 120.00	<i>✓</i>

3610

Labour Total : \$ 5,060.00

Others

Other Description

No. Qty

Price (SGD)

		Front portion	
1	1	Number plate with casement <i>can be</i>	\$ 45.00 <i>✓</i>
2	10	Front bumper clip <i>new</i>	\$ 65.00 <i>30</i>
3	5	Front support panel top garnish clip <i>new</i>	\$ 32.50 <i>+</i>
4	6	Front fender liner clip <i>Not new</i>	\$ 39.00 <i>+</i>

Rear portion

1	1	Rear number plate <i>lt</i>	\$	45.00	✓
2	10	Rear bumper clip <i>lt</i>	\$	65.00	30
3	6	Rear fender liner clips <i>lt</i>	\$	39.00	+
4	10	Rear end panel trim clip <i>lt</i>	\$	65.00	20
5	1	Reverse sensor (1 set) <i>lt</i>	\$	440.00	300
6	1	Rear reverse camera <i>lt</i>	\$	280.00	x.
7	1	Rear end panel insulation seal <i>lt</i>	\$	120.00	60
8	1	Rear floor panel insulation seal <i>lt</i>	\$	180.00	60
9	13	Tail gate inner trim board clip <i>lt</i>	\$	84.50	30
10	1	Tailgate windscreen moulding <i>lt</i>	\$	120.00	✓
11	1	Tailgate windscreen sealant <i>lt</i>	\$	120.00	60
12	1	Tailgate windscreen solar film <i>lt</i>	\$	200.00	+

Other Total: \$ 1,940.00

GRAND TOTAL: \$ 25,862.43

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor
Suhaimi
HP : 9189 2617 Email - aceautosolution@gmail.com

Supplementary : 2353.50

total: 19368.23

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Finalisation : Adrian

Ace Auto Solution

Registration number : 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : AIG Asia Pacific Insurance Pte. Ltd

78 SHENTON WAY

#07-16

SINGAPORE 079120

Invoice No: ACC-2015001

Invoice Date:

Vehicle No: SLD521A

Chasis No : KL1YA7589GK341924

Engine No: A14NET160880145

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
<u>1</u>	1	FRT BUMPER	\$ 1,406.00
<u>2</u>	1	FRT BUMPER LOGO	\$ 158.00
<u>3</u>	1	FRT GRILLE MIDDLE	\$ 400.00
<u>4</u>	1	FRT NUMBER PLATE GARNISH	\$ 95.00
<u>5</u>	1	FRT BUMPER LOWER GARNISH(silver colour)	\$ 333.00
<u>6</u>	1	FRT BUMPER SIDE RETAINER LH, SUPPORT	\$ 133.00
<u>7</u>	1	FRT BUMPER SIDE RETAINER RH, SUPPORT	\$ 133.00
<u>8</u>	1	FRT BUMPER BRACKET LH, GUIDE	\$ 111.00
<u>9</u>	1	FRT BUMPER BRACKET RH, GUIDE	\$ 111.00
<u>10</u>	1	FRT BUMPER SPONGE	\$ 263.00
<u>11</u>	1	FRT BUMPER REINFORCEMENT, IMPACT BAR	\$ 927.00
<u>12</u>	1	LHR TAILLAMP	\$ 629.00
<u>13</u>	1	REAR TAILGATE	\$ 1,850.00
<u>14</u>	1	CHEVROLET LETTERING	\$ 50.00
<u>15</u>	1	ORLANDO LETTERING	\$ 40.00
<u>16</u>	1	LS LETTERING	\$ 25.00
<u>17</u>	1	TURBO LETTERING	\$ 45.00
<u>18</u>	1	CHEVROLET EMBLEM	\$ 120.00
<u>19</u>	1	LHR TAILGATE LAMP	\$ 290.00
<u>20</u>	1	REAR TAILGATE INNER TRIM	\$ 340.00
<u>21</u>	1	REAR TAILGATE WEATHERSTRIP	\$ 240.00
<u>22</u>	1	REAR TAIL LID LATCH	\$ 220.00
<u>23</u>	1	REAR BUMPER STEP PLATE	\$ 160.25
<u>24</u>	1	REAR BUMPER UPPER	\$ 1,467.00
<u>25</u>	1	REAR BUMPER LOWER	\$ 540.00
<u>26</u>	1	REAR BUMPER SILL PLATE(SILVER)	\$ 300.00
<u>27</u>	1	REAR BUMPER TOWING COVER	\$ 75.00
<u>28</u>	1	LHR BUMPER REFLECTOR	\$ 95.00
<u>29</u>	1	RHR BUMPER REFLECTOR	\$ 95.00
<u>30</u>	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 401.00

31	1	REAR BUMPER CENTRE GUIDE	\$ 120.00
32	1	RHR BUMPER GUIDE, OTR	\$ 60.00
33	1	LHR BUMPER GUIDE, OTR	\$ 60.00
34	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 50.00
35	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00
36	1	REAR BUMPER BEAM	\$ 743.00
37	1	REAR END PANEL TRIM	\$ 125.00
38	1	REAR END PANEL OUTER	\$ 680.00
39	1	REAR END PANEL INNER	\$ 470.00
40	1	TOOL BOX COVER	\$ 375.00
41	1	TOOL BOX COMPARTMENT	\$ 220.00

Supplementary

42	1	LHR FENDER INNER TRIM <i>crushed</i>	\$ 450.00	✓
43	1	RHR FENDER INNER TRIM <i>crushed</i>	\$ 450.00	✓
44	1	SPARE TYRE LIFTING MECHANISM <i>best</i>	\$ 420.00	✓
45	1	LHR FENDER LINER <i>Tom</i>	\$ 90.00	✓
46	1	CONDENSOR <i>Dented</i>	\$ 875.00	✓
47	1	RHF FOGLAMP <i>crushed</i>	\$ 330.00	✓

2615
2353.50

Total: \$ 16,620.25
Less 10%: \$ 1,662.03
Parts Total : \$ 14,958.23

Labour

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 400.00
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 400.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 1,400.00
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,000.00
3	To conduct anti rust of under carriage tuff coat	\$ 50.00
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
5	To remove and refix reverse sensor and conduct test	\$ 50.00
6	To remove and refix reverse camera and conduct test	\$ 50.00
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
8	To remove and refix rear tail gate windscreen	\$ 120.00

Labour Total : \$ 3,610.00

Other

No.			Price (SGD)
Front portion			
1	1	Number plate with casement	\$ 45.00
2	10	Front bumper clip	\$ 30.00
Rear portion			
1	1	Rear number plate	\$ 45.00
2	10	Rear bumper clip	\$ 30.00
3	10	Rear end panel trim clip	\$ 20.00
4	1	Reverse sensor (1 set)	\$ 300.00
5	1	Rear end panel insulation seal	\$ 60.00
6	1	Rear flooe panel insulation seal	\$ 60.00
7	13	Tail gate inner trim board clip	\$ 30.00
8	1	Tailgate windscreen moulding	\$ 120.00
9	1	Tailgate windscreen sealant	\$ 60.00

Other Total : \$ 800.00

Total : \$ 19,368.23

Grand Total: \$ 19,368.23

Yours Faithfully,



Suhaimi

Service Executive

Tel: 9189 2617 Fax:6844 5185

Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice