



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 13.09.2018

FWD Singapore Pte. Ltd.
6 Temasek Boulevard #18-01
Suntec Tower Four
Singapore 038986

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SJK6951P TOYOTA ALTIS (2008)

To Supply

1) 1pc	Right rear door	\$	1,198.50
2) 1pc	Right rear door top hinge	\$	79.10
3) 1pc	Right rear door lower hinge	\$	78.40
4) 1pc	Right rear door checker	\$	159.40
Sub total parts		\$	1,515.40
Less: 25% discount		\$	378.85
		\$	1,136.55

L/charges

1)	To tuff kote	\$	50.00
2)	To transfer right rear door trim, handle, window glass, mechanism parts	\$	40.00
3)	To remove & replace right rear door. Knock right rear door pillar. Align & adjust right rear door.	\$	300.00
4)	To putty, respray painting right rear door inlet & outer. To polish	\$	300.00

Sub total L/charges	\$	690.00
Estimate Grand Total	\$	1,826.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanpin 97445749
- WP
14/9/18
02 days
Resurvey after repair
S40 @ lkkauto.com