

CS REC BY:

REF: CS / CWF18016804 / Tibs2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Gary Ng of Crawford Date/Time: 14092018 1057am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 1044R Insured: Public Liability

at Workshop m/s Kahn Motor Tel:

of 355 Alexandra Rd

Policy No: Claim No: 1089923 / G / GN

Sum Insured: Excess:

Make of Veh: D.O.A. 07092018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 14092018 1136am Person Contacted: Gary Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 1044R - X
	Public Liability - X
	Sent preli to Gary thru email.
	Confirm with Jack \$8,259.11 @ 8 days

Surveyor

Taylor

REF:

COF

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLP 1044R.

at Workshop m/s Kah Motor.

of 355 Alexandra Rd.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Owner Owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP1044R.

Yr Regn:

2017 May

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey.

C.C.

2356

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

024472.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

SHMRC18809C209261.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim, or

Tyre Size:

F:

215/55R17

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

0

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Kah Motor

12/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rooftop, windshield

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Call Gary to confirm report type: soft & hardcopy.

RECEIVED 00 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) typst

☒

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

7P

Lump Sum / I.B.I: (\$ 2299.11

170

50

50

30

80

380

Catherine Chong (LKK Auto)

From: gary.ng@crawford.com.sg
Sent: Friday, 14 September, 2018 10:57 AM
To: assignments@lkkauto.com
Subject: Re: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018

Dear Catherine

We refer to our discussion and confirm that we are the Loss Adjusters appointed by AXA Insurance Pte Ltd to look into the above matter on a 'without prejudice' basis.

This incident reportedly involved a window dislodged and hit a car SLP 1044R causing damage to its windscreen and roof.

The car repairs estimated at S\$10,000.00.

On behalf of AXA Insurance Pte Ltd, kindly assist to arrange your motor surveyor to survey this car SLP 1044R.

Please contact Mr Jack Ng at 82886309 (of Kah Motors - Body Repair and Paint Centre), 255 Alexandra Road Singapore 159937 to arrange the survey.

Please let us have your motor surveyor report with the invoice addressed to the following: -

AXA Insurance Pte Ltd
c/o Crawford & Company International Pte Ltd
8 Shenton Way
#03-01 AXA Tower
Singapore 068811

Kindly acknowledge this assignment.

Please contact us if you have any further queries.

Regards

Gary Ng • B.Sc(Hons), M.Sc, ACLA, ANZIIIF (Snr Assoc), CIP • Manager • Singapore
Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXA Tower, 068811, Singapore
Direct: +65 6632 8648 • Mobile: +65 8809 9498 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email:
gary.ng@crawford.com.sg • Web Site: www.crawfordandcompany.com



From: Gary Ng/SG/Crawco-AP
To: assignments@lkk.com
Date: 14/09/2018 10:57 AM
Subject: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018

Dear Catherine

We refer to our discussion and confirm that we are the Loss Adjusters appointed by AXA Insurance Pte Ltd to look into the above matter on a 'without prejudice' basis.

This incident reportedly involved a window dislodged and hit a car SLP 1044R causing damage to its windscreen and roof.

The car repairs estimated at S\$10,000.00.

On behalf of AXA Insurance Pte Ltd, kindly assist to arrange your motor surveyor to survey this car SLP 1044R.

Please contact Mr Jack Ng at 82886309 (of Kah Motors - Body Repair and Paint Centre), 255 Alexandra Road Singapore 159937 to arrange the survey.

Please let us have your motor surveyor report with the invoice addressed to the following: -

AXA Insurance Pte Ltd
c/o Crawford & Company International Pte Ltd
8 Shenton Way
#03-01 AXA Tower
Singapore 068811

Please contact us if you have any further queries.

Regards

Gary Ng • B.Sc(Hons), M.Sc, ACLA, ANZIIF (Snr Assoc), CIP • Manager • Singapore
Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXA Tower, 068811, Singapore
Direct: +65 6632 8648 • Mobile: +65 8809 9498 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email:
gary.ng@crawford.com.sg • Web Site: www.crawfordandcompany.com



Please think of the environment before printing out this message.

This message and any files transmitted with it may contain confidential, proprietary or legally privileged information and is intended solely for the use of the individual or entity to whom it is addressed. No confidentiality or privilege is waived or lost by any mistransmission. If you have received this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not review or in any way use or publish the content to any party. Crawford reserves the right to monitor communications through its network.

Please think of the environment before printing out this message.

This message and any files transmitted with it may contain confidential, proprietary or legally privileged information and is intended solely for the use of the individual or entity to whom it is addressed. No confidentiality or privilege is waived or lost by any mistransmission. If you have received this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not review or in any way use or publish the content to any party. Crawford reserves the right to monitor communications through its network.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, September 27, 2018 9:13 AM
To: gary.ng@crawford.com.sg
Subject: RE: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018
Attachments: SLP 1044R.pdf

Dear Gary,

Enclosed preliminary revised for SLP 1044R.

Kindly let us have your reference number.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: gary.ng@crawford.com.sg [mailto:gary.ng@crawford.com.sg]
Sent: Friday, September 14, 2018 2:04 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018

Dear Catherine

Thank you for your assistance.

We look forward to hear from you further in due course.

Regards

Gary Ng • B.Sc(Hons), M.Sc, ACLA, ANZIIF (Snr Assoc), CIP • Manager • Singapore
Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXA Tower, 068811, Singapore
Direct: +65 6632 8648 • Mobile: +65 8809 9498 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email:
gary.ng@crawford.com.sg • Web Site: www.crawfordandcompany.com



From: "Catherine Chong \LKK Auto\" <admin-d@lkkauto.com>
To: <gary.ng@crawford.com.sg>
Cc: 'assignments' <assignments@lkkauto.com>, 'SUR' <sur@lkkauto.com>
Date: 14/09/2018 11:38 AM
Subject: RE: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018

Dear Gary,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: gary.ng@crawford.com.sg [<mailto:gary.ng@crawford.com.sg>]
Sent: Friday, 14 September, 2018 10:57 AM
To: assignments@lkkauto.com
Subject: Re: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018

Dear Catherine

We refer to our discussion and confirm that we are the Loss Adjusters appointed by AXA Insurance Pte Ltd to look into the above matter on a 'without prejudice' basis.

This incident reportedly involved a window dislodged and hit a car SLP 1044R causing damage to its windscreen and roof.

The car repairs estimated at S\$10,000.00.

On behalf of AXA Insurance Pte Ltd, kindly assist to arrange your motor surveyor to survey this car SLP 1044R.

Please contact Mr Jack Ng at 82886309 (of Kah Motors - Body Repair and Paint Centre), 255 Alexandra Road Singapore 159937 to arrange the survey.

Please let us have your motor surveyor report with the invoice addressed to the following: -

AXA Insurance Pte Ltd
c/o Crawford & Company International Pte Ltd
8 Shenton Way
#03-01 AXA Tower
Singapore 068811

Kindly acknowledge this assignment.

Please contact us if you have any further queries.

Regards

Gary Ng • B.Sc(Hons), M.Sc, ACLA, ANZIIF (Snr Assoc), CIP • Manager • Singapore
Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXA Tower, 068811, Singapore

Janice Lee (LKKAUTO)

From: gary.ng@crawford.com.sg
Sent: Thursday, September 27, 2018 9:35 AM
To: Janice Lee (LKKAUTO)
Subject: RE: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018 | Crawford Ref : 1089923/G/GN

Dear Janice

Thank you for your email of 27.9.18.

Kindly note our claim reference no. as above.

We have checked and confirm that we do not have the GIA report as the third party had asked Kah Motors to make the claim against us. Could you assist to ask Jack of Kah Motors to see if he can pass you a copy.

Meantime, for your information, our investigations on the incident on a 'without prejudice' basis are as follows:-
Our Principal's Insured, Bounty Design Pte Ltd is carrying out interior renovation works to an apartment at No. 1 Pandan Valley #06-104, Singapore 597625.

At about 9.30 am on Friday, 7 September 2018, Bounty Design's worker was pushing open the bathroom window to ventilate the apartment, when the window suddenly broke at its hinge and fell from #06-104. The window landed on the car SLP 1044R.

We await your report on the matter.

Regards

Gary Ng • B.Sc(Hons), M.Sc, ACLA, ANZIIF (Snr Assoc), CIP • Manager • Singapore
Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXA Tower, 068811, Singapore
Direct: +65 6632 8648 • Mobile: +65 8809 9498 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email:
gary.ng@crawford.com.sg • Web Site: www.crawfordandcompany.com



From: "Janice Lee (LKKAUTO)" <JaniceLee@lkkauto.com>
To: "gary.ng@crawford.com.sg" <gary.ng@crawford.com.sg>
Date: 27/09/2018 09:13 AM
Subject: RE: Our Principal : AXA Insurance Pte Ltd - Window dislodged and hit onto vehicle SLP1044R on 07/09/2018

Dear Gary,

Enclosed preliminary revised for SLP 1044R.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/09/2018 16:09
Date Of Accident	07/09/2018 09:20
Exact Location Of Accident	1 PANDAN VALLY (S)597625 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP1044R
Insured/Policyholder	
Name Of Registered Owner	JOGJAMAN JAP
NRIC No	S8579008J
Email Address	JOGJAMAN@SPECTRONIK.COM
Mobile Phone No	(LOCAL) +65-98158945
Alternative Phone No	OFFICE-98158945

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY 2.4

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JOGJAMAN JAP
NRIC No	S8579008J
Date Of Birth	16/06/1985
Occupation	INDOOR
Date Of Driving Pass	22/08/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98158945
Fax Number	
Contact Number	OFFICE-98158945
Email Address	JOGJAMAN@SPECTRONIK.COM

Address	1 PANDAN VALLY #08-103
Postcode	597625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	0

Details of Police Action





Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	



Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Vehicle No <u>SLP 1044 R</u>	SKETCH PLAN	APPCA B
IMPORTANT NOTICE		
1. Please report correctly the details of the accident to speed up the claims process. 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u> . 3. Information provided must be as <u>truthful and accurate as possible</u> . Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u> . 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. 5. <u>Any false reporting may be referred to the Police for investigation.</u> 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties. 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid. 8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that: (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of: (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims; (ii) investigating the accident and/or my claims; (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me; (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes") (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.		
 7 SEPT 2018	 7 SEPT 2018	
Policyholder's Signature / Date & Time	Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
Sketch Plan		
		
Please continue to Annex C		

<p>Vehicle No <u>SLP 1044R</u></p>	<p>Amber E</p>
<p>Describe Circumstances of the Accident</p> <ul style="list-style-type: none"> • Car was parked at 1 Pandan valley Carpark. • Construction work was ongoing at #06-104 directly above car. • Toilet window was dropped & smashed the car windshield & roof. • Construction company (Bounty Design Pte Ltd) willing to pay for all damages. • No one was injured. 	
<div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a <u>Fourteen (14) days clause</u> whereby the claim must be made within the stipulated timeframe from the day of occurrence.</p> </div>	
<p>Declaration</p> <p>We declare the foregoing particulars are true in every respect.</p>	
	
<p>Policyholder's Signature / Date & Time</p>	<p>Driver's Signature (If driver is not the policyholder) / Date & Time</p>
<p>Witnessed by Reporting Centre Personnel</p>	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9008J
Vehicle Details	
Vehicle No.:	SLP1044R
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Purple
Manufacturing Year:	2016
Engine No.:	K24W72013815
Chassis No.:	JHMRC1880GC209261
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,653.00
Original Registration Date:	25 May 2017
First Registration Date:	25 May 2017
Transfer Count:	0
Actual ARF Paid:	\$30,715.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2027
PARF Rebate Amount:	\$23,036.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$47,094.00
Total Rebate Amount:	\$70,130.00

The information contained herein is correct as at 27 Sep 2018

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLP1044R

Chassis No : JHMRC1880GC209261

Model : ODYSSEY 2.4 EX-S 16YM

Owner's Name : JOGJAMAN JAP

Ins Policy No. :

Date of Accident : 7/9/2018

Document No. : SQT18003788

Date : 10. Sep 2018

Customer No. : WZA006

Svc Advisor : JACK NG

Engine No : K24W72013815

Date | Time : 10. Sep 2018 7:48:54 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: JOGJAMAN JAP						
	OWNER INSURER: AVIVA						
	ACC DATE: 08/09/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA						
	TP VEH:						
62100-T6A-405ZZ	PANEL COMP.ROOF	1 <i>bt</i>	1097.10	25	822.82	57.60	880.42
93404-08016-08	BOLT-WASHER8X16	8 <i>ne</i>	0.70	25	4.20	0.29	4.49
73111-T6A-U01	GLASS SET,FR.WINDSHIELD	1 <i>cm</i>	2318.90	25	1739.17	121.74	1860.91
73126-SYY-000	RUBBER BFR W/SHIELD	3 <i>ne</i>	3.60	25	8.10	0.57	8.67
73163-T6A-013	MOLDINGL.DRIP SIDE	1 <i>ne</i>	235.00	25	176.25	12.34	188.59
73153-T6A-013	MOLDING,R.DRIP SIDE	1 <i>ne</i>	235.00	25	176.25	12.34	188.59
73150-T6A-003	MOLDINGFR.WINDSHIELD	1 <i>ne</i>	19.20	25	14.40	1.01	15.41
77466-TL0-G01	SEALFR.INSTRUMENT	1 <i>ne</i>	13.30	25	9.97	0.70	10.67
91568-TA0-A00	CUPFR WINDSHIELD UPPER	2 <i>ne</i>	5.80	25	8.70	0.61	9.31
BO-IU-BKT(NEW)	IU BRACKET TAPE(N)	1 <i>ne</i>	26.00		26.00	1.82	27.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 <i>ne</i>	60.00		120.00	8.40	128.40
Sum Item					3105.86	217.42	3,323.28
BO-V-KOOL-FWS	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN.	1 <i>✓</i>	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00
BOSUN	SUNDRIES	1 <i>ne</i> <i>30</i>	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT ROOF	1 <i>ne</i> <i>80</i>	100.00		100.00	7.00	107.00
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1 <i>560</i>	800.00		800.00	56.00	856.00
BG01D	REMOVE & INSTALL FR. WINDSCREEN.(N)	1 <i>✓</i>	560.00		560.00	39.20	599.20

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLP1044R

Chassis No : JHMRC1880GC209261

Model : ODYSSEY 2.4 EX-S 16YM

Owner's Name : JOGJAMAN JAP

Ins Policy No. :

Date of Accident : 7/9/2018

Document No. : SQT18003788

Date : 10. Sep 2018

Customer No. : WZA006

Svc Advisor : JACK NG

Engine No : K24W72013815

Date | Time : 10. Sep 2018 7:48:54 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKROR	REMOVE & RENEW ROOF PANEL.	1	2800.00		2800.00	196.00	2996.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	1	1500.00		1500.00	105.00	1605.00
Sum Labor					5960.00	417.20	6,377.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,365.86 655.62 10,021.48

Total (Inclusive of GST) 10,021.48

cc: suv@lkkauto.com

Resurvey before paint

3 days.

tayfah e lkkauto.com

27/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 10/9/2018 8:46:03 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 40851. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRC1880GC209261
License No: SLP1044R
Mileage: 24894
Engine No: K24W72013815

Document No: SVO18056202
Printed By: JACKNG
Order Date: 24. September 2018
Order Time: 1:43:21 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: JOGJAMAN JAP						
	OWNER INSURER: AVIVA						
	ACC DATE: 08/09/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA						
	TP VEH:						
62100-T6A-405ZZ	PANEL COMP,ROOF	1	1,097.10	25	822.82	57.60	880.42
93404-08016-08	BOLT-WASHER8X16	8	0.70	25	4.20	0.29	4.49
73111-T6A-Q11	GLASS SETFR.WINDSHIELD	1	2,189.90	25	1,642.42	114.97	1,757.39
73126-SYY-000	RUBBER BFR W/SHIELD	3	3.60	25	8.10	0.57	8.67
73163-T6A-013	MOLDINGL.DRIP SIDE	1	235.00	25	176.25	12.34	188.59
73153-T6A-013	MOLDING,R.DRIP SIDE	1	235.00	25	176.25	12.34	188.59
73150-T6A-003	MOLDINGFR.WINDSHIELD	1	19.20	25	14.40	1.01	15.41
77466-TL0-G01	SEALFR.INSTRUMENT	1	13.30	25	9.97	0.70	10.67
91568-TA0-A00	CUPFR WINDSHIELD UPPER	2	5.80	25	8.70	0.61	9.31
BO-IU-BKT(NEW)	IU BRACKET TAPE(N)	1	26.00		26.00	1.82	27.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
	SUM PARTS:				3,009.11	210.65	3,219.76
BOSUN	0671	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOJSE	1610	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT ROOF						
BMI01D	1757	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL ROOF LINING						
	GARNISHES SEATS						
	SPEAKER BOARD CARPET & ETC.(N)						
BG01D	1757	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL FR. WINDSCREEN.						
	(N)						
BODAMKIT	0671	1	100.00		100.00	7.00	107.00
	WINDSCREEN DAM KIT.						
BKROR	0671	1	2,240.00		2,240.00	156.80	2,396.80
	REMOVE & RENEW ROOF PANEL.						
BP02R	1610	1	1,350.00		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR						
	REPLACED AREAS.(2P)						
	SUM LABOUR:				4,920.00	344.40	5,264.40
BO-V-KOOL-FWS	SUPPLY & INSTALL SOLAR FILM ON	1	300.00		300.00	21.00	321.00
	FRONT WINDSCREEN.						
	SUM EXT SERVICE:				300.00	21.00	321.00
	TOTAL SGD				8,229.11	576.05	8,805.16
	Total Payable (SGD)						8,805.16

GST Amount is calculated from individual line(s)

Janice Lee (LKKAuto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Wednesday, October 03, 2018 10:58 AM
To: gary.ng@crawford.com.sg; claims@insurehub.com.sg; Admin-D (LKKAuto)
Subject: FINALIZATION FOR SLP 1044 R
Attachments: 4818_001.pdf; FW: Resurvey B4 Paint _ SLP 1044 R

Importance: High

Dear All,

We enclosed the total final repair costs for,

Vehicle No.	SLP 1044 R
Final Repair Costs (exclude GST)	S\$8,299.11
Repair Period* (Days)	8 WORKING DAYS

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

Janice Lee (LKKAUTO)

From: Jack Ng <jackng@honda.com.sg>
Sent: Monday, October 08, 2018 10:59 AM
To: Janice Lee (LKKAUTO)
Cc: SUR
Subject: RE: FINALIZATION FOR SLP 1044 R

Dear Janice,

Noted with thanks

Jack

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Sent: Monday, October 08, 2018 10:51 AM
To: Jack Ng <jackng@honda.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: FINALIZATION FOR SLP 1044 R

Dear Jack,

Confirm \$8,229.11 @ 8 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng [<mailto:jackng@honda.com.sg>]
Sent: Wednesday, October 03, 2018 10:58 AM
To: gary.ng@crawford.com.sg; claims@insurehub.com.sg; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: FINALIZATION FOR SLP 1044 R
Importance: High

Dear All,

We enclosed the total final repair costs for,

Vehicle No.	SLP 1044 R
Final Repair Costs (exclude GST)	S\$8,299.11
Repair Period* (Days)	8 WORKING DAYS




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CRAWFORD & COMPANY INTERNATIONAL PL		Ref : CS/CWF18016804/T1rbs2		
NO.8 SHENTON WAY #03-01 AXA TOWERSINGAPORE 068811		Date : 08-10-2018		
		Code : CWF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLP 1044R	
Policy No.		Coverage (\$)	0.00	
Claim No.	1089923/G/GN	Excess (\$)	0.00	
Assign From	GARY NG	Assign Date	14/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1880GC209261	Colour	GREY	
Odometer	024472	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55R17	DUNLOP	6 mm	
L/H Front Tyre	215/55R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP AND WINDSCREEN. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2018	Inspection Date	17/09/2018	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 1044R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL COMP, ROOF (SN)	BENT	822.82	822.82
8	BOLT-WASHER8X16 (SN)	NECESSARY	4.20	4.20
1	GLASS SET,FR.WINDSHIELD (SN)	CRACKED	1,739.17	1,642.42
3	RUBBER BFR W/SHIELD (SN)	NECESSARY	8.10	8.10
1	MOLDINGL.DRIP SIDE (SN)	NECESSARY	176.25	176.25
1	MOLDING,R.DRIP SIDE (SN)	NECESSARY	176.25	176.25
1	MOLDINGFR.WINDSHIELD (SN)	NECESSARY	14.40	14.40
1	SEALFR.INSTRUMENT (SN)	NECESSARY	9.97	9.97
2	CUPFR WINDSHIELD UPPER (SN)	NECESSARY	8.70	8.70
1	IU BRACKET TAPE (SN)	NECESSARY	26.00	26.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	BODY JOINT SEALANT ROOF (SN)	NECESSARY	100.00	80.00
1	WINDSCREEN DAM KIT (SN)	NECESSARY	100.00	100.00
			3,405.86	3,219.11
LABOUR				
	SUPPLY & INSTALL SOLAR FILM ON FRONT WINDSCREEN.		300.00	300.00
	REMOVE & INSTALL ROOF LINING GARNISHES SEATS.		800.00	560.00
	REMOVE & INSTALL FR. WINDSCREEN.		560.00	560.00
	REMOVE & RENEW ROOF PANEL.		2,800.00	2,240.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,500.00	1,350.00
			5,960.00	5,010.00
GRAND TOTAL			9,365.86	8,229.11
RECOMMENDED COST REPAIRS				8,299.11

Report Ref No. CS/CWF18016804/T1rbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.