

ASS. REC. BY:

REF:

CS/ALH18016805/Agbnz

Special Instruction:

SURVEXOR

Aadnan

ASSIGNMENT (Office)

From (Person):

Nushwan

of

Alh

Date/Time: 14/09/2018 10:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 8946A

Insured:

GBF 7646K

at Workshop m/s

ACE Autolubation

Tel:

6844 1184

of

13 Kaki Bukit Rd 4 #03-39

Policy No:

2100502458

Claim No:

590477765454

Sum Insured:

Excess:

Make of Veh:

D.O.A

13092018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpr

H.O.D. Endorsement:

Date/Time:

14/09/2018 10:56am

Person Contacted:

Anna

Vehicle (IN) / OUT

Date/Time

Action/Instruction (✓) Estimate

SLX 8946A - x

GBF 7646K - x

US \$ 4600, 5 days Cred \$ 9877, 68%.

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX8946A Yr Regn: 2018 AprilType: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel cc 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 14611 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ru1123280Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/09/18Survey held at ACE AutomationDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

RECEIVED 05 SEP 2019

86119101

Date/Time, File Pass to?

☐ : Preli. Report1) 05/11/18 turner☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

\$ + RE \$

Photos

Others

TOTAL

150

20

270

Report Format: MEK-7PLump Sum / I.B.T. (\$) 4600

- Pre repair inspection request - SLX8946A VS GBF7646K (OI) DOA: 13/09/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Sent: Friday, 14 September, 2018 10:22:23 AM
Attachments: 20180914171719914.pdf

Hi,

Please refer to the enclosed request from CHIA S ARUL LLC.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours.

If you have any queries/concerns, please let us know.

Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Weng Kit [mailto:wengkit@chiaarul.com]
Sent: Friday, September 14, 2018 10:04 AM
To: Mithoosingh, Aashweenjeetkaur
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi; 'Jerone'
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF7646K AND SLX8946A ON 13/09/2018

Dear Sirs,

We refer to your email below.

Our client would like to appoint Adrian Ling – LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE) for the matter herein.

Kindly let us have your confirmation on the same.

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of internet transmission.

From: Mithoosingh, Aashweenjeetkaur [mailto:Aashweenjeetkaur.Mithoosingh@aig.com]
Sent: Friday, September 14, 2018 8:18 AM
To: wengkit@chiaarul.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF7646K AND SLX8946A ON 13/09/2018



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสเพื่ออ่านฉบับเปิดให้สิทธิ์เฉพาะ

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 열어야 합니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-09-21 08:17 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2008-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Aashweenjeet Kaur Mitthosingh@aig.com

To: wengkit@chiaarui.com

Cc: Lily Tan@aig.com, Andy-SY.Fong@aig.com, Baljit Kaur@aig.com, Lee-

Ying.Chin@aig.com, NoorManesa.AbuKassim@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF7646K AND SLX8946A ON 13/09/2018

Date: Fri, 14 Sep 2018 00:17:45 +0000

Without Prejudice

Your Reference : SLX 8946A (wk)

Our Reference : GBF7646K

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Weng Kit [mailto:wengkit@chiaarui.com]

Sent: Thursday, September 13, 2018 5:18 PM

To: AIG SGP, Claims-Survey

Cc: 'Jerome'

Subject: Our Ref: SLX 8946A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SLX 8946A & GBF 7646K ALONG BEACH ROAD ON 13 SEPTEMBER 2018

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 13 September 2018 for your attention.

Best Regards,

Mr Wang Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiasarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SLX 8946A (wk)

Your Ref : To be advised

13 September 2018

AIG Asia Pacific Insurance Pte Ltd

BY EMAIL ONLY

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : HITACHI CAPITAL ASIA PACIFIC PTE LTD
ACCIDENT INVOLVING SLX 8946A & GBF 7646K ALONG BEACH ROAD ON
13 SEPTEMBER 2018
PRE-REPAIR SURVEY NOTICE

1. We act for Hitachi Capital Asia Pacific Pte Ltd, the owner of motor vehicle no. SLX 8946A which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. GBF 7646K for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	Ace Autolution
Address	13 Kaki Bukit Road 4 #03 - 29 Bartley Biz Centre Singapore 417807
Contact Person	Ms. Anna (6844 1184)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiasarul.com

M/s Chia S Arul LLC
Page 2

Our Ref : SLX 8946A (wk)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

Enquire Vehicle & Owner Information (Vehicle No. GBF7646K As At 13 Sep 2018 / 13:06:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SLX8946A

Current Owner Details

Owner ID Type: Company
Owner ID: 201500674C
Owner Name: A MEDIA PRINT PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 970
Registered Street Name: TOA PAYOH NORTH
Registered Unit No.: # 06 - 22
Registered Building Name: -
Registered Postal Code: 318992

Current Vehicle Details

Vehicle No.: GBF7646K
Make Description/Model: NISSAN / NV350 PANEL VAN 2.5 SAT 5DR EURO V
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



ACE AUTOLUTION

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

96572154

Ru11233280

Page No. 1

Vehicle No. SLX 8946 A HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT	
PARTS (LIST ITEMS)						
2	FRONT FENDER RH & LH @ \$850.00 <i>LH dated</i>	<i>11434.90</i> <i>3547.92</i>		1700.00	<i>688.70</i>	
2	FRONT FENDER WHEEL ARCH GARNISH RH & LH @ \$385.00 <i>cut</i>			770.00	<i>310.60</i>	
1	FRONT FENDER INNER SHIELD LH <i>top</i>			270.00	<i>189.80</i>	
1	HEADLAMP LH <i>deleted</i>			2150.00	<i>1784.50</i>	
1	HEADLAMP BRACKET LH <i>new</i>			210.00	X	
1	FRONT BUMPER <i>distorted</i>			1250.00	<i>880</i>	
1	FRONT BUMPER SIDE RETAINER LH <i>cond.</i>			85.00	<i>25.30</i>	
1	FRONT BUMPER LOWER GRILLE <i>Garnish - deleted</i>			550.00	<i>351</i>	
1	FOGLAMP COVER LH <i>new</i>			420.00	X	
1	FRONT DOOR LH <i>new</i>			1150.00	X	
1	FRONT BONNET <i>new</i>			1510.00	X	
1	LOWER ARM LH <i>new</i>			500.00	<i>X 385.30</i>	
1	KNUCKLE ARM LH <i>new</i>			600.00	<i>X</i>	
1	WHEEL BEARING LH <i>new</i>			350.00	<i>X 245</i>	
				11715.00		
			less 20%	2343.00	20%	
				9372.00		
SPECIAL NETT ITEMS						
1 SET	FRONT BUMPER CLIPS <i>new</i>	<i>830</i>		50.00	<i>30</i>	
1 SET	FRONT WHEEL ARCH CLIPS <i>new</i>			50.00	✓	
1	SPORT RIM LH <i>cut</i>			980.00	<i>550</i>	
1	FRONT TYRE RH <i>cut</i>			350.00	<i>200</i>	
Total Parts				10802.00		

**ACE AUTOLUTION**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SLX 8946 A HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1400.00 <i>700</i>	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 <i>600</i>	
3	To remove and refix wiring at damaged areas	200.00 <i>30</i>	
4	To perform anti rust treatment on affected areas	240.00 <i>x</i>	
5	To do tyre rotation & balancing	100.00 <i>x</i>	
6	To conduct full computerised wheel alignment test	180.00 <i>80</i>	
7	Check for proper functions and focus headlamp beam	100.00 <i>x</i>	<i>1410</i>
8	To remove & refix front undercarriage parts	200.00 <i>x</i>	
	Labour Total :	3620.00	
	TOTAL (PARTS & LABOUR):	14422.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 5787.92
h/c: A6K
05 Days

A6K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18016805/AQBN2

Date: 09/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100502458
Claimant Vehicle No :	SLX8946A	Insured Vehicle No :	GBF7646K
Date of Loss:	13/09/2018	Nature of Claim:	TP
		Claim No:	5804777654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX8946A	Engine No:	L15B4433289
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11233280
Reg. Date:	16/04/2018 (Man. Year: 2018)	Odometer:	14611 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,802.00	4,377.92	6,424.08	59.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,410.00	2,210.00	61.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,422.00	5,787.92	8,634.08	59.87
Approved Total (Overridden) (\$\$)		4,600.00		
Nett Amount (\$\$)	14,422.00	4,600.00	9,822.00	68.10

INSPECTION

Date of Assignment:	14/09/2018	
Date Inspected:	14/09/2018	Inspected At:
		Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER RH & LH	N/s Dented	1,700.00 FL	*688.70 FL
2	2	*FRONT FENDER WHEEL ARCH GARNISH RH & LH	Cut	770.00 FL	*310.60 FL
3	1	*FRONT FENDER INNER SHIELD LH	Torn	270.00 FL	*149.80 FL
4	1	*HEADLAMP LH	Cracked	2,150.00 FL	*1,784.50 FL
5	1	*HEADLAMP BRACKET LH	Not Necessary	210.00 FL	*- FL
6	1	*FRONT BUMPER	Distorted	1,250.00 FL	*880.00 FL
7	1	*FRONT BUMPER SIDE RETAINER LH	Damaged	85.00 FL	*25.30 FL
8	1	*FRONT BUMPER LOWER GARNISH	Deformed	550.00 FL	*351.00 FL
9	1	*FOGLAMP COVER LH	Not Necessary	420.00 FL	*- FL
10	1	*FRONT DOOR LH	Not Necessary	1,150.00 FL	*- FL
11	1	*FRONT BONNET	Not Necessary	1,510.00 FL	*- FL
12	1	*LOWER ARM LH	Not Necessary	500.00 FL	*- FL
13	1	*KNUCKLE ARM LH	Not Necessary	600.00 FL	*- FL
14	1	*WHEEL BEARING LH	Damaged	550.00 FL	*245.00 FL
15	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1	*SET FRONT WHEEL ARCH CLIPS	Necessary	50.00 FS	*50.00 FS
17	1	*SPORT RIM LH	Cut	980.00 FS	*550.00 FS
18	1	*FRONT TYRE RH	Cut	350.00 FS	*200.00 FS

F=Franchise part. S=SpchNett. L=ListItemDisc.

Sub Total (\$\$) 13,145.00 5,264.90
 - List Item Discount on L Items 20.00/20.00% (\$\$) 2,343.00 886.98

Total Parts (\$\$) 10,802.00 4,377.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	700.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY.RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	600.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	200.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	240.00	0.00
5	TO DO TYRE ROTATION & BALANCING	New	100.00	0.00
6	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST	New	180.00	80.00
7	CHECK FOR PROPER FUNCTIONS AND FOCUS HEADLAMP BEAM	New	100.00	0.00
8	TO REMOVE & REFIX FRONT UNDERCARRIAGE PARTS	New	200.00	0.00
Gross Labour Cost (S\$)			3,620.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >